

PCI Bus/PCI Express

Motor Control Board

MC8000P Device Driver

User's Manual

2018-01-30 Ver. 8.0.0.0

Supported board

MC8000P series	MC8043P/ MC8043Pe
	MC8082P/ MC8082Pe
	MC8022P
	MC8042P
MC8500P series	MC8541P/ MC8541Pe
	MC8581P/ MC8581Pe

NOVA electronics

Introduction

■ Before You Begin

Before using MC8000P and MC8500P, please read this manual carefully to fully understand for correct use and observe all the instructions given in this manual. We shall be exempted from taking responsibility and held harmless for damage or losses incurred by the user if the user fails to observe the instructions.

Information in this manual is subject to change without notice.

You can download the latest manual and software from our web site: <http://www.novaelec.co.jp/eng>

■ Board Manual

Regarding the board specifications, please refer to the User's Manual of each board.

■ Terms in this Manual

IC

IC indicates IC chips such as MCX314As, MCX304 or MCX514.

IC-A, IC-B

When a board has multiple IC chips on it, the first IC is described as "IC-A", and the second IC is described as "IC-B".

When a board has only one IC chip on it, the IC is described as "IC-A".

1.Outline	1
1.1 Boards	1
1.2 Operating Systems	1
1.3 Languages.....	1
1.4 Maximum Number of Boards	1
1.5 IC on the Board	1
2.Installation	2
2.1 Preparation of Driver Software	2
2.2 Settings When Using Multiple Boards	2
2.3 Installation of the Board into your PC	2
2.4 Installation of Device Driver.....	2
2.5 Uninstallation of Device Driver	5
2.5.1 Uninstallation of Device Driver	5
2.5.2 Uninstallation When the Different kinds of the Boards are installed.....	9
2.6 Updating Device Driver.....	9
3.Programming.....	13
3.1 Operating Environment.....	13
3.2 Software Configuration	13
3.2.1 Software List	13
3.2 When error occurs in executing sample program and evaluation tool.....	15
3.3 Development Procedure	16
3.3.1 When using VC++	16
3.3.2 When using VB.NET	16
3.3.3 When using C#.....	16
4.MC8000P series board.....	17
4.1 API.....	17
4.1.1. Function list.....	17
4.1.2. Function Specifications.....	20
4.1.3. Footnote.....	71
4.1.4. Usage.....	84
4.2 Notes on Programming.....	89
4.3 Evaluation Tool of MCX304	91
4.3.1 Execution Program.....	91
4.3.2 Function Overview.....	91
4.3.3 Main Window.....	92
4.3.4 Mode Setting Window	93
4.3.5 Automatic Home Search Mode Setting Window.....	93

4.3.6	Status Window	94
4.3.7	Port A, B, C Output Window	94
4.4	MCX314As Evaluation Tool	94
4.4.1	Execution Program.....	94
4.4.2	Function Overview.....	95
4.4.3	Main Window.....	95
4.4.4	Mode Setting Window	96
4.4.5	Expansion Mode Setting Window	96
4.4.6	Synchronous Action Mode Setting Window	96
4.4.7	Status Window	97

5.API for MC8500P series..... 98

5.1	API.....	98
5.1.1	Function List.....	98
5.1.2	Function Specifications.....	102
5.1.3	Footnote.....	196
5.1.4	Usage.....	212
5.2	Notes on Programming.....	219
5.3	Evaluation tool for MCX514.....	220
5.3.1	Execution Program.....	220
5.3.2	Function overview	220
5.3.3	Main Window.....	221
5.3.4	Write register setting window.....	222
5.3.5	Synchronous action setting window.....	223
5.3.6	Automatic home search setting window.....	223
5.3.7	PIO signal setting window	224
5.3.8	Multi-purpose register / input signal filter setting window.....	224
5.3.9	Interpolation mode setting window	224
5.3.10	Read register window.....	225

1. Outline

This device driver is a common device driver for the PCI-bus/PCI Express motor control board of NOVA electronics. Regarding the specifications of the board, please refer to the user's manuals of each board and IC.

1.1 Boards

This device driver supports the following boards. Multiple boards can be installed into a single PC.

Supported Boards	
MC8000P series	MC8043P / MC8043Pe
	MC8082P / MC8082Pe
	MC8022P
	MC8042P
MC8500P series	MC8541P/MC8541Pe
	MC8581P/MC8581Pe

1.2 Operating Systems

This device driver supports the following OS.

Supported OS
Windows7(32bit,64bit)
Windows8.1(32bit,64bit)
Windows10(32bit,64bit)

1.3 Languages

This device driver supports the following languages.

The user can control each board from an application by calling DLL provided by NOVA electronics.

Supported Languages
Microsoft Visual C++
Microsoft Visual Basic
Microsoft Visual C#

Note: Supported version of Microsoft Visual Studio and the latest information about development environment and OS for each language, see the Microsoft website and our website.

1.4 Maximum Number of Boards

This device driver can recognize the boards up to 16 simultaneously.

When using multiple boards in a single PC, the device driver also can recognize the boards up to 16 simultaneously.

1.5 IC on the Board

Each board is equipped with 1 or more ICs, as shown in the table below.

Board	IC	Number of IC	Number of Axis
MC8043P / MC8043Pe	MCX314As	1	4
MC8082P / MC8082Pe	MCX304	2	8
MC8022P	MCX304	1	2
MC8042P	MCX304	1	4
MC8541P / MC8541Pe	MCX514	1	4
MC8581P / MC8581Pe	MCX514	2	8

2. Installation

This chapter describes how to install the board into your PC and install the device driver.

2.1 Preparation of Driver Software

When installing the driver from CD-ROM, prepare MC8000P device driver CD-ROM.

When installing the driver from the downloaded file from our homepage, extract the file.

2.2 Settings When Using Multiple Boards

This device driver can recognize the boards up to 16 simultaneously.

When using multiple boards on a system (PC), in order to individually recognize each board, set the board number of second or later board by the rotary switch on the board. For the location of the rotary switch (SW1), see chapter "Board Dimensions" in the user's manual of each board.

The rotary switch can be set from 0 to F. Make sure that there is no duplicate number among multiple boards and the different boards.

The rotary switch of factory default is set to 0.

2.3 Installation of the Board into your PC

Note: Make sure the PC's power is shut off before installing the board. Otherwise, the circuit elements may be damaged.

- (1) Make sure that the PC is powered OFF, and then remove the external cover and slot cover.
- (2) Insert the board into an empty expansion slot. Be sure that the board's edge connector fits into the PC's PCI bus/PCI Express connector.
- (3) Screw the mounting bracket. Make sure that you fix the screws appropriately; otherwise, short out, breakdown or operation error may result.
- (4) Replace the external cover.

2.4 Installation of Device Driver


This chapter describes of how to install device driver.

Make sure to close the other application.


Before starting the installation procedure, ensure that you are logged on to Windows with a user name having administrator authority. Otherwise, the installation is not successfully completed.

There is no difference for the procedure of the installation for each Windows OS.


- (1) Prepare the device driver by chapter 2.1.
- (2) Make sure that the board is seated properly in the PC by chapter 2.2 and 2.3.
- (3) Turn on the PC and start Windows 7
- (4) Log on to Windows with a user name having administrator authority.
- (5) Select Driver folder in the attached CD-ROM (When the attached CD-ROM in D drive, D:\Driver) or the downloaded software, double click [64 install XXXX INF.exe] in 64Driver folder. (For 32bit, double click [32 install XXXX INF.exe] in 32driver folder.)
(XXXX indicates the model name.)



(6) When the following wizard appears. Click “Yes”. (Read by replacing MC8043P in the dialog box with your model name.)



(7) Device driver installation window appears. Click Next. (Read by replacing MC8043P in the dialog box with your model name.)



(8) If the other board has already been installed, the following window appears. Enter [C] (This window does not appear for the first installation.)



```

cmd: F:\Windows\system32\cmd.exe
F:\Users\Win764dd\AppData\Local\Temp\eptemp.$$$\64bit install MC8581P INF>rem ec
ho off
F:\Users\Win764dd\AppData\Local\Temp\eptemp.$$$\64bit install MC8581P INF>wdreg
-inf WD_MC8000P_driver.inf install
WDREG utility v12.1.0. Build Jan 5 2016 14:42:37


Processing HWID WD_MC8000P
There is currently 1 connected device using WinDriver.
Please disconnect or uninstall all connected devices from the Device Manager
and press Retry.
To reload WinDriver, press Cancel and reboot.
Please press 'R' to retry or 'C' to cancel...

```


(9) The following 2 dialogs appear, click [Install].




(10) When installation has completed, the window will automatically close. (Installation may take time.)




(11) Click OK to complete the driver installation.



(12) The installation has finished. Check the installation is successfully completed by the following steps:
 [Control Panel] → [System and security] → [Device Manager] (shown on the left below). [MC XXXX P] and [WD_MC8000P] is shown under "NOVA", and then click the "General" tab to display the window shown on the right below. If the driver is correctly installed, you can see "This device is working properly" in the Device status field. (Read by replacing MC8043P in the dialog box with your model name.)
 (If PCI-express board is installed, board name is the same as PCI. For example, MC8082Pe is installed, its name is "MC8082P".)



After the installation is successfully completed, check the resource settings and No conflicts.



2.5 Uninstallation of Device Driver

This chapter describes how to uninstall device driver.

There is no difference for the procedure of the installation for each Windows OS.

2.5.1 Uninstallation of Device Driver

This chapter describes how to uninstall device driver.

When the different kinds of boards are installed (For example, MC8043P and MC8541P are installed.), refer to the chapter 2.5.2 Uninstallation When the Different kinds of the Boards are installed.

2.5.1.1 Execute Uninstall XXXX INF.exe

Execute uninstall XXXX INF.exe (XXXX indicates the model name) as below.


- (1) Select Driver folder in the attached CD-ROM (When the attached CD-ROM in D drive, D:\Driver) or the downloaded software, double click [64 uninstall XXXX INF.exe] in 64Driver folder.

When using the device driver before Ver.8.0.0.0, delete it using the software Ver.8.0.0.0 or later.


(For 32bit, double click [32 uninstall XXXX INF.exe] in 32driver folder.)

(Read by replacing MC8043P in the dialog box with your model name.)


(2) When the following wizard appears. Click “Yes”. (Read by replacing MC8043P in the dialog box with your model name.)




(3) Uninstallation window, click “Next”. (Read by replacing MC8541P in the dialog box with your model name.)



(4) When installation has completed, the window will automatically close. (Installation may take time.)



(5) Click OK to complete the driver installation.



Next, 2.5.1.2 Execute Uninstall WD_MC8000P.exe.


(When not uninstalling a board, do not execute 2.5.1.2 Execute Uninstall WD_MC8000P.exe., proceed 2.5.1.3 Confirm Device Manager.)

2.5.1.2 Execute Uninstall WD_MC8000P.exe.


Execute Uninstall WD_MC8000P.exe as below.

(1) Select Driver folder in the attached CD-ROM (When the attached CD-ROM in D drive, D:\Driver) or the downloaded software, double click [uninstall WD_MC8000P.exe] in 64Driver folder.

(For 32bit, double click [32 uninstall WD_MC8000P.exe] in 32driver folder.)




(2) When the following wizard appears. Click “Yes”.




(3) Uninstallation window, click “Next”.



(4) When uninstallation has completed, the window will automatically close. (Uninstallation may take time.)




(5) Click OK to complete the driver uninstallation.




2.5.1.3 Confirm Device Manager


- (1) Make sure that the board is deleted from [Control Panel] → [System and security] → [System] → [Device Manager].
For example, if you have deleted MC8043P board, ensure that the highlighted text (MC8043P) in the window is also deleted.



- (2) When execute 2.5.1.2 Execute Uninstall WD_MC8000P.exe, ensure that the highlighted text (WD_MC8000P) in the window is also deleted.



- (3) When not deleted, click the undeleted driver, select [Delete] from [Operation] menu and check [Delete this driver software]. Click [OK] and delete driver.



- (4) Make sure that the PC is powered OFF and then remove the external cover and slot cover.
 (5) Unscrew the mounting bracket.
 (6) Remove the board by lifting steadily.

2.5.2 Uninstallation When the Different kinds of the Boards are installed.

This chapter describes how to uninstall when the different kind boards are installed. (For example, MC8043P and MC8541P are installed.),

- (1) Refer to 2.5.1.1 Execute Uninstall XXXX INF.exe and execute [uninstall XXXX INF.exe] of the board to be uninstalled.
 (2) Execute other than (2) of 2.5.13 Confirm Device Manager.
 If delete the multiple boards, execute (1) and (2) repeatedly.
 (3) If uninstall all the boards, execute [Uninstall WD_MC8000P.exe] referring to 2.5.1.2 Execute Uninstall WD_MC8000P.exe.
 (4) Execute 2.5.1.3 Confirm Device Manager

2.6 Updating Device Driver



To update the driver, follow the steps below.

Make sure to close the other application.


Before starting the installation procedure, ensure that you are logged on to Windows with a user name having administrator authority. Otherwise, the installation is not successfully completed.

There is no difference for the procedure of the installation for each Windows OS.


- (1) Delete device driver as 2.5.
- (2) Reboot PC.
- (3) Make sure that the board is deleted from [Control Panel] → [System and security] → [System] → [Device Manager]. When deleted, [Unknown device] is shown as the highlighted text in the left lower. When undeleted, board name and WD_MC8000P is shown as the highlighted text in the right lower.




When not deleted, click the undeleted driver, select [Delete] from [Operation] menu and check [Delete this driver software]. Click [OK] and delete driver.




- (4) [Operation] → [Scan for hardware changes], execute (3) again. Execute (3) → (4) repeatedly until correctly deleted .



- (5) Prepare the device driver to be installed as the chapter 2.1 after confirming correctly deleted.
- (6) Install it referring to (5) ~ (10) of the chapter 2.4.
- (7) Confirm whether the version of [1. Driver version] of \64 Driver\Version.txt of driver folder in CD-ROM (When CD-ROM is in D drive, select D:\Driver), or select the downloaded driver folder on hard disc, and then double click “64bit uninstall xxxxx INF.exe” in the driver folder is the same with the following
(For 32bit, confirm 32 Driver\Version.txt file.)
(Read by replacing MC8541P in the dialog box with your model name.)





3. Programming

This chapter describes software specifications and how to program applications.

Applications can be developed with Microsoft Visual C++ (VC++), Microsoft Visual Basic (VB) or Microsoft Visual C# (C#).

3.1 Operating Environment

Operating Systems	Windows 7(32bit,64bit), Windows 8.1(32bit,64bit) & Windows 10(32bit,64bit)
Support Languages	Microsoft Visual C++ 2008 or later
	Microsoft Visual Basic 2008 or later
	Microsoft Visual C# 2008 or later

Notes: When developing applications, refer to the MSDN website for more information about development tools.

When you run a sample program in Visual Studio.2010 or later, migrate a sample program with reference to MSDN documentation. 64bit device driver only applies to 64bit application, 32bit device driver to 32bit application.

For MC8082Pe, use the same file with MC8082P, for MC8043Pe same one with MC8043P.

For MC8541Pe, use the same file with MC8541P, for MC8581Pe same one with MC8581P.

For MC8022P/MC8042P, use the file for MC8082P.

3.2 Software Configuration

3.2.1 Software List

Software	Folder	File Name, Folder	Description
Device driver	Driver\ 32 Driver	32 install MC8043P INF.exe	32bit device driver installer for MC8043P.
		32 install MC8082P INF.exe	32bit device driver installer for MC8082P
		32 install MC8541P INF.exe	32bit device driver installer for MC8541P
		32 install MC8581P INF.exe	32bit device driver installer for MC8581P
		32 uninstall MC8043P INF.exe	32bit device driver uninstaller for MC8043P
		32 uninstall MC8082P INF.exe	32bit device driver uninstaller for MC8082P
		32 uninstall MC8541P INF.exe	32bit device driver uninstaller for MC8541P
		32 uninstall MC8581P INF.exe	32bit device driver uninstaller for MC8581P
		uninstall WD_MC8000P.exe	32bit device driver uninstaller for WD_MC8000P

Software	Folder	File Name, Folder	Description
Device driver	Driver\ 64 Driver	64 install MC8043P INF.exe	64bit device driver installer for MC8043P
		64 install MC8082P INF.exe	64bit device driver installer for MC8082P
		64 install MC8541P INF.exe	64bit device driver installer for MC8541P
		64 install MC8581P INF.exe	64bit device driver installer for MC8581P
		64 uninstall MC8043P INF.exe	64bit device driver uninstaller for MC8043P
		64 uninstall MC8082P INF.exe	64bit device driver uninstaller for MC8082P
		64 uninstall MC8541P INF.exe	64bit device driver uninstaller for MC8541P
		64 uninstall MC8581P INF.exe	64bit device driver uninstaller for MC8581P
		64 uninstall WD_MC8000P.exe	64bit device driver uninstaller for WD_MC8000P
Library	Lib\VC \32 lib	MC8000P.LIB	Library to use MC8000P.DLL 32bit & VC++ only
		MC8000P_DLL.h	Header definition file to use MC8000P.DLL VC++ only
	Lib\VC \64 lib	MC8000P.LIB	Library to use MC8000P.DLL 64bit & VC++ only
		MC8000P_DLL.h	Header definition file to use MC8000P.DLL VC++ only
	Lib\VB.NET	MC8000P_DLL.vb	Declare definition to use MC8000P.DLL VB.NET only
Lib\C#	Mc8000pWrap.dll	Class library to use MC8000P.DLL C# only	
Sample program	Please download it from our website URL: http://www.novaelec.co.jp/eng/		
Evaluation tool for the board equipped with MCX304 ※MC8082P	Tool \MCX304 Board \64 Tool (\32 Tool)	MCX304-A.exe	Evaluation tool for the board with MCX304
		MCX304-B.exe	Application to execute each command with settings such as parameters and mode in the window.
		ParameterSample	Parameter sample file: The Action of each file can be checked in the plot pane by loading this file in MCX304-x.exe and executing the plot.
Evaluation tool for the board equipped with MCX314As ※MC8043P	Tool \MCX314As Board \64 Tool (\32 Tool)	MCX314As-A.exe	Evaluation tool for the board with MCX314As Application to execute each command with settings such as parameters and mode in the window.
		ParameterSample	Parameter sample file: The Action of each file can be checked in the plot pane by loading this file in MCX314As-x.exe and executing the plot. Parameter sample file: The Action of each file can be checked in the plot pane by loading this file in MCX314As-x.exe and executing the plot.
Evaluation tool for the board equipped with MCX514 ※MC8541P & MC8581P	Tool \MCX514 Board \64 Tool (\32 Tool)	MCX514.exe	Evaluation tool for the board with MCX514 Application to execute each command with settings such as parameters and mode in the window.

Note: Description about files automatically created by VC++ MFC AppWizard is omitted.

For the evaluation tool, use exe.file in 32bit folder (\32 Tool) for 32bit OS, 64bit folder (\64 Tool) for 64bit OS.

3.2.2 When error occurs in executing sample program and evaluation tool


■ Error when executing exe create by VC++.

When Visual Studio is not installed on PC which is not installed MC board, the error as below occurs in executing exe file. When the error occurs, install Redistributable Package from the website of Microsoft. Install the sample program for Visual Studio 2008 and the evaluation tool for Visual Studio 2013. There are 32bitOS and 64bitOS version, install either according to your PC. For example, to release the error of the evaluation tool on 64bitOS, install Redistributable Package for 64bit version of Visual Studio 2013. And, to release the error of the sample program, install Redistributable Package for 64bit version of Visual Studio 2008.

Note : The details of errors and how to release them, see the support page of Microsoft and release the error according to Microsoft support.



Example of error when executing VC++ sample program.




Example of error when executing the evaluation tool.

■ Error when executing exe create by VB.NET.

When NET Framework 3.5 is not installed on PC which is not installed MC board, the error as below occurs in executing exe file. When the error occurs, install NET Framework 3.5 according to the window or enable NET Framework 3.5 as follows. [Control panel]- [Program]-[turn windows features on or off].

Note : The details of errors and how to release them, see the support page of Microsoft and release the error according to Microsoft support



Example of error when executing VB.NET sample program.

4. MC8000P series board

This chapter describes API used for the boards as below.

Board	IC	Number of IC	Number of axis
MC8043P / MC8043Pe	MCX314As	1	4
MC8082P / MC8082Pe	MCX304	2	8
MC8022P	MCX304	1	2
MC8042P	MCX304	1	4

4.1 API

API provided by MC8000P.SYS and MC8000P.DLL.

4.1.1. Function list

The following table is the API function list.

The column of VC, VB.NET, C# indicates the availability of each function in each language.

VC++ See VC column.

VB.NET See VB.NET column

C#. See C# columns.

○ is available and × is not.

(1) Basic Function

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_Open	Start to use the board	○	○	○	20	
Nmc_Close	Stop to use the board	○	○	○	"	
Nmc_CloseAll	Stop to use all the boards	○	○	○	21	
Nmc_GetBoardInfo	Get information about the opened board	○	○	○	"	
Nmc_OutPort	Write data to output port	○	○	○	22	
Nmc_InPort	Read data from input port	○	○	○	"	
Nmc_WriteReg	Write data to register of the board	○	○	○	23	
Nmc_ReadReg	Read data from register of the board	○	○	○	"	
Nmc_SetEvent	Set user function to handle an interrupt.	○	×	○	24	
Nmc_ResetEvent	Release user function to handle an interrupt.	○	×	○	25	
Nmc_ReadEvent	Read RR3 value of each axis right after the interrupt generated.	○	×	○	"	

(2) Reset, Command

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_Reset	Reset the IC on the board	○	○	○	26	
Nmc_Command	Execute the command of the specified axis	○	○	○	"	
Nmc_Command_IP	Execute the interpolation command	○	○	○	27	*1

(3) Write Register

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_WriteReg0	WR0 (Command Register) Writing	○	○	○	27	
Nmc_WriteReg1	WR1 (Mode Register 1) Writing	○	○	○	28	
Nmc_WriteReg2	WR2 (Mode Register 2) Writing	○	○	○	"	
Nmc_WriteReg3	WR3 (Mode Register 3) Writing	○	○	○	29	
Nmc_WriteReg4	WR4 (Output Register) Writing	○	○	○	"	
Nmc_WriteReg5	WR5 Writing	○	○	○	30	
Nmc_WriteReg6	WR6 (Write Data Register 1) Writing	○	○	○	"	
Nmc_WriteReg7	WR7 (Write Data Register 2) Writing	○	○	○	31	

(4) Read Register

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_ReadReg0	RR0 (Main Status Register) Reading	○	○	○	31	
Nmc_ReadReg1	RR1 (Status Register 1) Reading	○	○	○	32	
Nmc_ReadReg2	RR2 (Status Register 2) Reading	○	○	○	"	
Nmc_ReadReg4	RR4 (Input Register 1) Reading	○	○	○	"	
Nmc_ReadReg5	RR5 (Input Register 2) Reading	○	○	○	33	
Nmc_ReadReg6	RR6 (Read Data Register 1) Reading	○	○	○	"	
Nmc_ReadReg7	RR7 (Read Data Register 2) Reading	○	○	○	"	

(5) Parameter Settings

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_Range	Range Setting	○	○	○	34	
Nmc_Jerk	Jerk Setting	○	○	○	"	
Nmc_Acc	Acceleration Setting	○	○	○	35	
Nmc_Dec	Deceleration Setting	○	○	○	"	
Nmc_StartSpd	Initial Speed Setting	○	○	○	36	
Nmc_Speed	Drive Speed Setting	○	○	○	"	
Nmc_Pulse	Output Pulse Number/Interpolation Finish Point Setting (For VC, C#)	○	×	○	37	
Nmc_Pulse_VB	Output Pulse Number/Interpolation Finish Point Setting (For VB)	×	○	×	"	
Nmc_DecP	Manual Decelerating Point Setting (For VC, C#)	○	×	○	38	
Nmc_DecP_VB	Manual Decelerating Point Setting (For VB)	×	○	×	"	
Nmc_Center	Circular Center Point Setting	○	○	○	39	*1
Nmc_Lp	Logical Position Counter Setting	○	○	○	"	
Nmc_Ep	Real Position Counter Setting	○	○	○	40	
Nmc_CompP	COMP+ Register Setting	○	○	○	"	
Nmc_CompM	COMP- Register Setting	○	○	○	41	
Nmc_AccOfst	Acceleration Counter Offsetting	○	○	○	"	
Nmc_DJerk	Deceleration Increasing Rate Setting	○	○	○	42	*1
Nmc_HomeSpd	Home Search Speed Setting	○	○	○	"	

(6) Other Mode Settings

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_ExpMode	Extension Mode Setting	○	○	○	43	*1
Nmc_SyncMode	Synchronous Action Mode Setting	○	○	○	"	*1
Nmc_HomeMode	Automatic Home Search Mode Setting	○	○	○	44	*2

(7) Data Reading

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_ReadLp	Logical Position Counter Reading	○	○	○	44	
Nmc_ReadEp	Real Position Counter Reading	○	○	○	"	
Nmc_ReadSpeed	Current Drive Speed Reading	○	○	○	45	
Nmc_ReadAccDec	Current Acceleration/Deceleration Reading	○	○	○	"	
Nmc_ReadSyncBuff	Synchronous Buffer Register Reading	○	○	○	46	*1

(8) Status Reading

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_GetDriveStatus	Drive Status Reading	○	○	○	46	
Nmc_GetCNextStatus	The Status Reading of Ready Signal for Writing of Continuous Interpolation	○	○	○	47	*1
Nmc_GetBpSc	BP Interpolation Stack Counter Reading	○	○	○	"	*1

(9) Writing / Reading

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_WriteRegSetAxis	Axis Assignment Write Register Writing (WR1~3)	○	○	○	48	
Nmc_ReadRegSetAxis	Axis Assignment Read Register Reading (RR1~2)	○	○	○	〃	
Nmc_WriteData	Data Writing (Parameter)	○	○	○	49	
Nmc_WriteData2	Data Writing (Extension Mode, Synchronous Action Mode)	○	○	○	〃	*1
Nmc_ReadData	Data Reading	○	○	○	50	

(10) Interpolation Execution

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_2BPExec	2-axis BP Interpolation Execution	○	○	○	50	*1
Nmc_3BPExec	3-axis BP Interpolation Execution	○	○	○	52	*1
Nmc_2BPExec_BG	2-axis BP Interpolation Execution (run in the background)	○	○	○	53	*1
Nmc_3BPExec_BG	3-axis BP Interpolation Execution (run in the background)	○	○	○	56	*1
Nmc_2CIPExec	2-axis Continuous Interpolation Execution	○	○	○	58	*1
Nmc_3CIPExec	3-axis Continuous Interpolation Execution	○	○	○	60	*1
Nmc_2CIPExec_BG	2-axis Continuous Interpolation Execution (run in the background)	○	○	○	63	*1
Nmc_3CIPExec_BG	3-axis Continuous Interpolation Execution (run in the background)	○	○	○	66	*1
Nmc_IPStop	Stop the Interpolation Execution	○	○	○	69	*1
Nmc_IPGetMsgNo	Get board and IC number from received message at the end of the Interpolation	○	○	○	70	*1

*1: Function for MC8043P/MC8043Pe only

*2: Function for MC8082P/MC8082Pe, MC8022P and MC8042P only

4.1.2. Function Specifications

For VC++ users See **VC** and [VC]
 For VB.NET users See **VB.NET** and [VB.NET]
 For C# users See **C#** and [C#]
 And others are common to each language.

Function Name	Function and Content
Nmc_Open	<p>Start the board.</p> <pre> VC BOOL Nmc_Open(int No, BOOL IntrptFlg); VB.NET Function Nmc_Open(ByVal No As Integer, ByVal IntrptFlg As Integer) As Integer C# bool MC8000P.Nmc_Open(int No, bool IntrptFlg); </pre> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IntrptFlg Set the flag to use interrupt.</p> <p>[VC] TRUE: use interrupt. FALSE: not use. [VB.NET] FALSE only. Interrupt cannot be used in VB. [C#] true: use interrupt. false: not use.</p> <p>Return Value</p> <p>[VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>[VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0.</p> <p>[C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example</p> <pre> [VC] status = Nmc_Open(0, FALSE); // Open the board 0 and not use the interrupt. [VB.NET] status = Nmc_Open(0, False) [C#] status = MC8000P.Nmc_Open(0, false); </pre>
Nmc_Close	<p>Terminate the board.</p> <pre> VC BOOL Nmc_Close(int No); VB.NET Function Nmc_Close(ByVal No As Integer) As Integer C# bool MC8000P.Nmc_Close(int No); </pre> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>Return Value</p> <p>[VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>[VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0.</p> <p>[C#] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>Example</p> <pre> [VC] status = Nmc_Close(0); // Close the board 0. [VB.NET] status = Nmc_Close(0) [C#] status = MC8000P.Nmc_Close(0); </pre>

Function Name	Function and Content
Nmc_CloseAll	<p>Terminate all the boards.</p> <p>VC BOOL Nmc_CloseAll(void); VB.NET Function Nmc_CloseAll() As Integer C# bool MC8000P.Nmc_CloseAll();</p> <p>Input Parameter None</p> <p>Return Value [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example [VC] status = Nmc_CloseAll(); // Close all the boards. [C#] status = MC8000P.Nmc_CloseAll();</p>
Nmc_GetBoardInfo	<p>Get Device ID of the opened board.</p> <p>VC BOOL Nmc_GetBoardInfo(int No, USHORT* DeviceID); VB.NET Function Nmc_GetBoardInfo(ByVal No As Integer, ByRef DeviceID As Short) As Integer C# bool MC8000P.Nmc_GetBoardInfo(int No, out ushort DeviceID);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) DeviceID [VC] Address of a variable to store the Device ID obtained from the board. [VB.NET] [C#] Address of a variable to store the Device ID obtained from the board. See 4.1.3 (1) ③ regarding Device ID of each board. [VC][VB.NET] MC8082P/MC8082Pe,42P,22P are ID_MC8082P, MC8043P/MC8043Pe are ID_MC8043P, [C#] MC8082P/MC8082Pe,42P,22P are Dev_ID.MC8082P, MC8080P is Dev_ID.MC8080P, MC8043P/MC8043Pe are Dev_ID.MC8043P.</p> <p>Return Value [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example [VC] USHORT DeviceID; status = Nmc_GetBoardInfo(No, &DeviceID); // Get Device ID. if(DeviceID == ID_MC8082P) // When the board is MC8082P. [VB.NET] Dim DeviceID As Short status = Nmc_GetBoardInfo(No, DeviceID) If DeviceID = ID_MC8082P Then [C#] ushort DeviceID; status = Nmc_GetBoardInfo(No, out DeviceID); if(DeviceID == Dev_ID.MC8082P)</p>

Function Name	Function and Content
Nmc_OutPort	<p>Write 2-byte data into output port.</p> <p>VC void Nmc_OutPort(int No, long Adr, long Data); VB.NET Sub Nmc_OutPort(ByVal No As Integer, ByVal Adr As Integer, ByVal Data As Integer) C# void MC8000P.Nmc_OutPort(int No, REG_MCX Adr, int Dat);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) Adr Address to be written. I/O address described in User's Manual of each board. See 4.1.3 (1)①, (6) for more details. Data Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_OutPort(No, 0, 0x8000); // Soft reset IC-A.(Write into WR0) [VB.NET] Call Nmc_OutPort(No, 0, &H8000) [C#] MC8000P.Nmc_OutPort(No, REG_MCX.WR0_A, 0x8000);</p>
Nmc_InPort	<p>Read out 2-byte data from input port.</p> <p>VC long Nmc_InPort(int No, long Adr); VB.NET Function Nmc_InPort(ByVal No As Integer, ByVal adr As Integer) As Integer C# int MC8000P.Nmc_InPort(int No, REG_MCX Adr);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) Adr Address to be read. I/O address described in User's Manual of each board. See 4.1.3 (1)①, (6) for more details.</p> <p>Return Value</p> <p>Data read out from input port.</p> <p>Example</p> <p>[VC] data = Nmc_InPort(No, 0); // Read out the read register RR0 of IC-A. [VB.NET] data = Nmc_InPort(No, 0) [C#] data = MC8000P.Nmc_InPort(No, REG_MCX.RR0_A);</p> <p>Note</p> <p>[VC] [C#] Regarding reading RR3 register data, refer to Nmc_ReadEvent function.</p>

Function Name	Function and Content
Nmc_WriteReg	<p>Write data into write register (WR0~WR7) of the board.</p> <p>VC void Nmc_WriteReg(int No, int IcNo, long RegNum, long Dat); VB.NET Sub Nmc_WriteReg(ByVal No As Integer, ByVal IcNo As Integer, ByVal RegNum As Integer, ByVal Dat As Integer) C# void MC8000P.Nmc_WriteReg(int No, int IcNo, int RegNum, int Dat);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. RegNum Register to be written (MCX_WR0~MCX_WR7). See 4.1.3 (1) for more details. e.g. [VC][VB.NET] Specify MCX_WR0 for WR0 and MCX_WR1 for WR1. [C#] Specify REG_MCX.WR0 for WR0 and REG_MCX.WR1 for WR1. Dat Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg(No, 0, MCX_WR0, 0x8000); // Soft reset IC-A.(Write into WR0) [VB.NET] Call Nmc_WriteReg(No, 0, MCX_WR0, &H8000) [C#] MC8000P.Nmc_WriteReg(No, 0, REG_MCX.WR0, 0x8000);</p>
Nmc_ReadReg	<p>Read out data from read register (RR0~RR7) of the board.</p> <p>VC long Nmc_ReadReg(int No, int IcNo, long RegNum); VB.NET Function Nmc_ReadReg(ByVal No As Integer, ByVal IcNo As Integer, ByVal RegNum As Integer) As Integer C# void MC8000P.Nmc_ReadReg(int No, int IcNo, int RegNum);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. RegNum Register to be read (MCX_RR0~MCX_RR7). See 4.1.3 (1) for more details. e.g. [VC][VB.NET] Specify MCX_RR0 for RR0 and MCX_RR1 for RR1. [C#] Specify REG_MCX.RR0 for RR0 and REG_MCX.RR1 for RR1.</p> <p>Return Value</p> <p>Data read out from read register.</p> <p>Example</p> <p>[VC] data = Nmc_ReadReg(No, 0, MCX_RR0); // Read out the read register RR0 of IC-A. [VB.NET] data = Nmc_ReadReg(No, 0, MCX_RR0) [C#] data = MC8000P.Nmc_ReadReg(No, 0, REG_MCX.RR0);</p> <p>Note</p> <p>[VC] [C#] Regarding reading the RR3 register data, refer to Nmc_ReadEvent function.</p>

Function Name	Function and Content
Nmc_SetEvent	<p>Set user function to handle an interrupt.</p> <p>By executing this function, the user function is called when an interrupt occurs and then one specified argument is passed. This user function is run as one thread.</p> <p>To release user function to handle an interrupt, execute Nmc_ResetEvent.</p> <p>VC BOOL Nmc_SetEvent (int No, LPTHREAD_START_ROUTINE UserThread, LPVOID lpParameter);</p> <p>VB.NET cannot be used.</p> <p>C# bool MC8000P.Nmc_SetEvent(int No, UserThread Callback, int param);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p>[VC] UserThread User function address</p> <p>[VC] lpParameter Assign one argument to be pass to user function thread. Set the available pointer for the thread. When not using the argument, set NULL. When using the pointer, set the available pointer when the user function is called.</p> <p>[C#] Callback User method (delegate type) See 4.1.4 Usage for more details.</p> <p> param Assign one parameter (int only, such as numeric type) to pass to user function after an interrupt occurs.</p> <p>Return Value</p> <p>[VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>[C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example</p> <p>[VC]</p> <p>(When the board number is 0)</p> <pre>status = Nmc_SetEvent(0, MC_EventFunc0, lpParam); // Set the function address and argument Nmc_WriteReg1(0, 0, AXIS_ALL, 0x8000); // Interrupt occurs at the stop of IC-A (All axes)</pre> <p>(When the board number is 1)</p> <pre>status = Nmc_SetEvent(1, MC_EventFunc1, NULL); // Set the function address and argument Nmc_WriteReg1(1, 0, AXIS_ALL, 0x8000); // Interrupt occurs at the stop of IC-A (All axes)</pre> <p>■ Example of interrupt user function</p> <pre>DWORD WINAPI MC_EventFunc0(LPVOID lpParam) { long Rr3X, Rr3Y, Rr3Z, Rr3U; Nmc_ReadEvent(0, 0, &Rr3X,&Rr3Y,&Rr3Z,&Rr3U); //Board 0, read out RR3 interrupt data of IC-A return 0; } DWORD WINAPI MC_EventFunc1(LPVOID lpParam) { long Rr3X, Rr3Y, Rr3Z, Rr3U; Nmc_ReadEvent(1, 0, &Rr3X, &Rr3Y, &Rr3Z, &Rr3U); //Board 1, read RR3 interrupt data of IC-A return 0; }</pre> <p>[C#]</p> <pre>// Assign interrupt method isr to a delegate type variable MC8000P.callback[0] = new MC8000P.UserThread(isr); //Set user method to handle an interrupt MC8000P.Nmc_SetEvent(no, MC8000P.callback[0], param);</pre>

Function Name	Function and Content
Nmc_Reset	<p>Reset the IC on the board.</p> <p>VC void Nmc_Reset(int No, int IcNo); VB.NET Sub Nmc_Reset(ByVal No As Integer, ByVal IcNo As Integer) C# void MC8000P.Nmc_Reset(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_Reset(1, 0); // Reset IC-A of the board 1. [VB.NET] Call Nmc_Reset(1, 0) [C#] MC8000P.Nmc_Reset(1, 0);</pre>
Nmc_Command	<p>Execute the command of a specified axis. (Write the command of a specified axis into WR0.)</p> <p>VC void Nmc_Command(int No, int IcNo, int axis, int cmd); VB.NET Sub Nmc_Command(ByVal No As Integer, ByVal IcNo As Integer, ByVal Axis As Integer, ByVal cmd As Integer) C# void MC8000P.Nmc_Command(int No, int IcNo, AXIS axis, CMD cmd);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to execute the command. Multiple axes can be assigned. See 4.1.3 (2) for more details. cmd Command number. Specify one command from "Driving commands, Other commands" of "Command Definition" described in definition file (*1). For + direction fixed pulse drive, specify CMD_F_DRV_P. See 4.1.3 (4) for C#. *1: [VC] MC8000P_DLL.H, [VB.NET] MC8000P_DLL.vb</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_Command(No, IcNo, AXIS_X, CMD_F_DRV_P); // Execute the + direction fixed drive of X axis. [VB.NET] Call Nmc_Command(No, IcNo, AXIS_X, CMD_F_DRV_P) [C#] MC8000P.Nmc_Command(No, IcNo, AXIS.X, CMD.CMD_F_DRV_P);</pre>

Function Name	Function and Content
Nmc_Command_IP	<p>Execute interpolation command. (Write interpolation command into WR0.) *MCX314As only</p> <p>VC void Nmc_Command_IP(int No, int IcNo, int cmd); VB.NET Sub Nmc_Command_IP(ByVal No As Integer, ByVal IcNo As Integer, ByVal cmd As Integer) C# void MC8000P.Nmc_Command_IP(int No, int IcNo, CMD cmd);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. cmd Command number. Specify one command from "Interpolation Commands" of "Command Definition" described in definition file (*1). For 2-axis linear interpolation drive, specify CMD_IP_2ST. See 4.1.3 (4) for C#. *1: [VC] MC8000P_DLL.H, [VB.NET] MC8000P_DLL.vb</p> <p>Return Value None</p> <p>Example</p> <pre>[VC] Nmc_WriteReg5(No, IcNo, 0x0004); // Set the interpolation axis (Main axis: X, Second axis: Y). Nmc_Command_IP(No, IcNo, CMD_IP_2ST); // Execute 2-axis linear interpolation drive. [VB.NET] Call Nmc_WriteReg5(No, IcNo, &H0004) Call Nmc_Command_IP(No, IcNo, CMD_IP_2ST) [C#] MC8000P.Nmc_WriteReg5(No, IcNo, 0x0004); MC8000P.Nmc_Command_IP(No, IcNo, CMD.CMD_IP_2ST);</pre>
Nmc_WriteReg0	<p>Write data into WR0 (Command register).</p> <p>VC void Nmc_WriteReg0(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg0(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg0(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. wdata Data to be written.</p> <p>Return Value None</p> <p>Example</p> <pre>[VC] Nmc_WriteReg0(No, IcNo, 0x0120); // Execute the + direction fixed drive of X axis. [VB.NET] Call Nmc_WriteReg0(No, IcNo, &H120) [C#] MC8000P.Nmc_WriteReg0(No, IcNo, 0x0120);</pre>

Function Name	Function and Content
Nmc_WriteReg1	<p>Write data into WR1 (Mode register 1).</p> <p>VC void Nmc_WriteReg1(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_WriteReg1(ByVal No As Integer, ByVal IcNo As Integer, ByVal Axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg1(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to write data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg1(No, IcNo, AXIS_X, 0x8000); // Interrupt occurs at the stop (X axis). [VB.NET] Call Nmc_WriteReg1(No, IcNo, AXIS_X, &H8000) [C#] MC8000P.Nmc_WriteReg1(No, IcNo, AXIS.X, 0x8000);</p>
Nmc_WriteReg2	<p>Write data into WR2 (Mode register 2).</p> <p>VC void Nmc_WriteReg2(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_WriteReg2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg2(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to write data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg2(No, IcNo, AXIS_Y, 0x2000); // Enable ALARM (Y axis). [VB.NET] Call Nmc_WriteReg2(No, IcNo, AXIS_Y, &H2000) [C#] MC8000P.Nmc_WriteReg2(No, IcNo, AXIS.Y, 0x2000);</p>

Function Name	Function and Content
Nmc_WriteReg3	<p>Write data into WR3 (Mode register 3).</p> <p>VC void Nmc_WriteReg3(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_WriteReg3(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg3(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to write data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_WriteReg3(No, IcNo, AXIS_ALL, 0x0001); // Manual decelerating for all axes. [VB.NET] Call Nmc_WriteReg3(No, IcNo, AXIS_ALL, &H1) [C#] MC8000P.Nmc_WriteReg3(No, IcNo, AXIS.ALL, 0x0001);</pre>
Nmc_WriteReg4	<p>Write data into WR4 (Output register).</p> <p>VC void Nmc_WriteReg4(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg4(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg4(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_WriteReg4(No, IcNo, 0x0001); // Hi level output for X axis general output OUT0. [VB.NET] Call Nmc_WriteReg4(No, IcNo, &H0001) [C#] MC8000P.Nmc_WriteReg4(No, IcNo, 0x0001);</pre>

Function Name	Function and Content
Nmc_WriteReg5	<p>Write data into WR5.</p> <p>VC void Nmc_WriteReg5(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg5(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg5(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <ul style="list-style-type: none"> ■ MCX304 <pre>[VC] Nmc_WriteReg5(No, IcNo, 0x0001); // Enable X axis general output OUT0. [VB.NET] Call Nmc_WriteReg5(No, IcNo, &H1) [C#] MC8000P.Nmc_WriteReg5(No, IcNo, 0x0001);</pre> ■ MCX314As <pre>[VC] Nmc_WriteReg5(No, IcNo, 0x0024); // Set the interpolation axis (Main axis: X, Second axis: Y, Third axis: Z). [VB.NET] Call Nmc_WriteReg5(No, IcNo, &H0024) [C#] MC8000P.Nmc_WriteReg5(No, IcNo, 0x0024);</pre>
Nmc_WriteReg6	<p>Write data into WR6 (Write data register 1).</p> <p>VC void Nmc_WriteReg6(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg6(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg6(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_WriteReg6(No, IcNo, 0x1234); // Write data (1234)H into write data register 1. [VB.NET] Call Nmc_WriteReg6(No, IcNo, &H1234) [C#] MC8000P.Nmc_WriteReg6(No, IcNo, 0x1234);</pre>

Function Name	Function and Content
Nmc_WriteReg7	<p>Write data into WR7 (Write data register 2).</p> <p>VC void Nmc_WriteReg7(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg7(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg7(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg7(No, IcNo, 0x5678); // Write data (5678)H into write data register 2. [VB.NET] Call Nmc_WriteReg7(No, IcNo, &H5678) [C#] MC8000P.Nmc_WriteReg7(No, IcNo, 0x5678);</p>
Nmc_ReadReg0	<p>Read out data from RR0 (Main status register).</p> <p>VC long Nmc_ReadReg0(int No, int IcNo); VB.NET Function Nmc_ReadReg0(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadReg0(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p>The data of RR0 (Main status register)</p> <p>Example</p> <p>[VC] Data = Nmc_ReadReg0(No, IcNo); // Read out RR0. [VB.NET] Data = Nmc_ReadReg0(No, IcNo) [C#] Data = MC8000P.Nmc_ReadReg0(No, IcNo);</p>

Function Name	Function and Content
Nmc_ReadReg1	<p>Read out data from RR1 (Status register 1).</p> <p>VC long Nmc_ReadReg1(int No, int IcNo, int axis); VB.NET Function Nmc_ReadReg1(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer C# int MC8000P.Nmc_ReadReg1(int No, int IcNo, AXIS axis);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis and AXIS_U for U-axis. See 4.1.3 (2) for more details.</p> <p>Return Value The data of RR1 (Status register 1)</p> <p>Example [VC] Data = Nmc_ReadReg1(No, IcNo, AXIS_X); // Read out RR1 of X axis. [VB.NET] Data = Nmc_ReadReg1(No, IcNo, AXIS_X) [C#] Data = MC8000P.Nmc_ReadReg1(No, IcNo, AXIS.X);</p>
Nmc_ReadReg2	<p>Read out data from RR2 (Status register 2).</p> <p>VC long Nmc_ReadReg2(int No, int IcNo, int Axis); VB.NET Function Nmc_ReadReg2(ByVal No As Integer, ByVal IcNo As Integer, ByVal Axis As Integer) As Integer C# int MC8000P.Nmc_ReadReg2(int No, int IcNo, AXIS Axis);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis and AXIS_U for U-axis. See 4.1.3 (2) for more details.</p> <p>Return Value The data of RR2 (Status register 2)</p> <p>Example [VC] Data = Nmc_ReadReg2(No, IcNo, AXIS_Y); // Read out RR2 of Y axis. [VB.NET] Data = Nmc_ReadReg2(No, IcNo, AXIS_Y) [C#] Data = MC8000P.Nmc_ReadReg2(No, IcNo, AXIS.Y);</p>
Nmc_ReadReg4	<p>Read out data from RR4 (Input register 1).</p> <p>VC long Nmc_ReadReg4(int No, int IcNo); VB.NET Function Nmc_ReadReg4(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadReg4(int No, int IcNo);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value The data of RR4 (Input register 1)</p> <p>Example [VC] Data = Nmc_ReadReg4(No, IcNo); // Read out RR4. [VB.NET] Data = Nmc_ReadReg4(No, IcNo) [C#] Data = MC8000P.Nmc_ReadReg4(No, IcNo);</p>

Function Name	Function and Content
Nmc_ReadReg5	<p>Read out data from RR5 (Input register 2).</p> <p>VC long Nmc_ReadReg5(int No, int IcNo);</p> <p>VB.NET Function Nmc_ReadReg5(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadReg5(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p> The data of RR5 (Input register 2)</p> <p>Example</p> <p> [VC] Data = Nmc_ReadReg5(No, IcNo); // Read out RR5.</p> <p> [VB.NET] Data = Nmc_ReadReg5(No, IcNo)</p> <p> [C#] Data = MC8000P.Nmc_ReadReg5(No, IcNo);</p>
Nmc_ReadReg6	<p>Read out data from RR6 (Read data register 1).</p> <p>VC long Nmc_ReadReg6(int No, int IcNo);</p> <p>VB.NET Function Nmc_ReadReg6(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadReg6(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p> The data of RR6 (Read data register 1)</p> <p>Example</p> <p> [VC] Data = Nmc_ReadReg6(No, IcNo); // Read out RR6.</p> <p> [VB.NET] Data = Nmc_ReadReg6(No, IcNo)</p> <p> [C#] Data = MC8000P.Nmc_ReadReg6(No, int IcNo);</p>
Nmc_ReadReg7	<p>Read out data from RR7 (Read data register 2).</p> <p>VC long Nmc_ReadReg7(int No, int IcNo);</p> <p>VB.NET Function Nmc_ReadReg7(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadReg7(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p> The data of RR7 (Read data register 2)</p> <p>Example</p> <p> [VC] Data = Nmc_ReadReg7(No, IcNo); // Read out RR7.</p> <p> [VB.NET] Data = Nmc_ReadReg7(No, IcNo)</p> <p> [C#] Data = MC8000P.Nmc_ReadReg7(No, IcNo);</p>

Function Name	Function and Content
Nmc_Range	<p>Set the range.</p> <p>VC void Nmc_Range(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Range(ByVal No As Integer, ByVal IcNo As Integer, ByVal Axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Range(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Range(No, IcNo, AXIS_ALL, 800000); // Set 800000 (Multiple = 10) to range (All axes). [VB.NET] Call Nmc_Range(No, IcNo, AXIS_ALL, 800000) [C#] MC8000P.Nmc_Range(No, IcNo, AXIS.ALL, 800000);</p>
Nmc_Jerk	<p>Set jerk.</p> <p>VC void Nmc_Jerk(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Jerk(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Jerk(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Jerk(No, IcNo, AXIS_X, 1000); // Set 1000 as jerk (X axis). [VB.NET] Call Nmc_Jerk(No, IcNo, AXIS_X, 1000) [C#] MC8000P.Nmc_Jerk(No, IcNo, AXIS.X, 1000);</p>

Function Name	Function and Content
Nmc_Acc	<p>Set acceleration.</p> <p>VC void Nmc_Acc(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Acc(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Acc(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <p>[VC] Nmc_Acc(No, IcNo, AXIS_Y, 100); // Set 100 as acceleration (Y axis). [VB.NET] Call Nmc_Acc(No, IcNo, AXIS_Y, 100) [C#] MC8000P.Nmc_Acc(No, IcNo, AXIS.Y, 100);</p>
Nmc_Dec	<p>Set deceleration.</p> <p>VC void Nmc_Dec(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Dec(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Dec(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <p>[VC] Nmc_Dec(No, IcNo, AXIS_Z, 100); // Set 100 as deceleration (Z axis). [VB.NET] Call Nmc_Dec(No, IcNo, AXIS_Z, 100) [C#] MC8000P.Nmc_Dec(No, IcNo, AXIS.Z, 100);</p>

Function Name	Function and Content
Nmc_StartSpd	<p>Set initial speed.</p> <p>VC void Nmc_StartSpd(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_StartSpd(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_StartSpd(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VC] Nmc_StartSpd(No, IcNo, AXIS_U, 100); // Set 100 as initial speed (U axis). [VB.NET] Call Nmc_StartSpd(No, IcNo, AXIS_U, 100) [C#] MC8000P.Nmc_StartSpd(No, IcNo, AXIS.U, 100);</p>
Nmc_Speed	<p>Set drive speed.</p> <p>VC void Nmc_Speed(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Speed(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Speed(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VC] Nmc_Speed(No, IcNo, AXIS_X AXIS_Y, 1000); // Set 1000 as drive speed (X/Y axes). [VB.NET] Call Nmc_Speed(No, IcNo, AXIS_X Or AXIS_Y, 1000) [C#] MC8000P.Nmc_Speed(No, IcNo, AXIS.X AXIS.Y, 1000);</p>

Function Name	Function and Content
Nmc_Pulse	<p>Set output pulse number or interpolation finish point. (VC, C# only) *MCX304 has no interpolation function.</p> <p>The number of output pulses indicates the total number of pulses that are output in fixed pulse driving. For linear and circular interpolation driving, set the finish point of each axis. The finish point should be set the relative numbers to the current position. The output pulse number is unsigned 32-bit value. The interpolation finish point is signed 32-bit value.</p> <p>VC void Nmc_Pulse(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET cannot be used.</p> <p>C# To set the interpolation finish point (P) void MC8000P.Nmc_Pulse(int No, int IcNo, AXIS axis, int wdata); To set the output pulse number void MC8000P.Nmc_Pulse(int No, int IcNo, AXIS axis, uint wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <pre>[VC] Nmc_Pulse(No, IcNo, AXIS_X, 2000); // Set 2000 as output pulse number (X axis). Nmc_Pulse(No, IcNo, AXIS_Y, 300); // Set 300 as interpolation finish point (Y axis). Nmc_Pulse(No, IcNo, AXIS_Z, -400); // Set -400 as interpolation finish point (Z axis). [C#] MC8000P.Nmc_Pulse(No, IcNo, AXIS.X, 2000); MC8000P.Nmc_Pulse(No, IcNo, AXIS.Y, 300); MC8000P.Nmc_Pulse(No, IcNo, AXIS.Z, -400);</pre>
Nmc_Pulse_VB	<p>Set output pulse number or interpolation finish point. (VB.NET only) *MCX304 has no interpolation function.</p> <p>The number of output pulses indicates the total number of pulses that are output in fixed pulse driving. For linear and circular interpolation driving, set the finish point of each axis. The finish point should be set the relative numbers to the current position.</p> <p>VC cannot be used.</p> <p>VB.NET Sub Nmc_Pulse_VB(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Double)</p> <p>C#.NET cannot be used.</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <pre>[VB.NET] Call Nmc_Pulse_VB(No, IcNo, AXIS_X, 2000) ' Set 2000 as output pulse number (X axis). Call Nmc_Pulse_VB(No, IcNo, AXIS_Y, 300) ' Set 300 as interpolation finish point (Y axis). Call Nmc_Pulse_VB(No, IcNo, AXIS_Z, -400) ' Set -400 as interpolation finish point (Z axis)</pre>

Function Name	Function and Content
Nmc_DecP	<p>Set manual decelerating point. (VC, C# only)</p> <p>VC void Nmc_DecP(int No, int IcNo, int axis, ULONG wdata); VB.NET cannot be used. C# void MC8000P.Nmc_DecP(int No, int IcNo, AXIS axis, uint wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_DecP(No, IcNo, AXIS_U, 30000); // Set 30000 as manual decelerating point (U axis). [C#] MC8000P.Nmc_DecP(No, IcNo, AXIS.U, 30000);</p>
Nmc_DecP_VB	<p>Set manual decelerating point. (VB.NET only)</p> <p>VC cannot be used. VB.NET Sub Nmc_DecP_VB(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Double) C# cannot be used.</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VB.NET] Call Nmc_DecP_VB(No, IcNo, AXIS_X, 40000) ' Set 40000 as manual decelerating point (X axis).</p>

Function Name	Function and Content
Nmc_Center	<p>Set circular center point. *MCX314As only</p> <p>VC void Nmc_Center(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Center(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Center(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_Center(No, IcNo, AXIS_Y, 1500); // Set 1500 as circular center point (Y axis). [VB.NET] Call Nmc_Center(No, IcNo, AXIS_Y, 1500) [C#] MC8000P.Nmc_Center(No, IcNo, AXIS.Y, 1500);</pre>
Nmc_Lp	<p>Set logical position counter.</p> <p>VC void Nmc_Lp(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Lp(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Lp(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_Lp(No, IcNo, AXIS_ALL, 0); // Set 0 to logical position counter of all axes. [VB.NET] Call Nmc_Lp(No, IcNo, AXIS_ALL, 0) [C#] MC8000P.Nmc_Lp(No, IcNo, AXIS.ALL, 0);</pre>

Function Name	Function and Content
Nmc_Ep	<p>Set real position counter.</p> <p>VC void Nmc_Ep(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Ep(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Ep(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_Ep(No, IcNo, AXIS_ALL, 0); // Set 0 to real position counter of all axes. [VB.NET] Call Nmc_Ep(No, IcNo, AXIS_ALL, 0) [C#] MC8000P.Nmc_Ep(No, IcNo, AXIS.ALL, 0);</pre>
Nmc_CompP	<p>Set COMP+ register.</p> <p>VC void Nmc_CompP(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_CompP(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_CompP(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_CompP(No, IcNo, AXIS_X, 50000); // Set 50000 as COMP+ register (X axis). [VB.NET] Call Nmc_CompP(No, IcNo, AXIS_X, 50000) [C#] MC8000P.Nmc_CompP(No, IcNo, AXIS.X, 50000);</pre>

Function Name	Function and Content
Nmc_CompM	<p>Set COMP- register.</p> <p>VC void Nmc_CompM(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_CompM(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_CompM(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_CompM(No, IcNo, AXIS_X, -50000); // Set -50000 as COMP- register (X axis). [VB.NET] Call Nmc_CompM(No, IcNo, AXIS_X, -50000) [C#] MC8000P.Nmc_CompM(No, IcNo, AXIS.X, -50000);</pre>
Nmc_AccOfst	<p>Set acceleration counter offsetting.</p> <p>VC void Nmc_AccOfst(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_AccOfst(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_AccOfst(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_AccOfst(No, IcNo, AXIS_Y, 20); // Set 20 as acceleration counter offsetting (Y axis). [VB.NET] Call Nmc_AccOfst(No, IcNo, AXIS_Y, 20) [C#] MC8000P.Nmc_AccOfst(No, IcNo, AXIS.Y, 20);</pre>

Function Name	Function and Content
Nmc_DJerk	<p>Set deceleration increasing rate. *MCX314As only</p> <p>VC void Nmc_DJerk(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_DJerk(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_DJerk(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VC] Nmc_DJerk(No, IcNo, AXIS_Z, 1000); // Set 1000 as deceleration increasing rate (Z axis). [VB.NET] Call Nmc_DJerk(No, IcNo, AXIS_Z, 1000) [C#] MC8000P.Nmc_DJerk(No, IcNo, AXIS.Z, 1000);</p>
Nmc_HomeSpd	<p>Set home search speed.</p> <p>VC void Nmc_HomeSpd(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_HomeSpd(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_HomeSpd(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VC] Nmc_HomeSpd(No, IcNo, AXIS_U, 200); // Set 200 as home search speed (U axis). [VB.NET] Call Nmc_HomeSpd(No, IcNo, AXIS_U, 200) [C#] MC8000P.Nmc_HomeSpd(No, IcNo, AXIS.U, 200);</p>

Function Name	Function and Content
Nmc_ExpMode	<p>Set extension mode. *MCX314As only</p> <p>VC void Nmc_ExpMode(int No, int IcNo, int axis, long EM6_data, long EM7_data);</p> <p>VB.NET Sub Nmc_ExpMode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal EM6_data As Integer, ByVal EM7_data As Integer)</p> <p>C# void MC8000P.Nmc_ExpMode(int No, int IcNo, AXIS axis, int EM6_data, int EM7_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>EM6_data Data to be set in extension mode register EM6.</p> <p>EM7_data Data to be set in extension mode register EM7.</p> <p>Return Value</p> <p>None</p> <p>Example Set enable for all filters, delay time 512μs and execution of automatic home search step1, 2 and 4 to X axis extension mode.</p> <p>[VC] Nmc_ExpMode(No, IcNo, AXIS_X, 0x5F00, 0x0045);</p> <p>[VB.NET] Call Nmc_ExpMode(No, IcNo, AXIS_X, &H5F00, &H0045)</p> <p>[C#] MC8000P.Nmc_ExpMode(No, IcNo, AXIS.X, 0x5F00, 0x0045);</p>
Nmc_SyncMode	<p>Set synchronous action mode. *MCX314As only</p> <p>VC void Nmc_SyncMode(int No, int IcNo, int axis, long SM6_data, long SM7_data);</p> <p>VB.NET Sub Nmc_SyncMode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal SM6_data As Integer, ByVal SM7_data As Integer)</p> <p>C# void MC8000P.Nmc_SyncMode(int No, int IcNo, AXIS axis, int SM6_data, int SM7_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>SM6_data Data to be set in synchronous action mode register SM6.</p> <p>SM7_data Data to be set in synchronous action mode register SM7.</p> <p>Return Value</p> <p>None</p> <p>Example Set "start fixed pulse driving in the + direction of Y axis at the termination of X axis driving".</p> <p>(1) Set Y axis activation by the activation factor D-END to X axis synchronous action mode.</p> <p>(2) Set fixed pulse driving in the + direction (FDRV+) as action to Y axis synchronous action mode.</p> <p>[VC] (1) Nmc_SyncMode(No, IcNo, AXIS_X, 0x2020, 0); (2) Nmc_SyncMode(No, IcNo, AXIS_Y, 0, 0x0001);</p> <p>[VB.NET] (1) Call Nmc_SyncMode(No, IcNo, AXIS_X, &H2020, 0) (2) Call Nmc_SyncMode(No, IcNo, AXIS_Y, 0, &H0001)</p> <p>[C#] (1) MC8000P.Nmc_SyncMode(No, IcNo, AXIS.X, 0x2020, 0); (2) MC8000P.Nmc_SyncMode(No, IcNo, AXIS.Y, 0, 0x0001);</p>

Function Name	Function and Content
Nmc_HomeMode	<p>Set automatic home search mode. *MCX304 only</p> <p>VC void Nmc_HomeMode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_HomeMode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_HomeMode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>WR6_data Data to be set to WR6.</p> <p>Return Value</p> <p>None</p> <p>Example Set execution of automatic home search step1, 2 and 4 to X axis automatic home search mode.</p> <p>[VC] Nmc_HomeMode(No, IcNo, AXIS_X, 0x0045);</p> <p>[VB.NET] Call Nmc_HomeMode(No, IcNo, AXIS_X, &H0045)</p> <p>[C#] MC8000P.Nmc_HomeMode(No, IcNo, AXIS.X, 0x0045);</p>
Nmc_ReadLp	<p>Read out logical position counter.</p> <p>VC long Nmc_ReadLp(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadLp(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadLp(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis and AXIS_U for U-axis.</p> <p>Return Value</p> <p>The value of the current logical position counter</p> <p>Example</p> <p>[VC] Data = Nmc_ReadLp(No, IcNo, AXIS_X); // Read out logical position counter of X axis.</p> <p>[VB.NET] Data = Nmc_ReadLp(No, IcNo, AXIS_X)</p> <p>[C#] Data = MC8000P.Nmc_ReadLp(No, IcNo, AXIS.X);</p>
Nmc_ReadEp	<p>Read out real position counter.</p> <p>VC long Nmc_ReadEp(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadEp(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadEp(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis and AXIS_U for U-axis.</p> <p>Return Value</p> <p>The value of the current real position counter</p> <p>Example</p> <p>[VC] Data = Nmc_ReadEp(No, IcNo, AXIS_Y); // Read out real position counter of Y axis.</p> <p>[VB.NET] Data = Nmc_ReadEp(No, IcNo, AXIS_Y)</p> <p>[C#] Data = MC8000P.Nmc_ReadEp(No, IcNo, AXIS.Y)</p>

Function Name	Function and Content
Nmc_ReadSpeed	<p>Read out the current drive speed.</p> <pre> VC long Nmc_ReadSpeed(int No, int IcNo, int axis); VB.NET Function Nmc_ReadSpeed(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer As Integer) As Integer C# int MC8000P.Nmc_ReadSpeed(int No, int IcNo, AXIS axis); </pre> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis, AXIS_U for U-axis.</p> <p>Return Value</p> <p>The current drive speed.</p> <p>Example</p> <pre> [VC] Data = Nmc_ReadSpeed(No, IcNo, AXIS_Z); // Read out the current drive speed of Z axis. [VB.NET] Data = Nmc_ReadSpeed(No, IcNo, AXIS_Z) [C#] Data = MC8000P.Nmc_ReadSpeed(No, IcNo, AXIS.Z); </pre>
Nmc_ReadAccDec	<p>Read out the current acceleration/deceleration.</p> <p>Read out the value of the current acceleration or deceleration during driving. When the driving stops, the read data is random number.</p> <pre> VC long Nmc_ReadAccDec(int No, int IcNo, int Axis); VB.NET Function Nmc_ReadAccDec(ByVal No As Integer, ByVal IcNo As Integer, ByVal Axis As Integer) As Integer C# int MC8000P.Nmc_ReadAccDec(int No, int IcNo, AXIS Axis); </pre> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis, AXIS_U for U-axis. See 4.1.3 (2) for more details.</p> <p>Return Value</p> <p>The current acceleration/deceleration</p> <p>Example</p> <pre> [VC] Data = Nmc_ReadAccDec(No, IcNo, AXIS_U); // Read out the current acceleration/deceleration of U axis. [VB.NET] Data = Nmc_ReadAccDec(No, IcNo, AXIS_U) [C#] Data = MC8000P.Nmc_ReadAccDec(No, IcNo, AXIS.U); </pre>

Function Name	Function and Content
Nmc_ReadSyncBuff	<p>Read out synchronous action buffer register. *MCX314As only</p> <p>VC long Nmc_ReadSyncBuff(int No, int IcNo, int axis); VB.NET Function Nmc_ReadSyncBuff(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer C# int MC8000P.Nmc_ReadSyncBuff(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis, AXIS_U for U-axis. See 4.1.3 (2) for more details. See 4.1.3 (2) for more details.</p> <p>Return Value</p> <p>The value of synchronous buffer register</p> <p>Example</p> <pre>[VC] Data = Nmc_ReadSyncBuff(No, IcNo, AXIS_X); // Read out synchronous action buffer register of X axis. [VB.NET] Data = Nmc_ReadSyncBuff(No, IcNo, AXIS_X) [C#] Data = MC8000P.Nmc_ReadSyncBuff(No, IcNo, AXIS.X);</pre>
Nmc_GetDriveStatus	<p>Read drive status. The user can use to check whether the driving of the specified axis has finished or not.</p> <p>VC int Nmc_GetDriveStatus(int No, int IcNo, int axis); VB.NET Function Nmc_GetDriveStatus(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer C# int MC8000P.Nmc_GetDriveStatus(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to read drive status. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>Return Value</p> <p>If all the specified axes have finished driving, the return value is 0. If more than one of the specified axes is/are driving, the return value is nonzero.</p> <p>Example</p> <pre>[VC] if(Nmc_GetDriveStatus(No, IcNo, AXIS_X) == 0) // When X axis has finished driving. AfxMessageBox("X axis has finished driving"); else AfxMessageBox("X axis is driving"); [VB.NET] If Nmc_GetDriveStatus(No, IcNo, AXIS_X) = 0 Then Call MsgBox("X axis has finished driving") Else Call MsgBox("X axis is driving") End If [C#] if(MC8000P.Nmc_GetDriveStatus(No, IcNo, AXIS.X) == 0) MessageBox.Show("X axis has finished driving "); else MessageBox.Show("X axis is driving");</pre>

Function Name	Function and Content
Nmc_GetCNextStatus	<p>Read the status of ready signal for writing of continuous interpolation. *MCX314As only The user can use to check whether the signal for the writing of continuous interpolation is ready or not during continuous interpolation execution.</p> <p>VC int Nmc_GetCNextStatus(int No, int IcNo); VB.NET Function Nmc_GetCNextStatus(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_GetCNextStatus(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p> If the signal for the writing of continuous interpolation is ready, the return value is nonzero. If the signal for the writing of continuous interpolation is not ready, the return value is 0.</p> <p>Example</p> <pre>[VC] if(Nmc_GetCNextStatus(No, IcNo) != 0) // When the signal for the writing is ready. AfxMessageBox("The signal for the writing of continuous interpolation is ready"); else AfxMessageBox("The signal for the writing of continuous interpolation is not ready"); [VB.NET] If Nmc_GetCNextStatus(No, IcNo) <> 0 Then Call MsgBox("The signal for the writing of continuous interpolation is ready") Else Call MsgBox("The signal for the writing of continuous interpolation is not ready") End If [C#] if(MC8000P.Nmc_GetCNextStatus(No, IcNo) != 0) MessageBox.Show("The signal for the writing of continuous interpolation is ready"); else MessageBox.Show("The signal for the writing of continuous interpolation is not ready");</pre>
Nmc_GetBpSc	<p>Read the value of BP interpolation stack counter. *MCX314As only</p> <p>VC int Nmc_GetBpSc(int No, int IcNo); VB.NET Function Nmc_GetBpSc(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_GetBpSc(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p> The value of the current bit pattern interpolation stack counter.</p> <p>Example</p> <pre>[VC] Data = Nmc_GetBpSc(No, IcNo); // Read the value of BP interpolation stack counter. [VB.NET] Data = Nmc_GetBpSc(No, IcNo) [C#] Data = MC8000P.Nmc_GetBpSc(No, IcNo);</pre>

Function Name	Function and Content
Nmc_WriteRegSetAxis	<p>Write data into one specified write register of WR1~WR3 for the specified axis.</p> <p>VC void Nmc_WriteRegSetAxis(int No, int IcNo, int axis, int RegNumber, long wdata);</p> <p>VB.NET Sub Nmc_WriteRegSetAxis(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal RegNumber As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteRegSetAxis(int No, int IcNo, AXIS axis, int RegNumber, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to write data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>RegNumber Write register number to write data. [VC][VB.NET] Assign MCX_RR1 for RR1 and MCX_RR2 for RR2. [C#] Assign REG_MCX.RR1 for RR1 and REG_MCX.RR2 for RR2. See 4.1.3 (1).</p> <p>wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example Write ALARM Enable (2000)H into WR2 of all axes.</p> <p>[VC] Nmc_WriteRegSetAxis(No, IcNo, AXIS_ALL, MCX_WR2, 0x2000);</p> <p>[VB.NET] Call Nmc_WriteRegSetAxis(No, IcNo, AXIS_ALL, MCX_WR2, &H2000)</p> <p>[C#] MC8000P.Nmc_WriteRegSetAxis(No, IcNo, AXIS.ALL, REG_MCX.WR2, 0x2000);</p>
Nmc_ReadRegSetAxis	<p>Read out data from the specified read register (either RR1 or RR2) for the specified axis.</p> <p>VC long Nmc_ReadRegSetAxis(int No, int IcNo, int axis, int RegNumber);</p> <p>VB.NET Function Nmc_ReadRegSetAxis(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal RegNumber As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadRegSetAxis(int No, int IcNo, AXIS axis, int RegNumber);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis, AXIS_U for U-axis. See 4.1.3 (2) for more details.</p> <p>RegNumber Read register number to read data. [VC][VB.NET] Assign MCX_RR1 for RR1 and MCX_RR2 for RR2. [C#] Assign REG_MCX.RR1 for RR1 and REG_MCX.RR2 for RR2. See 4.1.3 (1).</p> <p>Return Value</p> <p>The data of the specified read register for the specified axis.</p> <p>Example Read out the data of X axis RR1.</p> <p>[VC] Data = Nmc_ReadRegSetAxis(No, IcNo, AXIS_X, MCX_RR1);</p> <p>[VB.NET] Data = Nmc_ReadRegSetAxis(No, IcNo, AXIS_X, MCX_RR1)</p> <p>[C#] Data = MC8000P.Nmc_ReadRegSetAxis(No, IcNo, AXIS.X, REG_MCX.RR1);</p>

Function Name	Function and Content
Nmc_WriteData	<p>Write the specified parameter into the specified axis. (Execute commands for data writing)</p> <p>VC void Nmc_WriteData(int No, int IcNo, int axis, int cmd, long wdata);</p> <p>VB.NET Sub Nmc_WriteData(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal cmd As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteData(int No, int IcNo, AXIS axis, CMD cmd, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to write data. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>cmd Commands for data writing ((00)H~(0E)H, (61)H). e.g. Range setting is (00)H. *(08)H and (0E)H are excluded for MCX304.</p> <p>wdata Data to be written.</p> <p>Return Value None</p> <p>Example Set 1000 as drive speed of all axes. Drive speed command code is (05)H.</p> <p>[VC] Nmc_WriteData(No, IcNo, AXIS_ALL, 0x05, 1000);</p> <p>[VB.NET] Call Nmc_WriteData(No, IcNo, AXIS_ALL, &H05, 1000)</p> <p>[C#] MC8000P.Nmc_WriteData(No, IcNo, AXIS.ALL, 0x05, 1000);</p>
Nmc_WriteData2	<p>Write the data of extension mode or synchronous action mode into the specified axis. *MCX314As only (Execute commands for data writing)</p> <p>VC void Nmc_WriteData2(int No, int IcNo, int axis, int cmd, long WR6_data, long WR7_data);</p> <p>VB.NET Sub Nmc_WriteData2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal cmd As Integer, ByVal WR6_data As Integer, ByVal WR7_data As Integer)</p> <p>C# void MC8000P.Nmc_WriteData2(int No, int IcNo, AXIS axis, CMD cmd, int WR6_data, int WR7_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Axis Axis to be written data into. Multiple axes can be assigned. See 4.1.3 (2) for more details.</p> <p>cmd Commands for data writing. Specify (60)H for extension mode, and (64)H for synchronous action mode.</p> <p>WR6_data Data to be written into EM6 in extension mode and into SM6 in synchronous action mode.</p> <p>WR7_data Data to be written into EM7 in extension mode and into SM7 in synchronous action mode.</p> <p>Return Value None</p> <p>Example Write EM6 data (5F00)H and EM7 data (45)H into extension mode of X axis.</p> <p>[VC] Nmc_WriteData2(No, IcNo, AXIS_X, 0x60, 0x5F00, 0x0045);</p> <p>[VB.NET] Call Nmc_WriteData2(No, IcNo, AXIS_X, &H60, &H5F00, &H45)</p> <p>[C#] MC8000P.Nmc_WriteData2(No, IcNo, AXIS.X, 0x60, 0x5F00, 0x0045);</p>

Function Name	Function and Content
Nmc_ReadData	<p>Read out data by executing commands for reading data.</p> <p>VC long Nmc_ReadData(int No, int IcNo, int Axis, int cmd); VB.NET Function Nmc_ReadData(ByVal No As Integer, ByVal IcNo As Integer, ByVal Axis As Integer, ByVal cmd As Integer) As Integer C# int MC8000P.Nmc_ReadData(int No, int IcNo, AXIS Axis, CMD cmd);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. Axis Axis to read data. Specify AXIS_X for X-axis, AXIS_Y for Y-axis, AXIS_Z for Z-axis, AXIS_U for U-axis. See 4.1.3 (2) for more details. cmd Commands for reading data ((10)H~(14)H). e.g. Logical position counter reading is (10)H. *(14)H is excluded for MCX304.</p> <p>Return Value Data to be read.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadData(No, IcNo, AXIS_X, 0x10); // Read logical position counter of X axis.</p> <p>[VB.NET] Data = Nmc_ReadData(No, IcNo, AXIS_X, &H10) [C#] Data = MC8000P.Nmc_ReadData(No, IcNo, AXIS.X, 0x10);</p>
Nmc_2BPExec	<p>Execute 2-axis bit pattern interpolation using the specified interpolation data. *MCX314As only This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_2BPExec(int No, int IcNo, DATA_2BP* pData2Bp, int DataCnt, int IpAxis, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_2BPExec(ByVal No As Integer, ByVal IcNo As Integer, ByRef pData2Bp As DATA_2BP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_2BPExec(int No, int IcNo, DATA_2BP[] pData2Bp, int DataCnt, int IpAxis, bool ContinueFlg);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. pData2Bp Pointer to an array of DATA_2BP structures (user-defined type in VB). Set the 2-axis BP interpolation data to DATA_2BP. See 4.1.3 (3) for DATA_2BP. DataCnt The number of 2-axis BP interpolation data. Specify the number of the DATA_2BP structure (user-defined type) array. IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4). ContinueFlg Set the flag to continue when BP interpolation stopped during driving (because the driving speed is too fast to stack the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB.NET] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the function succeeds, the return value is BP_END. If the function fails, the return value is the following Error code. For C#, See 4.1.3 (1).</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> BP_END BP interpolation has been successfully completed. ■ Error code <ul style="list-style-type: none"> BP_CNT_ERR The number of the specified data is out of range. BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. BP_PARAM_ERR The parameter is incorrect. BP_NOT_OPEN_ERR The specified board is not opened. BP_OTHER_ERR Other errors.

BP_STOP BP interpolation stopped during driving (too fast to stack next data).
 BP_USER_STOP The user aborted BP interpolation.
 BP_DRIVE_ERR Error occurred in the board during BP interpolation.
 (When the error status was set to RR0.)

Example

```
[VC] // 2-axis BP interpolation data BP1P, BP1M, BP2P, BP2M
DATA_2BP Data2Bp[2] = {{0x0000, 0x2BFF, 0xFFD4, 0x0000},
                      {0xF6FE, 0x0000, 0x000F, 0x3FC0}};

Nmc_WriteReg5(No, IcNo, 0x04);
// Axis assignment for interpolation. Main axis: X, Second axis: Y
Ret = Nmc_2BPExec(No, IcNo, Data2Bp, 2, 0x04);
// Execute 2-axis BP interpolation. The number of data is 2, X, Y axes.
if(Ret == BP_END) AfxMessageBox("Successful completion");
// Return value is correct.

[VB.NET] Dim Data2Bp(1) As DATA_2BP ' 2-axis BP interpolation data
' 2-axis BP interpolation data setting
Data2Bp(0).Bp1p = &H0: Data2Bp(0).Bp1m = &H2BFF
Data2Bp(0).Bp2p = &HFFD4: Data2Bp(0).Bp2m = &H0
Data2Bp(1).Bp1p = &HF6FE: Data2Bp(1).Bp1m = &H0
Data2Bp(1).Bp2p = &HF: Data2Bp(1).Bp2m = &H3FC0
Call Nmc_WriteReg5(No, IcNo, &H4)
' Axis assignment for interpolation. Main axis: X, Second axis: Y
Ret = Nmc_2BPExec(No, IcNo, Data2Bp(0), 2, &H4, False)
' Execute 2-axis BP interpolation. The number of data is 2, X, Y axes.
If Ret = BP_END Then ' Return value is correct.
    Call MsgBox("Successful completion")
End If

[C#]
DATA_2BP [] Data2Bp = new DATA_2BP[1]; // 2-axis BP interpolation data
// Set interpolation data
Data2Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 + direction10 pulse
Data2Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 - direction0 pulse
Data2Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 + direction0 pulse
Data2Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2 - direction10 pulse

IpAxis = IP_AXIS.IP_X | IP_AXIS.IP_Y << 2; // Axis for interpolation

MC8000P.Nmc_WriteReg5(No, IcNo, IpAxis); // Axis assignment for interpolation.
MC8000P.Nmc_StartSpd(No, IcNo, AXIS.ALL, 1); // Set initial speed
MC8000P.Nmc_Speed(gBoardNo, IcNo, AXIS.ALL, 1); // Set drive speed
// Execute 2-axis BP interpolation.
Ret = MC8000P.Nmc_2BPExec(No, IcNo, Data2Bp, DataCnt, Axis, ContinueFlg);

if(Ret == Nmc_Status.BP_END) // Return value is correct.
```

Function Name	Function and Content
Nmc_3BPExec	<p>Execute 3-axis bit pattern interpolation using the specified interpolation data. *MCX314As only This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_3BPExec(int No, int IcNo, DATA_3BP* pData3Bp, int DataCnt, int IpAxis, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_3BPExec(ByVal No As Integer, ByVal IcNo As Integer, ByRef pData3Bp As DATA_3BP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3BPExec(int No, int IcNo, DATA_3BP[] pData3Bp, int DataCnt, int IpAxis, bool ContinueFlg);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>pData3Bp Pointer to an array of DATA_3BP structures (user-defined type). Set the 3-axis BP interpolation data to DATA_3BP. See 4.1.3 (3) for DATA_3BP.</p> <p>DataCnt The number of 3-axis BP interpolation data. Specify the number of the DATA_3BP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4).</p> <p>ContinueFlg Set the flag to continue when BP interpolation stopped during driving (because the driving speed is too fast to stack the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB.NET] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the function succeeds, the return value is BP_END. If the function fails, the return value is the following Error code. For C#, See 4.1.3 (1).</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> BP_END BP interpolation has been successfully completed. ■ Error code <ul style="list-style-type: none"> BP_CNT_ERR The number of the specified data is out of range. BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. BP_PARAM_ERR The parameter is incorrect. BP_NOT_OPEN_ERR The specified board is not opened. BP_OTHER_ERR Other errors. BP_STOP BP interpolation stopped during driving (too fast to stack next data). BP_USER_STOP The user aborted BP interpolation. BP_DRIVE_ERR Error occurred in the board during BP interpolation. (When the error status was set to RR0.) <p>Example</p> <pre>[VC] // 3-axis BP interpolation data BP1P, BP1M, BP2P, BP2M, BP3P, BP3M DATA_3BP Data3Bp[2] = {{0xFF30, 0, 0, 0x84FF, 0, 0xAC35}, {0xAC35, 0, 0xC000, 0x36E7, 0xC000, 0x3F3F}}; Nmc_WriteReg5(No, IcNo, 0x24); // Axis assignment for interpolation. Main axis: X, Second axis: Y, Third axis: Z Ret = Nmc_3BPExec(No, IcNo, Data3Bp, 2, 0x24); // Execute 3-axis BP interpolation. The number of data is 2, X, Y, Z axes. if(Ret == BP_END) AfxMessageBox ("Successful completion"); // Return value is correct.</pre> <pre>[VB.NET] Dim Data3Bp(1) As DATA_3BP ' 3-axis BP interpolation data ' 3-axis BP interpolation data setting Data3Bp(0).Bp1p = &HFF30: Data3Bp(0).Bp1m = &H0 Data3Bp(0).Bp2p = &H0: Data3Bp(0).Bp2m = &H84FF Data3Bp(0).Bp3p = &H0: Data3Bp(0).Bp3m = &HAC35 Data3Bp(1).Bp1p = &HAC35: Data3Bp(1).Bp1m = &H0 Data3Bp(1).Bp2p = &HC000: Data3Bp(1).Bp2m = &H36E7 Data3Bp(1).Bp3p = &HC000: Data3Bp(1).Bp3m = &H3F3F Call Nmc_WriteReg5(No, IcNo, &H24) ' Axis assignment for interpolation. Main axis: X, Second axis: Y, Third axis: Z Ret = Nmc_3BPExec(No, IcNo, Data3Bp(0), 2, &H24, False)</pre>

	<pre> ' Execute 3-axis BP interpolation. The number of data is 2, X, Y, Z axes. If Ret = BP_END Then Call MsgBox("Successful completion") End If ' Return value is correct. [C#] DATA_3BP [] Data3Bp = new DATA_3BP[1]; // 3-axis BP interpolation data // Set interpolation data Data3Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 + direction 10 pulse Data3Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 - direction 0 pulse Data3Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 + direction 0 pulse Data3Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2- direction 10 pulse Data3Bp[0].Bp3p = 0; // 0000 0000 0000 0000 BP3 + direction 0 pulse Data3Bp[0].Bp3m = 0xAC35; // 1010 1100 0011 0101 BP3 - direction 8 pulse IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2 IP_AXIS.IP_Z << 4; // Axis for interpolation MC8000P.Nmc_WriteReg5(No, IcNo, IpAxis); // Axis assignment for interpolation. MC8000P.Nmc_StartSpd(No, IcNo, AXIS.ALL, 1); // Set initial speed MC8000P.Nmc_Speed(No, IcNo, AXIS.ALL, 1); // Set drive speed // Execute 3-axis BP interpolation. Ret = MC8000P.Nmc_3BPExec(No, IcNo, Data3Bp, DataCnt, IpAxis, ContinueFlg); if(Ret == Nmc_Status.BP_END) // Return value is correct. </pre>
Nmc_2BPExec_BG	<p>Execute 2-axis bit pattern interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_BP_END message is sent to the specified window at the end of the interpolation and finishing status is passed. *MCX314As only</p> <p>VC DWORD Nmc_2BPExec_BG(HWND User_hWnd, int No, int IcNo, DATA_2BP* pData2Bp, int DataCnt, int IpAxis, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_2BPExec_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByRef pData2Bp As DATA_2BP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_2BPExec_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_2BP[] pData2Bp, int DataCnt, int IpAxis, bool ContinueFlg);</p> <p>Input Parameter</p> <p>User_hWnd Window handle of the user application</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>pData2Bp Pointer to an array of DATA_2BP structures (user-defined type). Set the 2-axis BP interpolation data to DATA_2BP. See 4.1.3 (3) for DATA_2BP.</p> <p>DataCnt The number of 2-axis BP interpolation data. Specify the number of the DATA_2BP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4).</p> <p>ContinueFlg Set the flag to continue when BP interpolation stopped during driving (because the driving speed is too fast to stack the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB.NET] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is BP_START.</p> <p>If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See 4.1.3 (1).</p> <ul style="list-style-type: none"> ■ Normal start BP_START BP interpolation has been successfully started in the background. ■ Error code (errors before starting the interpolation)

BP_CNT_ERR The number of the specified data is out of range.
 BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running.
 BP_THREAD_ERR Thread cannot be started.
 BP_MALLOC_ERR Memory cannot be allocated.
 BP_PARAM_ERR The parameter is incorrect.
 BP_NOT_OPEN_ERR The specified board is not opened.
 BP_OTHER_ERR Other errors.

After the interpolation process has been successfully started in the background, WM_BP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_BP_END message received function and finishing status is passed to the second argument.

If the interpolation has been successfully completed, the finishing status is BP_END.

If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.

■ Normal end

BP_END BP interpolation has been successfully completed.

■ Error code (errors after starting the interpolation)

BP_STOP BP interpolation stopped during driving (too fast to stack next data).

BP_USER_STOP The user aborted BP interpolation.

BP_DRIVE_ERR Error occurred in the board during BP interpolation.
 (When the error status was set to RR0.)

Example

```
[VC]
{
  // 2-axis BP interpolation data   BP1P,  BP1M,  BP2P,  BP2M
  DATA_2BP Data2Bp[2] = {{0x0000, 0x2BFF, 0xFFD4, 0x0000},
                          {0xF6FE, 0x0000, 0x000F, 0x3FC0}};

  Nmc_WriteReg5(No, IcNo, 0x04);
  // Axis assignment for interpolation. Main axis: X, Second axis: Y
  Ret = Nmc_2BPExec_BG(hWnd, No, IcNo, Data2Bp, 2, 0x04);
  // Execute 2-axis BP interpolation. The number of data is 2, X, Y axes.
  if(Ret == BP_START)   AfxMessageBox ("Interpolation has started");
  // Return value is correct. (Interpolation has started)
}
BEGIN_MESSAGE_MAP(CMC_SAMPLEDlg, CDialog)
  // WM_BP_END message received function setting
  ON_MESSAGE( WM_BP_END, OnMsg_BP )
END_MESSAGE_MAP()

// WM_BP_END message received function
afx_msg LRESULT CMC_SAMPLEDlg::OnMsg_BP(WPARAM BoardNo, LPARAM Status)
{
  if(Status == BP_END)   AfxMessageBox("Interpolation has been successfully completed");
// Return value is correct. (Interpolation completed.)

  return 0;
}

[VB.NET]
Dim Data2Bp(1) As DATA_2BP       ' 2-axis BP interpolation data

' 2-axis BP interpolation data setting
Data2Bp(0).Bp1p = &H0:    Data2Bp(0).Bp1m = &H2BFF
Data2Bp(0).Bp2p = &HFFD4: Data2Bp(0).Bp2m = &H0
Data2Bp(1).Bp1p = &HF6FE: Data2Bp(1).Bp1m = &H0
Data2Bp(1).Bp2p = &HF:    Data2Bp(1).Bp2m = &H3FC0

Call Nmc_WriteReg5(No, IcNo, &H4)
' Axis assignment for interpolation. Main axis: X, Second axis: Y.
Ret = Nmc_2BPExec_BG(hWnd,No,IcNo, Data2Bp(0), 2, &H4, False)
' Execute 2-axis BP interpolation. The number of data is 2, X, Y axes.
If Ret = BP_START Then
' Return value is correct. (Interpolation has started)
```

	<pre> Call MsgBox("Interpolation has started") End If End Sub ' WM_BP_END message received function Protected Overrides Sub WndProc(ByRef m As Message) If m.Msg = WM_BP_END Then ' BP interpolation finishing message If lParam = BP_END Then ' Return value is correct. (Interpolation has finished) Call MsgBox("Interpolation has been successfully completed") End If End If End If MyBase.WndProc(m) End Sub [C#] DATA_2BP [] Data2Bp = new DATA_2BP[1]; // 2-axis BP interpolation data // Set interpolation data Data2Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 + direction 10 pulse Data2Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 - direction 0 pulse Data2Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 + direction 0 pulse Data2Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2 - direction 10 pulse IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2; // Axis for interpolation MC8000P.Nmc_WriteReg5(No, IcNo, IpAxis); // Axis assignment for interpolation. MC8000P.Nmc_StartSpd(No, IcNo, AXIS.ALL, 1); // Set initial speed MC8000P.Nmc_Speed(gBoardNo, IcNo, AXIS.ALL, 1); // Set drive speed // Execute 2-axis BP interpolation in the background. Ret = MC8000P.Nmc_2BPExec_BG((System.IntPtr)parent.Handle, No, IcNo, Data2Bp, DataCnt, IpAxis, ContinueFlg); if(Ret == Nmc_Status.BP_START) // Interpolation has been successfully started. // WM_BP_END message received function protected override void WndProc(ref Message m) { // Call original WndProc (call a constructor explicitly) base.WndProc (ref m); if (m.Msg == (int)MSG_ID.WM_BP_END) { // BP interpolation has been successfully completed. if((uint)m.LParam == Nmc_Status.BP_END) } } </pre>
--	---

Function Name	Function and Content
Nmc_3BPExec_BG	<p>Execute 3-axis bit pattern interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_BP_END message is sent to the specified window at the end of the interpolation and finishing status is passed. *MCX314As only</p> <p>VC DWORD Nmc_3BPExec_BG(HWND User_hWnd, int No, int IcNo, DATA_3BP* pData3Bp, int DataCnt, int IpAxis, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_3BPExec_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByRef pData3Bp As DATA_3BP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3BPExec_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_3BP[] pData3Bp, int DataCnt, int IpAxis, bool ContinueFlg);</p> <p>Input Parameter</p> <p>User_hWnd Window handle of the user application No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details. pData3Bp Pointer to an array of DATA_3BP structures (user-defined type in VB). Set the 3-axis BP interpolation data to DATA_3BP. See 4.1.3 (3) for DATA_3BP. DataCnt The number of 3-axis BP interpolation data. Specify the number of the DATA_3BP structure (user-defined type) array. IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4). ContinueFlg Set the flag to continue when BP interpolation stopped during driving (because the driving speed is too fast to stack the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB.NET] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is BP_START. If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See 4.1.3 (1).</p> <ul style="list-style-type: none"> ■ Normal start BP_START BP interpolation has been successfully started in the background. ■ Error code (errors before starting the interpolation) BP_CNT_ERR The number of the specified data is out of range. BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. BP_THREAD_ERR Thread cannot be started. BP_MALLOC_ERR Memory cannot be allocated. BP_PARAM_ERR The parameter is incorrect. BP_NOT_OPEN_ERR The specified board is not opened. BP_OTHER_ERR Other errors. <p>After the interpolation process has been successfully started in the background, WM_BP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_BP_END message received function and finishing status is passed to the second argument. If the interpolation has been successfully completed, the finishing status is BP_END. If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.</p> <ul style="list-style-type: none"> ■ Normal end BP_END BP interpolation has been successfully completed. ■ Error code (errors after starting the interpolation) BP_STOP BP interpolation stopped during driving (too fast to stack next data). BP_USER_STOP The user aborted BP interpolation.

	<pre> BP_DRIVE_ERR Error occurred in the board during BP interpolation. (When the error status was set to RR0.) Example [VC] { // 3-axis BP interpolation data BP1P, BP1M, BP2P, BP2M, BP3P, BP3M DATA_3BP Data3Bp[2] = {{0xFF30, 0, 0, 0x84FF, 0, 0xAC35}, {0xAC35, 0, 0xC000, 0x36E7, 0xC000, 0x3F3F}}; Nmc_WriteReg5(No, IcNo, 0x24); // Axis assignment for interpolation. Main axis: X, Second axis: Y. Third axis: Z Ret = Nmc_3BPExec_BG(hWnd, No, IcNo, Data3Bp, 2, 0x24); // Execute 3-axis BP interpolation. The number of data is 2, X, Y, Z axes. if(Ret == BP_START) AfxMessageBox("Interpolation has started"); // Return value is correct. (Interpolation has started) } BEGIN_MESSAGE_MAP(CMC_SAMPLEDIg, CDIALOG) // WM_BP_END message received function setting ON_MESSAGE(WM_BP_END, OnMsg_BP) END_MESSAGE_MAP() // WM_BP_END message received function afx_msg LRESULT CMC_SAMPLEDIg::OnMsg_BP(WPARAM BoardNo, LPARAM Status) { if(Status == BP_END) AfxMessageBox("Interpolation has been successfully completed "); // Return value is correct. (Interpolation has finished) return 0; } [VB.NET] Dim Data3Bp(1) As DATA_3BP ' 3-axis BP interpolation data ' 3-axis BP interpolation data setting Data3Bp(0).Bp1p = &HFF30: Data3Bp(0).Bp1m = &H0 Data3Bp(0).Bp2p = &H0: Data3Bp(0).Bp2m = &H84FF Data3Bp(0).Bp3p = &H0: Data3Bp(0).Bp3m = &HAC35 Data3Bp(1).Bp1p = &HAC35: Data3Bp(1).Bp1m = &H0 Data3Bp(1).Bp2p = &HC000: Data3Bp(1).Bp2m = &H36E7 Data3Bp(1).Bp3p = &HC000: Data3Bp(1).Bp3m = &H3F3F Call Nmc_WriteReg5(No, IcNo, &H24) ' Axis assignment for interpolation. Main axis: X, Second axis: Y, Third axis: Z Ret = Nmc_3BPExec_BG(hWnd,No,IcNo,Data3Bp(0),2,&H24,False) ' Execute 3-axis BP interpolation. The number of data is 2, X, Y, Z axes. If Ret = BP_START Then ' Return value is correct. (Interpolation has started) Call MsgBox("Interpolation has started") End If End Sub ' WM_BP_END message received function Protected Overrides Sub WndProc(ByRef m As Message) If m.Msg = WM_BP_END Then ' BP interpolation finishing message If IParam = BP_END Then ' Return value is correct. (Interpolation has finished) Call MsgBox("Interpolation has been successfully completed ") End If End If End Sub MyBase.WndProc(m) End Sub [C#] DATA_3BP [] Data3Bp = new DATA_3BP[1]; // 3-axis BP interpolation data // Set interpolation data Data3Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 + direction 10 pulse Data3Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 - direction 0 pulse Data3Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 + direction 0 pulse Data3Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2 - direction 10 pulse Data3Bp[0].Bp3p = 0; // 0000 0000 0000 0000 BP3 + direction 0 pulse </pre>
--	---

	<pre> Data3Bp[0].Bp3m = 0xAC35; // 1010 1100 0011 0101 BP3 - direction 8 pulse IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2 IP_AXIS.IP_Z << 4; // Axis for interpolation MC8000P.Nmc_WriteReg5(No, IcNo, IpAxis); // Axis assignment for interpolation. MC8000P.Nmc_StartSpd(No, IcNo, AXIS.ALL, 1); // Set initial speed MC8000P.Nmc_Speed(gBoardNo, IcNo, AXIS.ALL, 1); // Set drive speed // Execute 3-axis BP interpolation in the background. Ret = MC8000P.Nmc_3BPExec_BG((System.IntPtr)parent.Handle, No, IcNo, Data3Bp, DataCnt, IpAxis, ContinueFlg); if(Ret == Nmc_Status.BP_START) // Interpolation has been successfully started. // WM_BP_END message received function protected override void WndProc(ref Message m) { // Call original WndProc (call a constructor explicitly) base.WndProc (ref m); if (m.Msg == (int)MSG_ID.WM_BP_END) { // BP interpolation has been successfully completed. if((uint)m.LParam == Nmc_Status.BP_END) } } } </pre>
<p>Nmc_2CIPExec</p>	<p>Execute 2-axis continuous interpolation using the specified interpolation data. *MCX314As only This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_2CIPExec(int No, int IcNo, DATA_2CIP* pData2Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_2CIPExec(ByVal No As Integer, ByVal IcNo As Integer, ByRef pData2Cip As DATA_2CIP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P. Nmc_2CIPExec(int No, int IcNo, DATA_2CIP[] pData2Cip, int DataCnt, int IpAxis, bool SpdChgFlg, bool ContinueFlg);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>pData2Cip Pointer to an array of DATA_2CIP structures (user-defined type in VB). Set the 2-axis continuous interpolation data to DATA_2CIP. See 4.1.3 (3) for DATA_2CIP.</p> <p>DataCnt The number of 2-axis continuous interpolation data. Specify the number of the DATA_2CIP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See 4.1.3 (5). [VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE. [VB.NET] True: Change, False: Not change [C#] true: Change, false: Not change</p> <p>When selecting Change: Refers to the setting value of DATA_2CIP Speed. Set 1~8000 to Speed . . . Changes to the setting speed. Set 0 to Speed Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_2CIP Speed.</p> <p>ContinueFlg Set the flag to continue when continuous interpolation stopped during driving (because the driving speed is too fast to set the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB.NET] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value If the function succeeds, the return value is CIP_END.</p>

	<pre> // Set interpolation data Data2Cip[0].Command = (ushort)CMD.COMD_IP_CW; // CW circular interpolation Data2Cip[0].EndP1 = 2000; Data2Cip[0].EndP2 = 2000; Data2Cip[0].Center1 = 2000; Data2Cip[0].Center2 = 0; Data2Cip[0].Speed = 200; // Change speed (200) IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2; // Axis for interpolation MC8000P.Nmc_WriteReg5(No, IpAxis); // Axis assignment for interpolation. // Execute 2-axis continuous interpolation. // This function will not return control unless the interpolation process ends. Ret = MC8000P.Nmc_2CIPExec(No, int IcNo, Data2Cip, DataCnt, IpAxis, SpdChgFlg, ContinueFlg); if(Ret == Nmc_Status.CIP_END) // Continuous interpolation has been successfully completed. </pre>
Nmc_3CIPExec	<p>Execute 3-axis continuous interpolation using the specified interpolation data. *MCX314As only This function returns control after the interpolation process has finished. That is the control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_3CIPExec(int No, int IcNo, DATA_3CIP* pData3Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_3CIPExec(ByVal No As Integer, ByVal IcNo As Integer, ByRef pData3Cip As DATA_3CIP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3CIPExec(int No, IcNo, DATA_3CIP[] pData3Cip, int DataCnt, int IpAxis, bool SpdChgFlg, bool ContinueFlg);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>pData3Cip Pointer to an array of DATA_3CIP structures (user-defined type in VB). Set the 3-axis continuous interpolation data to DATA_3CIP. See 4.1.3 (3) for DATA_3CIP.</p> <p>DataCnt The number of 3-axis continuous interpolation data. Specify the number of the DATA_3CIP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See 4.1.3 (5). [VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE. [VB] True: Change, False: Not change [C#] true: Change, false: Not change</p> <p>When selecting Change: Refers to the setting value of DATA_3CIP Speed. Set 1~8000 to Speed · · · Changes to the setting speed. Set 0 to Speed · · · · · Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_3CIP Speed.</p> <p>ContinueFlg Set the flag to continue when continuous interpolation stopped during driving (because the driving speed is too fast to set the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the function succeeds, the return value is CIP_END. If the function fails, the return value is the following Error code. For C#, See 4.1.3 (1).</p>

- Normal end
 - CIP_END Continuous interpolation has been successfully completed.

- Error code
 - CIP_CNT_ERR The number of the specified data is out of range.
 - CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running.
 - CIP_CMD_ERR The wrong command was specified.
 - CIP_PARAM_ERR The parameter is incorrect.
 - CIP_NOT_OPEN_ERR The specified board is not opened.
 - CIP_OTHER_ERR Other errors.
 - CIP_STOP Continuous interpolation stopped during driving
(too fast to set next data).
 - CIP_USER_STOP The user aborted continuous interpolation.
 - CIP_DRIVE_ERR Error occurred in the board during continuous interpolation.
(When the error status was set to RR0.)

NOTE

Before using this function, set 8000 to initial speed. (Don't change initial speed during executing this function.) For the details, please see chapter 4.1.4.

Example

```
[VC] DATA_3CIP Data3Cip[2];                    // 3-axis continuous interpolation data

// 3-axis continuous interpolation data setting
Data3Cip[0].EndP1 = 1000;
Data3Cip[0].EndP2 = 2000;
Data3Cip[0].EndP3 = 3000;
Data3Cip[0].Speed = 0;

Data3Cip[1].EndP1 = 2000;
Data3Cip[1].EndP2 = -1000;
Data3Cip[1].EndP3 = 3000;
Data3Cip[1].Speed = 0;

Nmc_WriteReg5(No, IcNo, 0x24);
// Axis assignment for interpolation. Main axis: X, Second axis: Y, Third axis: Z.
Ret = Nmc_3CIPExec(No, IcNo, Data3Cip, 2, 0x24);
// Execute 3-axis continuous interpolation. The number of data is 2, X, Y, Z axes.
if(Ret == CIP_END)    AfxMessageBox ("Successful completion");
// Return value is correct.

[VB.NET] Dim Data3Cip(1) As DATA_3CIP    ' 3-axis continuous interpolation data

' 3-axis continuous interpolation data setting
Data3Cip(0).EndP1 = 1000
Data3Cip(0).EndP2 = 2000
Data3Cip(0).EndP3 = 3000
Data3Cip(0).Speed = 0

Data3Cip(1).EndP1 = 2000
Data3Cip(1).EndP2 = -1000
Data3Cip(1).EndP3 = 3000
Data3Cip(1).Speed = 0

Call Nmc_WriteReg5(No, IcNo, &H24)
' Axis assignment for interpolation. Main axis: X, Second axis: Y, Third axis: Z.
Ret = Nmc_3CIPExec(No,IcNo, Data3Cip(0), 2, &H24, False,False)
' 3-axis continuous interpolation. The number of data is 2, X, Y, Z axes.
If Ret = CIP_END Then
' Return value is correct.
```

	<pre> Call MsgBox("Successful completion") End If [C#] DATA_3CIP [] Data3Cip = new DATA_3CIP[1]; // 3-axis continuous interpolation data // Set interpolation data Data3Cip[0].EndP1 = 1000; Data3Cip[0].EndP2 = 2000; Data3Cip[0].EndP3 = 3000; Data3Cip[0].Speed = 0; IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2 IP_AXIS.IP_Z << 4; // Axis for interpolation MC8000P.Nmc_WriteReg5(gBoardNo, IcNo, IpAxis); // Axis assignment for interpolation. MC8000P.Nmc_StartSpd(gBoardNo, IcNo, AXIS.ALL, 8000); // Set initial speed MC8000P.Nmc_Speed(gBoardNo, IcNo, AXIS.ALL, 100); // Set drive speed // Execute 3-axis continuous interpolation. // This function will not return control unless the interpolation process ends. Ret = MC8000P.Nmc_3CIExec(No, IcNo, Data3Cip, DataCnt, IpAxis, SpdChgFlg, ContinueFlg); if(Ret == Nmc_Status.CIP_END) // Continuous interpolation has been successfully completed.</pre>
--	--

Function Name	Function and Content
Nmc_2CIPExec_BG	<p>Execute 2-axis continuous interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_CIP_END message is sent to the specified window at the end of the interpolation and finishing status is passed. *MCX314As only</p> <p>VC DWORD Nmc_2CIPExec_BG(HWND User_hWnd, int No, int IcNo, DATA_2CIP* pData2Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_2CIPExec_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByRef pData2Cip As DATA_2CIP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_2CIPExec_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_2CIP[] pData2Cip, int DataCnt, int IpAxis, bool SpdChgFlg, bool ContinueFlg);</p> <p>Input Parameter</p> <p>User_hWnd Window handle of the user application</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>pData2Cip Pointer to an array of DATA_2CIP structures (user-defined type). Set the 2-axis continuous interpolation data to DATA_2CIP. See 4.1.3 (3) for DATA_2CIP.</p> <p>DataCnt The number of 2-axis continuous interpolation data. Specify the number of the DATA_2CIP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See 4.1.3 (5). [VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE. [VB] True: Change, False: Not change [C#] true: Change, false: Not change When selecting Change: Refers to the setting value of DATA_2CIP Speed. Set 1~8000 to Speed · · · Changes to the setting speed. Set 0 to Speed · · · · · Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_2CIP Speed.</p> <p>ContinueFlg Set the flag to continue when continuous interpolation stopped during driving (because the driving speed is too fast to set the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is CIP_START. If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See 4.1.3 (1).</p> <ul style="list-style-type: none"> ■ Normal start CIP_START Continuous interpolation has been successfully started in the background. ■ Error code (errors before starting the interpolation) <ul style="list-style-type: none"> CIP_CNT_ERR The number of the specified data is out of range. CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. CIP_THREAD_ERR Thread cannot be started. CIP_MALLOC_ERR Memory cannot be allocated. CIP_CMD_ERR The wrong command was specified. CIP_PARAM_ERR The parameter is incorrect. CIP_NOT_OPEN_ERR The specified board is not opened. CIP_OTHER_ERR Other errors. <p>After the interpolation process has been successfully started in the background, WM_CIP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_CIP_END message received function and finishing status is passed to the second argument.</p>

If the interpolation has been successfully completed, the finishing status is CIP_END.
If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.

- Normal end
CIP_END Continuous interpolation has been successfully completed.
- Error code (errors after starting the interpolation)
 - CIP_STOP Continuous interpolation stopped during driving
 (too fast to set next data).
 - CIP_USER_STOP The user aborted continuous interpolation.
 - CIP_DRIVE_ERR Error occurred in the board during continuous interpolation.
 (When the error status was set to RR0.)

NOTE

Before using this function, set 8000 to initial speed. (Don't change initial speed during executing this function.) For the details, please see chapter 4.1.4.

Example

```
[VC] {
    // 2-axis continuous interpolation data Command, Speed, Finishing point 1, Finishing point
    // 2, Center point 1, Center point 2
    DATA_2CIP Data2Cip[2]= {{CMD_IP_2ST, 0, 4500, 0, 0, 0},
                             // 2-axis linear interpolation
                             {CMD_IP_CCW, 0, 1500, 1500, 0, 1500}};
                             // CCW circular interpolation

    Nmc_WriteReg5(No, IcNo, 0x04);
    // Axis assignment for interpolation. Main axis: X, Second axis: Y.
    Ret = Nmc_2CIPExec_BG(hWnd, No, IcNo, Data2Cip, 2, 0x04);
    // Execute 2-axis continuous interpolation. The number of data is 2, X, Y axes.
    if(Ret == CIP_START) AfxMessageBox("Interpolation has started");
    // Return value is correct. (Interpolation has started)
}
BEGIN_MESSAGE_MAP(CMC_SAMPLEDlg, CDialog)
    // WM_CIP_END message received function setting
    ON_MESSAGE( WM_CIP_END, OnMsg_CIP )
END_MESSAGE_MAP()
// WM_CIP_END message received function
afx_msg LRESULT CMC_SAMPLEDlg::OnMsg_CIP(WPARAM BoardNo, LPARAM Status)
{
    if(Status == CIP_END) AfxMessageBox("Interpolation has been successfully completed");
    // Return value is correct. (Interpolation has finished)
    return 0;
}

[VB.NET] Dim Data2Cip(1) As DATA_2CIP ' 2-axis continuous interpolation data
' 2-axis continuous interpolation data setting
Data2Cip(0).Command = CMD_IP_2ST ' 2-axis linear interpolation
Data2Cip(0).EndP1 = 4500
Data2Cip(0).EndP2 = 0

Data2Cip(1).Command = CMD_IP_CCW ' CCW circular interpolation
Data2Cip(1).EndP1 = 1500
Data2Cip(1).EndP2 = 1500
Data2Cip(1).Center1 = 0
Data2Cip(1).Center2 = 1500

Call Nmc_WriteReg5(No, IcNo, &H4)
' Axis assignment for interpolation. Main axis: X, Second axis: Y.
' 2-axis continuous interpolation. The number of data is 2, X, Y axes.
Ret = Nmc_2CIPExec_BG(hWnd, No, IcNo, Data2Cip(0), 2, &H4, False, False)
If Ret = CIP_START Then ' Return value is correct. (Interpolation has started)
    Call MsgBox("Interpolation has started")
End If
End Sub

' WM_CIP_END message received function
Protected Overrides Sub WndProc(ByRef m As Message)
    If m.Msg = WM_CIP_END Then ' Continuous interpolation finishing message
        If lParam = CIP_END Then ' Return value is correct. (Interpolation has finished)
            Call MsgBox("Interpolation has been successfully completed")
        End If
    End If
End Sub
```

	<pre> End If End If MyBase.WndProc(m) End Sub [C#] DATA_2CIP [] Data2Cip = new DATA_2CIP[1]; // 2-axis continuous interpolation data // Set interpolation data Data2Cip[0].Command = (ushort)CMD.CMD_IP_CW; // CW circular interpolation Data2Cip[0].EndP1 = 2000; Data2Cip[0].EndP2 = 2000; Data2Cip[0].Center1 = 2000; Data2Cip[0].Center2 = 0; Data2Cip[0].Speed = 200; // Change speed (200) IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2; // Axis for interpolation MC8000P.Nmc_WriteReg5(No, int IcNo, IpAxis); // Axis assignment for interpolation. // Execute 2-axis continuous interpolation. // Execute in the background. Ret = MC8000P.Nmc_2CIPExec_BG((System.IntPtr)parent.Handle, dNo, int IcNo, Data2Cip, DataCnt, IpAxis, SpdChgFlg, ContinueFlg); if(Ret == Nmc_Status.CIP_START) // Continuous interpolation has been successfully started. // WM_BP_END message received function protected override void WndProc(ref Message m) { // Call original WndProc (call a constructor explicitly) base.WndProc (ref m); if (m.Msg == (int)MSG_ID.WM_CIP_END) { if((uint)m.LParam == Nmc_Status.CIP_END) // Continuous interpolation has been successfully completed. } } </pre>
--	---

Function Name	Function and Content
Nmc_3CIPExec_BG	<p>Execute 3-axis continuous interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_CIP_END message is sent to the specified window at the end of the interpolation and finishing status is passed. *MCX314As only</p> <p>VC DWORD Nmc_3CIPExec_BG(HWND User_hWnd, int No, int IcNo, DATA_3CIP* pData3Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE, BOOL ContinueFlg = FALSE);</p> <p>VB.NET Function Nmc_3CIPExec_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByRef pData3Cip As DATA_3CIP, ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer, ByVal ContinueFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3CIPExec_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_3CIP[] pData3Cip, int IpAxis, bool SpdChgFlg, bool ContinueFlg);</p> <p>Input Parameter</p> <p>User_hWnd Window handle of the user application</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>pData3Cip Pointer to an array of DATA_3CIP structures (user-defined type in VB). Set the 3-axis continuous interpolation data to DATA_3CIP. See 4.1.3 (3) for DATA_3CIP.</p> <p>DataCnt The number of 3-axis continuous interpolation data. Specify the number of the DATA_3CIP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of WR5 D0~D5 (Axis assignment). See 4.1.3 (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See 4.1.3 (5). [VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE. [VB] True: Change, False: Not change [C#] true: Change, false: Not change When selecting Change: Refers to the setting value of DATA_3CIP Speed. Set 1~8000 to Speed · · · Changes to the setting speed. Set 0 to Speed · · · · · Not change the speed. When selecting Not change: Not refers to the setting value of DATA_3CIP Speed.</p> <p>ContinueFlg Set the flag to continue when continuous interpolation stopped during driving (because the driving speed is too fast to set the next data). [VC] TRUE: Continue, FALSE: Not continue Can be omitted. Default is FALSE. [VB] True: Continue, False: Not continue [C#] true: Continue, false: Not continue</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is CIP_START. If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See 4.1.3 (1).</p> <ul style="list-style-type: none"> ■ Normal start CIP_START Continuous interpolation has been successfully started in the background. ■ Error code (errors before starting the interpolation) <ul style="list-style-type: none"> CIP_CNT_ERR The number of the specified data is out of range. CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. CIP_THREAD_ERR Thread cannot be started. CIP_MALLOC_ERR Memory cannot be allocated. CIP_CMD_ERR The wrong command was specified. CIP_PARAM_ERR The parameter is incorrect. CIP_NOT_OPEN_ERR The specified board is not opened. CIP_OTHER_ERR Other errors. <p>After the interpolation process has been successfully started in the background, WM_CIP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_CIP_END message received function and finishing status is passed to the second argument.</p> <p>If the interpolation has been successfully completed, the finishing status is CIP_END.</p>

	<pre> Protected Overrides Sub WndProc(ByRef m As Message) If m.Msg = WM_CIP_END Then ' Continuous interpolation finishing message If lParam = CIP_END Then ' Return value is correct. (Interpolation has finished) Call MsgBox("Interpolation has been successfully completed ") End If End If End Sub MyBase.WndProc(m) End Sub [C#] DATA_3CIP [] Data3Cip = new DATA_3CIP[1]; // 3-axis continuous interpolation data // Set interpolation data Data3Cip[0].EndP1 = 1000; Data3Cip[0].EndP2 = 2000; Data3Cip[0].EndP3 = 3000; Data3Cip[0].Speed = 0; IpAxis = IP_AXIS.IP_X IP_AXIS.IP_Y << 2 IP_AXIS.IP_Z << 4; // Axis for interpolation MC8000P.Nmc_WriteReg5(gBoardNo, int IcNo, IpAxis); // Axis assignment for interpolation. MC8000P.Nmc_StartSpd(gBoardNo, int IcNo, AXIS.ALL, 8000); // Set initial speed MC8000P.Nmc_Speed(gBoardNo, int IcNo, AXIS.ALL, 100); // Set drive speed // Execute 3-axis continuous interpolation. // Execute in the background. Ret = MC8000P.Nmc_3CIPExec_BG((System.IntPtr)parent.Handle, gBoardNo, int IcNo, Data3Cip, DataCnt, IpAxis, SpdChgFlg, ContinueFlg); if(Ret == Nmc_Status.CIP_START) // Continuous interpolation has been successfully started. // WM_BP_END message received function protected override void WndProc(ref Message m) { // Call original WndProc (call a constructor explicitly) base.WndProc (ref m); if (m.Msg == (int)MSG_ID.WM_CIP_END) { if((uint)m.LParam == Nmc_Status.CIP_END) // Continuous interpolation has been successfully completed. } } </pre>
--	--

Function Name	Function and Content
Nmc_IPStop	<p>Stop the interpolation process during driving. *MCX314As only</p> <p>The interpolation driving stops immediately and terminates the executed interpolation process in Nmc_xxx interpolation function.</p> <p>When stopping the interpolation process using Nmc_IPStop, the return value of each interpolation function is the following error code.</p> <ul style="list-style-type: none"> ◆ BP interpolation: BP_USER_STOP ◆ Continuous interpolation: CIP_USER_STOP <p>VC BOOL Nmc_IPStop(int No int IcNo,);</p> <p>VB.NET Function Nmc_IPStop(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# bool MC8000P.Nmc_IPStop(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 4.1.3 (7) for more details.</p> <p>Return Value</p> <p>[VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>[VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0.</p> <p>[C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example</p> <p>[VC] Nmc_IPStop(No, IcNo); // Stop the interpolation process during driving.</p> <p>[VB.NET] Call Nmc_IPStop(No, IcNo)</p> <p>[C#] MC8000P.Nmc_IPStop(No, IcNo);</p>

Function Name	Function and Content
Nmc_IPGetMsgNo	<p>Read the board and IC number from the parameter wParam of the following received message at the end of the Interpolation. *MCX314As only</p> <ul style="list-style-type: none"> ◆ BP interpolation: WM_BP_END ◆ Continuous interpolation: WM_CIP_END <p>VC void Nmc_IPGetMsgNo(int wParam, int* No, int* IcNo);</p> <p>VB.NET Sub Nmc_IPGetMsgNo(ByVal wParam As Integer, ByRef No As Integer, ByRef IcNo As Integer)</p> <p>C# bool MC8000P.Nmc_IPGetMsgNo(int wParam, out int No, out int IcNo)</p> <p>Input Parameter</p> <p>wParam The parameter wParam of received message at the end of the Interpolation.</p> <p>No [VC] Address of a variable to store the board number. [VB.NET] [C#] Variable to store the board number.</p> <p>IcNo [VC] Address of a variable to store the IC number. [VB.NET] [C#] Variable to store the IC number.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] int BdNo; // Board number int IcNo; // IC number Nmc_IPGetMsgNo(wParam, &BdNo, &IcNo);</pre> <pre>[VB.NET] Dim BdNo As Integer ' Board number Dim IcNo As Integer ' IC number Call Nmc_IPGetMsgNo(m.WParam.ToInt32(), BdNo, IcNo)</pre> <pre>[C#] int BdNo; // Board number int IcNo; // IC number (0~1) MC8000P.Nmc_IPGetMsgNo(WParam, out BdNo, out IcNo)</pre>

4.1.3. Footnote

(1) Each definition is defined in the following files.

VC	MC8000P_DLL.H
VB.NET	MC8000P_DLL.vb
C#	Users can refer to or input each definition through the IntelliSense.

VC++, VB.NET and C# definitions are as follows:

① Register number

[VC]

```
#define MCX_WR0      0x0000 // WR0
#define MCX_WR1      0x0001 // WR1
#define MCX_WR2      0x0002 // WR2
#define MCX_WR3      0x0003 // WR3
#define MCX_WR4      0x0004 // WR4
#define MCX_WR5      0x0005 // WR5
#define MCX_WR6      0x0006 // WR6
#define MCX_WR7      0x0007 // WR7

#define MCX_RR0      0x0000 // RR0
#define MCX_RR1      0x0001 // RR1
#define MCX_RR2      0x0002 // RR2
#define MCX_RR3      0x0003 // RR3
#define MCX_RR4      0x0004 // RR4
#define MCX_RR5      0x0005 // RR5
#define MCX_RR6      0x0006 // RR6
#define MCX_RR7      0x0007 // RR7
```

[C#]

```
// ■Nmc_OutPort / Nmc_InPort
// When the board has one IC, use WR0_A ~ WR7_A / RR0_A ~ RR7_A
// When the board has 2 ICs, use WR0_A~WR7_A/RR0_A~RR7_A for IC_A, and
// WR0_B~WR7_B/RR0_B~RR7_B for IC_B.
// ■Nmc_WriteReg / Nmc_ReadReg
// Use WR0~WR7/RR0~RR7.
```

```
public enum REG_MCX : int
{
    // ■Nmc_OutPort
    // Write register address
    // WR0~WR7 for IC-A
    WR0_A = 0x0000,
    WR1_A = 0x0001,
    WR2_A = 0x0002,
    WR3_A = 0x0003,
    WR4_A = 0x0004,
    WR5_A = 0x0005,
    WR6_A = 0x0006,
    WR7_A = 0x0007,

    // WR0~WR7 for IC-B
    WR0_B = 0x0008,
    WR1_B = 0x0009,
    WR2_B = 0x000A,
    WR3_B = 0x000B,
    WR4_B = 0x000C,
    WR5_B = 0x000D,
    WR6_B = 0x000E,
    WR7_B = 0x000F,
```

```

// PIX132 address
WR14   =0x0014,
WR15   =0x0015,
WR16   =0x0016,

//■Nmc_InPort
// Read register address
// RR0~RR7 for IC-A
RR0_A  =0x0000,
RR1_A  =0x0001,
RR2_A  =0x0002,
RR3_A  =0x0003,
RR4_A  =0x0004,
RR5_A  =0x0005,
RR6_A  =0x0006,
RR7_A  =0x0007,

// RR0~RR7 for IC-B
RR0_B  =0x0008,
RR1_B  =0x0009,
RR2_B  =0x000A,
RR3_B  =0x000B,
RR4_B  =0x000C,
RR5_B  =0x000D,
RR6_B  =0x000E,
RR7_B  =0x000F,

// PIX132 address
RR14   =0x0014,
RR15   =0x0015,
RR16   =0x0016,

//■Nmc_WriteReg
// Write register address
WR0    =0x0000,
WR1    =0x0001,
WR2    =0x0002,
WR3    =0x0003,
WR4    =0x0004,
WR5    =0x0005,
WR6    =0x0006,
WR7    =0x0007,

//■Nmc_ReadReg
// Read register address
RR0    =0x0000,
RR1    =0x0001,
RR2    =0x0002,
RR3    =0x0003,
RR4    =0x0004,
RR5    =0x0005,
RR6    =0x0006,
RR7    =0x0007
}
Example) REG_MCX of WR0      REG_MCX.WR0

```

② Axis assignment

```
[VC]
#define AXIS_ALL      0xF      // All axes
#define AXIS_X       0x1      // X axis
#define AXIS_Y       0x2      // Y axis
#define AXIS_Z       0x4      // Z axis
#define AXIS_U       0x8      // U axis
#define AXIS_NONE    0        // No axis assignment
```

[C#]

```
public enum AXIS : int
{
    // Axis assignment
    ALL      =0xF,    // All axes
    X        =0x1,    // X axis
    Y        =0x2,    // Y axis
    Z        =0x4,    // Z axis
    U        =0x8,    // U axis
    NONE     =0       // No axis assignment
}
```

Example) To assign all axes, AXIS.ALL

③ Device ID

Device Id is the fixed number assigned to a board.

Number of each board is as below.

Board	Device ID
MC8043P / MC8043Pe	0xA0A2
MC8082P / MC8082Pe	0xA0D0

[Note] Device ID of MC8022P and MC8042P are the same with that of MC8082P.

[VC]

```
#define ID_MC8043P    0xA0A2    // MC8043P and MC8043Pe
#define ID_MC8082P    0xA0D0    // MC8082P, 42P, 22P and MC8082Pe
```

Example) MC8082P, 42P, 22P and MC8082Pe are ID_MC8082P, MC8043P and MC8082Pe are ID_MC8043P.

[C#]

```
public enum Dev_ID : ushort
{
    MC8043P =0xA0A2, // MC8043P and MC8043Pe
    MC8082P =0xA0D0 // MC8082P, 42P, 22P and MC8082Pe
}
```

Example) MC8082P, 42P, 22P and MC8082Pe are Dev_ID.MC8082P, MC8043P and MC8043Pe are Dev_ID.MC8043P.

④ Command definition

*Refer to the User's Manual of each IC for available commands.

Commands of both (I) and (II) are available.

[VC]

```
// Driving commands
```

```
//( I )
```

```
#define CMD_F_DRV_P    0x20    // + direction fixed pulse driving
#define CMD_F_DRV_M    0x21    // - direction fixed pulse driving
#define CMD_C_DRV_P    0x22    // + direction continuous pulse driving
#define CMD_C_DRV_M    0x23    // - direction continuous pulse driving
#define CMD_START_HOLD 0x24    // Drive start holding
#define CMD_START_FREE 0x25    // Drive start holding release/ Drive finish status clear
#define CMD_STP_STS_CLR 0x25    // Drive start holding release/ Drive finish status clear
#define CMD_STOP_DEC   0x26    // Decelerating stop
```

```

#define CMD_STOP_SUDDEN 0x27 // Sudden stop
//( I )
#define MC8000P_CMD_DRVFP CMD_F_DRV_P // + direction fixed pulse driving
#define MC8000P_CMD_DRVFM CMD_F_DRV_M // - direction fixed pulse driving
#define MC8000P_CMD_DRVVP CMD_C_DRV_P // + direction continuous pulse driving
#define MC8000P_CMD_DRVVM CMD_C_DRV_M // - direction continuous pulse driving
#define MC8000P_CMD_DHOLD CMD_START_HOLD // Drive start holding
#define MC8000P_CMD_DFREE CMD_START_FREE // Drive start holding release
#define MC8000P_CMD_STSCLR CMD_STP_STS_CLR // Drive finish status clear
#define MC8000P_CMD_DRVSBRK CMD_STOP_DEC // Decelerating stop
#define MC8000P_CMD_DRVFBRK CMD_STOP_SUDDEN // Sudden stop

// Interpolation commands *MCX314As only
//( I )
#define CMD_IP_2ST 0x30 // 2-axis linear interpolation
#define CMD_IP_3ST 0x31 // 3-axis linear interpolation
#define CMD_IP_CW 0x32 // CW circular interpolation
#define CMD_IP_CCW 0x33 // CCW circular interpolation
#define CMD_IP_2BP 0x34 // 2-axis bit pattern interpolation
#define CMD_IP_3BP 0x35 // 3-axis bit pattern interpolation
#define CMD_BP_ENABLED 0x36 // BP register data writing enabling
#define CMD_BP_DISABLED 0x37 // BP register data writing disabling
#define CMD_BP_STACK 0x38 // BP data stack
#define CMD_BP_CLR 0x39 // BP data clear
#define CMD_IP_1STEP 0x3A // Single step interpolation
#define CMD_IP_DEC_VALID 0x3B // Decelerating enabling
#define CMD_IP_DEC_INVALID 0x3C // Decelerating disabling
#define CMD_IP_INTRPT_CLR 0x3D // Interpolation interrupt clear
( II )
#define MC8000P_CMD_2CIP CMD_IP_2ST // 2-axis linear interpolation
#define MC8000P_CMD_3CIP CMD_IP_3ST // 3-axis linear interpolation
#define MC8000P_CMD_CIPCW CMD_IP_CW // CW circular interpolation
#define MC8000P_CMD_CIPCCW CMD_IP_CCW // CCW circular interpolation
#define MC8000P_CMD_BPIP2 CMD_IP_2BP // 2-axis bit pattern interpolation
#define MC8000P_CMD_BPIP3 CMD_IP_3BP // 3-axis bit pattern interpolation
#define MC8000P_CMD_BPENABLED CMD_BP_ENABLED // BP register data writing enabling
#define MC8000P_CMD_BPDISABLED CMD_BP_DISABLED // BP register data writing disabling
#define MC8000P_CMD_BPSTACK CMD_BP_STACK // BP data stack
#define MC8000P_CMD_BPCLR CMD_BP_CLR // BP data clear
#define MC8000P_CMD_IP1STEP CMD_IP_1STEP // Single step interpolation
#define MC8000P_CMD_DECEN CMD_IP_DEC_VALID // Decelerating enabling
#define MC8000P_CMD_DECDIS CMD_IP_DEC_INVALID // Decelerating disabling
#define MC8000P_CMD_CLRINTRPT CMD_IP_INTRPT_CLR // Interpolation interrupt clear

// Other commands
//( I )
#define CMD_HOME_EXEC 0x62 // Automatic home search execution
#define CMD_DEVCTR_CLR 0x63 // Stack counter clear output
#define CMD_SYNC_ACTIVE 0x65 // Synchronous action activation *MCX314As only
#define CMD_NOP 0x0F // NOP (for axis switching)
//( II )
#define MC8000P_CMD_HMSRC CMD_HOME_EXEC // Automatic home search execution
#define MC8000P_CMD_DCC CMD_DEVCTR_CLR // Stack counter clear output
#define MC8000P_CMD_SYNCACT CMD_SYNC_ACTIVE // Synchronous action activation *MCX314As only
#define MC8000P_CMD_NOP CMD_NOP // NOP (for axis switching)
[C#]
public enum CMD : int
{
// Driving commands

```

```

//( I )
CMD_F_DRV_P      = 0x20,    // + direction fixed pulse driving
CMD_F_DRV_M      = 0x21,    // - direction fixed pulse driving
CMD_C_DRV_P      = 0x22,    // + direction continuous pulse driving
CMD_C_DRV_M      = 0x23,    // - direction continuous pulse driving
CMD_START_HOLD   = 0x24,    // Drive start holding
CMD_START_FREE   = 0x25,    // Drive start holding release/ Drive finish status clear
CMD_STP_STS_CLR  = 0x25,    // Drive start holding release/ Drive finish status clear
CMD_STOP_DEC     = 0x26,    // Decelerating stop
CMD_STOP_SUDDEN = 0x27,    // Sudden stop
//(II)
MC8000P_CMD_DRVFP      = CMD_F_DRV_P,      // + direction fixed pulse driving
MC8000P_CMD_DRVFM      = CMD_F_DRV_M,      // - direction fixed pulse driving
MC8000P_CMD_DRVVP      = CMD_C_DRV_P,      // + direction continuous pulse driving
MC8000P_CMD_DRVVM      = CMD_C_DRV_M,      // - direction continuous pulse driving
MC8000P_CMD_DHOLD      = CMD_START_HOLD,    // Drive start holding
MC8000P_CMD_DFEE       = CMD_START_FREE,    // Drive start holding release
MC8000P_CMD_STSCLR     = CMD_STP_STS_CLR,    // Drive finish status clear
MC8000P_CMD_DRVSBRK    = CMD_STOP_DEC,      // Decelerating stop
MC8000P_CMD_DRVFBRK    = CMD_STOP_SUDDEN,   // Sudden stop

// Interpolation commands *MCX314As only.
//( I )
CMD_IP_2ST        = 0x30,    // 2-axis linear interpolation
CMD_IP_3ST        = 0x31,    // 3-axis linear interpolation
CMD_IP_CW         = 0x32,    // CW circular interpolation
CMD_IP_CCW        = 0x33,    // CCW circular interpolation
CMD_IP_2BP        = 0x34,    // 2-axis bit pattern interpolation
CMD_IP_3BP        = 0x35,    // 3-axis bit pattern interpolation
CMD_BP_ENABLED    = 0x36,    // BP register data writing enabling
CMD_BP_DISABLED   = 0x37,    // BP register data writing disabling
CMD_BP_STACK      = 0x38,    // BP data stack
CMD_BP_CLR        = 0x39,    // BP data clear
CMD_IP_1STEP      = 0x3A,    // Single step interpolation
CMD_IP_DEC_VALID  = 0x3B,    // Decelerating enabling
CMD_IP_DEC_INVALID = 0x3C,    // Decelerating disabling
CMD_IP_INTRPT_CLR = 0x3D,    // Interpolation interrupt clear
//( II )
MC8000P_CMD_2CIP    = CMD_IP_2ST,          // 2-axis linear interpolation
MC8000P_CMD_3CIP    = CMD_IP_3ST,          // 3-axis linear interpolation
MC8000P_CMD_CIPCW   = CMD_IP_CW,          // CW circular interpolation
MC8000P_CMD_CIPCCW  = CMD_IP_CCW,         // CCW circular interpolation
MC8000P_CMD_BPIP2   = CMD_IP_2BP,         // 2-axis bit pattern interpolation
MC8000P_CMD_BPIP3   = CMD_IP_3BP,         // 3-axis bit pattern interpolation
MC8000P_CMD_BPENABLED = CMD_BP_ENABLED,    // BP register data writing enabling
MC8000P_CMD_BPDISABLED = CMD_BP_DISABLED,  // BP register data writing disabling
MC8000P_CMD_BPSTACK = CMD_BP_STACK,        // BP data stack
MC8000P_CMD_BPCLR   = CMD_BP_CLR,          // BP data clear
MC8000P_CMD_IP1STEP = CMD_IP_1STEP,        // Single step interpolation
MC8000P_CMD_DECEN   = CMD_IP_DEC_VALID,    // Decelerating enabling
MC8000P_CMD_DECDIS  = CMD_IP_DEC_INVALID,  // Decelerating disabling
MC8000P_CMD_CLRINTRPT = CMD_IP_INTRPT_CLR, // Interpolation interrupt clear

// Other commands
//( I )
CMD_HOME_EXEC      = 0x62,    // Automatic home search execution
CMD_DEVCTR_CLR     = 0x63,    // Stack counter clear output
CMD_SYNC_ACTIVE    = 0x65,    // Synchronous action activation
}

```

```

//(II)
MC8000P_CMD_HMSRC      = CMD_HOME_EXEC,           // Automatic home search execution
MC8000P_CMD_DCC        = CMD_DEVCTR_CLR,         // Deviation counter clear pulse output
MC8000P_CMD_SYNCACT    = CMD_SYNC_ACTIVE,        // Synchronous action activation ※MCX314As only
MC8000P_CMD_NOP        = CMD_NOP,               // NOP (For axis switching)
}

```

Example) To specify 2-axis liner interpolation drive, CMD.CMD_IP_2ST

```

⑤Interpolation finishing message, finishing status    *The board with MCX314As only
[VC]
// Interpolation finishing message
#define WM_BP_END      (WM_USER + 1)    // BP interpolation finishing message
#define WM_CIP_END     (WM_USER + 2)    // Continuous interpolation finishing message

//***** BP Interpolation    Finishing Status *****
// ■ Normal
#define BP_START    0x101    // BP interpolation has started in the background.
#define BP_END      0x102    // BP interpolation has been successfully completed.

// ■ Errors before starting the interpolation
#define BP_CNT_ERR    0x111    // The number of the specified data is out of range.
#define BP_ALREADY_EXEC 0x112    // BP interpolation or continuous interpolation is already running.
#define BP_THREAD_ERR 0x113    // Thread cannot be started.
#define BP_MALLOC_ERR 0x114    // Memory cannot be allocated.
#define BP_PARAM_ERR  0x116    // The parameter is incorrect.
#define BP_NOT_OPEN_ERR 0x117    // The specified board is not opened.
#define BP_OTHER_ERR  0x118    // Other errors.

// ■ Errors during the interpolation driving
#define BP_STOP      0x121    // BP interpolation stopped during driving. (too fast to stack next data)
#define BP_USER_STOP 0x122    // The user aborted BP interpolation.
#define BP_DRIVE_ERR 0x123    // Error occurred in the board during BP interpolation.
                          (When the error status was set to RR0.)

//***** Continuous Interpolation    Finishing Status *****
// ■ Normal
#define CIP_START    0x201    // Continuous interpolation has started in the background.
#define CIP_END      0x202    // Continuous interpolation has been successfully completed.

// ■ Errors before starting the interpolation
#define CIP_CNT_ERR    0x211    // The number of the specified data is out of range.
#define CIP_ALREADY_EXEC 0x212    // BP interpolation or continuous interpolation is already running.
#define CIP_THREAD_ERR 0x213    // Thread cannot be started.
#define CIP_MALLOC_ERR 0x214    // Memory cannot be allocated.
#define CIP_CMD_ERR    0x215    // Command error (The wrong command was specified by the user.)
#define CIP_PARAM_ERR  0x216    // The parameter is incorrect.
#define CIP_NOT_OPEN_ERR 0x217    // The specified board is not opened.
#define CIP_OTHER_ERR  0x218    // Other errors.

// ■ Errors during the interpolation driving
#define CIP_STOP      0x221    // Continuous interpolation stopped during driving. (too fast to set next data)
#define CIP_USER_STOP 0x222    // The user aborted Continuous interpolation.
#define CIP_DRIVE_ERR 0x223    // Error occurred in the board during Continuous interpolation.
                          (When the error status was set to RR0.)

[C#]
public enum MSG_ID : int
{
    // Interpolation finishing message

```



```

        WM_USER           =0x0400,
        WM_BP_END         =WM_USER+1,    // (WM_USER + 1) BP interpolation finishing message
        WM_CIP_END        =WM_USER+2     // (WM_USER + 2) Continuous interpolation finishing message
    }

```

Example) MSG_ID and WM_BP_END MSG_ID.WM_BP_END

```

public enum Nmc_Status : uint
{
    /****** BP Interpolation   Finishing Status *****/
    // ■ Normal
    BP_START           = 0x101 ,          // BP interpolation has started in the background.
    BP_END             = 0x102 ,          // BP interpolation has been successfully completed.

    // ■ Errors before starting the interpolation
    BP_CNT_ERR         = 0x111 ,          // The number of the specified data is out of range.
    BP_ALREADY_EXEC    = 0x112 ,          // BP interpolation or continuous interpolation is already running.
    BP_THREAD_ERR      = 0x113 ,          // Thread cannot be started.
    BP_MALLOC_ERR      = 0x114 ,          // Memory cannot be allocated.

    // ■ Errors during the interpolation driving
    BP_STOP            = 0x121 ,          // BP interpolation stopped during driving. (too fast to stack next data)
    BP_USER_STOP       = 0x122 ,          // The user aborted BP interpolation.
    BP_DRIVE_ERR       = 0x123 ,          // Error occurred in the board during BP interpolation.
                                        (When the error status was set to RR0.)

    /****** Continuous Interpolation   Finishing Status *****/
    // ■ Normal
    CIP_START          = 0x201 ,          // Continuous interpolation has started in the background.
    CIP_END            = 0x202 ,          // Continuous interpolation has been successfully completed.

    // ■ Errors before starting the interpolation
    CIP_CNT_ERR        = 0x211 ,          // The number of the specified data is out of range.
    CIP_ALREADY_EXEC   = 0x212 ,          // BP interpolation or continuous interpolation is already running.
    CIP_THREAD_ERR     = 0x213 ,          // Thread cannot be started.
    CIP_MALLOC_ERR     = 0x214 ,          // Memory cannot be allocated.
    CIP_CMD_ERR        = 0x215 ,          // Command error (The wrong command was specified by the user.)

    // ■ Errors during the interpolation driving
    CIP_STOP           = 0x221 ,          // Continuous interpolation stopped during driving. (too fast to set next data)
    CIP_USER_STOP      = 0x222 ,          // The user aborted Continuous interpolation.
    CIP_DRIVE_ERR      = 0x223 ,          // Error occurred in the board during Continuous interpolation.
                                        (When the error status was set to RR0.)
}

```

Example) When BP interpolation has started in the background, Nmc_Status.BP_START

```

public enum IP_AXIS : int
{
    // Axis for interpolation
    IP_X   =0,    // Assign X axis for interpolation.
    IP_Y   =1,    // Assign Y axis for interpolation.
    IP_Z   =2,    // Assign Z axis for interpolation.
    IP_U   =3     // Assign U axis for interpolation.
}

```

Example) To assign X axis for interpolation, IP_AXIS.IP_X

⑥ Constant definition

[C#]

```

public enum CONST : int
{
    MAX_BOARD_MC8000P   =16    // The maximum number of boards MC8000P device driver can recognize
}

```

simultaneously.

```
}
Example) To specify the maximum number of MC8000P boards,          CONST.MAX_BOARD_MC8000P
```

```
public enum MaxValue : uint
{
    MCX304 =268435455,          // The maximum value of MCX304 output pulse
    MCX314As =4294967295      // The maximum value of MCX314As output pulse
}
```

Example) To specify the maximum value of MCX304 output pulse, MaxValue.MCX304

⑦IC

[C#]

```
public enum IC : int
{
    A      =0,      // The first IC
    B      =1,      // The second IC
    MCX304 =0,      // MCX304
    MCX314AS =1     // MCX314AS
}
```

Example) To specify IC A, IC.A

(2) The method of axis assignment is as follows:

Axis	VC	C#
X	AXIS_X	AXIS.X
Y	AXIS_Y	AXIS.Y
Z	AXIS_Z	AXIS.Z
U	AXIS_U	AXIS.U
All	AXIS_ALL	AXIS.ALL

①To assign 1 axis

Specify one of the following axes: AXIS_X, AXIS_Y, AXIS_Z, AXIS_U.

Example) Set 1000 as the drive speed of X axis.

```
[VC]    Nmc_Speed(No, IcNo, AXIS_X, 1000);
[VB]    Call Nmc_Speed(No, IcNo, AXIS_X, 1000)
[C#]    MC8000P.Nmc_Speed(No, IcNo, AXIS.X, 1000);
```

②To assign 2 axes

Use Bit OR operator.

For instance, if the user tries to assign X and Y axes simultaneously,

```
[VC] . . . Specify AXIS_X | AXIS_Y.
[VB] . . . Specify AXIS_X Or AXIS_Y.
[C#] . . . Specify AXIS.X | AXIS.Y.
```

Example) Set 1000 as the drive speed of X and Y axes.

```
[VC]    Nmc_Speed(No, IcNo, AXIS_X | AXIS_Y, 1000);
[VB]    Call Nmc_Speed(No, IcNo, AXIS_X Or AXIS_Y, 1000)
[C#]    MC8000P.Nmc_Speed(No, IcNo, AXIS.X | AXIS.Y, 1000);
```

③To assign 3 axes

Use Bit OR operator.

For instance, if the user tries to assign X, Y and Z axes simultaneously,

```
[VC] . . . Specify AXIS_X | AXIS_Y | AXIS_Z.
[VB] . . . Specify AXIS_X Or AXIS_Y Or AXIS_Z.
[C#] . . . Specify AXIS.X | AXIS.Y | AXIS.Z.
```

Example) Set 1000 as the drive speed of X, Y and Z axes.

```
[VC] Nmc_Speed(No, IcNo, AXIS_X | AXIS_Y | AXIS_Z, 1000);
[VB] Call Nmc_Speed(No, IcNo, AXIS_X Or AXIS_Y Or AXIS_Z, 1000)
[C#] MC8000P.Nmc_Speed(No, IcNo, AXIS.X | AXIS.Y | AXIS.Z, 1000);
```

④ To assign all axes
Specify AXIS_ALL.

Example) Set 1000 as the drive speed of all axes.

```
[VC] Nmc_Speed(No, IcNo, AXIS_ALL, 1000);
[VB] Call Nmc_Speed(No, IcNo, AXIS_ALL, 1000)
[C#] MC8000P.Nmc_Speed(No, IcNo, AXIS.ALL, 1000);
```

(3) The structure (user-defined type in VB.NET) used in the interpolation function is defined as follows:

*The board with MCX314As only

① VC

// 2-axis BP interpolation

```
typedef struct _DATA_2BP
```

```
{
    USHORT Bp1p;           // BP1P data
    USHORT Bp1m;           // BP1M data
    USHORT Bp2p;           // BP2P data
    USHORT Bp2m;           // BP2M data
} DATA_2BP;
```

// 3-axis BP interpolation

```
typedef struct _DATA_3BP
```

```
{
    USHORT Bp1p;           // BP1P data
    USHORT Bp1m;           // BP1M data
    USHORT Bp2p;           // BP2P data
    USHORT Bp2m;           // BP2M data
    USHORT Bp3p;           // BP3P data
    USHORT Bp3m;           // BP3M data
} DATA_3BP;
```

// 2-axis continuous interpolation

```
typedef struct _DATA_2CIP
```

```
{
    USHORT Command; // Command number (Set one of CMD_IP_2ST, CMD_IP_CW, CMD_IP_CCW.)
    USHORT Speed;   // Speed (When changing the speed, set 1~8000. When not changing, set 0.)
    long EndP1;     // Finishing point (The first axis)
    long EndP2;     // Finishing point (The second axis)
    long Center1;   // Circular center point (The first axis)
    long Center2;   // Circular center point (The second axis)
} DATA_2CIP; // Note: The first or second axis must be specified by WR5.
```

// 3-axis continuous interpolation

```
typedef struct _DATA_3CIP
```

```
{
    long EndP1; // Finishing point (The first axis)
    long EndP2; // Finishing point (The second axis)
    long EndP3; // Finishing point (The third axis)
    USHORT Speed; // Speed (When changing the speed, set 1~8000. When not changing, set 0.)
} DATA_3CIP; // Note: The first or second axis must be specified by WR5.
```

② VB.NET

' 2-axis BP interpolation

Structure DATA_2BP

```

    Dim Bp1p As Short ' BP1P data
    Dim Bp1m As Short ' BP1M data
    Dim Bp2p As Short ' BP2P data
    Dim Bp2m As Short ' BP2M data

```

```
End Structure
```

```
' 3-axis BP interpolation
```

```
Structure DATA_3BP
```

```

    Dim Bp1p As Short ' BP1P data
    Dim Bp1m As Short ' BP1M data
    Dim Bp2p As Short ' BP2P data
    Dim Bp2m As Short ' BP2M data
    Dim Bp3p As Short ' BP3P data
    Dim Bp3m As Short ' BP3M data

```

```
End Structure
```

```
' 2-axis continuous interpolation
```

```
Structure DATA_2CIP
```

```

    Dim Cmd As Short          ' Command number (Set one of CMD_IP_2ST, CMD_IP_CW, CMD_IP_CCW.)
    Dim Speed As Short        ' Speed (When changing the speed, set 1~8000. When not changing, set 0.)
    Dim EndP1 As Integer      ' Finishing point (The first axis)
    Dim EndP2 As Integer      ' Finishing point (The second axis)
    Dim Center1 As Integer    ' Circular center point (The first axis)
    Dim Center2 As Integer    ' Circular center point (The second axis)

```

```
End Structure          ' Note: The first or second axis must be specified by WR5.
```

```
' 3-axis continuous interpolation
```

```
Structure DATA_3CIP
```

```

    Dim EndP1 As Integer      ' Finishing point (The first axis)
    Dim EndP2 As Integer      ' Finishing point (The second axis)
    Dim EndP3 As Integer      ' Finishing point (The third axis)
    Dim Speed As Short        ' Speed (When changing the speed, set 1~8000. When not changing, set 0.)

```

```
End Structure          ' Note: The first, second or third axis must be specified by WR5.
```

③C#

```
// 2-axis BP interpolation
```

```
[StructLayout(LayoutKind.Sequential)]
```

```
public struct DATA_2BP
```

```

{
    public    DATA_2BP(ushort bp1p,ushort bp1m,ushort bp2p,ushort bp2m)
    {
        this.Bp1p = bp1p;
        this.Bp1m = bp1m;
        this.Bp2p = bp2p;
        this.Bp2m = bp2m;
    }
    public    ushort    Bp1p;        // BP1P data
    public    ushort    Bp1m;        // BP1M data
    public    ushort    Bp2p;        // BP2P data
    public    ushort    Bp2m;        // BP2M data
}

```

```
// 3-axis BP interpolation
```

```
[StructLayout(LayoutKind.Sequential)]
```

```
public struct DATA_3BP
```

```

{
    public    DATA_3BP(ushort bp1p,ushort bp1m,ushort bp2p,ushort bp2m,ushort bp3p,ushort bp3m)
    {
        this.Bp1p = bp1p;

```

```

        this.Bp1m = bp1m;
        this.Bp2p = bp2p;
        this.Bp2m = bp2m;
        this.Bp3p = bp3p;
        this.Bp3m = bp3m;
    }
    public  ushort  Bp1p;      // BP1P data
    public  ushort  Bp1m;      // BP1M data
    public  ushort  Bp2p;      // BP2P data
    public  ushort  Bp2m;      // BP2M data
    public  ushort  Bp3p;      // BP3P data
    public  ushort  Bp3m;      // BP3M data
}

// 2-axis continuous interpolation
[StructLayout(LayoutKind.Sequential)]
public struct DATA_2CIP
{
    public  DATA_2CIP(ushort command,ushort speed,int endp1,int endp2,int center1,int center2)
    {
        this.Command      = command;
        this.Speed = speed;
        this.EndP1 = endp1;
        this.EndP2 = endp2;
        this.Center1      = center1;
        this.Center2      = center2;
    }
    public  ushort  Command; // Command number (Set one of CMD_IP_2ST, CMD_IP_CW, CMD_IP_CCW.)
    public  ushort  Speed;   // Speed (When specifying the speed, specify 1~8000. When not specifying, set 0.)
    public  int     EndP1;   // Finishing point (The first axis)
    public  int     EndP2;   // Finishing point (The second axis)
    public  int     Center1; // Circular center point (The first axis)
    public  int     Center2; // Circular center point (The second axis)
}
// Note: The first or second axis must be specified by WR5.

// 3-axis continuous interpolation
[StructLayout(LayoutKind.Sequential)]
public struct DATA_3CIP
{
    public  DATA_3CIP(int endp1,int endp2,int endp3,ushort speed)
    {
        this.EndP1 = endp1;
        this.EndP2 = endp2;
        this.EndP3 = endp3;
        this.Speed = speed;
    }
    public  int     EndP1;   // Finishing point (The first axis)
    public  int     EndP2;   // Finishing point (The second axis)
    public  int     EndP3;   // Finishing point (The third axis)
    public  ushort  Speed;   // Speed (When specifying the speed, specify 1~8000. When not specifying, set 0.)
}
// Note: The first, second or third axis must be specified by WR5.

```

Examples of structure are as follows:

Example 1) Not define and initialize at the same time

```
DATA_2BP [] Data2Bp = new DATA_2BP[4]; // 2-axis BP interpolation
```

```
// Interpolation data setting
```

```
Data2Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 + direction 10 pulse
Data2Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 - direction 0 pulse
Data2Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 + direction 0 pulse
Data2Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2 - direction 10 pulse

Data2Bp[1].Bp1p = 0xAC35; // 1010 1100 0011 0101 BP1 + direction 8 pulse
Data2Bp[1].Bp1m = 0; // 0000 0000 0000 0000 BP1 - direction 0 pulse
Data2Bp[1].Bp2p = 0xC000; // 1100 0000 0000 0000 BP2 + direction 2 pulse
Data2Bp[1].Bp2m = 0x36E7; // 0011 0110 1110 0111 BP2 - direction 10 pulse


Data2Bp[2].Bp1p = 0x3F3F; // 0011 1111 0011 1111 BP1 + direction 12 pulse
Data2Bp[2].Bp1m = 0xC000; // 1100 0000 0000 0000 BP1 - direction 2 pulse
Data2Bp[2].Bp2p = 0xFBDA; // 1111 1011 1101 1010 BP2 + direction 12 pulse
Data2Bp[2].Bp2m = 0; // 0000 0000 0000 0000 BP2 - direction 0 pulse

Data2Bp[3].Bp1p = 0; // 0000 0000 0000 0000 BP1 + direction 0 pulse
Data2Bp[3].Bp1m = 0x1CF2; // 0001 1100 1111 0010 BP1 - direction 8 pulse
Data2Bp[3].Bp2p = 0xFFFF; // 1111 1111 1111 1111 BP2 + direction 16 pulse
Data2Bp[3].Bp2m = 0; // 0000 0000 0000 0000 BP2 - direction 0 pulse
```

Example 2) Define and initialize at the same time

```
// 2-axis BP interpolation data BP1P, BP1M, BP2P, BP2M (Data for Fig.2.32 in MCX314As Manual)
DATA_2BP[] Data2Bp = new DATA_2BP[]
{
    new DATA_2BP(0x0000, 0x2BFF, 0xFFD4, 0x0000),
    new DATA_2BP(0xF6FE, 0x0000, 0x000F, 0x3FC0),
    new DATA_2BP(0x1FDB, 0x0000, 0x00FF, 0xFC00),
    new DATA_2BP(0x4000, 0x7FF5, 0x0000, 0x0AFF),
};
```

(4) The interpolation axis (IpAxis) specified by the interpolation function is as follows: *The board with MCX314As only
Set the interpolation axis data from X, Y, Z and U axis to the lower 6-bit of 16-bit data. For 2-axis interpolation, set to the first and second axis, for 3-axis interpolation, set to the first, second and third axis.



◆ Description of each bit

D1, 0 AX11, 10 Specify the first axis (main axis) for interpolation driving. Axis codes are as follows:

Axis	Code (Binary)
X	00
Y	01
Z	10
U	11

Example of the first axis: X, Second axis: Y, Third axis: Z

```
D5 D4 D3 D2 D1 D0
1 0 0 1 0 0
```

D3, 2 AX21, 20 Specify the second axis using the code in the table above for interpolation driving.

D5, 4 AX31, 30 Specify the third axis using the code in the table above for 3-axis interpolation driving.
This is not used in 2-axis interpolation driving, so it doesn't matter to set any code.

- ◆ For C#, specify the axis for interpolation by using the following default value.

```
public enum IP_AXIS : int
{
    IP_X    =0,    // Assign X axis for interpolation.
    IP_Y    =1,    // Assign Y axis for interpolation.
    IP_Z    =2,    // Assign Z axis for interpolation.
    IP_U    =3,    // Assign U axis for interpolation.
}
```

Axis	Example
X	IP_AXIS.IP_X
Y	IP_AXIS.IP_Y
Z	IP_AXIS.IP_Z
U	IP_AXIS.IP_U

To specify the axis for interpolation, set it by using bit operations as follows.

Example) For 3-axis interpolation of the first axis: X, the second axis: Y and the third axis: Z, set them by using bit operations as follows.

```
IpAxis = IP_AXIS.IP_X | IP_AXIS.IP_Y<<2 | IP_AXIS.IP_Z<<4 ;
```

(5) About the speed change when continuous interpolation function is executed. *The board with MCX314As only
 Continuous interpolation function can change the speed during interpolation driving. The user can set the speed to each segment. To change the speed during interpolation driving, set TRUE(True) to the function parameter SpdChgFlg.

- ◆ How to change the speed for each segment

Set the speed of each segment to the Speed of DATA_2CIP or the Speed of DATA_3CIP.

- When set the different speed from the previous segment, set 1~8000.
- When set the same speed as the previous segment, set 0.

- ◆ About the timing of changing the speed

When the Speed of DATA_2CIP or the Speed of DATA_3CIP is set to 1~8000, the process of interpolation function is described as follows:

For the first segment, set the speed before executing the segment.

For the second or later segment, set the speed right after that segment has started (when the next segment is ready to be written).

For instance, when the second segment starts and the third segment is ready to be written, set the speed of the second segment. Therefore, after the second segment has started, the speed of the first segment is applied until the speed of the second segment is set.

- (6) Address assignment

The address of Nmc_OutPort and Nmc_InPort function should be assigned I/O address described in each board manual.

I/O addresses such as Write register or Read register are as follows. See each board manual for more details.

Board	Address of Write register	Address of Read register	Address of MSM82C55	Address of PIX132
MC8082P	0~F	0~F	----	14~16
MC8042P	0~F	0~F	----	14~16
MC8022P	0~F	0~F	----	14~16
MC8043P	0~7	0~7	----	----
MC8082Pe	0~F	0~F	----	14~16
MC8043Pe	0~7	0~7	----	----

Note1: The address is given in hexadecimal.

Note2: It is easy to access the write or read register by using not Nmc_OutPort or Nmc_InPort function but the functions for write or read registers.

(7) IC number assignment

- ① When the board has one IC, set 0.
- ② When the board has 2 ICs, set the following value.
 - IC-A: 0
 - IC-B: 1

The number of IC chips and the assignment of IC number for each board are shown in the table below.

Board	Number of IC	IC number
MC8082P	2	0, 1
MC8042P	1	0
MC8022P	1	0
MC8043P	1	0
MC8082Pe	2	0, 1
MC8043Pe	1	0

Note: IC indicates IC chips such as MCX314As or MCX304.

4.1.4. Usage

■ API Function Declaration

API function declaration is defined in the following files.

VC++, VC++.NET	MC8000P_DLL.H
VB.NET	MC8000P_DLL.vb
C#.NET	Refer to User's Manual or IntelliSense.

■ Usage

- (1) Start process . . . Execute Nmc_Open once before using each function.
- (2) End process . . . Execute Nmc_Close or Nmc_CloseAll at the end of program.

■ Board Number

The board number specified from an application should be as follows.

	Rotary switch value of board	Board number should be specified (decimal number)
1	0 ~ 9	0 ~ 9
2	A ~ F	10 ~ 15

■ Notes for Use of Function

(1) About VC, VB.NET, C# (all languages)

- ① When each function is used before executing Nmc_Open function, operation is not guaranteed.
- ② When the board number, which is not connected, is assigned, the operation of each function is not guaranteed.
- ③ Do not access the one board from 2 or more applications at the same time (such as Nmc_Open).

(2) VC, C# only

- ① When using the interrupt handling function, the time from the interrupt generation to user-defined function is not guaranteed by the nature of Windows.
- ② When the user tries to perform the interrupt, do not execute the close handling (Nmc_Close or Nmc_CloseAll) while the interrupt user-defined function (the function designated by Nmc_SetEvent) is running. Before executing the close handling, make sure that the interrupt user-defined function is finished.

■ How to handle an interrupt by VC

① Set the interrupt by using Nmc_Open function.

```
Nmc_Open(No, TRUE); // The second argument TRUE: interrupt FALSE: not interrupt
```

② Set the user-defined function handling an interrupt by using Nmc_SetEvent function, and set which interrupt is allowed or not.

```
Nmc_SetEvent(No, MC_EventProc, IpParam); // Set the user function address and argument.
```

```
Nmc_WriteReg(No, IcNo, AXIS_ALL, 0x8000); // Interrupt occurs at the stop of the specified IC (All axes).
```


③ If an interrupt occurs, the interrupt user-defined function set by `Nmc_SetEvent` is called.

The interrupt user-defined function can check the interrupt factor. To read the interrupt factor of RR3, use `Nmc_ReadEvent` function.

```

■ The example of the interrupt user-defined function
DWORD WINAPI MC_EventProc(LPVOID IpParam)
{
    . . . .
    long Rr3X, Rr3Y, Rr3Z, Rr3U;
    Nmc_ReadEvent(No, IcNo, &Rr3X, &Rr3Y, &Rr3Z, &Rr3U);
    . . . .
    return 0;
}

```

④ Use `Nmc_ResetEvent` to release the interrupt user-defined function. By executing this function, the user-defined function is not called if an interrupt occurs in the board.

```
Nmc_ResetEvent(No);
```

■ How to handle an interrupt by C# (C# only)

① Set the method to handle an interrupt by using `MC8000P.Nmc_SetEvent` function. When multiple boards are used, example is as follows.

(When the board number is 0)

```

MC8000P.callback[0] = new MC8000P.User Thread(isr);           // isr is the interrupt user-defined function.
bool ret = MC8000P.Nmc_SetEvent(0, MC8000P.callback[0]);    // Board number 0 is specified to the first argument.
                                                         // Set the function address.
MC8000P.Nmc_WriteReg1(0, (int)IC.A, AXIS.ALL, 0x8000);     // Generate an interrupt at the stop (All axes).
. . .

```

(When the board number is 1)

```

MC8000P.callback[1] = new MC8000P.User Thread(isr2);       // isr is the interrupt user-defined function.
bool ret = MC8000P.Nmc_SetEvent(1, MC8000P.callback[1]);  // Board number 1 is specified to the first argument.
                                                         // Set the function address.
MC8000P.Nmc_WriteReg1(1, (int)IC.A, AXIS.ALL, 0x8000);   // Generate an interrupt at the stop (All axes).
. . .

```

② The interrupt handling function can check the interrupt factor. To read the interrupt factor of RR3, use `MC8000P.Nmc_ReadEvent` function.

(Interrupt handling process of the board number 0)

```

static void isr()
{
    int Rr3X, Rr3Y, Rr3Z, Rr3U;
    MC8000P.Nmc_ReadEvent(0, (int)IC.A, out Rr3X, out Rr3Y, out Rr3Z, out Rr3U);
    . . . .
}

```

(Interrupt handling process of the board number 1)

```

static void isr2()
{
    int Rr3X, Rr3Y, Rr3Z, Rr3U;
    MC8000P.Nmc_ReadEvent(1, (int)IC.A, out Rr3X, out Rr3Y, out Rr3Z, out Rr3U);
    . . . .
}

```

③ Use `MC8000P.Nmc_ResetEvent` method to release the interrupt handling function. By executing this function, the interrupt user-defined function method is not called if an interrupt occurs in the board.

■ Continuous Interpolation

*The board with MCX314As only

When executing the continuous interpolation, please read the chapter “2.4.5 Continuous Interpolation” of MCX314As user’s manual carefully and execute the process described in the chapter in the application. Continuous Interpolation Functions *1 execute some of the process by DLL. So they will be used to execute the process of the continuous interpolation. But there are some notes when using Continuous Interpolation Functions. Please note them.

*1 Nmc_2CIPExec, Nmc_3CIPExec, Nmc_2CIPExec_BG, Nmc_3CIPExec_BG

Notes for when using Continuous Interpolation Function:

Continuous interpolation function writes the next segment data such as the finish point, the center point, etc. and writes the interpolation command, and checks the error. If the error occurs, the function returns. If not, it will check whether the data of the next segment is writable or not (check the bit D9 of RR0). When it becomes writable, it will write the data of the next segment and the command of the interpolation. This function repeats the process until the continuous interpolation is completed.

Because the loops that check the error and check whether the next segment data is writable are always executed in DLL, the use of this function isn’t suitable if you want to execute other process by the application during this function is executing. In this case the continuous interpolation function shouldn’t be used and the user must make the source code of the continuous interpolation in the applications by referring to MCX314As user’s manual. Please see the chapter “2.4.6 The Acceleration / Deceleration Control in Interpolation” of MCX314As user’s manual about the acceleration/deceleration drive of continuous interpolation.

When using continuous interpolation function, the initial speed should be set 8,000. (Don’t change the initial speed during this function is executing.) In this case the fixed speed driving mode is applied in each segment.

■ The BP (Bit Pattern) Interpolation

*The board with MCX314As only

When executing the BP interpolation, please read the chapter “2.4.3 The Bit Pattern Interpolation” of MCX314As user’s manual carefully and execute the process described in the chapter in the application. The BP interpolation functions *2 execute some of the process by DLL. So, they will be used to execute the process of the BP interpolation. But there are some notes when using the BP interpolation functions. Please note them.

*2 Nmc_2BPExec, Nmc_3BPExec, Nmc_2BPExec_BG, Nmc_3BPExec_BG

Notes for when using the BP Interpolation Function

The BP interpolation function writes the next BP data and the interpolation command and checks the error. If the error occurs, the function returns. If not, it will check whether the stack counter becomes 2 or less (check the bit D14,13 of RR0). When it becomes 2 or less, it will write the next BP data. This function repeats the process until the BP interpolation is completed. Because the loops that check the error and check the stack counter are always executed in DLL, the use of this function isn’t suitable if you want to execute other process by the application during this function is executing. In this case the BP interpolation function shouldn’t be used and the user must make the source code of the BP interpolation in the applications by referring to MCX314As user’s manual. Please see chapter “2.4.6 The Acceleration / Deceleration Control in Interpolation” of MCX314As user’s manual about the acceleration/deceleration drive of BP interpolation.

■ Notes for Use of Interpolation Function

*The board with MCX314As only

(1) Concerning the following interpolation function, the user can execute only one interpolation function at once.

While executing the interpolation function, the other interpolation function cannot be executed. If executed, an error will return.

Nmc_2BPExec	Nmc_2BPExec_BG	Nmc_2CIPExec	Nmc_2CIPExec_BG
Nmc_3BPExec	Nmc_3BPExec_BG	Nmc_3CIPExec	Nmc_3CIPExec_BG

(2) While executing the above interpolation function, do not perform the following operation.

- ① Execution of the interpolation command (30h~3Dh)
- ② Change of WR5 interpolation mode register

(3) The following interpolation function is executed in the background, so that the memory for interpolation data is allocated at the start of interpolation function and then the interpolation data specified by the user is copied. Then, when the interpolation process in the background is finished, the memory will be released and the message will be sent to the user window.

Therefore, while executing the following interpolation function in the background, do not exit the application.

Then, while executing the following interpolation function in the background, do not execute the close handling (Nmc_Close or Nmc_CloseAll).

If you want to stop the execution of interpolation function, execute the interpolation stop function (Nmc_IPStop) and make sure to receive the stop message.

Nmc_2BPExec_BG	Nmc_2CIPExec_BG
Nmc_3BPExec_BG	Nmc_3CIPExec_BG

(4) While the interpolation function is executed and when the speed is too fast, the interpolation driving may stop before setting the next data.

■ Notes for when developing multithread applications

This chapter describes the notes for developing applications which work in multithread.

In Nmc_xxx function, there are functions executing axis switching, data writing into WR6, WR7 and data reading to RR6, RR7. Each Nmc_xxx function is as follows:

◆ Functions executing axis switching

Nmc_Reset	Nmc_Command	Nmc_Command_IP			
Nmc_WriteReg0	Nmc_WriteReg1	Nmc_WriteReg2	Nmc_WriteReg3		
Nmc_ReadReg1	Nmc_ReadReg2				
Nmc_Range	Nmc_Jerk	Nmc_Acc	Nmc_Dec	Nmc_StartSpd	Nmc_Speed
Nmc_Pulse	Nmc_Pulse_VB	Nmc_DecP	Nmc_DecP_VB	Nmc_Center	Nmc_Lp
Nmc_Ep	Nmc_CompP	Nmc_CompM	Nmc_AccOfst	Nmc_DJerk	Nmc_HomeSpd
Nmc_ExpMode	Nmc_SyncMode	Nmc_HomeMode			
Nmc_ReadLp	Nmc_ReadEp	Nmc_ReadSpeed	Nmc_ReadAccDec	Nmc_ReadSyncBuff	
Nmc_2BPExec	Nmc_3BPExec	Nmc_2BPExec_BG	Nmc_3BPExec_BG		
Nmc_2CIPExec	Nmc_3CIPExec	Nmc_2CIPExec_BG	Nmc_3CIPExec_BG		
Nmc_WriteRegSetAxis	Nmc_ReadRegSetAxis		Nmc_WriteData	Nmc_WriteData2	Nmc_ReadData

◆ Functions executing data writing into WR6, WR7

Nmc_Range	Nmc_Jerk	Nmc_Acc	Nmc_Dec	Nmc_StartSpd	Nmc_Speed
Nmc_Pulse	Nmc_Pulse_VB	Nmc_DecP	Nmc_DecP_VB	Nmc_Center	Nmc_Lp
Nmc_Ep	Nmc_CompP	Nmc_CompM	Nmc_AccOfst	Nmc_DJerk	Nmc_HomeSpd
Nmc_ExpMode	Nmc_SyncMode	Nmc_HomeMode	Nmc_WriteData	Nmc_WriteData2	
Nmc_2CIPExec	Nmc_3CIPExec	Nmc_2CIPExec_BG	Nmc_3CIPExec_BG		
Nmc_WriteReg6	Nmc_WriteReg7				

When writing into WR6, WR7 by Nmc_OutPort or Nmc_WriteReg.

◆ Functions executing data reading to RR6, RR7

Nmc_ReadLp	Nmc_ReadEp	Nmc_ReadSpeed	Nmc_ReadAccDec	Nmc_ReadSyncBuff	Nmc_ReadData
------------	------------	---------------	----------------	------------------	--------------

To perform WR1~WR3 writing, RR1~RR2 reading, data writing command and data reading command, basically use the following Nmc_xxx function.

◆ WR1~WR3 writing

Nmc_WriteReg1	Nmc_WriteReg2	Nmc_WriteReg3	Nmc_WriteRegSetAxis
---------------	---------------	---------------	---------------------

◆ RR1~RR2 reading

Nmc_ReadReg1	Nmc_ReadReg2	Nmc_ReadRegSetAxis
--------------	--------------	--------------------

◆ Data writing command

Nmc_Range	Nmc_Jerk	Nmc_Acc	Nmc_Dec	Nmc_StartSpd	Nmc_Speed
Nmc_Pulse	Nmc_Pulse_VB	Nmc_DecP	Nmc_DecP_VB	Nmc_Center	Nmc_Lp
Nmc_Ep	Nmc_CompP	Nmc_CompM	Nmc_AccOfst	Nmc_DJerk	Nmc_HomeSpd
Nmc_ExpMode	Nmc_SyncMode	Nmc_HomeMode	Nmc_WriteData	Nmc_WriteData2	

◆ Data reading command

Nmc_ReadLp Nmc_ReadEp Nmc_ReadSpeed Nmc_ReadAccDec Nmc_ReadSyncBuff Nmc_ReadData

When trying to execute the commands such as WR1~WR3 data writing, RR1~RR2 data reading, data writing and data reading, the user must take care in multithread environment if the same operations are performed without these functions.

(1) For example, when writing into WR1, Nmc_WriteReg1 is used; however, there is other way as follows:

```
①Nmc_OutPort(No, MCX_WR0, 0x010F);           // Switch to X axis (IC-A).
②Nmc_OutPort (No, MCX_WR1, Data);           // Write to WR1 (IC-A).
```

Also, the following functions can perform the same operation.

```
③Nmc_WriteReg(No, IcNo, MCX_WR0, 0x010F);    // Switch to X axis.
④Nmc_WriteReg (No, IcNo, MCX_WR1, Data);     // Write to WR1.
```

In this case, if Nmc_xxx function to switch the axis is executed between ① and ② or ③ and ④, the data will be written into WR1 of a different axis.

(2) For example, when setting the speed, Nmc_Speed is used; however, there is other way as follows:

```
①Nmc_OutPort(No, MCX_WR6, Data);           // Write to WR6 (IC-A).
②Nmc_OutPort(No, MCX_WR0, 0x0105);         // Set WR6 data to the speed of X axis (IC-A).
```

Also, the following functions can perform the same operation.

```
③Nmc_WriteReg6(No, IcNo, Data);           // Write to WR6.
④Nmc_Command(No, IcNo, AXIS_X, 0x05);     // Set WR6 data as the speed of X axis.
```

In this case, if Nmc_xxx function to write data into WR6, WR7 is executed between ① and ② or ③ and ④, the other data will be set as the speed.

(3) For example, when reading logical position counter, Nmc_ReadLp is used; however, there is other way as follows:

```
①Nmc_OutPort(No, MCX_WR0, 0x0110);         // Read logical position counter of X axis to RR6, RR7 (IC-A).
②d6 = Nmc_InPort(No, MCX_RR6);           // Read from RR6 (IC-A).
③d7 = Nmc_InPort(No, MCX_RR7);           // Read from RR7 (IC-A).
```

In this case, if Nmc_xxx function to read data to RR6, RR7 is executed between ① and ② or ② and ③, the different data will be read.

Thus, in multithread environment, when calling API function more than twice to execute the objective operation, the user needs not to perform such an operation or needs to take exclusive control.

When the operation is finished by calling Nmc_xxx function once, it properly works in multithread environment. Each function of Nmc_xxx takes exclusive control each other.

4.2 Notes on Programming

(1) Initial setting of input signal filter

■ The board equipped with MCX314As

Each input signal of the board, for example, a limit signal, uses the built-in integral filter of MCX314As. The device driver provided by NOVA electronics sets the filter as shown below for each input signal by writing extension mode setting command (60h) to MCX314As by default when PC is powered on.

Filter delay time: 512 μ sec

Each Input Signal Filter Enable/Disable:

Signal Name	Enable / Disable
EMG, nLMT+, nLMT-, nIN0, nIN1	Enable
nIN2	Enable
nINPOS, nALARM	Enable
nEXOP+, nEXOP-	Enable
nIN3	Enable

To switch Enable/Disable of these input signal filters on the application, see chapter 6.16 of MCX314As user's manual. It can be changed by extension mode setting command (60h). The following example shows that all ICs of all axes (X, Y, Z and U axes) of the board number 0 are set to the same setting as the table above. Nmc_ExpMode executes extension mode setting command (60h).

Example 1)

```
Nmc_ExpMode(0, 0, AXIS_ALL, 0x5F00, 0x0000);
```

Example 2)

```
Nmc_WriteReg6(0, 0, 0x5F00);
```

```
Nmc_WriteReg7(0, 0, 0x0000);
```

```
Nmc_WriteReg0(0, 0, 0x0F60);
```

Notes:

① Extension mode setting command (60h) also sets the automatic home search (WR7) setting with input signal filter (WR6) setting. If the user tries to set either, be sure to set the proper value to both WR6 and WR7.

② When the user executes soft reset (set 1 to WR0/D15) in the application, the device driver sets the above setting, the same setting as the above table, to the filter of each input signal.

■ The board equipped with MCX304

Each input signal of the board, for example, a limit signal, uses the built-in integral filter of MCX304. The device driver provided by NOVA electronics sets the filter as shown below for each input signal by writing the data into mode register 3 (WR3) of MCX304 by default when PC is powered on.

Filter delay time: 512 μ sec

Each Input Signal Filter Enable/Disable:

Signal Name	Enable / Disable
EMG, nLMT+, nLMT-, nSTOP0, nSTOP1	Enable
nSTOP2	Enable
nINPOS, nALARM	Enable
nEXOP+, nEXOP-	Enable

To switch Enable/Disable of these input signal filters on the application, see chapter 2.6.9 and 4.6 of MCX304 user's manual. It can be changed by writing the data into mode register 3 (WR3). The following example shows that all ICs of all axes (X, Y, Z and U axes) of the board number 0 are set to the same setting as the table above.

Example)

```
Nmc_WriteReg3(0, 0, AXIS_ALL, 0x4F00); // Setting for IC-A
Nmc_WriteReg3(0, 1, AXIS_ALL, 0x4F00); // Setting for IC-B (For the board with multiple ICs)
```

Note:

When the user executes soft reset (set 1 to WR0/D15) in the application, the device driver sets the above setting, the same setting as the above table, to the filter of each input signal.

(2) PC standby mode and hibernation mode

In this device driver, the operation after standby or hibernation mode is not guaranteed.

When the user tries to access the board after standby or hibernation mode, be sure to restart PC before access.

(3) Interrupt support

The user can use the interrupt in the application only developed in VC++ and C#.

And the user cannot use the interrupt in the application developed in VB.

Supported interrupts are as follows:

- The board equipped with MCX314As
 - All interrupts reported by RR3 register
- The board equipped with MCX304
 - All interrupts reported by RR3 register
 - The interrupt that occurs when the next segment data and interpolation command is writable in continuous interpolation.
 - The interrupt that occurs when the value of stack counter changes from 2 to 1 in bit pattern interpolation.

(4) Interrupt clearing

① The interrupt reported by RR3 register

The interrupt is cleared after the driver read RR3, just after the interrupt occurs in the board.

Then, user-defined function of the application for interrupt is called. (Only when user-defined function has been set.)

② The interrupt that occurs when the next segment data and interpolation command is writable in continuous interpolation.

*The board with MCX314As only

The interpolation interrupt is cleared in the driver, just after the interrupt occurs in the board.

Then, user-defined function of the application for interrupt is called. (Only when user-defined function has been set.)

③ The interrupt that occurs when the value of stack counter changes from 2 to 1 in bit pattern interpolation.

*The board with MCX314As only

The interpolation interrupt is cleared in the driver, just after the interrupt occurs in the board.

Then, user-defined function of the application for interrupt is called. (Only when user-defined function has been set.)

(5) When using both RR3 interrupt and the Interpolation Interrupt *The board with MCX314As only

When both the interrupt reported by register RR3 and the interpolation interrupt ^{*1} are enabled, do as follows. When checking the factor of the interrupt in the interrupt user function ^{*2}, read the factor of RR3 interrupt first and after that check whether the interpolation interrupt occurs or not.

Example) The Interrupt User Function Process when the interrupt occurs

1. Read the factor of RR3 interrupt by using Nmc_ReadEvent. And check if there is the interrupt in RR3 or not.
2. Check if there is the interpolation interrupt or not. (Check the bit CNEXT of RR0 or the bit BPSC1, 0 of RR0)

^{*1} The interrupt that occurs when the next segment data and interpolation command is writable in continuous interpolation.

Or the interrupt that occurs when the value of the stack counter has changed into 1 from 2 during the BP interpolation.

^{*2} The user function specified by Nmc_SetEvent function.

4.3 Evaluation Tool of MCX304

MCX304 evaluation tool program is the tool to evaluate the board equipped with MCX304 (such as MC8082P, MC8082Pe, MC8042P, MC8022P).

You can download it from our web site: <http://www.novaelec.co.jp/eng> (attached to MC8000P device driver)

Before executing the evaluation tool, install MC8000P device driver.

Note: This chapter describes the outline of MCX304 evaluation tool. For more details, see ReadMe.txt in Tool\MCX304 Board folder.

4.3.1 Execution Program

There are 2 types of execution program, MCX304-A.exe and MCX304-B.exe.

■ Regarding MCX304

Each evaluation tool evaluates the MCX304 described below.

● MCX304-A.exe

- ① MCX304 of the board equipped with only one MCX304 (such as MC8042P, MC8022P).
- ② The first MCX304 (MCX304-A) of the board equipped with 2 or more MCX304 (such as MC8082P, MC8082Pe).

● MCX304-B.exe

- ① The second MCX304 (MCX304-B) of the board equipped with 2 or more MCX304 (such as MC8082P, MC8080P, MC8082Pe).

■ Regarding program execution

MCX304-A and MCX304-B can be executed to the same board simultaneously. However, the user cannot use or set the interrupt in this case.

When either MCX304-A.exe or MCX304-B.exe is executed to the one board, the user can use the interrupt.

MCX304-A and MCX304-B can be executed to the different board simultaneously. And the user can use the interrupt in this case.

4.3.2 Function Overview

Start the evaluation tool, and the Board Number Select Window appears. The user can select the board number (setting value of rotary switch (0~F) on the board). And if the Board Name Display button is pressed, the board name will be shown at the side of the board number (only the board using this device driver). After selecting the board number, press OK button, and the Main Window appears.

In the Main Window, the user can perform parameter settings for each axis, drive/other command execution, current position/speed display, interrupt window display and save/load parameter/mode setting values. In the Mode Setting Window or Status Window, the user can also set the mode or check the status.

The general output of port A, B and C can be performed in the Port A, B, C Output Window.

4.3.3 Main Window

In the main window, the user can do the following operations as shown below.

Display of the current position during driving or current drive speed Drive/other command execution for each axis

Position counter settings →

Parameter settings for each axis

Open mode setting/status windows and Port A, B, C output window.

Save/load each parameter/mode setting values.

Display of X axis drive speed trajectory (only during plotting).

割り込み発生 このRR3は、Nmc_ReadEvent 関数で読み出しています。 閉じる

	D15	D14	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
RR3																
X	○	○	○	○	○	○	○	○	●	○	○	○	○	○	○	○
Y	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
Z	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
U	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○

Interrupt window appears when an interrupt occurs. →

4.3.4 Mode Setting Window

In the mode setting window, the user can set WR1~WR5 of MCX304 (mode register, output register).

モード設定

	D15	D14	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
WR1	D-END	C-STA	C-END	P \geq C+	P<C+	P<C-	P \geq C-	SMOD	EPINV	EPCLR	SP2-E	SP2-L	SP1-E	SP1-L	SP0-E	SP0-L
X	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Y	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Z	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WR2	INP-E	INP-L	ALM-E	ALM-L	PIND1	PIND0	PINMD	DIR-L	PLS-L	PLSMD	CMPSL	HLMT-	HLMT+	LMTMD	SLMT-	SLMT+
X	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Y	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Z	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WR3	FL2	FL1	FL0	FE3	FE2	FE1	FE0	VRING	AVTRI	EXOP1	EXOP0	SACC	DSNDE	MANLD		
X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Y	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Z	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WR4	UOUT3	UOUT2	UOUT1	UOUT0	ZOUT3	ZOUT2	ZOUT1	ZOUT0	YOUT3	YOUT2	YOUT1	YOUT0	XOUT3	XOUT2	XOUT1	XOUT0
X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Y	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Z	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WR5	UOT3E	UOT2E	UOT1E	UOT0E	ZOT3E	ZOT2E	ZOT1E	ZOT0E	YOT3E	YOT2E	YOT1E	YOT0E	XOT3E	XOT2E	XOT1E	XOT0E
X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Y	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Z	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

4.3.5 Automatic Home Search Mode Setting Window

In the automatic home search mode setting window, the user can set the automatic home search mode of MCX304.


自動原点出しモード設定

	D15	D14	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
WR6	DCCW2	DCCW1	DCCW0	DCC-L	DCC-E	LIMIT	SAND	PCLR	ST4-D	ST4-E	ST3-D	ST3-E	ST2-D	ST2-E	ST1-D	ST1-E
X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Y	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Z	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
U	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

4.3.6 Status Window


The status window shows the current values of RR0, RR1, RR2, RR4 and RR5 (status register, input register) which are read out from MCX304 at regular intervals. This data reading interval is 50 milliseconds.

RR3 is displayed in the interrupt window when an interrupt occurs.



4.3.7 Port A, B, C Output Window

In the port A, B, C output window, the user can set the general output for general output port A, B and C of MC8082P or MC8082Pe. This is only available to MC8082P and MC8082Pe.



4.4 MCX314As Evaluation Tool

MCX314As evaluation tool program is the tool to evaluate the board equipped with MCX314As (such as MC8043P, MC8043Pe).

You can download it from our web site: <http://www.novaelec.co.jp/eng> (attached to MC8000P device driver)

Before executing the evaluation tool, install MC8000P device driver.

Note:

This chapter describes the outline of MCX314As evaluation tool. For more details, see ReadMe.txt in Tool\MCX314As Board folder.

4.4.1 Execution Program

MCX314As-A.exe is execution program.

■ Regarding MCX314As

Each evaluation tool evaluates the MCX314As described below.

● MCX314As-A.exe

- ① MCX314As of the board equipped with only one MCX314As (such as MC8043P, MC8043Pe).

■ Regarding program execution

MCX314As-A can be executed to the different board simultaneously. Before executing, change the different name between the boards. (For instance, such as MCX314As-A.exe and MCX314As-B.exe)

Multiple MCX314As-A cannot be executed to the same board simultaneously.

4.4.2 Function Overview

Start the evaluation tool, and the Board Number Select Window appears. The user can select the board number (setting value of rotary switch (0~F) on the board). And if the Board Name Display button is pressed, the board name will be shown at the side of the board number (only the board using this device driver). After selecting the board number, press OK button, and the Main Window appears.

In the Main Window, the user can perform parameter settings for each axis, drive/other command execution, current position/speed display, interrupt window display and save/load parameter/mode setting values. In the 3 kinds of Mode Setting Window or Status Window, the user can also set the mode or check the status.

4.4.3 Main Window

In the main window, the user can do the following operations as shown below.

Display of the current position during driving or current drive speed

Drive/other command execution for each axis

Position counter settings

Parameter settings for each axis

Interpolation commands execution

Open mode setting (three kinds)/status windows.

Display of X axis drive speed trajectory (only during plotting).

Save/load each parameter/mode setting value.

割り込み

割り込み発生 このRR3は、Nmc_ReadEvent 開放で読み出しています。

RR3


	D15	D14	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
RR3							SYNC	HMEND	D-END	C-STA	C-END	P<C+	P<C-	P<C-	P<C-	PULSE
X	○	○	○	○	○	○	○	○	●	○	○	○	○	○	○	○
Y	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
Z	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
U	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○

閉じる

Interrupt window appears when an interrupt occurs.


4.4.4 Mode Setting Window

In the mode setting window, the user can set WR1~WR5 of MCX314As (mode register, output register).




4.4.5 Expansion Mode Setting Window

In the expansion mode setting window, the user can set the extension mode register of MCX314As (EM6, EM7).



4.4.6 Synchronous Action Mode Setting Window

In the synchronous action mode setting window, the user can set the synchronous action mode register of MCX314As (SM6, SM7).



4.4.7 Status Window

The status window shows the current values of RR0, RR1, RR2, RR4 and RR5 (status register, input register) which are read out from MCX314As at regular intervals. This data reading interval is 50 milliseconds.

RR3 is displayed in the interrupt window when an interrupt occurs.

		D15	D14	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
RR0		BPSC1	BPSC0	ZONE2	ZONE1	ZONE0	CNEXT	I-DRV	U-ERR	Z-ERR	Y-ERR	X-ERR	U-DRV	Z-DRV	Y-DRV	X-DRV	
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
RR1		EMG	ALARM	LMT-	LMT+	IN3	IN2	IN1	IN0	ADSND	ACNST	AASND	DSND	CNST	ASND	CMP-	CMP+
X		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Y		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Z		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
U		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
RR2		HMST4 HMST3 HMST2 HMST1 HMST0 HOME										EMG	ALARM	HLMT-	HLMT+	SLMT-	SLMT+
X		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Y		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Z		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RR4		Y-ALM	Y-INP	Y-EX-	Y-EX+	Y-IN3	Y-IN2	Y-IN1	Y-IND	X-ALM	X-INP	X-EX-	X-EX+	X-IN3	X-IN2	X-IN1	X-IND
		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
RR5		U-ALM	U-INP	U-EX-	U-EX+	U-IN3	U-IN2	U-IN1	U-IND	Z-ALM	Z-INP	Z-EX-	Z-EX+	Z-IN3	Z-IN2	Z-IN1	Z-IND
		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

※ RR3は、割り込み発生時、割り込み画面に表示します。

5. API for MC8500P series

This chapter describes API function which can be used with the following boards

Board	IC	Number of IC	Axis
MC8541P / MC8541Pe	MCX514	1	4
MC8581P / MC8581Pe	MCX514	2	8

5.1 API

API provided by MC8000P.SYS and MC8000P.DLL.

5.1.1 Function List

The following table is the API function list.

The column of VC, VB.NET indicates the availability of each function in each language.

VC++ See VC column.

VB.NET See VB.NET column

C# See C# column.

○ is available and × is not.

(1) Basic Function

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_Open	Start to use the board	○	○	○	106	
Nmc_Close	Stop to use the board	○	○	○	"	
Nmc_CloseAll	Stop to use all the boards	○	○	○	107	
Nmc_GetBoardInfo	Get information about the opened board	○	○	○	"	
Nmc_OutPort	Write data to output port	○	○	○	108	
Nmc_InPort	Read data from input port	○	○	○	"	
Nmc_WriteReg	Write data to register of the board	○	○	○	109	
Nmc_ReadReg	Read data from register of the board	○	○	○	"	
Nmc_SetEvent	Set user function to handle an interrupt.	○	×	○	110	
Nmc_ResetEvent	Release user function to handle an interrupt.	○	×	○	111	
Nmc_ReadEvent	Read RR1 value of each axis right after the interrupt generated.	○	×	○	"	

(2) Reset, Command

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_Reset	Reset the IC on the board	○	○	○	112	
Nmc_Command	Execute the command of the specified axis	○	○	○	"	
Nmc_Command_IP	Execute the interpolation command	○	○	○	113	

(3) Write register

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_WriteReg0	WR0 (Command Register) Writing	○	○	○	113	
Nmc_WriteReg1	WR1 (Mode Register 1) Writing	○	○	○	114	
Nmc_WriteReg2	WR2 (Mode Register 2) Writing	○	○	○	"	
Nmc_WriteReg3	WR3 (Mode Register 3) Writing	○	○	○	115	
Nmc_WriteReg4	WR4 (Output Register1) Writing	○	○	○	"	
Nmc_WriteReg5	WR5 (Output Register1) Writing	○	○	○	116	
Nmc_WriteReg6	WR6 (Write Data Register 1) Writing	○	○	○	"	
Nmc_WriteReg7	WR7 (Write Data Register 2) Writing	○	○	○	"	

(4) Read Register

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_ReadReg0	RR0(Main Status Register)	○	○	○	117	
Nmc_ReadReg2	RR2(Status Register 2)	○	○	○	"	
Nmc_ReadReg3	RR3(Status Register 3)	○	○	○	118	
Nmc_ReadReg3P	(Page not specified.)	○	○	○	"	
Nmc_ReadReg4	RR3(Status Register 3)	○	○	○	119	
Nmc_ReadReg5	(Page specified.)	○	○	○	"	
Nmc_ReadReg6	RR4(Input Register 1)	○	○	○	"	
Nmc_ReadReg7	RR5(Input Register 2)	○	○	○	120	

(5) Parameter Settings

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_Jerk	Jerk Setting	○	○	○	121	
Nmc_DJerk	Deceleration increasing rate setting	○	○	○	"	
Nmc_Acc	Acceleration Setting	○	○	○	122	
Nmc_Dec	Deceleration Setting	○	○	○	123	
Nmc_StartSpd	Initial Speed Setting	○	○	○	"	
Nmc_Speed	Drive Speed Setting	○	○	○	124	
Nmc_Pulse	Moving Pulse Number/Interpolation Finish Point Setting (For VC, C#)	○	×	○	"	
Nmc_Pulse_VB	Moving Pulse Number/Interpolation Finish Point Setting (For VB.NET)	×	○	×	125	
Nmc_DecP	Manual Decelerating Point Setting (For VC, C#)	○	×	○	"	
Nmc_DecP_VB	Manual Decelerating Point Setting (For VB.NET)	×	○	×	126	
Nmc_Center	Circular Center Point Setting	○	○	○	"	
Nmc_Lp	Logical Position Counter Setting	○	○	○	127	
Nmc_Ep	Real Position Counter Setting	○	○	○	"	
Nmc_CompP	Software limit + register setting	○	○	○	128	
Nmc_CompM	Software limit - register setting	○	○	○	"	
Nmc_AccOfst	Acceleration counter offset setting	○	○	○	129	
Nmc_HomeSpd	Home search speed setting	○	○	○	"	
Nmc_LpMax	Logical Position Counter Maximum Value Setting	○	○	○	130	
Nmc_RpMax	Real Position Counter Maximum Value Setting	○	○	○	"	
Nmc_MR0	Multi-purpose register 0 setting	○	○	○	131	
Nmc_MR1	Multi-purpose register 1 setting	○	○	○	"	
Nmc_MR2	Multi-purpose register 2 setting	○	○	○	132	
Nmc_MR3	Multi-purpose register 3 setting	○	○	○	133	
Nmc_SpeedInc	Speed increase/decrease value setting	○	○	○	"	
Nmc_Timer	Timer value setting	○	○	○	134	
Nmc_TPMMax	Interpolation/finish point Maximum Value Setting	○	○	○	135	
Nmc_HLNumber	Helical rotation number setting	○	○	○	"	
Nmc_HLValue	Helical calculation value setting	○	○	○	"	

(6) Other Mode Settings

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_MRmMode	Multi-purpose register mode setting	○	○	○	136	
Nmc_PIO1Mode	PIO signal setting1	○	○	○	"	
Nmc_PIO2Mode	PIO signal setting1·other setting	○	○	○	137	
Nmc_HMSrch1Mode	Automatic Home Search Mode Setting1	○	○	○	138	
Nmc_HMSrch2Mode	Automatic Home Search Mode Setting2	○	○	○	"	
Nmc_FilterMode	Input signal filter mode setting	○	○	○	139	
Nmc_Sync0Mode	Synchronous ActionSYNC0 Setting	○	○	○	"	
Nmc_Sync1Mode	Synchronous ActionSYNC1 Setting	○	○	○	140	
Nmc_Sync2Mode	Synchronous ActionSYNC2 Setting	○	○	○	141	
Nmc_Sync3Mode	Synchronous ActionSYNC3 Setting	○	○	○	"	
Nmc_IPMode	Interpolation Mode Setting	○	○	○	142	

(7) Data Reading

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_ReadLp	Logical Position Counter Reading	○	○	○	143	
Nmc_ReadEp	Real Position Counter Reading	○	○	○	"	
Nmc_ReadSpeed	Current Drive Speed Reading	○	○	○	144	
Nmc_ReadAccDec	Current Acceleration/Deceleration Reading	○	○	○	145	
Nmc_ReadMR0	Multi-purpose register 0 Reading	○	○	○	"	
Nmc_ReadMR1	Multi-purpose register 1 Reading	○	○	○	146	
Nmc_ReadMR2	Multi-purpose register 2 Reading	○	○	○	147	
Nmc_ReadMR3	Multi-purpose register 3 Reading	○	○	○	"	
Nmc_ReadCT	Current timer value Reading	○	○	○	148	
Nmc_ReadTX	Interpolation/finish point Maximum Value reading	○	○	○	149	
Nmc_ReadCHLN	Current Helical rotation number reading	○	○	○	"	
Nmc_ReadHLV	Helical calculation value reading	○	○	○	150	
Nmc_ReadWR1	WR1 setting value reading	○	○	○	151	
Nmc_ReadWR2	WR2 setting value reading	○	○	○	"	
Nmc_ReadWR3	WR3 setting value reading	○	○	○	152	
Nmc_ReadMRM	Multi-purpose register setting reading	○	○	○	153	
Nmc_ReadP1M	PIO signal setting1 reading	○	○	○	"	
Nmc_ReadP2M	PIO signal setting and other setting reading	○	○	○	154	
Nmc_ReadAc	Acceleration setting value reading	○	○	○	155	
Nmc_ReadStartSpd	Initial speed setting value reading	○	○	○	"	
Nmc_ReadSetSpeed	Drive speed setting value reading	○	○	○	156	
Nmc_ReadPulse	Moving Pulse Number/ Finish Point Setting value reading	○	○	○	157	

(8) Status reading

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_GetDriveStatus	Drive Status Reading	○	○	○	157	
Nmc_GetCNextStatus	The Status Reading of Ready Signal for Writing of Continuous Interpolation	○	○	○	158	
Nmc_GetSc	Continuous interpolation pre-buffer Stack Counter Reading	○	○	○	"	

(9) Writing / Reading

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_WriteRegSetAxis	Axis Assignment Write Register Writing (WR1~3)	○	○	○	159	
Nmc_ReadRegSetAxis	Axis Assignment Read Register Reading (RR1~2)	○	○	○	"	
Nmc_WriteData	Data Writing (Parameter)	○	○	○	160	
Nmc_ReadData	Data Reading (4 bytes reading)	○	○	○	"	

(10) BP Interpolation/ continuous interpolation Execution

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_2BPExecMC8500P	2-axis BP Interpolation Execution	○	○	○	161	
Nmc_3BPExecMC8500P	3-axis BP Interpolation Execution	○	○	○	163	
Nmc_4BPExecMC8500P	4-axis BP Interpolation Execution	○	○	○	166	
Nmc_2BPExecMC8500P_BG	2-axis BP Interpolation Execution (run in the background)	○	○	○	169	
Nmc_3BPExecMC8500P_BG	3-axis BP Interpolation Execution (run in the background)	○	○	○	172	
Nmc_4BPExecMC8500P_BG	4-axis BP Interpolation Execution (run in the background)	○	○	○	175	
Nmc_2CIPExecMC8500P	2-axis Continuous Interpolation Execution	○	○	○	179	
Nmc_3CIPExecMC8500P	3-axis Continuous Interpolation Execution	○	○	○	182	
Nmc_4CIPExecMC8500P	4-axis Continuous Interpolation Execution	○	○	○	185	
Nmc_2CIPExecMC8500P_BG	2-axis Continuous Interpolation Execution (run in the background)	○	○	○	188	
Nmc_3CIPExecMC8500P_BG	3-axis Continuous Interpolation Execution (run in the background)	○	○	○	192	
Nmc_4CIPExecMC8500P_BG	4-axis Continuous Interpolation Execution (run in the background)	○	○	○	196	
Nmc_IPStop	Stop the Interpolation Execution	○	○	○	200	
Nmc_IPGetMsgNo	Get board and IC number from received message at the end of the Interpolation	○	○	○	"	

(11) Helical interpolation Execution

Function Name	Description	VC	VB.NET	C#	Page	Note
Nmc_HLValueExe	Helical calculation Execution	○	○	○	202	
Nmc_HLExec	Helical interpolation Execution	○	○	○	205	

5.1.2 Function Specifications

For VC++ : See **VC** and [VC]
 For VB.NET : See **VB.NET** and [VB.NET]
 For C# : See **C#** and [C#]

And others are common to each language.

Function Name	Function and Content
Nmc_Open	<p>Start the board.</p> <p>VC BOOL Nmc_Open(int No, BOOL IntrptFlg); VB.NET Function Nmc_Open(ByVal No As Integer, ByVal IntrptFlg As Integer) As Integer C# bool MC8000P.Nmc_Open(int No, bool IntrptFlg);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IntrptFlg Set the flag to use interrupt. [VC] TRUE: use interrupt. FALSE: not use. [VB.NET] FALSE only. Interrupt cannot be used in VB. [C#] true: use interrupt. false: not use.</p> <p>Return Value [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example [VC] status = Nmc_Open(0, FALSE); // Open the board 0 and not use the interrupt. [VB.NET] status = Nmc_Open(0, false) [C#] status = MC8000P.Nmc_Open(0, false);</p>
Nmc_Close	<p>Terminate the board.</p> <p>VC BOOL Nmc_Close(int No); VB.NET Function Nmc_Close(ByVal No As Integer) As Integer C# bool MC8000P.Nmc_Close(int No);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board)</p> <p>Return Value [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>Example [VC] status = Nmc_Close(0); // Close the board 0. [VB.NET] status = Nmc_Close(0) [C#] status = MC8000P.Nmc_Close(0);</p>

Function Name	Function and Content
Nmc_CloseAll	<p>Terminate all the boards.</p> <p>VC BOOL Nmc_CloseAll(void); VB.NET Function Nmc_CloseAll() As Integer C# bool MC8000P.Nmc_CloseAll();</p> <p>Input Parameter None</p> <p>Return Value [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example [VC] status = Nmc_CloseAll(); // Close all the boards. [VB.NET] status = Nmc_CloseAll() [C#] status = MC8000P.Nmc_CloseAll(); [</p>
Nmc_GetBoardInfo	<p>Get Device ID of the opened board.</p> <p>VC BOOL Nmc_GetBoardInfo(int No, USHORT* pDeviceID); VB.NET Function Nmc_GetBoardInfo(ByVal No As Integer, ByRef DeviceID As Short) As Integer C# bool MC8000P.Nmc_GetBoardInfo(int No, out ushort DeviceID);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) DeviceID [VC] Address of a variable to store the Device ID obtained from the board. [VB.NET][C#] Address of a variable to store the Device ID obtained from the board. See [4.1.3] (1)③ regarding Device ID of each board. [VC][VB] MC8541P/MC8541Pe are ID_MC8541P, MC8581P/MC8581Pe are ID_MC8581P. [C#] MC8541P/MC8541Pe are Dev_ID.MC8541P, MC8581P/MC8581Pe are Dev_ID.MC8581P.</p> <p>Return Value [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example [VC] USHORT DeviceID; status = Nmc_GetBoardInfo(No, &DeviceID); // Get Device ID. if(DeviceID == ID_MC8581P) // When the board is MC8581P. [VB.NET] Dim DeviceID As Short status = Nmc_GetBoardInfo(No, DeviceID) If DeviceID = ID_MC8581P Then [C#] ushort DeviceID; status = Nmc_GetBoardInfo(No, out DeviceID); if(DeviceID == Dev_ID.MC8581P)</p>

Function Name	Function and Content
Nmc_OutPort	<p>Write 2-byte data into output port.</p> <p>VC void Nmc_OutPort(int No, long Adr, long Dat); VB.NET Sub Nmc_OutPort(ByVal No As Integer, ByVal adr As Integer, ByVal Dat As Integer) C# void MC8000P.Nmc_OutPort(int No, REG_MCX Adr, int Dat);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) Adr Address to write. I/O address described in User's Manual of each board. See [5.1.3] (1)①, (6) for more details. Data Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_OutPort(No, 0, MC8500P_CMD_RST); // Soft reset IC-A.(Write into WR0) [VB.NET] Call Nmc_OutPort(No, 0, MC8500P_CMD_RST) [C#] MC8000P.Nmc_OutPort(No, REG_MCX.WR0_A, MC8500P_CMD_RST);</p>
Nmc_InPort	<p>Read out 2-byte data from input port.</p> <p>VC long Nmc_InPort(int No, long Adr); VB.NET Function Nmc_InPort(ByVal No As Integer, ByVal adr As Integer) As Integer C# int MC8000P.Nmc_InPort(int No, REG_MCX Adr);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) Adr Address to read. I/O address described in User's Manual of each board. See [5.1.3] (1)①, (6) for more details.</p> <p>Return Value</p> <p>Data read out from input port.</p> <p>Example</p> <p>[VC] data = Nmc_InPort(No, 0); // Read out the read register RR0 of IC-A. [VB.NET] data = Nmc_InPort(No, 0) [C#] data = MC8000P.Nmc_InPort(No, REG_MCX.RR0_A);</p> <p>Note</p> <p>[VC][C#] Regarding reading the RR1 register data, refer to Nmc_ReadEvent function.</p>

Function Name	Function and Content
Nmc_WriteReg	<p>Write data into write register (WR0~WR7) of the board.</p> <p>VC void Nmc_WriteReg(int No, int IcNo, long RegNum, long Dat);</p> <p>VB.NET Sub Nmc_WriteReg(ByVal No As Integer, ByVal IcNo As Integer, ByVal RegNum As Integer, ByVal Dat As Integer)</p> <p>C# void MC8000P.Nmc_WriteReg(int No, int IcNo, int RegNum, int Dat);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>RegNum Register to be written (MCX_WR0~MCX_WR7). See [5.1.3] (1) for more details. e.g. [VC][VB.NET] Specify MCX_WR0 for WR0 and MCX_WR1 for WR1. [C#] Specify REG_MCX.WR0 for WR0 and REG_MCX.WR1 for WR1.</p> <p>Dat Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] Nmc_WriteReg(No, 0, MCX_WR0, MC8500P_CMD_RST); // Soft reset IC-A.(Write into WR0) [VB.NET] Call Nmc_WriteReg(No, 0, MCX_WR0, MC8500P_CMD_RST) [C#] MC8000P.Nmc_WriteReg(No, 0, REG_MCX.WR0, MC8500P_CMD_RST);</pre>
Nmc_ReadReg	<p>Read out data from read register (RR0~RR7) of the board.</p> <p>VC long Nmc_ReadReg(int No, int IcNo, long RegNum);</p> <p>VB.NET Function Nmc_ReadReg(ByVal No As Integer, ByVal IcNo As Integer, ByVal RegNum As Integer) As Integer</p> <p>C# void MC8000P.Nmc_ReadReg(int No, int IcNo, int RegNum);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>RegNum Register to read (MCX_RR0~MCX_RR7). See Footnote (1) for more details. e.g. [VC], [VB.NET] Specify MCX_RR0 for RR0 and MCX_RR1 for RR1. [C#] Specify REG_MCX.RR0 for RR0 and REG_MCX.RR1 for RR1.</p> <p>Return Value</p> <p>Data read out from read register.</p> <p>Example</p> <pre>[VC] data = Nmc_ReadReg(No, 0, MCX_RR0); // Read out the read register RR0 of IC-A. [VB.NET] data = Nmc_ReadReg(No, 0, MCX_RR0) [C#] data = MC8000P.Nmc_ReadReg(No, 0, REG_MCX.WR0);</pre> <p>Note</p> <p>[VC][C#] Regarding reading the RR1 register data, refer to Nmc_ReadEvent function.</p>

Function Name	Function and Content
Nmc_SetEvent	<p>Set user function to handle an interrupt.</p> <p>By executing this function, the user function is called when an interrupt occurs and then one specified argument is passed. (C# cannot specify an argument.) This user function is run as one thread.</p> <p>To release user function to handle an interrupt, execute Nmc_ResetEvent.</p> <p>VC <code>BOOL Nmc_SetEvent(int No, LPTHREAD_START_ROUTINE UserFunc, LPVOID lpParameter);</code></p> <p>VB.NET Cannot be used.</p> <p>C# <code>bool MC8000P.Nmc_SetEvent(int No, UserThread Callback, int param);</code></p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>[VC]UserFunc User function address.</p> <p>[VC]lpParameter Assign one argument to be pass to user function thread. Set the available pointer for the thread. When not using the argument, set NULL. When using the pointer, set the available pointer when the user function is called.</p> <p>[C#] Callback User method (delegate type). See 4.1.4 Usage for more details.</p> <p>[C#] param Assign one parameter (int only, such as numeric type) to pass to user function after an interrupt occurs.</p> <p>Return Value</p> <p>If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE.</p> <p>Example</p> <p>[VC]</p> <p>(When the board number is 0)</p> <pre>status = Nmc_SetEvent(0, MC_EventFunc0, lpParam); // Set the function address and argument Nmc_WriteReg1(0, 0, AXIS_ALL, 0x0080); // Interrupt occurs at the stop of IC-A</pre> <p>(All axes)</p> <p>(When the board number is 1)</p> <pre>status = Nmc_SetEvent(1, MC_EventFunc1, NULL); // Set the function address and argument Nmc_WriteReg1(1, 0, AXIS_ALL, 0x0080); // Interrupt occurs at the stop of IC-A</pre> <p>(All axes)</p> <p>■Example of interrupt user function</p> <pre>DWORD WINAPI MC_EventFunc0(LPVOID lpParam) { long Rr1X, Rr1Y, Rr1Z, Rr1U; Nmc_ReadEvent(0, 0, &Rr1X,&Rr1Y,&Rr1Z,&Rr1U); // Board 0, read out RR1 interrupt data of IC-A return 0; } DWORD WINAPI MC_EventFunc1(LPVOID lpParam) { long Rr1X, Rr1Y, Rr1Z, Rr1U; Nmc_ReadEvent(1, 0, &Rr1X,&Rr1Y,&Rr1Z,&Rr1U); // Board 1, read RR3 interrupt data of IC-A return 0; } [C#] // Assign interrupt method is to a delegate type variable MC8000P.callback[0] = new MC8000P.UserThread(isr); //Set user method to handle an interrupt MC8000P.Nmc_SetEvent(no, MC8000P.callback[0], param);</pre>

Nmc_ResetEvent	<p>Release user function to handle an interrupt. By executing this function, the user function is not called when an interrupt occurs.</p> <p>VC BOOL Nmc_ResetEvent(int No); VB.NET cannot be used. C# bool MC8000P.Nmc_ResetEvent(int No);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p>Return Value</p> <p> [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example</p> <p> [VC] status = Nmc_ResetEvent(No); [C#] status = MC8000P.Nmc_ResetEvent(No);</p>
Nmc_ReadEvent	<p>Read the value of RR1 of each axis right after an interrupt generation. (RR1 will be cleared after reading.)</p> <p>VC BOOL Nmc_ReadEvent(int No, int IcNo, long* Rr1X, long* Rr1Y, long* Rr1Z, long* Rr1U); VB.NET cannot be used. C# bool MC8000P.Nmc_ReadEvent(int No, int IcNo, out int Rr1X, out int Rr1Y, out int Rr1Z, out int Rr1U);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See 5.1.3 (7) for more details. Rr1X Pointer to a variable that receives the X axis RR1 value. Rr1Y Pointer to a variable that receives the Y axis RR1 value. Rr1Z Pointer to a variable that receives the Z axis RR1 value. Rr1U Pointer to a variable that receives the U axis RR1 value.</p> <p>Return Value</p> <p> [VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example</p> <p> [VC] long Rr1X[2], Rr1Y[2], Rr1Z[2], Rr1U[2]; Nmc_ReadEvent(No, 0, &Rr1X[0], &Rr1Y[0], &Rr1Z[0], &Rr1U[0]); // Read out RR1 data of IC-A Nmc_ReadEvent(No, 1, &Rr1X[1], &Rr1Y[1], &Rr1Z[1], &Rr1U[1]); // Read out RR1 data of IC-B [C#] int Rr1X,Rr1Y,Rr1Z,Rr1U ; // X-axis, Y-axis, Z-axis, U-Axis MC8000P.Nmc_ReadEvent(No, IcNo, out Rr1X, out Rr1Y, out Rr1Z, out Rr1U);</p> <p>Note</p> <p> The RR1 value is cleared due to the driver operation, just after the interrupt occurs. The user must use this function in order to know the interrupt factor. In addition, when the interrupt occurs, the driver certainly reads and saves RR1 data regardless of the execution of Nmc_SetEvent or Nmc_ResetEvent functions. RR1 data saved in the driver can be cleared after reading by execution of Nmc_ReadEvent function. To clear the RR1 data of the driver, execute Nmc_ReadEvent function.</p>

Function Name	Function and Content
Nmc_Reset	<p>Reset the IC on the board.</p> <p>VC void Nmc_Reset(int No, int IcNo); VB.NET Sub Nmc_Reset(ByVal No As Integer, ByVal IcNo As Integer) C# void MC8000P.Nmc_Reset(int No, int IcNo);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value None</p> <p>Example [VC] Nmc_Reset(1, 0); // Reset IC-A of the board 1. [VB.NET] Call Nmc_Reset(1, 0) [C#] MC8000P.Nmc_Reset(1, 0);</p>
Nmc_Command	<p>Execute the command of a specified axis. (Write the command of a specified axis into WR0.)</p> <p>VC void Nmc_Command(int No, int IcNo, int axis, int cmd); VB.NET Sub Nmc_Command(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal cmd As Integer) C# void MC8000P.Nmc_Command(int No, int IcNo, AXIS axis, CMD cmd);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. axis Axis to execute the command. Multiple axes can be assigned. See [5.1.3] (2) for more details. cmd Command number. Specify one command from "Driving commands, Other commands of "Command Definition" described in definition file (*1). For relative position drive, specify MC8500P_CMD_DRVRL. See [5.1.3] (4) for C#. *1 : [VC]MC8000P_DLL.H / [VB.REMAINING]MC8000P_DLL.vb</p> <p>Return Value None</p> <p>Example [VC] Nmc_Command(No, IcNo, AXIS_X, MC8500P_CMD_DRVRL); // Execute the relative position drive of X axis. [VB.NET] Call Nmc_Command(No, IcNo, AXIS_X, MC8500P_CMD_DRVRL) [C#] MC8000P.Nmc_Command(No, IcNo, AXIS.X, CMD.MC8500P_CMD_DRVRL);</p>

Function Name	Function and Content
Nmc_WriteReg1	<p>Write data into WR1 (Mode register 1).</p> <p>VC void Nmc_WriteReg1(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_WriteReg1(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteReg1(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to write data. Axis to write data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg1(No, IcNo, AXIS_X, 0x0080); // Interrupt occurs at the stop (X axis).</p> <p>[VB.NET] Call Nmc_WriteReg1(No, IcNo, AXIS_X, &H80)</p> <p>[C#] MC8000P.Nmc_WriteReg1(No, IcNo, AXIS.X, 0x0080);</p>
Nmc_WriteReg2	<p>Write data into WR2 (Mode register 2).</p> <p>VC void Nmc_WriteReg2(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_WriteReg2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteReg2(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to write data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg2(No, IcNo, AXIS_Y, 0x0200); // Enable ALARM (Y axis)</p> <p>[VB.NET] Call Nmc_WriteReg2(No, IcNo, AXIS_Y, &H200)</p> <p>[C#] MC8000P.Nmc_WriteReg2(No, IcNo, AXIS.Y, 0x0200);</p>

Function Name	Function and Content
Nmc_WriteReg3	<p>Write data into WR3 (Mode register 3).</p> <p>VC void Nmc_WriteReg3(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_WriteReg3(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteReg3(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to write data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg3(No, IcNo, AXIS_ALL, 0x0004); // Set S-curve acceleration/deceleration to the all axes.</p> <p>[VB.NET] Call Nmc_WriteReg3(No, IcNo, AXIS_ALL, &H4)</p> <p>[C#] MC8000P.Nmc_WriteReg3(No, IcNo, AXIS.ALL, 0x0004);</p>
Nmc_WriteReg4	<p>Write data into WR4 (Output register).</p> <p>VC void Nmc_WriteReg4(int No, int IcNo, long wdata);</p> <p>VB.NET Sub Nmc_WriteReg4(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteReg4(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>wdata Data to be written.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_WriteReg4(No, IcNo, 0x0001); // Hi level output for X axis general output PIO0.</p> <p>[VB.NET] Call Nmc_WriteReg4(No, IcNo, &H1)</p> <p>[C#] MC8000P.Nmc_WriteReg4(No, IcNo, 0x0001);</p>

Function Name	Function and Content
Nmc_WriteReg5	<p>Write data into WR5 (Output register2).</p> <p>VC void Nmc_WriteReg5(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg5(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg5(int No, int IcNo, int wdata);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1).Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. wdata Data to be written.</p> <p>Return Value None</p> <p>Example [VC] Nmc_WriteReg5(No, IcNo, 0x0001); // Hi level output for Z axis general output PIO0. [VB.NET] Call Nmc_WriteReg5(No, IcNo, &H1) [C#] MC8000P.Nmc_WriteReg5(No, IcNo, 0x0024);</p>
Nmc_WriteReg6	<p>Write data into WR6 (Write data register 1).</p> <p>VC void Nmc_WriteReg6(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg6(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg6(int No, int IcNo, int wdata);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details wdata Data to be written.</p> <p>Return Value None</p> <p>Example [VC] Nmc_WriteReg6(No, IcNo, 0x1234); // Write data (1234)H into write data register 1. [VB.NET] Call Nmc_WriteReg6(No, IcNo, &H1234) [C#] MC8000P.Nmc_WriteReg6(No, IcNo, 0x1234);</p>
Nmc_WriteReg7	<p>Write data into WR7 (Write data register 2).</p> <p>VC void Nmc_WriteReg7(int No, int IcNo, long wdata); VB.NET Sub Nmc_WriteReg7(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_WriteReg7(int No, int IcNo, int wdata);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. wdata Data to be written</p> <p>Return Value None</p> <p>Example [VC] Nmc_WriteReg7(No, IcNo, 0x5678); // Write data (5678) into write register2. [VB.NET] Call Nmc_WriteReg7(No, IcNo, &H5678) [C#] MC8000P.Nmc_WriteReg7(No, IcNo, 0x5678);</p>

Function Name	Function and Content
Nmc_ReadReg0	<p>Read out data from RR0 (Main status register).</p> <p>VC long Nmc_ReadReg0(int No, int IcNo);</p> <p>VB.NET Function Nmc_ReadReg0(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadReg0(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> wdata Data to be written</p> <p>Return Value</p> <p> The data of RR0 (Main status register)</p> <p>Example</p> <p> [VC] Data = Nmc_ReadReg0(No, IcNo); // Read out RR0.</p> <p> [VB.NET] Data = Nmc_ReadReg0(No, IcNo)</p> <p> [C#] Data = MC8000P.Nmc_ReadReg0(No, IcNo);</p>
Nmc_ReadReg2	<p>Read out data from RR2 (Status register 2).</p> <p>VC long Nmc_ReadReg2(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadReg2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadReg2(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis, See [5.1.3] (2) for more details.</p> <p>Return Value</p> <p> The data of RR2 (Status register 2)</p> <p>Example</p> <p> [VC] Data = Nmc_ReadReg2(No, IcNo, AXIS_Y); // Read out RR2 Y axis.</p> <p> [VB.NET] Data = Nmc_ReadReg2(No, IcNo, AXIS_Y)</p> <p> [C#] Data = MC8000P.Nmc_ReadReg2(No, IcNo, AXIS.Y);</p>

Function Name	Function and Content
Nmc_ReadReg3	<p>Read out data from RR3 (Status register 3).</p> <p>VC long Nmc_ReadReg3(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadReg3(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000.Nmc_ReadReg3(int No, int IcNo, AXIS axis);</p> <p>Input parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis, See [5.1.3] (2) for more details.</p> <p>Return Value</p> <p>The data of RR3 (Status register 3)</p> <p>Example</p> <p>[VC] Nmc_Command(No, IcNo, AXIS_Y, MC8500P_CMD_RR3P0); // Indicate page0 of RR3 of Y axis.</p> <p>Data = Nmc_ReadReg3(No, IcNo, AXIS_Y); // Read out RR3 of Y axis.</p> <p>[VB.NET] Call Nmc_Command(No, IcNo, AXIS_Y, MC8500P_CMD_RR3P0)</p> <p>Data = Nmc_ReadReg3(No, IcNo, AXIS_Y)</p> <p>[C#] MC8000P.Nmc_Command(No, IcNo, AXIS.Y, CMD.MC8500P_CMD_RR3P0);</p> <p>Data = MC8000P.Nmc_ReadReg3(No, IcNo, AXIS.Y);</p> <p>Note</p> <p>Regarding RR3 register, there are 2 kinds: Page 0 and Page1. The page can be specified by writing RR3 page display command (7Ah, 7Bh). It will be Page 0 at reset.</p>
Nmc_ReadReg3P	<p>Read out data from RR3 (Status register 3. Specify page.).</p> <p>VC long Nmc_ReadReg3P(int No, int IcNo, int axis, int Page);</p> <p>VB.NET Function Nmc_ReadReg3P(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal Page As Integer) As Integer</p> <p>C# int MC8000.Nmc_ReadReg3P(int No, int IcNo, AXIS axis, int Page);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis, See [5.1.3] (2) for more details.</p> <p>Page Page to read data. Pge0 is 0, page1 is 1.</p> <p>Return Value</p> <p>RR3 (Status register3) data of the specified page.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadReg3P(No, IcNo, AXIS_Y, 0); // Read out page0 of RR3 of Y axis.</p> <p>[VB.NET] Data = Nmc_ReadReg3P(No, IcNo, AXIS_Y, 0)</p> <p>[C#] Data = MC8000P.Nmc_ReadReg3P(No, IcNo, AXIS.Y, 0);</p>

Function name	Function and Content
Nmc_ReadReg4	<p>Read out data from RR4 (PIO read register 1).</p> <p>VC long Nmc_ReadReg4(int No, int IcNo); VB.NET Function Nmc_ReadReg4(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadReg4(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>The data of RR4 (PIO read register 1).</p> <p>Example</p> <pre>[VC] Data = Nmc_ReadReg4(No, IcNo); // Read out RR4. [VB.NET] Data = Nmc_ReadReg4(No, IcNo) [C#] Data = MC8000P.Nmc_ReadReg4(No, IcNo);</pre>
Nmc_ReadReg5	<p>Read out data from RR5 (PIO read register 2).</p> <p>VC long Nmc_ReadReg5(int No, int IcNo); VB.NET Function Nmc_ReadReg5(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadReg5(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>The data of RR5 (PIO read register 2).</p> <p>Example</p> <pre>[VC] Data = Nmc_ReadReg5(No, IcNo); // Read out RR5. [VB.NET] Data = Nmc_ReadReg5(No, IcNo) [C#] Data = MC8000P.Nmc_ReadReg5(No, IcNo);</pre>
Nmc_ReadReg6	<p>Read out data from RR6 (Read data register 1).</p> <p>VC long Nmc_ReadReg6(int No, int IcNo); VB.NET Function Nmc_ReadReg6(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadReg6(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>The data of RR6 (Read data register 1)</p> <p>Example</p> <pre>[VC] Data = Nmc_ReadReg6(No, IcNo); // Read out RR6. [VB.NET] Data = Nmc_ReadReg6(No, IcNo) ' Read out RR6. [C#] Data = MC8000P.Nmc_ReadReg6(No, int IcNo);</pre>

Function Name	Function and Content
Nmc_ReadReg7	<p>Read out data from RR7 (Read data register 2).</p> <p>VC long Nmc_ReadReg7(int No, int IcNo);</p> <p>VB.NET Function Nmc_ReadReg7(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadReg7(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p> The data of RR7 (Read data register 2)</p> <p>Example</p> <p> [VC] Data = Nmc_ReadReg7(No, IcNo); // Read out RR7.</p> <p> [VB.NET] Data = Nmc_ReadReg7(No, IcNo) ' Read out RR7.</p> <p> [C#] Data = MC8000P.Nmc_ReadReg7(No, IcNo);</p>

Function Name	Function and Content
Nmc_Jerk	<p>Set jerk .</p> <p>VC void Nmc_Jerk(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Jerk(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Jerk(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> None</p> <p>Example</p> <p> [VC] Nmc_Jerk(No, IcNo, AXIS_X, 1000); // Set 1000 to jerk (X axis).</p> <p> [VB.NET] Call Nmc_Jerk(No, IcNo, AXIS_X, 1000)</p> <p> [C#] MC8000P.Nmc_Jerk(No, IcNo, AXIS.X, 1000);</p>

Function Name	Function and Content
Nmc_DJerk	<p>Set deceleration increasing rate.</p> <p>VC void Nmc_DJerk(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_DJerk(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_DJerk(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_DJerk(No, IcNo, AXIS_X, 1000); // Set 1000 to deceleration increasing rate (Z axis).</p> <p>[VB.NET] Call Nmc_DJerk(No, IcNo, AXIS_X, 1000)</p> <p>[C#] MC8000P.Nmc_DJerk(No, IcNo, AXIS.X, 1000);</p>
Nmc_Acc	<p>Set acceleration.</p> <p>VC void Nmc_Acc(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Acc(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Acc(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Acc(No, IcNo, AXIS_Y, 100); // Set 100 to acceleration (Y axis).</p> <p>[VB.NET] Call Nmc_Acc(No, IcNo, AXIS_Y, 100)</p> <p>[C#] MC8000P.Nmc_Acc(No, IcNo, AXIS.Y, 100);</p>

Function Name	Function and Content
Nmc_Dec	<p>Set deceleration.</p> <p>VC void Nmc_Dec(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Dec(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Dec(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Dec(No, IcNo, AXIS_Z, 100); // Set 100 to deceleration (Z axis).</p> <p>[VB.NET] Call Nmc_Dec(No, IcNo, AXIS_Z, 100)</p> <p>[C#] MC8000P.Nmc_Dec(No, IcNo, AXIS.Z, 100);</p>
Nmc_Speed	<p>Set drive speed.</p> <p>VC void Nmc_Speed(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Speed(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Speed(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Speed(No, IcNo, AXIS_X AXIS_Y, 1000); // Set 1000 to drive speed (X/Y axes).</p> <p>[VB.NET] Call Nmc_Speed(No, IcNo, AXIS_X or AXIS_Y, 1000)</p> <p>[C#] MC8000P.Nmc_Speed(No, IcNo, AXIS.X AXIS.Y, 1000);</p>

Function Name	Function and Content
Nmc_Pulse	<p>Set output pulse number or interpolation finish point. (VC/C# only)</p> <p>The number of output pulses indicates the total number of pulses that are output in fixed pulse driving. For linear and circular interpolation driving, set the finish point of each axis. For helical interpolation, set the feed amount of Z and U axis. The finish point should be specified relative value to the current position.</p> <p>VC void Nmc_Pulse(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET cannot be used.</p> <p>C# void MC8000P.Nmc_Pulse(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <pre>[VC] Nmc_Pulse(No, IcNo, AXIS_X, 2000); // Set 2000 to output pulse number (X axis). Nmc_Pulse(No, IcNo, AXIS_Y, 300); // Set 300 to interpolation finish point (Y axis) Nmc_Pulse(No, IcNo, AXIS_Z, -400); // Set -400 to interpolation finish point (Z axis) [C#] MC8000P.Nmc_Pulse(No, IcNo, AXIS.X, 2000); MC8000P.Nmc_Pulse(No, IcNo, AXIS.Y, 300); MC8000P.Nmc_Pulse(No, IcNo, AXIS.Z, -400);</pre>
Nmc_Pulse_VB	<p>Set output pulse number or interpolation finish point. (VB/VB.NET only).</p> <p>The number of output pulses indicates the total number of pulses that are output in fixed pulse driving. For linear and circular interpolation driving, set the finish point of each axis. For helical interpolation, set the feed amount of Z and U axis. The finish point should be specified relative value to the current position.</p> <p>VC cannot be used.</p> <p>VB.NET Sub Nmc_Pulse_VB(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Double)</p> <p>C# cannot be used.</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <pre>[VB.NET] Call Nmc_Pulse_VB(No, IcNo, AXIS_X, 2000) ' Set 2000 to output pulse number (X axis). Call Nmc_Pulse_VB(No, IcNo, AXIS_Y, 300) ' Set 300 to interpolation finish point (Y axis). Call Nmc_Pulse_VB(No, IcNo, AXIS_Z, -400) ' Set -400 to interpolation finish point (Z axis).</pre>

Function Name	Function and Content
Nmc_DecP	<p>Set manual decelerating point. (VC, C# only)</p> <p>VC void Nmc_DecP(int No, int IcNo, int axis, ULONG wdata); VB.NET cannot be used. C# void MC8000P.Nmc_DecP(int No, int IcNo, AXIS axis, uint wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VC] Nmc_DecP(No, IcNo, AXIS_U, 30000); // Set 30000 to manual decelerating point (U axis) [C#] MC8000P.Nmc_DecP(No, IcNo, AXIS.U, 30000);</p>
Nmc_DecP_VB	<p>Set manual decelerating point. (VB.NET only)</p> <p>VC cannot be used. VB.NET Sub Nmc_DecP_VB(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Double) C# cannot be used.</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VB.NET] Call Nmc_DecP_VB(No, IcNo, AXIS_X, 40000) ' Set 40000 to manual decelerating point (X axis).</p>
Nmc_Center	<p>Set circular center point.</p> <p>VC void Nmc_Center(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_Center(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_Center(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example [VC] Nmc_Center(No, IcNo, AXIS_Y, 1500); // Set 1500 to circular center point (Y axis). [VB.NET] Call Nmc_Center(No, IcNo, AXIS_Y, 1500) [C#] MC8000P.Nmc_Center(No, IcNo, AXIS.Y, 1500);</p>

Function Name	Function and Content
Nmc_Lp	<p>Set logical position counter.</p> <p>VC void Nmc_Lp(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Lp(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Lp(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Lp(No, IcNo, AXIS_ALL, 0); // Set 0 to logical position counter of all axes.</p> <p>[VB.NET] Call Nmc_Lp(No, IcNo, AXIS_ALL, 0)</p> <p>[C#] MC8000P.Nmc_Lp(No, IcNo, AXIS.ALL, 0);</p>
Nmc_Ep	<p>Set real position counter.</p> <p>VC void Nmc_Ep(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Ep(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Ep(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Ep(No, IcNo, AXIS_ALL, 0); // Set 0 to real position counter of all axes.</p> <p>[VB.NET] Call Nmc_Ep(No, IcNo, AXIS_ALL, 0)</p> <p>[C#] MC8000P.Nmc_Ep(No, IcNo, AXIS.ALL, 0);</p>

Function Name	Function and Content
Nmc_CompP	<p>Set software limit +register.</p> <p>VC void Nmc_CompP(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_CompP(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_CompP(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_CompP(No, IcNo, AXIS_X, 50000); // Set 50000 to software limit +register (X axis) [VB.NET] Call Nmc_CompP(No, IcNo, AXIS_X, 50000) [C#] MC8000P.Nmc_CompP(No, IcNo, AXIS.X, 50000);</p>
Nmc_CompM	<p>Set software limit -register.</p> <p>VC void Nmc_CompM(int No, int IcNo, int axis, long wdata); VB.NET Sub Nmc_CompM(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_CompM(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_CompM(No, IcNo, AXIS_X, -50000); // Set -50000 to software limit +register (X axis). [VB.NET] Call Nmc_CompM(No, IcNo, AXIS_X, -50000) [C#] MC8000P.Nmc_CompM(No, IcNo, AXIS.X, -50000);</p>

Function Name	Function and Content
Nmc_AccOfst	<p>Set acceleration counter offsetting.</p> <p>VC void Nmc_AccOfst(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_AccOfst(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_AccOfst(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_AccOfst(No, IcNo, AXIS_Y, 20); // Set 20 to acceleration counter offsetting (Y axis).</p> <p>[VB.NET] Call Nmc_AccOfst(No, IcNo, AXIS_Y, 20)</p> <p>[C#] MC8000P.Nmc_AccOfst(No, IcNo, AXIS.Y, 20);</p>
Nmc_HomeSpd	<p>Set home search speed.</p> <p>VC void Nmc_HomeSpd(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_HomeSpd(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_HomeSpd(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_HomeSpd(No, IcNo, AXIS_Z, 200); // Set 200 to home search speed (Z axis).</p> <p>[VB.NET] Call Nmc_HomeSpd(No, IcNo, AXIS_Z, 200)</p> <p>[C#] MC8000P.Nmc_HomeSpd(No, IcNo, AXIS.U, 200);</p>

Function Name	Function and Content
Nmc_LpMax	<p>Set logical position counter maximum value.</p> <p>VC void Nmc_LpMax(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_LpMax(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_LpMax(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_LpMax(No, IcNo, AXIS_U, 2000); // Set 2000 to logical position counter maximum value (U axis).</p> <p>[VB.NET] Call Nmc_LpMax(No, IcNo, AXIS_U, 2000)</p> <p>[C#] MC8000P.Nmc_LpMax(No, IcNo, AXIS.U, 2000);</p>
Nmc_RpMax	<p>Set real position counter maximum value.</p> <p>VC void Nmc_RpMax(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_RpMax(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_RpMax(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_RpMax(No, IcNo, AXIS_X, 1000); // Set 1000 to real position counter maximum value (X axis).</p> <p>[VB.NET] Call Nmc_RpMax(No, IcNo, AXIS_X, 1000)</p> <p>[C#] MC8000P.Nmc_RpMax(No, IcNo, AXIS.X, 1000);</p>

Function Name	Function and Content
Nmc_MR0	<p>Set multi-purpose register 0.</p> <p>VC void Nmc_MR0(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_MR0(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_MR0(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> None</p> <p>Example</p> <p> [VC] Nmc_MR0(No, IcNo, AXIS_Z, 500000); // Set 500000 to multi-purpose register 0 (Z axis).</p> <p> [VB.NET] Call Nmc_MR0(No, IcNo, AXIS_Z, 500000)</p> <p> [C#] MC8000P.Nmc_MR0(No, IcNo, AXIS.Z, 500000);</p>
Nmc_MR1	<p>Set multi-purpose register 1.</p> <p>VC void Nmc_MR1(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_MR1(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_MR1(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> None</p> <p>Example</p> <p> [VC] Nmc_MR1(No, IcNo, AXIS_U, 5000); // Set 5000 to multi-purpose register 0(U axis).</p> <p> [VB.NET] Call Nmc_MR1(No, IcNo, AXIS_U, 5000)</p> <p> [C#] MC8000P.Nmc_MR1(No, IcNo, AXIS.U, 5000);</p>

Function Name	Function and Content
Nmc_MR2	<p>Set multi-purpose register 2.</p> <p>VC void Nmc_MR2(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_MR2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_MR2(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_MR2(No, IcNo, AXIS_X, 5000000); // Set 5000000 to multi-purpose register 2 (X axis).</p> <p>[VB.NET] Call Nmc_MR2(No, IcNo, AXIS_X, 5000000)</p> <p>[C#] MC8000P.Nmc_MR2(No, IcNo, AXIS.X, 5000000);</p>
Nmc_MR3	<p>Set multi-purpose register 3.</p> <p>VC void Nmc_MR3(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_MR3(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_MR3(int No, int IcNo, AXIS axis, int wdata);</p> <p>In No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_MR3(No, IcNo, AXIS_Y, 30000); // Set 30000 to multi-purpose register 2(Y axis).</p> <p>[VB.NET] Call Nmc_MR3(No, IcNo, AXIS_Y, 30000)</p> <p>[C#] MC8000P.Nmc_MR3(No, IcNo, AXIS.Y, 30000);</p>

Function Name	Function and Content
Nmc_SpeedInc	<p>Set speed increase/decrease value setting</p> <p>VC void Nmc_SpeedInc(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_SpeedInc(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_SpeedInc(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_SpeedInc(No, IcNo, AXIS_Z, 100); // Set 100 to speed increase/decrease value(Z-axis).</p> <p>[VB.NET] Call Nmc_SpeedInc(No, IcNo, AXIS_Z, 100)</p> <p>[C#] MC8000P.Nmc_SpeedInc(No, IcNo, AXIS.Z, 100);</p>
Nmc_Timer	<p>Set timer value</p> <p>VC void Nmc_Timer(int No, int IcNo, int axis, long wdata);</p> <p>VB.NET Sub Nmc_Timer(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_Timer(int No, int IcNo, AXIS axis, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Specify AXIS_X, AXIS_Y and so on. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>[VC] Nmc_Timer(No, IcNo, AXIS_U, 10000); // Set 10000 to timer value (U axis)</p> <p>[VB.NET] Call Nmc_Timer(No, IcNo, AXIS_U, 10000)</p> <p>[C#] MC8000P.Nmc_Timer(No, IcNo, AXIS.U, 10000);</p>

Function Name	Function and Content
Nmc_TPMax	<p>Set Interpolation/finish point Maximum Value Setting</p> <p>VC void Nmc_TPMax(int No, int IcNo, long wdata); VB.NET Sub Nmc_TPMax(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_TPMax(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <p>[VC] Nmc_TPMax(No, IcNo, 10000); // Set 10000 to Interpolation/finish point Maximum Value. [VB.NET] Call Nmc_TPMax(No, IcNo, 10000) [C#] MC8000P.Nmc_TPMax(No, IcNo, 10000);</p>
Nmc_HLNumber	<p>Set helical rotation number.</p> <p>VC void Nmc_HLNumber(int No, int IcNo, long wdata); VB.NET Sub Nmc_HLNumber(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_HLNumber(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <p>[VC] Nmc_HLNumber(No, IcNo, 7); // Set 7 to helical rotation number. [VB.NET] Call Nmc_HLNumber(No, IcNo, 7) [C#] MC8000P.Nmc_HLNumber(No, IcNo, 7);</p>
Nmc_HLValue	<p>Set helical calculation value.</p> <p>VC void Nmc_HLValue(int No, int IcNo, long wdata); VB.NET Sub Nmc_HLValue(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer) C# void MC8000P.Nmc_HLValue(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example</p> <p>[VC] Nmc_HLValue(No, IcNo, 36799); // Set 36799 to helical calculation value. [VB.NET] Call Nmc_HLValue(No, IcNo, 36799) [C#] MC8000P.Nmc_HLValue(No, IcNo, 36799);</p>

Function Name	Function and Content
Nmc_MRmMode	<p>Set multi-purpose register mode.</p> <p>VC void Nmc_MRmMode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_MRmMode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_MRmMode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> None</p> <p>Example</p> <p> // Set comparative object (current speed) and comparison condition (>) of MR1 to X axis multi-purpose register mode.</p> <p> [VC] Nmc_MRmMode(No, IcNo, AXIS_X, 0x0060);</p> <p> [VB.NET] Call Nmc_MRmMode(No, IcNo, AXIS_X, &H60)</p> <p> [C#] MC8000P.Nmc_MRmMode(No, IcNo, AXIS.X, 0x0060);</p>
Nmc_PIO1Mode	<p>Set PIO signal setting 1 (Function of nPIO7~0).</p> <p>VC void Nmc_PIO1Mode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_PIO1Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_PIO1Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> None</p> <p>Example</p> <p> [VC] Nmc_PIO1Mode(No, IcNo, AXIS_X, 0x0055); //Set general purpose output by X-axis PIO signal 0~3.</p> <p> [VB.NET] Call Nmc_PIO1Mode(No, IcNo, AXIS_X, &H55)</p> <p> [C#] MC8000P.Nmc_PIO1Mode(No, IcNo, AXIS.X, 0x0055);</p>

Function Name	Function and Content
Nmc_PIO2Mode	<p>Set PIO signal setting 2/others (synchronous pulse output logic, pulse width and so on.)</p> <p>VC void Nmc_PIO2Mode(int No, int IcNo, int axis, long WR6_data); VB.NET Sub Nmc_PIO2Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer) C# void MC8000P.Nmc_PIO2Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example //Set positive to X axis pulse signal and 1msec to pulse width. [VC] Nmc_PIO2Mode(No, IcNo, AXIS_X, 0x0070); [VB.NET] Call Nmc_PIO2Mode(No, IcNo, AXIS_X, &H70) [C#] MC8000P.Nmc_PIO2Mode(No, IcNo, AXIS.X, 0x0070);</p>
Nmc_HMSrch1Mode	<p>Set automatic home search mode setting 1.</p> <p>VC void Nmc_HMSrch1Mode(int No, int IcNo, int axis, long WR6_data); VB.NET Sub Nmc_HMSrch1Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer) C# void MC8000P.Nmc_HMSrch1Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details. wdata Data to be set.</p> <p>Return Value None</p> <p>Example Set as follows to automatic home search mode setting 1.</p> <ul style="list-style-type: none"> • Step 1,2,3,4 : Execute • Direction of Step 1,2,3 : — direction • Search signal of Step1,2 : STOP1 • DCC output, RP clear, LP clear of STEP2 : Disable • DCC output, RP clear, LP clear of STEP3 : Enable <p>[VC] Nmc_HMSrch1Mode(No, IcNo, AXIS_X, 0xFC37); [VB.NET] Call Nmc_HMSrch1Mode(No, IcNo, AXIS_X, &HFC37) [C#] MC8000P.Nmc_HMSrch1Mode(No, IcNo, AXIS.X, 0xFC37);</p>

Function Name	Function and Content
Nmc_HMSrch2Mode	<p>Set automatic home search mode setting 2.</p> <p>VC void Nmc_HMSrch2Mode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_HMSrch2Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_HMSrch2Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>Set as follows to automatic home search mode setting 2.</p> <ul style="list-style-type: none"> • Step 2&3 : Disable • LP clear at automatic home search termination : Enable • RP clear at automatic home search termination : Enable • DCC pulse logic : 10μsec • DCC pulse width : Hi pulse • Timer between steps : Disable • Timer value : 0 <p>[VC] Nmc_HMSrch2Mode(No, IcNo, AXIS_X, 0x0006);</p> <p>[VB.NET] Call Nmc_HMSrch2Mode(No, IcNo, AXIS_X, &H6)</p> <p>[C#] MC8000P.Nmc_HMSrch2Mode(No, IcNo, AXIS.X, 0x0006);</p>
Nmc_FilterMode	<p>Set input signal mode.</p> <p>VC void Nmc_FilterMode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_FilterMode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_FilterMode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>Set all the filters enable and delay 512μs to X axis input signal mode.</p> <p>[VC] Nmc_FilterMode(No, IcNo, AXIS_X, 0xA AFF);</p> <p>[VB.NET] Call Nmc_FilterMode(No, IcNo, AXIS_X, &HA AFF)</p> <p>[C#] MC8000P.Nmc_FilterMode(No, IcNo, AXIS.X, 0xA AFF);</p>

Function Name	Function and Content
Nmc_Sync0Mode	<p>Set synchronous action SYNC0.</p> <p>VC void Nmc_Sync0Mode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_Sync0Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_Sync0Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0-15) on the board)</p> <p>IcNo IC number (0-1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>Set [Save logical position counter to MR0 after starting constant speed area of acceleration drive during X axis driving.].</p> <p>[VC] Nmc_Sync0Mode(No, IcNo, AXIS_X, 0x0054);</p> <p>[VB.NET] Call Nmc_Sync0Mode(No, IcNo, AXIS_X, &H54)</p> <p>[C#] MC8000P.Nmc_Sync0Mode(No, IcNo, AXIS.X, 0x0054);</p>
Nmc_Sync1Mode	<p>Set synchronous action SYNC1.</p> <p>VC void Nmc_Sync1Mode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_Sync1Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_Sync1Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0-15) on the board)</p> <p>IcNo IC number (0-1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>Set [Save current timer value to MR1 after MR1 object changes to positive during X axis driving.].</p> <p>[VC] Nmc_Sync1Mode(No, IcNo, AXIS_X, 0x0071);</p> <p>[VB.NET] Call Nmc_Sync1Mode(No, IcNo, AXIS_X, &H71)</p> <p>[C#] MC8000P.Nmc_Sync1Mode(No, IcNo, AXIS.X, 0x0071);</p>

Function Name	Function and Content
Nmc_Sync2Mode	<p>Set synchronous action SYNC2.</p> <p>VC void Nmc_Sync2Mode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_Sync2Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_Sync2Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>Set [Activate X axis SYNC3 after internal timer is expired during X axis driving and then save logical position counter to MR2].</p> <p>[VC] Nmc_Sync2Mode(No, IcNo, AXIS_X, 0x0252);</p> <p>[VB.NET] Call Nmc_Sync2Mode(No, IcNo, AXIS_X, &H252)</p> <p>[C#] MC8000P.Nmc_Sync2Mode(No, IcNo, AXIS.X, 0x0252);</p>
Nmc_Sync3Mode	<p>Set synchronous action SYNC3.</p> <p>VC void Nmc_Sync3Mode(int No, int IcNo, int axis, long WR6_data);</p> <p>VB.NET Sub Nmc_Sync3Mode(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal WR6_data As Integer)</p> <p>C# void MC8000P.Nmc_Sync3Mode(int No, int IcNo, AXIS axis, int WR6_data);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to set data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>wdata Data to be set.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <p>Set [Activate Y-axis SYNC0 after MR3 object changes to positive during X axis driving and then save logical position counter to MR3].</p> <p>[VC] Nmc_Sync3Mode(No, IcNo, AXIS_X, 0x1051);</p> <p>[VB.NET] Call Nmc_Sync3Mode(No, IcNo, AXIS_X, &H1051)</p> <p>[C#] MC8000P.Nmc_Sync3Mode(No, IcNo, AXIS.X, 0x1051);</p>

Function Name	Function and Content
Nmc_IPMode	<p>Set interpolation mode.</p> <p>VC void Nmc_IPMode(int No, int IcNo, long wdata);</p> <p>VB.NET Sub Nmc_IPMode(ByVal No As Integer, ByVal IcNo As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P. Nmc_IPMode(int No, int IcNo, int wdata);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> None</p> <p>Example</p> <p> [VC] Nmc_IPMode(No, IcNo, 0x0007); //Specify interpolation axis, X,Y,Z.</p> <p> [VB.NET] Call Nmc_IPMode(No, IcNo, &H7)</p> <p> [C#] MC8000P. Nmc_IPMode(No, IcNo, 0x0007);</p>

Function Name	Function and Content
Nmc_ReadLp	<p>Read out logical position counter.</p> <p>VC long Nmc_ReadLp(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadLp(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadLp(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,.</p> <p> wdata Data to be set.</p> <p>Return Value</p> <p> Current value of the logical position counter.</p> <p>Example</p> <p> [VC] Data = Nmc_ReadLp(No, IcNo, AXIS_X); // Read out logical position counter of X axis.</p> <p> [VB.NET] Data = Nmc_ReadLp(No, IcNo, AXIS_X)</p> <p> [C#] Data = MC8000P.Nmc_ReadLp(No, IcNo, AXIS.X);</p>
Nmc_ReadEp	<p>Read out real position counter.</p> <p>VC long Nmc_ReadEp(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadEp(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadEp(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p> Current value of the real position counter.</p> <p>Example</p> <p> [VC] Data = Nmc_ReadEp(No, IcNo, AXIS_Y); // Read out real position counter of Y axis.</p> <p> [VB.NET] Data = Nmc_ReadEp(No, IcNo, AXIS_Y) ' Read out real position counter of Y axis.</p> <p> [C#] Data = MC8000P.Nmc_ReadEp(No, IcNo, AXIS.Y)</p>

Function Name	Function and Content
Nmc_ReadSpeed	<p>Read out the current drive speed.</p> <p>VC long Nmc_ReadSpeed(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadSpeed(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadSpeed(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p> The current drive speed.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadSpeed(No, IcNo, AXIS_Z); // Read out the current drive speed of Z-axis.</p> <p>[VB.NET] Data = Nmc_ReadSpeed(No, IcNo, AXIS_Z)</p> <p>[C#] Data = MC8000P.Nmc_ReadSpeed(No, IcNo, AXIS.Z);</p>
Nmc_ReadAccDec	<p>Read out the current acceleration/deceleration.</p> <p>Read out the value of the current acceleration or deceleration during driving. When the driving stops, the read data is random number.</p> <p>VC long Nmc_ReadAccDec(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadAccDec(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadAccDec(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return Value</p> <p> Current value of acceleration/deceleration speed.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadAccDec(No, IcNo, AXIS_U); // Read out the current acceleration/deceleration of U axis.</p> <p>[VB.NET] Data = Nmc_ReadAccDec(No, IcNo, AXIS_U)</p> <p>[C#] Data = MC8000P.Nmc_ReadAccDec(No, IcNo, AXIS.U);</p>

Function Name	Function and Content
Nmc_ReadMR0	<p>Read multi-purpose register 0.</p> <p>VC long Nmc_ReadMR0(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadMR0(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadMR0(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p>Value of multi-purpose register 0.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadMR0(No, IcNo, AXIS_X); // Read multi-purpose register 0 of X axis</p> <p>[VB.NET] Data = Nmc_ReadMR0(No, IcNo, AXIS_X)</p> <p>[C#] Data = MC8000P.Nmc_ReadMR0(No, IcNo, AXIS.X);</p>
Nmc_ReadMR1	<p>Read multi-purpose register 1.</p> <p>VC long Nmc_ReadMR1(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadMR1(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadMR1(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p>Value of multi-purpose register 1.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadMR1(No, IcNo, AXIS_Y); // Read multi-purpose register 1 of Y axis</p> <p>[VB.NET] Data = Nmc_ReadMR1(No, IcNo, AXIS_Y)</p> <p>[C#] Data = MC8000P.Nmc_ReadMR1(No, IcNo, AXIS.Y);</p>

Function Name	Function and Content
Nmc_ReadMR2	<p>Read multi-purpose register 2.</p> <p>VC long Nmc_ReadMR2(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadMR2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadMR2(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p>Value of multi-purpose register 2.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadMR2(No, IcNo, AXIS_Z); // Read multi-purpose register 2 of Z axis</p> <p>[VB.NET] Data = Nmc_ReadMR2(No, IcNo, AXIS_Z)</p> <p>[C#] Data = MC8000P.Nmc_ReadMR2(No, IcNo, AXIS.Z);</p>
Nmc_ReadMR3	<p>Read multi-purpose register 3.</p> <p>VC long Nmc_ReadMR3(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadMR3(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadMR3(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p>Value of multi-purpose register 3.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadMR3(No, IcNo, AXIS_U); // Read multi-purpose register 3 of U axis</p> <p>[VB.NET] Data = Nmc_ReadMR3(No, IcNo, AXIS_U)</p> <p>[C#] Data = MC8000P.Nmc_ReadMR3(No, IcNo, AXIS.U);</p>

Function Name	Function and Content
Nmc_ReadCT	<p>Read current timer value.</p> <p>VC long Nmc_ReadCT(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadCT(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadCT(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p> Current value of timer.</p> <p>Example</p> <p> [VC] Data = Nmc_ReadCT(No, IcNo, AXIS_X); // Read current timer value of X axis.</p> <p> [VB.NET] Data = Nmc_ReadCT(No, IcNo, AXIS_X)</p> <p> [C#] Data = MC8000P.Nmc_ReadMR3(No, IcNo, AXIS.X);</p>
Nmc_ReadTX	<p>Read interpolation/finish point Maximum Value.</p> <p>VC long Nmc_ReadTX(int No, int IcNo);</p> <p>VB.NET Function Nmc_ReadTX(ByVal No As Integer, ByVal IcNo As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadTX(int No, int IcNo);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p> Value of interpolation/finish point maximum value.</p> <p>Example</p> <p> [VC] Data = Nmc_ReadTX(No, IcNo); // Read interpolation/finish point Maximum Value.</p> <p> [VB.NET] Data = Nmc_ReadTX(No, IcNo)</p> <p> [C#] Data = MC8000P.Nmc_ReadTX(No, IcNo);</p> <p>Note</p> <p> Value to be read is different from that of before interpolation driving and during driving. Finish maximum value of interpolation segment which is being input is read before interpolation driving. And, finish point maximum value of the current interpolation driving segment is read during interpolation driving.</p>

Function Name	Function and Content
Nmc_ReadCHLN	<p>Read current helical rotation number.</p> <p>VC long Nmc_ReadCHLN(int No, int IcNo); VB.NET Function Nmc_ReadCHLN(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadCHLN(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>Current number of helical rotation.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadCHLN(No, IcNo); // Read current helical rotation number. [VB.NET] Data = Nmc_ReadCHLN(No, IcNo) [C#] Data = MC8000P.Nmc_ReadCHLN(No, IcNo);</p>
Nmc_ReadHLV	<p>Read helical calculation value. Use this function when reading the result of helical calculation command(6Bh,6Ch)</p> <p>VC long Nmc_ReadHLV(int No, int IcNo); VB.NET Function Nmc_ReadHLV(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_ReadHLV(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>Value of helical calculation.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadHLV(No, IcNo); // Read helical calculation value. [VB.NET] Data = Nmc_ReadHLV(No, IcNo) [C#] Data = MC8000P.Nmc_ReadHLV(No, IcNo);</p>
Nmc_ReadWR1	<p>Read WR1 setting value.</p> <p>VC long Nmc_ReadWR1(int No, int IcNo, int axis); VB.NET Function Nmc_ReadWR1(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer C# int MC8000P.Nmc_ReadWR1(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p>WR1 value.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadWR1(No, IcNo, AXIS_Y); // Read WR1 setting value of Y axis. [VB.NET] Data = Nmc_ReadWR1(No, IcNo, AXIS_Y) [C#] Data = MC8000P.Nmc_ReadWR1(No, IcNo, AXIS.Y);</p>

Function Name	Function and Content
Nmc_ReadWR2	<p>Read WR2 setting value.</p> <p>VC long Nmc_ReadWR2(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadWR2(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadWR2(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p> WR2 value.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadWR2(No, IcNo, AXIS_Z); // Read WR2 setting value of Z axis.</p> <p>[VB.NET] Data = Nmc_ReadWR2(No, IcNo, AXIS_Z) ' Read WR2 setting value of Z axis.</p> <p>[C#] Data = MC8000P.Nmc_ReadWR2(No, IcNo, AXIS.Z);</p>
Nmc_ReadWR3	<p>Read WR3 setting value.</p> <p>VC long Nmc_ReadWR3(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadWR3(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadMR3(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p> WR3 value.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadWR3(No, IcNo, AXIS_U); // Read WR3 setting value of U axis.</p> <p>[VB.NET] Data = Nmc_ReadWR3(No, IcNo, AXIS_U)</p> <p>[C#] Data = MC8000P.Nmc_ReadWR3(No, IcNo, AXIS.U);</p>

Function Name	Function and Content
Nmc_ReadMRM	<p>Read multi-purpose mode register setting value.</p> <p>VC long Nmc_ReadMRM(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadMRM(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadMRM(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis,</p> <p>Return Value</p> <p> Multi-purpose register mode value.</p> <p>Example</p> <p> [VC] Data = Nmc_ReadMRM(No, IcNo, AXIS_X); // Read multi-purpose mode register setting value of X axis.</p> <p> [VB.NET] Data = Nmc_ReadMRM(No, IcNo, AXIS_X)</p> <p> [C#] Data = MC8000P.Nmc_ReadMRM(No, IcNo, AXIS.X);</p>
Nmc_ReadP1M	<p>Read PIO signal setting value 1.</p> <p>VC long Nmc_ReadP1M(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadP1M(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadP1M(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return Value</p> <p> PIO signal setting 1 value.</p> <p>Example</p> <p> [VC] Data = Nmc_ReadP1M(No, IcNo, AXIS_Y); // Read PIO signal setting value 1 of Y axis.</p> <p> [VB.NET] Data = Nmc_ReadP1M(No, IcNo, AXIS_Y)</p> <p> [C#] Data = MC8000P.Nmc_ReadP1M(No, IcNo, AXIS.Y);</p>

Function Name	Function and Content
Nmc_ReadP2M	<p>Read PIO signal setting value1 / other setting.</p> <p>VC long Nmc_ReadP2M(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadP2M(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadP2M(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return Value</p> <p>PIO signal setting 1/other setting value.</p> <p>Example</p> <pre>// Read PIO signal setting value1 / other setting of Z axis. [VC] Data = Nmc_ReadP2M(No, IcNo, AXIS_Z); [VB.NET] Data = Nmc_ReadP2M(No, IcNo, AXIS_Z) [C#] Data = MC8000P.Nmc_ReadP2M(No, IcNo, AXIS.Z);</pre>
Nmc_ReadAc	<p>Read out the current acceleration/deceleration.</p> <p>VC long Nmc_ReadAc(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadAc(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadAc(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return Value</p> <p>Acceleration speed value to be set.</p> <p>Example</p> <pre>[VC] Data = Nmc_ReadAc(No, IcNo, AXIS_U); // Read out the current acceleration/deceleration of U axis. [VB.NET] Data = Nmc_ReadAc(No, IcNo, AXIS_U) [C#] Data = MC8000P.Nmc_ReadAc(No, IcNo, AXIS.U);</pre>

Function Name	Function and Content
Nmc_ReadSetSpeed	<p>Read out drive speed setting value.</p> <p>VC long Nmc_ReadSetSpeed(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadSetSpeed(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadSetSpeed(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return Value</p> <p>Drive speed value to be set.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadSetSpeed(No, IcNo, AXIS_Y); // Read out drive speed setting value of Y axis.</p> <p>[VB.NET] Data = Nmc_ReadSetSpeed(No, IcNo, AXIS_Y)</p> <p>[C#] Data = MC8000P.Nmc_ReadSetSpeed(No, IcNo, AXIS.Y);</p>
Nmc_ReadPulse	<p>Read moving pulse number/ Finish Point Setting value.</p> <p>VC long Nmc_ReadPulse(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_ReadPulse(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadPulse(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return Value</p> <p>Moving Pulse Number/ Finish Point Setting value to be set.</p> <p>Example</p> <p>[VC] Data = Nmc_ReadPulse(No, IcNo, AXIS_Z); // Read Moving Pulse Number/ Finish Point Setting value of Z axis.</p> <p>[VB.NET] Data = Nmc_ReadPulse(No, IcNo, AXIS_Z)</p> <p>[C#] Data = MC8000P.Nmc_ReadSetSpeed(No, IcNo, AXIS.Z);</p>

Function Name	Function and Content
Nmc_GetDriveStatus	<p>Drive Status Reading. Use this function to check whether drive of specified axis finishes.</p> <p>VC int Nmc_GetDriveStatus(int No, int IcNo, int axis);</p> <p>VB.NET Function Nmc_GetDriveStatus(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer) As Integer</p> <p>C# int MC8000P.Nmc_GetDriveStatus(int No, int IcNo, AXIS axis);</p> <p>Input Parameter</p> <p> No Board number (setting value of rotary switch (0~15) on the board)</p> <p> IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p> Axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis.</p> <p>Return value</p> <p> If all the specified axes have finished driving, the return value is 0.</p> <p> If more than one of the specified axes is/are driving, the return value is nonzero.</p> <p>Example</p> <pre>[VC] if(Nmc_GetDriveStatus(No, IcNo, AXIS_X) == 0) // When X axis has finished driving. AfxMessageBox("X axis has finished driving"); else AfxMessageBox("X axis is driving ");</pre> <pre>[VB.NET] If Nmc_GetDriveStatus(No, IcNo, AXIS_X) = 0 Then Call MsgBox("X axis has finished driving") Else Call MsgBox("X axis is driving") End If</pre> <pre>[C#] if(MC8000P.Nmc_GetDriveStatus(No, IcNo, AXIS.X) == 0) MessageBox.Show(" X axis has finished driving "); else MessageBox.Show(" X axis is driving ");</pre>

Function Name	Function and Content
Nmc_GetCNextStatus	<p>Read the status of ready signal for writing of continuous interpolation. The user can use to check whether the signal for the writing of continuous interpolation is ready or not during continuous interpolation execution.</p> <pre> VC int Nmc_GetCNextStatus(int No, int IcNo); VB.NET Function Nmc_GetCNextStatus(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_GetCNextStatus(int No, int IcNo); </pre> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>If the signal for the writing of continuous interpolation is ready, the return value is nonzero. If the signal for the writing of continuous interpolation is not ready, the return value is 0.</p> <p>Example</p> <pre> [VC] if(Nmc_GetCNextStatus(No, IcNo) != 0) // When the signal for the writing is ready. AfxMessageBox("The signal for the writing of continuous interpolation is ready "); else AfxMessageBox("The signal for the writing of continuous interpolation is not ready "); [VB.NET] If Nmc_GetCNextStatus(No, IcNo) <> 0 Then Call MsgBox("The signal for the writing of continuous interpolation is ready ") Else Call MsgBox("The signal for the writing of continuous interpolation is not ready ") End If [C#] if(MC8000P.Nmc_GetCNextStatus(No, IcNo) != 0) MessageBox.Show(" The signal for the writing of continuous interpolation is ready ") else MessageBox.Show(" The signal for the writing of continuous interpolation is not ready "); </pre>
Nmc_GetSc	<p>Read the value of Continuous interpolation pre-buffer Stack Counter.</p> <pre> VC int Nmc_GetSc(int No, int IcNo); VB.NET Function Nmc_GetSc(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# int MC8000P.Nmc_GetSc(int No, int IcNo); </pre> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return Value</p> <p>The value of the current Continuous interpolation pre-buffer Stack Counter.</p> <p>Example</p> <pre> [VC] Data = Nmc_GetSc(No, IcNo); // Read the value of BP interpolation stack counter. [VB.NET] Data = Nmc_GetSc(No, IcNo) [C#] Data = MC8000P.Nmc_GetSc(No, IcNo) </pre>

Function Name	Function and Content
Nmc_WriteRegSetAxis	<p>Write data into one specified write register of WR1~WR3 for the specified axis.</p> <p>VC void Nmc_WriteRegSetAxis(int No, int IcNo, int axis, int RegNumber, long wdata);</p> <p>VB.NET Sub Nmc_WriteRegSetAxis(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal RegNumber As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteRegSetAxis(int No, int IcNo, AXIS axis, int RegNumber, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to write data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>RegNumber Write register number to write data.</p> <p> [VC][VB.NET] Assign MCX_WR1 for WR1, MCX_WR2 for WR2, MCX_WR3 for WR3</p> <p> [C#] Assign REG_MCX.RR1 for RR1, REG_MCX.RR2 for RR2.</p> <p> See [5.1.3] (1) for more detail.</p> <p>wdata Data to be written</p> <p>Return Value</p> <p>None</p> <p>Example Set hardware limit enable.</p> <p>[VC] Nmc_WriteRegSetAxis(No, IcNo, AXIS_ALL, MCX_WR2, 0x0800);</p> <p>[VB.NET] Call Nmc_WriteRegSetAxis(No, IcNo, AXIS_ALL, MCX_WR2, &H800)</p> <p>[C#] MC8000P.Nmc_WriteRegSetAxis(No, IcNo, AXIS.ALL, REG_MCX.WR2, 0x0800);</p>
Nmc_ReadRegSetAxis	<p>Read out data from the specified read register (either RR2 or RR3) for the specified axis.</p> <p>VC long Nmc_ReadRegSetAxis(int No, int IcNo, int axis, int RegNumber);</p> <p>VB.NET Function Nmc_ReadRegSetAxis(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal RegNumber As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadRegSetAxis(int No, int IcNo, AXIS axis, int RegNumber);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis. See [5.1.3] (2) for more details.</p> <p>RegNumber Read register number to read data.</p> <p> [VC] [VB.NET] Assign MCX.RR1 for RR1, MCX.RR2 for RR2.</p> <p> [C#] Assign REG_MCX.RR1 for RR1, REG_MCX.RR2 for RR2.</p> <p> See [5.1.3] (1) for more detail.</p> <p>Return Value</p> <p>The data of the specified read register for the specified axis.</p> <p>Example Read out the data of X axis RR2.</p> <p>[VC] Data = Nmc_ReadRegSetAxis(No, IcNo, AXIS_X, MCX_RR2);</p> <p>[VB.NET] Data = Nmc_ReadRegSetAxis(No, IcNo, AXIS_X, MCX_RR2)</p> <p>[C#] Data = MC8000P.Nmc_ReadRegSetAxis(No, IcNo, AXIS.X, REG_MCX.RR2);</p> <p>Note</p> <p>Regarding RR3 register, there are 2 kinds: Page 0 and Page1. The page can be specified by writing RR3 page display command (7Ah, 7Bh). It will be Page 0 at reset.</p>

Function Name	Function and Content
Nmc_WriteData	<p>Write the specified parameter into the specified axis. (Execute commands for data writing)</p> <p>VC void Nmc_WriteData(int No, int IcNo, int axis, int cmd, long wdata);</p> <p>VB.NET Sub Nmc_WriteData(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal cmd As Integer, ByVal wdata As Integer)</p> <p>C# void MC8000P.Nmc_WriteData(int No, int IcNo, AXIS axis, CMD cmd, int wdata);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to write data. Multiple axes can be assigned. See [5.1.3] (2) for more details.</p> <p>cmd Commands for data writing ((00)H~(0E)H, (61)H). E.g. Jerk setting is (00)H.</p> <p>wdata Data to be written</p> <p>Return Value</p> <p>None</p> <p>Example Set 1000 to the drive speed of all axes. Drive speed command code is (05)H.</p> <p>[VC] Nmc_WriteData(No, IcNo, AXIS_ALL, 0x05, 1000);</p> <p>[VB.NET] Call Nmc_WriteData(No, IcNo, AXIS_ALL, &H5, 1000)</p> <p>[C#] MC8000P.Nmc_WriteData(No, IcNo, AXIS.ALL, 0x05, 1000);</p>
Nmc_ReadData	<p>Read out data by executing commands for reading data.</p> <p>VC long Nmc_ReadData(int No, int IcNo, int axis, int cmd);</p> <p>VB.NET Function Nmc_ReadData(ByVal No As Integer, ByVal IcNo As Integer, ByVal axis As Integer, ByVal cmd As Integer) As Integer</p> <p>C# int MC8000P.Nmc_ReadData(int No, int IcNo, AXIS axis, CMD cmd);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>axis Axis to read data. Specify AXIS_X for X axis, AXIS_Y for Y axis, AXIS_Z for Z axis, AXIS_U for U axis. See [5.1.3] (2) for more details.</p> <p>cmd Commands for reading data ((10)H~(14)H). E.g. Logical position counter reading is (30)H.</p> <p>Return Value</p> <p>Data to be read.</p> <p>Example // Read the logical position counter of X axis.</p> <p>[VC] Data = Nmc_ReadData(No, IcNo, AXIS_X, 0x30);</p> <p>[VB.NET] Data = Nmc_ReadData(No, IcNo, AXIS_X, &H30)</p> <p>[C#] Data = MC8000P.Nmc_ReadData(No, IcNo, AXIS.X, 0x30);</p>

[VB.NET]

'2-axis BP interpolation data setting

Dim Data2Bp(1) As DATA_2BP

Data2Bp(0).Bp1p = 0

Data2Bp(0).Bp1m = &H2BFFS

Data2Bp(0).Bp2p = &HFFD4S

Data2Bp(0).Bp2m = 0

Data2Bp(1).Bp1p = &HF6FES

Data2Bp(1).Bp1m = 0

Data2Bp(1).Bp2p = &HFS

Data2Bp(1).Bp2m = &H3FC0S

Call Nmc_IPMode(No, IcNo, &H3)

' Interpolation mode setting.
Assign X and Y axis.

' Parameter setting related to speed(The actual setting description is omitted)

Ret = Nmc_2BPExecMC8500P(No, IcNo, Data2Bp, 2, &H3)

' Execute 2-axis BP interpolation. The number of data is 2, X, Y axes.

If Ret = BP_END Then ' Return value is correct

Call MsgBox("Successful completion")

End If

[C#]

DATA_2BP [] Data2Bp = new DATA_2BP[2];

// 2-axis BP interpolation data

// Interpolation data setting

Data2Bp[0].Bp1p = 0; // 0000 0000 0000 0000 BP1 +direction 0pulse

Data2Bp[0].Bp1m = 0x2BFF; // 0010 1011 1111 1111 BP1 -direction 12pulse

Data2Bp[0].Bp2p = 0xFFD4; // 1111 1111 1101 0100 BP2 +direction 12pulse

Data2Bp[0].Bp2m = 0; // 0000 0000 0000 0000 BP2 -direction 0pulse

Data2Bp[1].Bp1p = 0xF6FE; // 1111 0110 1111 1110 BP1 +direction 13pulse

Data2Bp[1].Bp1m = 0; // 0000 0000 0000 0000 BP1 -direction 0pulse

Data2Bp[1].Bp2p = 0xF; // 0000 0000 0000 1111 BP2 +direction 4pulse

Data2Bp[1].Bp2m = 0x3FC0; // 0011 1111 1100 0000 BP2 +direction 8pulse

MC8000P.Nmc_IPMode(No, IcNo, 0x0003);

// Interpolation mode setting. Assign X and Y axis.

// Parameter setting related to speed(The actual setting description is omitted)

// Execute 2-axis BP interpolation. The number of data is 2, X, Y axes.

Ret = MC8000.Nmc_2BPExecMC8500P(No, IcNo, Data2Bp, 2, 0x3);

if(Ret == Nmc_Status.BP_END) // Return value is

correct.

Note

Make sure to set interpolation axis and so on in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.

This function operates in constant speed driving. Set speed parameter to constant speed drive.

Function Name	Function and Content
Nmc_3BPExecMC8500P	<p>Execute 3-axis bit pattern interpolation using the specified interpolation data. This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_3BPExecMC8500P(int No, int IcNo, DATA_3BP* pData3Bp, int DataCnt, int IpAxis);</p> <p>VB.NET Function Nmc_3BPExecMC8500P(ByVal No As Integer, ByVal IcNo As Integer, ByVal pData3Bp As DATA_3BP(), ByVal DataCnt As Integer, ByVal IpAxis As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3BPExecMC8500P(int No, int IcNo, DATA_3BP[] pData3Bp, int DataCnt, int IpAxis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData3Bp Pointer to an array of DATA_3BP structures (user-defined type in VB). Set the 3-axis BP interpolation data to DATA_3BP. See [5.1.3] (3) for DATA_3BP.</p> <p>DataCnt The number of 3-axis BP interpolation data. Specify the number of the DATA_3BP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>Return Value</p> <p>If the function succeeds, the return value is BP_END. If the function fails, the return value is the following Error code. For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal end <p>BP_END BP interpolation has been successfully completed.</p> ■ Error code <p>BP_CNT_ERR The number of the specified data is out of range.</p> <p>BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running.</p> <p>BP_MALLOC_ERR Memory cannot be collocated.</p> <p>BP_PARAM_ERR The parameter is incorrect.</p> <p>BP_NOT_OPEN_ERR The specified board is not opened.</p> <p>BP_OTHER_ERR Other errors.</p> <p>BP_FUNC_ERR Unusable function is used.</p> <p>BP_STOP BP interpolation stopped during driving (too fast to stack next data).</p> <p>BP_USER_STOP The user aborted BP interpolation.</p> <p>BP_DRIVE_ERR Error occurred in the board during BP interpolation. (When the error status was set to RR0.)</p> <p>BP_STOP_CERR BP interpolation stopped during driving. (Due to RR2 error.)</p> <p>BP_GETSC_ERR Stack counter reading error</p> <p>When interpolation is terminated if end code is written, error code, BP_END or BP_STOP, is returned.</p> <p>Example</p> <pre>[VC] // 3 axis BP interpolation data BP1P, BP1M, BP2P, BP2M, BP3P, BP3M DATA_3BP Data3Bp[2] = {{0xFF30, 0, 0, 0x84FF, 0, 0xAC35}, {0xAC35, 0, 0xC000, 0x36E7, 0xC000, 0x3F3F}}; Nmc_IPMode(No, IcNo, 0x0007); // Interpolation mode setting. Assign X, Y and Z axis. // Parameter setting related to speed(The actual setting description is omitted)</pre>

```

Ret = Nmc_3BPExecMC8500P(No, IcNo, Data3Bp, 2, 0x7); // Execute 3-axis BP
                                                    interpolation. The
                                                    number of data is 2, X,
                                                    Y, Z axes.

if(Ret == BP_END)  AfxMessageBox("Successful completion "); // Return
value is correct.

[VB.NET]
'3-axis BP interpolation data
'Interpolation data setting
Dim Data3Bp(1) As DATA_3BP
Data3Bp(0).Bp1p = &HFF30S
Data3Bp(0).Bp1m = 0
Data3Bp(0).Bp2p = 0
Data3Bp(0).Bp2m = &H84FFS
Data3Bp(0).Bp3p = 0
Data3Bp(0).Bp3m = &HAC35S

Data3Bp(1).Bp1p = &HAC35S
Data3Bp(1).Bp1m = 0
Data3Bp(1).Bp2p = &HC000S
Data3Bp(1).Bp2m = &H36E7S
Data3Bp(1).Bp3p = &HC000S
Data3Bp(1).Bp3m = &H3F3FS

Call Nmc_IPMode(No, IcNo, &H7) ' Interpolation mode setting.
Assign X, Y and Z axis.

' Parameter setting related to speed(The actual setting description is omitted)

Ret = Nmc_3BPExecMC8500P(No, IcNo, Data3Bp, 2, &H7)
' Execute 2-axis BP interpolation. The number of data is 2, X, Y, Z axes.

If Ret = BP_END Then ' Return value is correct
Call MsgBox("Successful completion")
End If

[C#]
DATA_3BP [] Data3Bp = new DATA_3BP[2];
// 3-axis BP interpolation data
// Interpolation data setting
Data3Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 +direction 10pulse
Data3Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 -direction 0pulse
Data3Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 +direction 0pulse
Data3Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2 -direction 10pulse
Data3Bp[0].Bp3p = 0; // 0000 0000 0000 0000 BP3 +direction 0pulse
Data3Bp[0].Bp3m = 0xAC35; // 1010 1100 0011 0101 BP3 -direction 8pulse

Data3Bp[1].Bp1p = 0xAC35; // 1010 1100 0011 0101 BP1 +direction 8pulse
Data3Bp[1].Bp1m = 0; // 0000 0000 0000 0000 BP1 -direction 0pulse
Data3Bp[1].Bp2p = 0xC000; // 1100 0000 0000 0000 BP2 +direction 2pulse
Data3Bp[1].Bp2m = 0x36E7; // 0011 0110 1110 0111 BP2 -direction 10pulse
Data3Bp[1].Bp3p = 0xC000; // 1100 0000 0000 0000 BP3 +direction 2pulse
Data3Bp[1].Bp3m = 0x3F3F; // 0011 1111 0011 1111 BP3 -direction 12pulse

MC8000P.Nmc_IPMode(No, IcNo,0x0007); // Interpolation mode setting.
Assign X, Y and Z axis.

// Parameter setting related to speed(The actual setting description is omitted)

Ret = MC8000P.Nmc_3BPExecMC8500P(No, IcNo, Data3Bp, 2, 0x7); // Execute 3-axis BP
interpolation.

```

	<pre>if(Ret == Nmc_Status.BP_END) // Return value is correct</pre> <p>Note</p> <p>Make sure to set interpolation axis and so on in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.</p> <p>This function operates in constant speed driving. Set speed parameter to constant speed drive.</p>
--	--

Function Name	Function and Content
Nmc_4BPExecMC8500P	<p>Execute 4-axis bit pattern interpolation using the specified interpolation data. This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_4BPExecMC8500P(int No, int IcNo, DATA_4BP* pData4Bp, int DataCnt, int IpAxis);</p> <p>VB.NET Function Nmc_4BPExecMC8500P(ByVal No As Integer, ByVal IcNo As Integer, ByVal pData4Bp As DATA_4BP(), ByVal DataCnt As Integer, ByVal IpAxis As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_4BPExecMC8500P(int No, int IcNo, DATA_4BP[] pData4Bp, int DataCnt, int IpAxis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData4Bp Pointer to an array of DATA_4BP structures (user-defined type in VB). Set the 4-axis BP interpolation data to DATA_4BP. See [5.1.3] (3) for DATA_4BP.</p> <p>DataCnt The number of 4-axis BP interpolation data. Specify the number of the DATA_4BP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>Return Value</p> <p>If the function succeeds, the return value is BP_END. If the function fails, the return value is the following Error code. For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> BP_END BP interpolation has been successfully completed. ■ Error code <ul style="list-style-type: none"> BP_CNT_ERR The number of the specified data is out of range. BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. BP_MALLOC_ERR Memory cannot be collocated. BP_PARAM_ERR The parameter is incorrect. BP_NOT_OPEN_ERR The specified board is not opened. BP_OTHER_ERR Other errors. BP_STOP BP interpolation stopped during driving (too fast to stack next data). BP_USER_STOP The user aborted BP interpolation. BP_DRIVE_ERR Error occurred in the board during BP interpolation. (When the error status was set to RR0.) BP_STOP_CERR BP interpolation stopped during driving. (Due to RR2 error.) BP_GETSC_ERR Stack counter reading error <p>When interpolation is terminated if end code is written, error code, BP_END or BP_STOP, is returned.</p> <p>Example</p> <pre>[VC] // 4 axis BP interpolation data BP1P, BP1M, BP2P, BP2M, BP3P, BP3M, BP4P, BP4M DATA_4BP Data4Bp[2] = {{0xFFE4, 0x0000, 0x03FF, 0x4000, 0x0000, 0xFFFF, 0xFE80, 0x000F}, {0x0000, 0x03FF, 0xFFD0, 0x0000, 0x4AAB, 0x0000, 0x1FFF, 0x0000}}}; Nmc_IPMode(No, IcNo,0x000F); // Interpolation mode setting. Assign X, Y, Z and U axis. // Parameter setting related to speed(The actual setting description is omitted)</pre>

```

// Execute 4-axis BP interpolation. The number of data is 2, X, Y, Z, U axes.

Ret = Nmc_4BPExecMC8500P(No, IcNo, Data4Bp, 2, 0xF);    if(Ret == BP_END)

AfxMessageBox("Successful completion ");    // Return value is correct.

[VB.NET]
'4-axis BP interpolation data
Dim Data4Bp(1) As DATA_4BP
Data4Bp(0).Bp1p = &HFFE4S
Data4Bp(0).Bp1m = 0
Data4Bp(0).Bp2p = &H3FFS
Data4Bp(0).Bp2m = &H4000S
Data4Bp(0).Bp3p = 0
Data4Bp(0).Bp3m = &HFFFFS
Data4Bp(0).Bp4p = &HFE80S
Data4Bp(0).Bp4m = &H000FS

Data4Bp(1).Bp1p = 0
Data4Bp(1).Bp1m = &H3FFS
Data4Bp(1).Bp2p = &HFFD0S
Data4Bp(1).Bp2m = 0
Data4Bp(1).Bp3p = &H4AABS
Data4Bp(1).Bp3m = 0
Data4Bp(1).Bp4p = &H1FFFS
Data4Bp(1).Bp4m = 0

Call Nmc_IPMode(No, IcNo, &HF)    ' Interpolation mode setting. Assign X, Y, Z and U axis.

' Parameter setting related to speed(The actual setting description is omitted)

'Execute 4-axis BP interpolation. The number of data is 2, X, Y, Z, U axes.
Ret = Nmc_4BPExecMC8500P(No, IcNo, Data4Bp, 2, &HF)

If Ret = BP_END Then    ' Return value is correct
    Call MsgBox("Successful completion ")
End If

[C#]
DATA_4BP [] Data4Bp = new DATA_4BP[2];    // 4-axis BP interpolation data
// Interpolation data setting
Data4Bp[0].Bp1p = 0xFFE4;    // 1111 1111 1110 0100    BP1 +direction    12pulse
Data4Bp[0].Bp1m = 0;    // 0000 0000 0000 0000    BP1 +direction    0pulse
Data4Bp[0].Bp2p = 0x03FF;    // 0000 0011 1111 1111 BP2 +direction    10pulse
Data4Bp[0].Bp2m = 0x4000;    // 0100 0000 0000 0000    BP2 -direction    1pulse
Data4Bp[0].Bp3p = 0;    // 0000 0000 0000 0000    BP3 +direction    0pulse
Data4Bp[0].Bp3m = 0xFFFF;    // 1111 1111 1111 1111 BP3 -direction    16pulse
Data4Bp[0].Bp4p = 0xFE80;    // 1111 1110 1000 0000    BP4 +direction    6pulse
Data4Bp[0].Bp4m = 0x000F;    // 0000 0000 0000 1111    BP4 -direction    4pulse

Data4Bp[1].Bp1p = 0;    // 0000 0000 0000 0000    BP1 +direction    0pulse
Data4Bp[1].Bp1m = 0x03FF;    // 0000 0011 1111 1111 BP1 -direction    10pulse
Data4Bp[1].Bp2p = 0xFFD0;    // 1111 1111 1101 0000 BP2 +direction    11pulse
Data4Bp[1].Bp2m = 0;    // 0000 0000 0000 0000    BP2 -direction    0pulse
Data4Bp[1].Bp3p = 0x4AAB;    // 0100 1010 1010 1011    BP3 +direction    8pulse
Data4Bp[1].Bp3m = 0;    // 0000 0000 0000 0000    BP3 -direction    0pulse
Data4Bp[1].Bp4p = 0x1FFF;    // 0001 1111 1111 1111 BP4 +direction    13pulse
Data4Bp[1].Bp4m = 0;    // 0000 0000 0000 0000    BP4 -direction    0pulse

MC8000P.Nmc_IPMode(No, IcNo, 0x000F);    // Interpolation mode setting.
// Assign X,Y,Z and U axis.

// Parameter setting related to speed(The actual setting description is omitted)

Ret = MC8000P.Nmc_4BPExecMC8500P(No, IcNo, Data4Bp, 1, 0xF); // Execute 4-axis BP
interpolation.

```

	<pre>if(Ret == Nmc_Status.BP_END) // Return value is correct</pre> <p>Note</p> <p>Make sure to set interpolation axis and so on in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.</p> <p>This function operates in constant speed driving. Set speed parameter to constant speed drive.</p>
--	--

Function Name	Function and Content
Nmc_2BPExecMC8500P_BG	<p>Execute 2-axis bit pattern interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_BP_END message is sent to the specified window at the end of the interpolation and finishing status is passed.</p> <p>VC DWORD Nmc_2BPExecMC8500P_BG(HWND User_hWnd, int No, int IcNo, DATA_2BP* pData2Bp, int DataCnt, int IpAxis);</p> <p>VB.NET Function Nmc_2BPExecMC8500P_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByVal pData2Bp As DATA_2BP(), ByVal DataCnt As Integer, ByVal IpAxis As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_2BPExecMC8500P_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_2BP[] pData2Bp, int DataCnt, int IpAxis);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0-15) on the board)</p> <p>IcNo IC number (0-1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData2Bp Pointer to an array of DATA_2BP structures (user-defined type in VB). Set the 2-axis BP interpolation data to DATA_2BP. See [5.1.3] (3) for DATA_2BP.</p> <p>DataCnt The number of 2-axis BP interpolation data. Specify the number of the DATA_2BP structure (user-defined type) array.</p>

IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).

Return Value

If the interpolation process has been successfully started in the background, the return value is BP_START.

If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See [5.1.3] (1).

■ Normal start

BP_START BP interpolation has been successfully started in the background.

■ Error code (errors before starting the interpolation)

BP_CNT_ERR The number of the specified data is out of range.

BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running.

BP_THREAD_ERR Thread cannot be started.

BP_MALLOC_ERR Memory cannot be allocated.

BP_PARAM_ERR The parameter is incorrect.

BP_NOT_OPEN_ERR The specified board is not opened.

BP_OTHER_ERR Other errors.

BP_FUNC_ERR Unusable function is used.

After the interpolation process has been successfully started in the background, WM_BP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_BP_END message received function and finishing status is passed to the second argument.

If the interpolation has been successfully completed, the finishing status is BP_END.

If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.

■ Normal end

BP_END BP interpolation has been successfully completed.

■ Error code (errors after starting the interpolation)

BP_STOP BP interpolation stopped during driving (too fast to stack next data).

BP_USER_STOP The user aborted BP interpolation.

BP_DRIVE_ERR Error occurred in the board during BP interpolation. (When the error status was set to RR0.)

BP_STOP_CERR BP interpolation stopped during driving. (Due to RR2 error.)

BP_GETSC_ERR Stack counter reading error

When interpolation is terminated if end code is written, error code, BP_END or BP_STOP, is returned.

Example

```
[VC]
{
    // 2-axis BP interpolation data BP1P, BP1M, BP2P, BP2M
    DATA_2BP Data2Bp[2] = {{0x0000, 0x2BFF, 0xFFD4, 0x0000},
                          {0xF6FE, 0x0000, 0x000F, 0x3FC0}};

    Nmc_IPMode(No, IcNo, 0x0003); // Interpolation mode setting. Assign
X and Y axis.

    // Parameter setting related to speed(The actual setting description is omitted)

    Ret = Nmc_2BPExecMC8500P_BG(hWnd, No, IcNo, Data2Bp, 2, 0x3);
    // Execute 2-axis BP interpolation. The number of data is 2, X, Y axes

    if(Ret == BP_START) AfxMessageBox("Interpolation has started ");
    // Return value is correct. (Interpolation has started)
}

BEGIN_MESSAGE_MAP(CMC_SAMPLEDlg, CDialog) // WM_BP_END message
```

```

received function setting
    ON_MESSAGE( WM_BP_END, OnMsg_BP )
END_MESSAGE_MAP()

// WM_BP_END message received function
afx_msg LRESULT CMC_SAMPLEDlg::OnMsg_BP(WPARAM BoardNo, LPARAM Status)
{
    if(Status == BP_END)    AfxMessageBox("Interpolation has been successfully completed");
        // Return value is correct. (Interpolation has finished)
    return 0;
}

[VB.NET]
'2-axis BP interpolation data
Dim Data2Bp(1) As DATA_2BP
Data2Bp(0).Bp1p = 0
Data2Bp(0).Bp1m = &H2BFFS
Data2Bp(0).Bp2p = &HFFD4S
Data2Bp(0).Bp2m = 0

Data2Bp(1).Bp1p = &HF6FES
Data2Bp(1).Bp1m = 0
Data2Bp(1).Bp2p = &HFS
Data2Bp(1).Bp2m = &H3FC0S
Call Nmc_IPMode(No, IcNo, &H3)           ' Interpolation mode setting. Assign X
                                         and Y axis.

' Parameter setting related to speed(The actual setting description is omitted)

' Execute 2-axis BP interpolation. The number of data is 2, X, Y axes
Ret = Nmc_2BPExecMC8500P_BG(Handle.ToInt32, No, IcNo, Data2Bp, 2, &H3)
If Ret = BP_START Then    ' Return value is correct (Interpolation has started)
    Call MsgBox("Interpolation has started ")
End If
End Sub

' WM_BP_END message received function
Protected Overrides Sub WndProc(ByRef m As Message)
    Select Case (m.Msg)
        Case WM_BP_END           'BP completion message.
            If m.LParam.ToInt32 = BP_END Then    ' Return value is correct. (Interpolation
                has started)
                Call MsgBox("Interpolation has been successfully completed")
            End If
        Exit Select
    End Select
    MyBase.WndProc(m)
End Sub

[C#]
DATA_2BP [] Data2Bp = new DATA_2BP[2];           // 2-axis BP interpolation
data
// Interpolation data setting
Data2Bp[0].Bp1p = 0;           // 0000 0000 0000 0000  BP1 +direction  0pulse
Data2Bp[0].Bp1m = 0x2BFF;     // 0010 1011 1111 1111  BP1 -direction  12pulse
Data2Bp[0].Bp2p = 0xFFD4;     // 1111 1111 1101 0100  BP2 +direction  12pulse
Data2Bp[0].Bp2m = 0;         // 0000 0000 0000 0000  BP2 -direction  0pulse

Data2Bp[1].Bp1p = 0xF6FE;     // 1111 0110 1111 1110  BP1 +direction  13pulse
Data2Bp[1].Bp1m = 0;         // 0000 0000 0000 0000  BP1 -direction  0pulse
Data2Bp[1].Bp2p = 0xF;       // 0000 0000 0000 1111  BP2 +direction  4pulse

```

	<pre> Data2Bp[1].Bp2m = 0x3FC0; // 0011 1111 1100 0000 BP2 -direction 8pulse MC8000P.Nmc_IPMode(No, IcNo, 0x0003); // Interpolation mode setting. Assign X and Y axis. // Parameter setting related to speed(The actual setting description is omitted) // Execute 2-axis BP interpolation in the background. Ret = MC8000P.Nmc_2BPExecMC8500P_BG((System.IntPtr)parent.Handle, No, IcNo, Data2Bp,2,0x3); if(Ret == Nmc_Status.BP_START) // Interpolation has successfully started. // WM_BP_END message received function protected override void WndProc(ref Message m) { // C Call original WndProc (call a constructor explicitly) base.WndProc (ref m); if (m.Msg == (int)MSG_ID.WM_BP_END) { if((uint)m.LParam == Nmc_Status.BP_END) // BP interpolation has been successfully completed. } } </pre> <p>Note</p> <p>Make sure to set interpolation axis and so on in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.</p> <p>This function operates in constant speed driving. Set speed parameter to constant speed drive.</p>
--	--

Function Name	Function and Content
Nmc_3BPExecMC8500P_BG	<p>Execute 3-axis bit pattern interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_BP_END message is sent to the specified window at the end of the interpolation and finishing status is passed.</p> <p>VC DWORD Nmc_3BPExecMC8500P_BG(HWND User_hWnd, int No, int IcNo, DATA_3BP* pData3Bp, int DataCnt, int IpAxis);</p> <p>VB.NET Function Nmc_3BPExecMC8500P_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByVal pData3Bp As DATA_3BP(), ByVal DataCnt As Integer, ByVal IpAxis As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3BPExec_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_3BP[] pData3Bp, int DataCnt, int IpAxis,);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData3Bp Pointer to an array of DATA_3BP structures (user-defined type in VB). Set the 3-axis BP interpolation data to DATA_3BP. See [5.1.3] (3) for DATA_3BP.</p> <p>DataCnt The number of 2-axis BP interpolation data. Specify the number of the DATA_3BP structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is BP_START.</p> <p>If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal start <ul style="list-style-type: none"> BP_START BP interpolation has been successfully started in the background. ■ Error code (errors before starting the interpolation) <ul style="list-style-type: none"> BP_CNT_ERR The number of the specified data is out of range. BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. BP_THREAD_ERR Thread cannot be started. BP_MALLOC_ERR Memory cannot be allocated. BP_PARAM_ERR The parameter is incorrect. BP_NOT_OPEN_ERR The specified board is not opened. BP_OTHER_ERR Other errors. BP_FUNC_ERR Unusable function is used. <p>After the interpolation process has been successfully started in the background, WM_BP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_BP_END message received function and finishing status is passed to the second argument.</p> <p>If the interpolation has been successfully completed, the finishing status is BP_END.</p> <p>If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> BP_END BP interpolation has been successfully completed. ■ Error code (errors after starting the interpolation) <ul style="list-style-type: none"> BP_STOP BP interpolation stopped during driving (too fast to stack next data). BP_USER_STOP The user aborted BP interpolation. BP_DRIVE_ERR Error occurred in the board during BP interpolation. (When the error status was set to RR0.)

BP_STOP_CERR BP interpolation stopped during driving. (Due to RR2 error.)
 BP_GETSC_ERR Stack counter reading error

When interpolation is terminated if end code is written, error code, BP_END or BP_STOP, is returned

Example

[VC]

```
{
  // 3-axis BP interpolation data  BP1P,  BP1M,  BP2P,  BP2M,  BP3P,  BP3M
  DATA_3BP Data3Bp[2] = {{0xFF30, 0x0000, 0x0000, 0x84FF, 0x0000, 0xAC35},
                          {0xAC35, 0x0000, 0xC000, 0x36E7, 0xC000, 0x3F3F}};

  Nmc_IPMode(No, IcNo, 0x0007); // Interpolation mode setting. Assign X, Y
and Z axis.

  // Parameter setting related to speed(The actual setting description is omitted)

  Ret = Nmc_3BPExecMC8500P_BG(hWnd, No, IcNo, Data3Bp, 2, 0x7);
  // Execute 3-axis BP interpolation. The number of data is 2, X, Y,Z axes
  if(Ret == BP_START)  AfxMessageBox("Interpolation has started ");
  // Return value is correct. (Interpolation has started)
}
```

```
BEGIN_MESSAGE_MAP(CMC_SAMPLEDlg, CDialog)
```

```
// WM_BP_END message received function setting
```

```
ON_MESSAGE( WM_BP_END, OnMsg_BP )
```

```
END_MESSAGE_MAP()
```

```
// WM_BP_END message received function
```

```
afx_msg LRESULT CMC_SAMPLEDlg::OnMsg_BP(WPARAM BoardNo, LPARAM Status)
```

```
{
  if(Status == BP_END)  AfxMessageBox("Interpolation has been successfully completed");
  // Return value is correct. (Interpolation has finished)
  return 0;
}
```

[VB.NET]

```
'3-axis BP interpolation data
Dim Data3Bp (1) As DATA_3BP
Data3Bp(0).Bp1p = &HFF30S
Data3Bp(0).Bp1m = 0
Data3Bp(0).Bp2p = 0
Data3Bp(0).Bp2m = &H84FFS
Data3Bp(0).Bp3p = 0
Data3Bp(0).Bp3m = &HAC35S
```

```
Data3Bp(1).Bp1p = &H0xAC35S
Data3Bp(1).Bp1m = 0
Data3Bp(1).Bp2p = &HC000S
Data3Bp(1).Bp2m = &H36E7S
Data3Bp(1).Bp3p = &HC000S
Data3Bp(1).Bp3m = &H3F3FS
```

```
Call Nmc_IPMode(No, IcNo, &H7) ' Interpolation mode setting. Assign X, Y
and Z axis
```

```
' Parameter setting related to speed(The actual setting description is omitted)
```

```
' Execute 3-axis BP interpolation. The number of data is 2, X, Y, Z axes
```

```
Ret = Nmc_3BPExecMC8500P_BG(Handle.ToInt32, No, IcNo, Data3Bp, 2, &H7)
```

	<pre> If Ret = BP_START Then ' Return value is correct (Interpolation has started) Call MsgBox("Interpolation has started ") End If End Sub ' WM_BP_END message received function Protected Overrides Sub WndProc(ByRef m As Message) Select Case (m.Msg) Case WM_BP_END ' BP completion message If m.LParam.ToInt32 = BP_END Then ' Return value is correct. (Interpolation Call MsgBox("Interpolation has been successfully completed ") End If Exit Select End Select MyBase.WndProc(m) End Sub [C#] DATA_3BP [] Data3Bp = new DATA_3BP[2]; // 3-axis BP interpolation data // Interpolation data setting Data3Bp[0].Bp1p = 0xFF30; // 1111 1111 0011 0000 BP1 +direction 10pulse Data3Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 -direction 0pulse Data3Bp[0].Bp2p = 0; // 0000 0000 0000 0000 BP2 +direction 0pulse Data3Bp[0].Bp2m = 0x84FF; // 1000 0100 1111 1111 BP2 -direction 10pulse Data3Bp[0].Bp3p = 0; // 0000 0000 0000 0000 BP3 +direction 0pulse Data3Bp[0].Bp3m = 0xAC35; // 1010 1100 0011 0101 BP3 -direction 8pulse Data3Bp[1].Bp1p = 0xAC35; // 1010 1100 0011 0101 BP1 +direction 8pulse Data3Bp[1].Bp1m = 0; // 0000 0000 0000 0000 BP1 -direction 0pulse Data3Bp[1].Bp2p = 0xC000; // 1100 0000 0000 0000 BP2 +direction 2pulse Data3Bp[1].Bp2m = 0x36E7; // 0011 0110 1110 0111 BP2 -direction 10pulse Data3Bp[1].Bp3p = 0xC000; // 1100 0000 0000 0000 BP3 +direction 2pulse Data3Bp[1].Bp3m = 0x3F3F; // 0011 1111 0011 1111 BP3 -direction 12pulse MC8000P.Nmc_IPMode(No, IcNo,0x0007); // Interpolation mode setting. Assign X, Y and Z axis // Parameter setting related to speed(The actual setting description is omitted) // Execute 3-axis BP interpolation in the background. Ret = MC8000P.Nmc_3BPExecMC8500P_BG((System.IntPtr)parent.Handle, No, IcNo, Data3Bp,2,0x7); if(Ret == Nmc_Status.BP_START) // Interpolation has successfully started. // WM_BP_END message received function protected override void WndProc(ref Message m) { // C Call original WndProc (call a constructor explicitly) base.WndProc (ref m); if (m.Msg == (int)MSG_ID.WM_BP_END) { if((uint)m.LParam == Nmc_Status.BP_END) // BP interpolation has been successful completed. } } if(Ret == Nmc_Status.BP_END) // Return value is correct </pre> <p>Note</p> <p>Make sure to set interpolation axis and so on in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.</p> <p>This function operates in constant speed driving. Set speed parameter to constant speed drive.</p>
--	---

Function Name	Function and Content
Nmc_4BPExecMC8500P_BG	<p>Execute 4-axis bit pattern interpolation in the background using the specified interpolation data. This function returns control right after the interpolation process started and executes the interpolation in the background. WM_BP_END message is sent to the specified window at the end of the interpolation and finishing status is passed.</p> <p>VC DWORD Nmc_4BPExecMC8500P_BG(HWND User_hWnd, int No, int IcNo, DATA_4BP* pData4Bp, int DataCnt, int IpAxis);</p> <p>VB.NET Function Nmc_4BPExecMC8500P_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByVal pData4Bp As DATA_4BP(), ByVal DataCnt As Integer, ByVal IpAxis As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_4BPExec_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_4BP[] pData4Bp, int DataCnt, int IpAxis,);</p> <p>Input parameter</p> <p>User_hWnd Window handle of user application. No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. pData4Bp Pointer to an array of DATA_4BP structures (user-defined type in VB). Set the 4-axis BP interpolation data to DATA_4BP. See [5.1.3] (3) for DATA_4BP. DataCnt The number of 2-axis BP interpolation data. Specify the number of the DATA_4BP structure (user-defined type) array. IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is BP_START. If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation).For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal start <ul style="list-style-type: none"> BP_START BP interpolation has been successfully started in the background ■ Error code (errors before starting the interpolation) <ul style="list-style-type: none"> BP_CNT_ERR The number of the specified data is out of range. BP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. BP_THREAD_ERR Thread cannot be started. BP_MALLOC_ERR Memory cannot be allocated. BP_PARAM_ERR The parameter is incorrect. BP_NOT_OPEN_ERR The specified board is not opened. BP_OTHER_ERR Other errors. BP_FUNC_ERR Unusable function is used <p>After the interpolation process has been successfully started in the background, WM_BP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_BP_END message received function and finishing status is passed to the second argument. If the interpolation has been successfully completed, the finishing status is BP_END. If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> BP_END BP interpolation has been successfully completed. ■ Error code (errors after starting the interpolation) <ul style="list-style-type: none"> BP_STOP BP interpolation stopped during driving (too fast to stack next data).

	<pre> Data4Bp(1).Bp2p = &HFFD0S Data4Bp(1).Bp2m = 0 Data4Bp(1).Bp3p = &H4AABS Data4Bp(1).Bp3m = 0 Data4Bp(1).Bp4p = &H1FFFS Data4Bp(1).Bp4m = 0 Call Nmc_IPMode(No, IcNo, &HF) ' Interpolation mode setting. Assign X, Y, Z and U axis ' Parameter setting related to speed(The actual setting description is omitted) 'Execute 4-axis BP interpolation. The number of data is 2, X, Y, Z, U axes Ret = Nmc_4BPExecMC8500P_BG(Handle.ToInt32, No, IcNo, Data4Bp, 2, &HF) If Ret = BP_START Then ' Return value is correct (Interpolation has started) Call MsgBox("Interpolation has started ") End If End Sub ' WM_BP_END message received function Protected Overrides Sub WndProc(ByRef m As Message) Select Case (m.Msg) Case WM_BP_END ' BP completion message If m.LParam.ToInt32 = BP_END Then ' Return value is correct. (Interpolation has started) Call MsgBox("Interpolation has been successfully completed ") End If Exit Select End Select MyBase.WndProc(m) End Sub [C#] DATA_4BP [] Data4Bp = new DATA_4BP[2]; // 4-axis BP interpolation data // Interpolation data setting 12pulse Data4Bp[0].Bp1p = 0xFFE4; // 1111 1111 1110 0100 BP1 +direction Data4Bp[0].Bp1m = 0; // 0000 0000 0000 0000 BP1 -direction 0pulse Data4Bp[0].Bp2p = 0x03FF; // 0000 0011 1111 1111 BP2 +direction 10pulse Data4Bp[0].Bp2m = 0x4000; // 0100 0000 0000 0000 BP2 -direction 1pulse Data4Bp[0].Bp3p = 0; // 0000 0000 0000 0000 BP3 +direction 0pulse Data4Bp[0].Bp3m = 0xFFFF; // 1111 1111 1111 1111 BP3 -direction 16pulse 8pulse Data4Bp[0].Bp4p = 0xFE80; // 1111 1110 1000 0000 BP3 +direction 4pulse Data4Bp[0].Bp4m = 0x000F; // 0000 0000 0000 1111 BP3 -direction 8pulse Data4Bp[1].Bp1p = 0; // 0000 0000 0000 0000 BP1 +direction 10pulse Data4Bp[1].Bp1m = 0x03FF; // 0000 0011 1111 1111 BP1 -direction 11pulse Data4Bp[1].Bp2p = 0xFFD0; // 1111 1111 1101 0000 BP2 +direction 0pulse Data4Bp[1].Bp2m = 0; // 0000 0000 0000 0000 BP2 -direction 8pulse Data4Bp[1].Bp3p = 0x4AAB; // 0100 1010 1010 1011 BP3 +direction 0pulse Data4Bp[1].Bp3m = 0; // 0000 0000 0000 0000 BP3 -direction 13pulse Data4Bp[1].Bp4p = 0x1FFF; // 0001 1111 1111 1111 BP3 +direction 0pulse Data4Bp[1].Bp4m = 0; // 0000 0000 0000 0000 BP3 -direction MC8000P.Nmc_IPMode(No, IcNo, 0x000F); // Interpolation mode setting. Assign X, Y Z and U axis </pre>
--	---

```

// Parameter setting related to speed(The actual setting description is omitted)

// Execute 4-axis BP interpolation in the background.
Ret = MC8000P.Nmc_4BPExecMC8500P_BG((System.IntPtr)parent.Handle,No,
IcNo,Data3Bp,2,0xF);

if(Ret == Nmc_Status.BP_START) // Interpolation has
successfully started.

// WM_BP_END message received function
protected override void WndProc(ref Message m)
{
// C Call original WndProc (call a constructor explicitly)
base.WndProc ( ref m );
if ( m.Msg == (int)MSG_ID.WM_BP_END )
{
if((uint)m.LParam == Nmc_Status.BP_END) // BP interpolation has been
successfully completed.

}
}

if(Ret == Nmc_Status.BP_END) // Return value is correct

```

Note

Make sure to set interpolation axis and so on in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.

This function operates in constant speed driving. Set speed parameter to constant speed drive.

Function Name	Function and Content
Nmc_2CIPExecMC8500P	<p>Execute 2-axis continuous interpolation using the specified interpolation data. This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_2CIPExecMC8500P(int No, int IcNo, DATA_2CIP_MC8500P* pData2Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE);</p> <p>VB.NET Function Nmc_2CIPExecMC8500P(ByVal No As Integer, ByVal IcNo As Integer, ByVal pData2Cip As DATA_2CIP_MC8500P(), ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_2CIPExecMC8500P(int No, int IcNo, DATA_2CIP_MC8500P[] pData2Cip, int DataCnt, int IpAxis, bool SpdChgFlg);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData2Cip Pointer to an array (DATA_2CIP_MC8500P address) of DATA_2CIP_MC8500P structures (user-defined type). Set the 2-axis continuous interpolation data to DATA_2CIP_MC8500P. See [5.1.3] (3) for DATA_2CIP_MC8500P.</p> <p>DataCnt The number of 2-axis continuous interpolation data. Specify the number of the DATA_2CIP_MC8500P structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See [5.1.3] (5).</p> <p>[VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE.</p> <p>[VB.NET] True: Change, False: Not change</p> <p>[C#] true: Change, false: Not change</p> <p>When selecting Change : Refers to the setting value of DATA_2CIP_MC8500P Speed. Set 1~4000000 to Speed · · · Changes to the setting speed. Set 0 to Speed · · · · · Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_2CIP_MC8500 Speed.</p> <p>Return Value</p> <p>If the function succeeds, the return value is CIP_END. If the function fails, the return value is the following Error code. For C#, See [5.1.3] (1).</p> <p>■ Normal end</p> <p>CIP_END Continuous interpolation has been successfully completed.</p> <p>■ Error code</p> <p>CIP_CNT_ERR The number of the specified data is out of range.</p> <p>CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running.</p> <p>CIP_MALLOC_ERR Memory cannot be allocated.</p> <p>CIP_CMD_ERR The wrong command was specified.</p> <p>CIP_PARAM_ERR The parameter is incorrect.</p> <p>CIP_NOT_OPEN_ER The specified board is not opened.</p> <p>CIP_OTHER_ERR Other errors.</p> <p>CIP_FUNC_ERR Unusable function is used.</p> <p>CIP_STOP Continuous interpolation stopped during driving</p> <p>CIP_USER_STOP The user aborted continuous interpolation.</p> <p>CIP_DRIVE_ERR Error occurred in the board during continuous interpolation. (When the error status was set to RR0.)</p> <p>CIP_STOP_CERR Continuous interpolation stopped during driving. (Due to RR2 error.)</p> <p>CIP_GETSC_ERR Stack counter reading error</p>

Note

Set 4,000,000 to initial speed value before executing this function. (Don't change initial speed during executing this function). See [5.1.4] for more details.

Example

```
[VC]
// 2-axis continuous interpolation data Command, Speed, Finishing point 1, Finishing point 2, Center point
1, Center point 2
DATA_2CIP_MC8500P Data2Cip[2]={{MC8500P_CMD_2CIP, 0, 4500, 0, 0, 0},
//2-axis linear interpolation
{MC8500P_CMD_CIPCCW, 0, 1500, 1500, 0, 1500}};
// CCW circular interpolation

Nmc_IPMode(No, IcNo, 0x0003); //Interpolation mode setting. Assign X
Y axes.

// Parameter setting related to speed
Nmc_StartSpd(No, IcNo, AXIS_X, 4000000); // Set 4M to execute constant
speed drive
// The other setting description is omitted

Ret = Nmc_2CIPExecMC8500P(No, IcNo, Data2Cip, 2, 0x3);
// Execute 2-axis continuous interpolation. The number of data is 2, X, Y axes

if(Ret == CIP_END) AfxMessageBox("Interpolation has finished"); // Return value is
correct.

[VB.NET]
'2-axis continuous interpolation data
Dim Data2Cip(1) As DATA_2CIP_MC8500P
Data2Cip(0).Command = MC8500P_CMD_2CIP '2-axis linear interpolation
Data2Cip(0).Speed = 0
Data2Cip(0).EndP1 = 4500
Data2Cip(0).EndP2 = 0
Data2Cip(0).Center1 = 0
Data2Cip(0).Center2 = 0

Data2Cip(1).Command = MC8500P_CMD_CIPCCW 'CCW circular interpolation
Data2Cip(1).Speed = 0
Data2Cip(1).EndP1 = 1500
Data2Cip(1).EndP2 = 1500
Data2Cip(1).Center1 = 0
Data2Cip(1).Center2 = 1500

Call Nmc_IPMode(No, IcNo, &H3) ' Interpolation mode setting. Assign X and Y axis

' Parameter setting related to speed
Call Nmc_StartSpd(No, IcNo, AXIS_X, 4000000) ' Set 4M to execute constant speed drive
'The other setting description is omitted.

'Execute 2-axis continuous interpolation. The number of data is 2, X, Y axes.

Ret = Nmc_2CIPExecMC8500P(No, IcNo, Data2Cip, 2, &H3, False)

If Ret = CIP_END Then ' Return value is correct.
Call MsgBox("Interpolation has finished")
End If

[C#]
DATA_2CIP_MC8500P [] Data2Cip = new DATA_2CIP_MC8500P[2];
```

	<pre> // 2-axis continuous interpolation data // Interpolation data setting. Data2Cip[0].Command = (ushort)CMD.MC8500P_CMD_2CIP; // 2-axis linear interpolation Data2Cip[0].EndP1 = 0; Data2Cip[0].EndP2 = 4500; Data2Cip[0].Center1 = 0; Data2Cip[0].Center2 = 0; Data2Cip[0].Speed = 0; Data2Cip[1].Command = (ushort)CMD.MC8500P_CMD_CIPCCW; // CCW circular interpolation Data2Cip[1].EndP1 = 1500; Data2Cip[1].EndP2 = 1500; Data2Cip[1].Center1 = 0; Data2Cip[1].Center2 = 1500; Data2Cip[1].Speed = 0; MC8000P.Nmc_IPMode(No, IcNo, 0x0003) // Interpolation mode setting. Assign X and Y axis. // Execute 2-axis continuous interpolation. // This function will not return control unless the interpolation process ends. Ret = MC8000P.Nmc_2CIPExecMC8500P(No, IcNo, Data2Cip, 2, 0x3, SpdChgFlg); if(Ret == Nmc_Status.CIP_END) // Continuous interpolation has been successfully completed Note Make sure to set interpolation axis in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis. This function operates in constant speed driving. Set speed parameter to constant speed drive. </pre>
--	---

Function Name	Function and Content
Nmc_3CIPExecMC8500P	<p>Execute 3-axis continuous interpolation using the specified interpolation data. This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_3CIPExecMC8500P(int No, int IcNo, DATA_3CIP_MC8500P* pData3Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE);</p> <p>VB.NET Function Nmc_3CIPExecMC8500P(ByVal No As Integer, ByVal IcNo As Integer, ByVal pData3Cip As DATA_3CIP_MC8500P(), ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3CIPExecMC8500P(int No, IcNo, DATA_3CIP_MC8500P[] pData3Cip, int DataCnt, int IpAxis, bool SpdChgFlg)</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData3Cip Pointer to an array (DATA_3CIP_MC8500P address) of DATA_3CIP_MC8500P structures (user-defined type). Set the 3-axis continuous interpolation data to DATA_3CIP_MC8500P. See [5.1.3] (3) for DATA_3CIP_MC8500P.</p> <p>DataCnt The number of 3-axis continuous interpolation data. Specify the number of the DATA_3CIP_MC8500P structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See [5.1.3] (5).</p> <p>[VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE.</p> <p>[VB.NET] True: Change, False: Not change</p> <p>[C#] true: Change, false: Not change</p> <p>When selecting Change : Refers to the setting value of DATA_3CIP_MC8500P Speed. Set 1~4000000 to Speed · · · Changes to the setting speed Set 0 to Speed · · · · · Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_3CIP_MC8500P Speed.</p> <p>Return Value</p> <p>If the function succeeds, the return value is CIP_END. If the function fails, the return value is the following Error code. For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> CIP_END Continuous interpolation has been successfully completed. ■ Error code <ul style="list-style-type: none"> CIP_CNT_ERR The number of the specified data is out of range. CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. CIP_MALLOC_ERR Memory cannot be allocated. CIP_CMD_ERR The wrong command was specified. CIP_PARAM_ERR The parameter is incorrect. CIP_NOT_OPEN_ER The specified board is not opened. CIP_OTHER_ERR Other errors. CIP_FUNC_ERR Unusable function is used. CIP_STOP Continuous interpolation stopped during driving CIP_USER_STOP The user aborted continuous interpolation. CIP_DRIVE_ERR Error occurred in the board during continuous interpolation. (When the error status was set to RR.)

Note

Set 4,000,000 to initial speed value before executing this function. (Don't change initial speed during executing this function). See [5.1.4] for more details.

Example

[VC]

```

DATA_3CIP_MC8500P Data3Cip[2];           // 3-axis continuous interpolation data
// 3-axis continuous interpolation data setting
Data3Cip[0].EndP1 = 1000;
Data3Cip[0].EndP2 = 2000;
Data3Cip[0].EndP3 = 3000;
Data3Cip[0].Speed = 0;

Data3Cip[1].EndP1 = 2000;
Data3Cip[1].EndP2 = -1000;
Data3Cip[1].EndP3 = 3000;
Data3Cip[1].Speed = 0;

Nmc_IPMode(No, IcNo, 0x0007);           // Interpolation mode setting. Assign X,
Y, Z axes.

// Parameter setting related to speed
Nmc_StartSpd(No, IcNo, AXIS_X, 4000000); // Set 4M to execute constant speed
drive
// The other
setting description is omitted.

Ret = Nmc_3CIPExecMC8500P(No, IcNo, Data3Cip, 2, 0x7);
// Execute 3-axis continuous interpolation. The number of data is 2, X, Y, Z axes
if(Ret == CIP_END)  AfxMessageBox("Interpolation has finished."); // Return value is correct

```

[VB.NET]

```

'3-axis continuous interpolation data setting
Dim Data3Cip(1) As DATA_3CIP_MC8500P
Data3Cip(0).EndP1 = 1000
Data3Cip(0).EndP2 = 2000
Data3Cip(0).EndP3 = 3000
Data3Cip(0).Speed = 0

Data3Cip(1).EndP1 = 2000
Data3Cip(1).EndP2 = -1000
Data3Cip(1).EndP3 = 3000
Data3Cip(1).Speed = 0

Call Nmc_IPMode(No, IcNo, &H7)           ' Interpolation mode setting. Assign
X, Y, Z axes.

' Parameter setting related to speed
Call Nmc_StartSpd(No, IcNo, AXIS_X, 4000000) ' Set 4M to execute constant
speed drive
'The other setting description is
omitted.

'Execute 3-axis continuous interpolation. The number of data is 2, X, Y, Z axes

Ret = Nmc_3CIPExecMC8500P(No, IcNo, Data3Cip, 2, &H7, False)

If Ret = CIP_END Then ' Return value is correct.
    Call MsgBox("Interpolation has finished ")
End If

```

```
[C#]
DATA_3CIP_MC8500P [] Data3Cip = new DATA_3CIP_MC8500P[2]; // 3-axis continuous
interpolation
// Interpolation mode setting
Data3Cip[0].EndP1 = 1000;
Data3Cip[0].EndP2 = 2000;
Data3Cip[0].EndP3 = 3000;
Data3Cip[0].Speed = 0;

Data3Cip[1].EndP1 = 2000;
Data3Cip[1].EndP2 = -1000;
Data3Cip[1].EndP3 = 3000;
Data3Cip[1].Speed = 0;

MC8000P.Nmc_IPMode(No, IcNo, 0x0007) // Interpolation mode setting. Assign
X, Y and Z axis

// Execute 3-axis continuous interpolation.
// This function will not return control unless the interpolation process ends.
Ret = MC8000P.Nmc_3CIPExecMC8500P(No, IcNo, Data3Cip, 2, 0x7, SpdChgFlg);

if(Ret == Nmc_Status.CIP_END) // Continuous interpolation has been
successfully completed
```

Note

Make sure to set interpolation axis in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.

This function operates in constant speed driving. Set speed parameter to constant speed drive.

Function Name	Function and Content
Nmc_4CIPExecMC8500P	<p>Execute 4-axis continuous interpolation using the specified interpolation data. This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_4CIPExecMC8500P(int No, int IcNo, DATA_4CIP_MC8500P* pData4Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE);</p> <p>VB.NET Function Nmc_4CIPExecMC8500P(ByVal No As Integer, ByVal IcNo As Integer, ByVal pData4Cip As DATA_4CIP_MC8500P(), ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_4CIPExecMC8500P(int No, IcNo, DATA_4CIP_MC8500P[] pData4Cip, int DataCnt, int IpAxis, bool SpdChgFlg);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board)</p> <p>IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>pData4Cip Pointer to an array (DATA_4CIP_MC8500P address) of DATA_4CIP_MC8500P structures (user-defined type). Set the 4-axis continuous interpolation data to DATA_4CIP_MC8500P. See [5.1.3] (3) for DATA_4CIP_MC8500P.</p> <p>DataCnt The number of 4-axis continuous interpolation data. Specify the number of the DATA_4CIP_MC8500P structure (user-defined type) array.</p> <p>IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4).</p> <p>SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See [5.1.3] (5).</p> <p>[VC] TRUE: Change, FALSE: Not change Can be omitted. Default is FALSE.</p> <p>[VB.NET] True: Change, False: Not change</p> <p>[C#] true: Change, false: Not change</p> <p>When selecting Change : Refers to the setting value of DATA_4CIP_MC8500P Speed. Set 1~4000000 to Speed · · · Changes to the setting speed. Set 0 to Speed · · · · · Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_4CIP_MC8500 Speed.</p> <p>Return Value</p> <p>If the function succeeds, the return value is CIP_END. If the function fails, the return value is the following Error code. For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal end <ul style="list-style-type: none"> CIP_END Continuous interpolation has been successfully completed. ■ Error code <ul style="list-style-type: none"> CIP_CNT_ERR The number of the specified data is out of range. CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. CIP_MALLOC_ERR Memory cannot be allocated. CIP_CMD_ERR The wrong command was specified. CIP_PARAM_ERR The parameter is incorrect. CIP_NOT_OPEN_ER The specified board is not opened. CIP_OTHER_ERR Other errors. CIP_FUNC_ERR Unusable function is used. CIP_STOP Continuous interpolation stopped during driving CIP_USER_STOP The user aborted continuous interpolation. CIP_DRIVE_ERR Error occurred in the board during continuous interpolation. (When the error status was set to RR0.) CIP_STOP_CERR Continuous interpolation stopped during driving. (Due to RR2 error.)

	<pre> Call MsgBox("Interpolation has finished ") End If [C#] DATA_4CIP_MC8500P [] Data4Cip = new DATA_4CIP_MC8500P[2]; // 4-axis continuous interpolation // Interpolation mode setting Data4Cip[0].EndP1 = 1000; Data4Cip[0].EndP2 = 2000; Data4Cip[0].EndP3 = 3000; Data4Cip[0].EndP4 = 3000; Data4Cip[0].Speed = 0; Data4Cip[1].EndP1 = 2000; Data4Cip[1].EndP2 = -1000; Data4Cip[1].EndP3 = 3000; Data4Cip[1].EndP4 = -2000; Data4Cip[1].Speed = 0; MC8000P.Nmc_IPMode(No, IcNo, 0x000F) // Interpolation mode setting. Assign X, Y, Z and U axis // Execute 4-axis continuous interpolation. // This function will not return control unless the interpolation process ends. Ret = MC8000P.Nmc_4CIPExecMC8500P(No, IcNo, Data4Cip, 2, 0xF, SpdChgFlg); if(Ret == Nmc_Status.CIP_END) // Continuous interpolation has been successfully completed </pre> <p>Note</p> <p>Make sure to set interpolation axis in interpolation mode setting (2A)H before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.</p> <p>This function operates in constant speed driving. Set speed parameter to constant speed drive</p>
--	--


```

Data2Cip(0).Command = MC8500P_CMD_2CIP '2-axis linear interpolation data
Data2Cip(0).Speed = 0 'Change speed
Data2Cip(0).EndP1 = 4500 ' Finishing point 1
Data2Cip(0).EndP2 = 0 ' Finishing point 2
Data2Cip(0).Center1 = 0 ' Center point 1
Data2Cip(0).Center2 = 0 ' Center point 2

Data2Cip(1).Command = MC8500P_CMD_CIPCCW ' CCW circular interpolation
Data2Cip(1).Speed = 0 ' Change speed
Data2Cip(1).EndP1 = 1500 ' Finishing point 1
Data2Cip(1).EndP2 = 1500 ' Finishing point 2
Data2Cip(1).Center1 = 0 ' Center point 1
Data2Cip(1).Center2 = 1500 ' Center point 2

Call Nmc_IPMode(No, IcNo, &H3) ' Interpolation mode setting. Assign X and Y
axis

' Parameter setting related to speed
Call Nmc_StartSpd(No, IcNo, AXIS_X, 4000000) ' Set 4M to execute constant speed drive
' The other setting description is omitted.
' Execute 2-axis continuous interpolation. The number of data is 2. X, Y axes
Ret = Nmc_2CIPExecMC8500P_BG(Handle.ToInt32, No, IcNo, Data2Cip, 2, &H3, False)

If Ret = CIP_START Then ' Return value is correct. (Interpolation has started.)
Call MsgBox("Interpolation has started ")
End If
End Sub

' WM_CIP_END message received function
Protected Overrides Sub WndProc(ByRef m As Message)
Select Case (m.Msg)
Case WM_CIP_END 'Continuous interpolation finish
message.
If m.LParam.ToInt32 = CIP_END Then ' Return value is correct. ("Interpolation
has finished")
Call MsgBox("Interpolation has finished")
End If
Exit Select
End Select
MyBase.WndProc(m)
End Sub

[C#]
DATA_2CIP_MC8500P [] Data2Cip = new DATA_2CIP_MC8500P[2];
// 2-axis continuous interpolation data
// Interpolation data setting
Data2Cip[0].Command = (ushort)CMD.MC8500P_CMD_2CIP; // 2-axis linear
interpolation
Data2Cip[0].EndP1 = 0;
Data2Cip[0].EndP2 = 4500;
Data2Cip[0].Center1 = 0;
Data2Cip[0].Center2 = 0;
Data2Cip[0].Speed = 0;

Data2Cip[1].Command = (ushort)CMD.MC8500P_CMD_CIPCCW; // CCW circular
interpolation
Data2Cip[1].EndP1 = 1500;
Data2Cip[1].EndP2 = 1500;
Data2Cip[1].Center1 = 0;

```

```
Data2Cip[1].Center2 = 1500;
Data2Cip[1].Speed = 0;

MC8000P.Nmc_IPMode(No, IcNo, 0x3);           // Interpolation mode setting. Assign X and
Y axis.

// Execute 2-axis continuous interpolation.
// This function will not return control unless the interpolation process ends
Ret = MC8000P.Nmc_2CIPExecMC8500P_BG(No, IcNo, Data2Cip, 2, 0x3, SpdChgFlg);

// WWM_CIP_END message received function
protected override void WndProc(ref Message m)
{
    // C Call original WndProc (call a constructor explicitly)
    base.WndProc ( ref m );
    if ( m.Msg == (int)MSG_ID.WM_CIP_END )
    {
        if((uint)m.LParam == Nmc_Status.CIP_END)
            // Continuous interpolation has been successfully completed.      }
    }
}
```

Note

Make sure to set interpolation axis and so on in interpolation mode setting before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.

This function operates in constant speed driving. Set speed parameter to constant speed drive.

Function Name	Function and Content
Nmc_3CIPExecMC8500P_BG G	<p>Execute 3-axis continuous interpolation in the background using the specified interpolation data. This function returns control after the interpolation process has finished. Control will not return unless the interpolation process ends, so it is recommended to create a thread in the application and call from the thread.</p> <p>VC DWORD Nmc_3CIPExecMC8500P_BG(HWND User_hWnd, int No, int IcNo, DATA_3CIP_MC8500P* pData3Cip, int DataCnt, int IpAxis, BOOL SpdChgFlg = FALSE);</p> <p>VB.NET Function Nmc_3CIPExecMC8500P_BG(ByVal User_hWnd As Integer, ByVal No As Integer, ByVal IcNo As Integer, ByVal pData3Cip As DATA_3CIP_MC8500P(), ByVal DataCnt As Integer, ByVal IpAxis As Integer, ByVal SpdChgFlg As Integer) As Integer</p> <p>C# Nmc_Status MC8000P.Nmc_3CIPExecMC8500P_BG(System.IntPtr User_hWnd, int No, int IcNo, DATA_3CIP_MC8500P[] pData3Cip, int IpAxis, bool SpdChgFlg);</p> <p>Input Parameter</p> <p>User_hWnd Window handle of the user application No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details. pData3Cip Pointer to an array (DATA_3CIP_MC8500P address) of DATA_3CIP_MC8500P structures (user-defined type). Set the 3-axis continuous interpolation data to DATA_3CIP_MC8500P. See [5.1.3] (3) for DATA_3CIP_MC8500P. DataCnt The number of 3-axis continuous interpolation data. Specify the number of the DATA_3CIP_MC8500P structure (user-defined type) array. IpAxis Axis to execute interpolation. Specify the same value as the setting value of D0~D3 (Axis assignment) of interpolation mode setting (2A). See [5.1.3] (4). SpdChgFlg Set the flag to change the speed during the interpolation process. If you change the speed, See [5.1.3] (5). [VC] TRUE: Change, FALSE: Not change. Can be omitted. Default is FALSE. [VB.NET] True: Change, False: Not change [C#] true: Change, false: Not change</p> <p>When selecting Change : Refers to the setting value of DATA_3CIP_MC8500P Speed. Set 1~4000000 to Speed · · · Changes to the setting speed. Set 0 to Speed · · · · · Not change the speed.</p> <p>When selecting Not change: Not refers to the setting value of DATA_3CIP_MC8500 Speed.</p> <p>Return Value</p> <p>If the interpolation process has been successfully started in the background, the return value is CIP_START. If an error occurred before starting the interpolation process, the return value is the following Error code (errors before starting the interpolation). For C#, See [5.1.3] (1).</p> <ul style="list-style-type: none"> ■ Normal start <ul style="list-style-type: none"> CIP_START Continuous interpolation has been successfully started in the background. ■ Error code (errors before starting the interpolation) <ul style="list-style-type: none"> CIP_CNT_ERR The number of the specified data is out of range. CIP_ALREADY_EXEC BP interpolation or continuous interpolation is already running. CIP_THREAD_ERR Thread cannot be started. CIP_MALLOC_ERR Memory cannot be allocated. CIP_CMD_ERR The wrong command was specified. CIP_PARAM_ERR The parameter is incorrect. CIP_NOT_OPEN_ERR The specified board is not opened. CIP_OTHER_ERR Other errors.

CIP_FUNC_ERR Unusable function is used.

After the interpolation process has been successfully started in the background, WM_CIP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_CIP_END message received function and finishing status is passed to the second argument.

If the interpolation has been successfully completed, the finishing status is CIP_END.

If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.

■ Normal end

CIP_END Continuous interpolation has been successfully completed.

■ Error code (errors after starting the interpolation)

CIP_USER_STOP The user aborted continuous interpolation.

CIP_DRIVE_ERR Error occurred in the board during continuous interpolation. (When the error status was set to RR0.)

CIP_STOP_CERR Continuous interpolation stopped during driving. (Due to RR2 error.)

CIP_GETSC_ERR Stack counter reading error

Note

Set 4,000,000 to initial speed value before executing this function. (Don't change initial speed during executing this function). See [5.1.4] for more details.

Example

```
[VC]
{
    DATA_3CIP_MC8500P Data3Cip[2];           // 3-axis continuous interpolation
data
    // 3-axis continuous interpolation data setting
    Data3Cip[0].EndP1 = 1000;
    Data3Cip[0].EndP2 = 2000;
    Data3Cip[0].EndP3 = 3000;

    Data3Cip[1].EndP1 = 2000;
    Data3Cip[1].EndP2 = -1000;
    Data3Cip[1].EndP3 = 3000;

    Nmc_IPMode(No, IcNo,0x0007);           // Interpolation mode setting. Assign
X, Y, Z axes.

    // Parameter setting related to speed
    Nmc_StartSpd(No, IcNo, AXIS_X, 4000000); // Set 4M to execute constant speed drive
// The
other setting description is omitted.
    Ret = Nmc_3CIPExecMC8500P_BG(hWnd,No, IcNo, Data3Cip, 2, 0x7);
    // Execute 3-axis continuous interpolation. The number of data is 2, X, Y, Z axes

    if(Ret == CIP_START)  AfxMessageBox("Interpolation has started");
    // Return value is correct(Interpolation has started)
}

BEGIN_MESSAGE_MAP(CMC_SAMPLEDlg, CDialog) // WM_CIP_END message received
function setting
    ON_MESSAGE( WM_CIP_END, OnMsg_CIP )
END_MESSAGE_MAP()

// WM_CIP_END message received function
afx_msg LRESULT CMC_SAMPLEDlg::OnMsg_CIP(WPARAM BoardNo, LPARAM Status)
{
```

```

if(Status == CIP_END)  AfxMessageBox("Interpolation has finished");
// Return value is correct. (Interpolation has finished)
return 0;
}

[VB.NET]
'3-axis BP interpolation data setting
Dim Data3Cip(1) As DATA_3CIP_MC8500P
Data3Cip(0).EndP1 = 10000
Data3Cip(0).EndP2 = 20000
Data3Cip(0).EndP3 = 30000
Data3Cip(0).Speed = 0

Data3Cip(1).EndP1 = 2000
Data3Cip(1).EndP2 = -1000
Data3Cip(1).EndP3 = 3000
Data3Cip(1).Speed = 0

Call Nmc_IPMode(No, IcNo, &H7)          ' Interpolation mode setting. Assign X,
                                         Y and Z axis.

' Parameter setting related to speed
Call Nmc_StartSpd(No, IcNo, AXIS_X, 4000000) ' Set 4M to execute constant speed drive
                                         'The other setting description is
omitted.

'Execute 3-axis continuous interpolation. The number of data is 2, X, Y, Z axes
Ret = Nmc_3CIPExecMC8500P_BG(Handle.ToInt32, No, IcNo, Data3Cip, 2, &H7, False)
If Ret = CIP_START Then                  ' Return value is correct. (Interpolation
has started.)
    Call MsgBox("Interpolation has started")
End If
End Sub

' WM_CIP_END message received function
Protected Overrides Sub WndProc(ByRef m As Message)
    Select Case (m.Msg)
        Case WM_CIP_END                  ' Continuous interpolation finish
message.
            If m.LParam.ToInt32 = CIP_END Then ' Return value is correct.
                ("Interpolation has finished")
                Call MsgBox("Interpolation has finished")
            End If
        Exit Select
    End Select
    MyBase.WndProc(m)
End Sub

[C#]
DATA_3CIP_MC8500P [] Data3Cip = new DATA_3CIP_MC8500P[2]; // 3-axis continuous
interpolation data // Interpolation data setting
Data3Cip[0].EndP1 = 1000;
Data3Cip[0].EndP2 = 2000;
Data3Cip[0].EndP3 = 3000;
Data3Cip[0].Speed = 0;

Data3Cip[1].EndP1 = 2000;
Data3Cip[1].EndP2 = -1000;
Data3Cip[1].EndP3 = 3000;
Data3Cip[1].Speed = 0;

```

```

MC8000P.Nmc_IPMode(No, IcNo, 0x0007);           // Interpolation mode setting. Assign
X, Y and Z axis.

// Execute 3-axis continuous interpolation.
// Execute in the background.
Ret = MC8000P.Nmc_3CIPExec_BG((System.IntPtr)parent.Handle, gBoardNo, int IcNo,
                             Data3Cip, 2, 0x7, SpdChgFlg, ContinueFlg);
if(Ret == Nmc_Status.CIP_START)
// Continuous interpolation has been successfully started.

// WM_CIP_END message received function
protected override void WndProc(ref Message m)
{
// Call original WndProc (call a constructor explicitly)
base.WndProc ( ref m );
if ( m.Msg == (int)MSG_ID.WM_CIP_END )
{
if((uint)m.LParam == Nmc_Status.CIP_END)
// Continuous interpolation has been successfully completed.
}
}
}

```

Note

Make sure to set interpolation axis and so on in interpolation mode setting before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.

This function operates in constant speed driving. Set speed parameter to constant speed drive.

CIP_NOT_OPEN_ERR The specified board is not opened.
 CIP_OTHER_ERR Other errors.
 CIP_FUNC_ERR Unusable function is used.

After the interpolation process has been successfully started in the background, WM_CIP_END message is sent to the specified window at the end of the interpolation. The board number is passed to the first argument received in WM_CIP_END message received function and finishing status is passed to the second argument.

If the interpolation has been successfully completed, the finishing status is CIP_END. If an error occurred during the interpolation process, the following Error code (errors after starting the interpolation) returns.

■ Normal end

CIP_END Continuous interpolation has been successfully completed.

■ Error code (errors after starting the interpolation)

CIP_USER_STOP The user aborted continuous interpolation.

CIP_DRIVE_ERR Error occurred in the board during continuous interpolation. (When the error status was set to RR0.)

CIP_STOP_CERR Continuous interpolation stopped during driving. (Due to RR2 error.)

CIP_GETSC_ERR Stack counter reading error

Note

Set 4,000,000 to initial speed value before executing this function. (Don't change initial speed during executing this function). See [5.1.4] for more details.

Example

```
[VC]
{
  DATA_4CIP_MC8500P Data4Cip[2];           // 4-axis continuous interpolation
data
  // 4-axis continuous interpolation data setting
  Data4Cip[0].EndP1 = 1000;
  Data4Cip[0].EndP2 = 2000;
  Data4Cip[0].EndP3 = 3000;
  Data4Cip[0].EndP4 = 4000;

  Data4Cip[1].EndP1 = 2000;
  Data4Cip[1].EndP2 = -1000;
  Data4Cip[1].EndP3 = 3000;
  Data4Cip[1].EndP4 = 4000;

  Nmc_IPMode(No, IcNo, 0x000F);           // Interpolation mode setting. Assign
X, Y, Z, U axes.

  // Parameter setting related to speed.
  Nmc_StartSpd(No, IcNo, AXIS_X, 4000000); // Set 4M to execute constant speed drive
// The
other setting description is omitted.
  Ret = Nmc_4CIPExecMC8500P_BG(hWnd, No, IcNo, Data4Cip, 2, 0xF);
  // Execute 4-axis continuous interpolation. The number of data is 2. X, Y, Z, U axes
  if(Ret == CIP_START)  AfxMessageBox("Interpolation has started");
  // Return value is correct. (Interpolation has started)
}

BEGIN_MESSAGE_MAP(CMC_SAMPLEDlg, CDialog)
// WM_CIP_END message received function setting.
  ON_MESSAGE( WM_CIP_END, OnMsg_CIP )
END_MESSAGE_MAP()

// WM_CIP_END message received function.
```

```

afx_msg LRESULT CMC_SAMPLEDIg::OnMsg_CIP(WPARAM BoardNo, LPARAM Status)
{
    if(Status == CIP_END)    AfxMessageBox("Interpolation has finished");
    // Return value is correct (Interpolation has finished")
    return 0;
}

[VB.NET]
' 4-axis continuous interpolation data
Dim Data4Cip(1) As DATA_4CIP_MC8500P
Data4Cip(0).EndP1 = 10000
Data4Cip(0).EndP2 = 20000
Data4Cip(0).EndP3 = 30000
Data4Cip(0).EndP4 = 40000
Data4Cip(0).Speed = 0

Data4Cip(1).EndP1 = 2000
Data4Cip(1).EndP2 = -1000
Data4Cip(1).EndP3 = 3000
Data4Cip(1).EndP4 = 4000
Data4Cip(1).Speed = 0

Call Nmc_IPMode(No, IcNo, &HF)           ' Interpolation mode setting. Assign X, Y, Z
                                         and U axis.

' Parameter setting related to speed
Call Nmc_StartSpd(No, IcNo, AXIS_X, 4000000) ' Set 4M to execute constant speed drive
                                             'The other setting description is omitted.

'Execute 4-axis continuous interpolation. The number of data is 2. X, Y, Z, U axes
Ret = Nmc_4CIPExecMC8500P_BG(Handle.ToInt32, No, IcNo, Data4Cip, 2, &HF, False)
If Ret = CIP_START Then    ' Return value is correct. (Interpolation has started.)
    Call MsgBox("Interpolation has started ")
End If
End Sub

' WM_CIP_END message received function.
Protected Overrides Sub WndProc(ByRef m As Message)
    Select Case (m.Msg)
        Case WM_CIP_END           ' Continuous interpolation finish
            message.
                If m.LParam.ToInt32 = CIP_END Then    ' Return value is correct.
                    ("Interpolation has finished")
                    Call MsgBox("Interpolation has finished ")
                End If
            Exit Select
        End Select
    MyBase.WndProc(m)
End Sub

[C#]
DATA_4CIP_MC8500P [] Data4Cip = new DATA_4CIP_MC8500P[2];
// 4-axis continuous interpolation data
// Interpolation data setting
Data4Cip[0].EndP1 = 1000;
Data4Cip[0].EndP2 = 2000;
Data4Cip[0].EndP3 = 3000;
Data4Cip[0].EndP4 = 3000;

```

```

Data4Cip[0].Speed = 0;

Data4Cip[1].EndP1 = 2000;
Data4Cip[1].EndP2 = -1000;
Data4Cip[1].EndP3 = 3000;
Data4Cip[1].EndP4 = -2000;
Data4Cip[1].Speed = 0;

MC8000P.Nmc_IPMode(No, IcNo, 0x000F);           // Interpolation mode setting. Assign
X, ,Y, Z and U axis

// This function will not return control unless the interpolation process ends.
// Execute 4-axis continuous interpolation.
// Execute in the background.
Ret = MC8000P.Nmc_4CIPExec_BG((System.IntPtr)parent.Handle, gBoardNo, int IcNo,
                             Data4Cip, 2, 0xF, SpdChgFlg, ContinueFlg);

if(Ret == Nmc_Status.CIP_START)
// Continuous interpolation has been successfully started.

// WM_BP_END message received function
protected override void WndProc(ref Message m)
{
    // Call original WndProc (call a constructor explicitly)
    base.WndProc ( ref m );
    if ( m.Msg == (int)MSG_ID.WM_CIP_END )
    {
        if((uint)m.LParam == Nmc_Status.CIP_END) // Continuous interpolation has been
successfully
    }
}

```

Note

Make sure to set interpolation axis and so on in interpolation mode setting before executing this function. Set the same value to axis to be set in interpolation mode setting and axis specified by argument IpAxis.

This function operates in constant speed driving. Set speed parameter to constant speed drive.

Function Name	Function and Content
Nmc_IPStop	<p>Stop the interpolation process during driving. The interpolation driving stops immediately and terminates the executed interpolation process in Nmc_XXX interpolation function.</p> <p>When stopping the interpolation process using Nmc_IPStop, the return value of each interpolation function is the following error code.</p> <ul style="list-style-type: none"> ◆ BP interpolation: BP_USER_STOP ◆ Continuous interpolation: CIP_USER_STOP <p>VC BOOL Nmc_IPStop(int No, int IcNo); VB.NET Function Nmc_IPStop(ByVal No As Integer, ByVal IcNo As Integer) As Integer C# bool MC8000P.Nmc_IPStop(int No, int IcNo);</p> <p>Input Parameter</p> <p>No Board number (setting value of rotary switch (0~15) on the board) IcNo IC number (0~1). Set 0 when the board has one IC. Set 0 to IC-A and 1 to IC-B when the board has 2 or more ICs. See [5.1.3] (7) for more details.</p> <p>Return value</p> <p>[VC] If the function succeeds, the return value is TRUE. If the function fails, the return value is FALSE. [VB.NET] If the function succeeds, the return value is nonzero. If the function fails, the return value is 0. [C#] If the function succeeds, the return value is true. If the function fails, the return value is false.</p> <p>Example</p> <pre>[VC] Nmc_IPStop(No, IcNo); // Stop the interpolation process during driving. [VB.NET] Call Nmc_IPStop(No, IcNo) ' Stop the interpolation process during driving. [C#] MC8000P.Nmc_IPStop(No, IcNo);</pre>
Nmc_IPGetMsgNo	<p>Read the board and IC number from the parameter wParam of the following received message at the end of the interpolation.</p> <ul style="list-style-type: none"> ◆BP interpolation : WM_BP_END ◆Continuous interpolation : WM_CIP_END <p>VC void Nmc_IPGetMsgNo(int wParam, int* No, int* IcNo); VB.NET Sub Nmc_IPGetMsgNo(ByVal wParam As Integer, ByRef No As Integer, ByRef IcNo As Integer) Integer) C# bool MC8000P.Nmc_IPGetMsgNo(int wParam, out int No, out int IcNo)</p> <p>Input Parameter</p> <p>wParam The parameter wParam of received message at the end of the Interpolation. No [VC] Address of a variable to store the board number. [VB.NET][C#] Variable to store the board number. IcNo [VC] Address of a variable to store the IC number. [VB.NET][C#] Variable to store the IC number.</p> <p>Return Value</p> <p>None</p> <p>Example</p> <pre>[VC] int BdNo; // Board number int IcNo; // IC number Nmc_IPGetMsgNo(wParam, &BdNo, &IcNo); [VB.NET] Dim BdNo As Integer ' Board number Dim IcNo As Integer ' IC number (0~1) Call Nmc_IPGetMsgNo(m.WParam.ToInt32(), BdNo, IcNo)</pre>

	<pre>[C#] int BdNo; // Board number int IcNo; // IC number (0~1) MC8000P.Nmc_IPGetMsgNo(WParam, out BdNo, out IcNo)</pre>
--	---


```

// Helical calculation value received
Value = DataHL.HIValue;           // Store the result to HI Value after calculation.

[VB.NET]
Dim IpMode As DATA_IPMODE      ' Interpolation mode
Dim DataHL As DATA_HL          ' Helical interpolation data

' Interpolation mode setting
IpMode.Cxiv = False             ' Interpolation axes are not changed.
IpMode.Lmdf = True              ' Enable short axis pulse equalization
IpMode.Vcnst = 3                ' 2-axis high accuracy constant vector speed
' Helical interpolation data setting
DataHL.Direction = HL_DIR_CCW   ' Rotation direction (CCW circular interpolation)
DataHL.Speed = 1000             ' Speed
DataHL.CenterX = 0              ' Center point of X axis
DataHL.CenterY = 10000          ' Center point of Y axis
DataHL.EndPX = 0                ' Finish point of X axis
DataHL.EndPY = 0                ' Finish point of Y axis
DataHL.MoveZ = 3000             ' Moving amount of Z axis
DataHL.MoveU = 400              ' Moving amount of U axis
DataHL.HINum = 1                ' Helical rotation number
DataHL.HIValue = 0              ' Helical calculation value
DataHL.IpMode = IpMode          ' Interpolation mode setting

' Execute helical calculation
Res = Nmc_HLValueExec(0, 0, DataHL)
If Res = HL_VALUE_END Then      ' Helical calculation has been successfully completed.
' Helical calculation value received
Value = DataHL.HIValue          ' Store the result to HI Value after calculation.
    Call MsgBox("Calculation has been finished. ")
End If

[C#]
DATA_HL DataHL = new DATA_HL();

// Helical interpolation data setting
DataHL.Direction = (ushort)HL_DIR.HL_DIR_CCW; // Rotation direction (CCW circular
interpolation)
DataHL.Speed = 1000;           // Speed
DataHL.CenterX = 0;           // Center point of X axis
DataHL.CenterY = 10000;      // Center point of Y axis
DataHL.EndPX = 0;            // Finish point of X axis
DataHL.EndPY = 0;            // Finish point of Y axis
DataHL.MoveZ = 3000;         // Moving amount of Z axis
DataHL.MoveU = 400;          // Moving amount of U axis
DataHL.HINum = 1;            // Helical rotation number
DataHL.HIValue = 0;          // Helical calculation value

// Interpolation mode setting
DataHL.IpMode.Cxiv = false;   // Interpolation axes are not changed.
DataHL.IpMode.Lmdf = true;    // Enable short axis pulse equalization
DataHL.IpMode.Vcnst = 3;     // 2-axis high accuracy constant vector speed

Ret = MC8000P.Nmc_HLValueExec(0, 0, ref DataHL);

if (Ret == Nmc_Status.HL_VALUE_END) // Helical calculation has been successfully completed.
{
// Helical calculation value received
Value = DataHL.HIValue;       // Store the result to HI Value after calculation
}

```

	<p>Note</p> <p>When executing this function, interpolation mode setting (2A)H is performed by the value of structures of helical interpolation data of argument. Interpolation mode setting which is set before executing this function, please note this.</p> <p>Don't call this function to the same IC during executing this function.</p>
--	--


```

Value = DataHL.HIValue;           // Store the result to HI Value after calculation

[VB.NET]
Dim IpMode As DATA_IPMODE       ' Interpolation mode
Dim DataHL As DATA_HL           ' Helical interpolation data

' Interpolation mode setting
IpMode.Cxiv = False              ' Interpolation axes are not changed.
IpMode.Lmdf = True               ' Enable short axis pulse equalization
IpMode.Vcnst = 3                 ' 2-axis high accuracy constant vector speed
' Helical interpolation data setting
DataHL.Direction = HL_DIR_CCW    ' Rotation direction (CCW circular interpolation)
DataHL.Speed = 1000              ' Speed
DataHL.CenterX = 0               ' Center point of X axis
DataHL.CenterY = 10000           ' Center point of Y axis
DataHL.EndPX = 0                 ' Finish point of X axis
DataHL.EndPY = 0                 ' Finish point of Y axis
DataHL.MoveZ = 3000              ' Moving amount of Z axis
DataHL.MoveU = 400               ' Moving amount of U axis
DataHL.HINum = 1                 ' Helical rotation number
DataHL.HIValue = 0               ' Helical calculation value
DataHL.IpMode = IpMode           ' Interpolation mode setting

' Execute helical calculation value
Res = Nmc_HLValueExec(0, 0, DataHL)
If Res = HL_VALUE_END Then       ' Helical calculation has been successfully completed.
    ' Helical calculation value received
    Value = DataHL.HIValue       ' Store the result to HI Value after calculation
    Call MsgBox("Calculation has been finished ")
End If

[C#]
DATA_HL DataHL = new DATA_HL();

// Helical interpolation data setting
DataHL.Direction = (ushort)HL_DIR.HL_DIR_CCW; // Rotation direction (CCW circular
interpolation)

DataHL.Speed = 1000;             // Speed
DataHL.CenterX = 0;              // Center point of X axis
DataHL.CenterY = 10000;         // Center point of Y axis
DataHL.EndPX = 0;               // Finish point of X axis
DataHL.EndPY = 0;               // Finish point of Y axis
DataHL.MoveZ = 3000;            // Moving amount of Z axis
DataHL.MoveU = 400;             // Moving amount of U axis
DataHL.HINum = 1;               // Helical rotation number
DataHL.HIValue = 0;             // Helical calculation value

// Interpolation mode setting
DataHL.IpMode.Cxiv = false;      // Interpolation axes are not changed.
DataHL.IpMode.Lmdf = true;       // Enable short axis pulse equalization
DataHL.IpMode.Vcnst = 3;        // 2-axis high accuracy constant vector speed

Ret = MC8000P.Nmc_HLValueExec(0, 0, ref DataHL);

if (Ret == Nmc_Status.HL_VALUE_END) // Helical calculation has been successfully completed.
{
    // Helical calculation value received
    Value = DataHL.HIValue;       // Store the result to HI Value after calculation

```

	<p data-bbox="501 159 512 181">}</p> <p data-bbox="435 226 488 248">Note</p> <p data-bbox="485 255 1469 344">When executing this function, interpolation mode setting (2A)H is performed by the value of structures of helical interpolation data of argument. Interpolation mode setting which is set before executing this function, please note this.</p> <p data-bbox="485 351 1171 374">Don't call this function to the same IC during executing this function.</p>
--	---

5.1.3 Footnote

(1) Each definition is defined in the following files.

```
VC++    · · · MC8000P_DLL.h
VB.NET · · · MC8000P_DLL.vb
C#     · · · Users can refer to or input each definition through the IntelliSense
```

VC++, VB.NET, and C# definitions are as follows:

① Register number

[VC]

```
#define MCX_WR0      0x0000 // WR0
#define MCX_WR1      0x0001 // WR1
#define MCX_WR2      0x0002 // WR2
#define MCX_WR3      0x0003 // WR3
#define MCX_WR4      0x0004 // WR4
#define MCX_WR5      0x0005 // WR5
#define MCX_WR6      0x0006 // WR6
#define MCX_WR7      0x0007 // WR7

#define MCX_RR0      0x0000 // RR0
#define MCX_RR1      0x0001 // RR1
#define MCX_RR2      0x0002 // RR2
#define MCX_RR3      0x0003 // RR3
#define MCX_RR4      0x0004 // RR4
#define MCX_RR5      0x0005 // RR5
#define MCX_RR6      0x0006 // RR6
#define MCX_RR7      0x0007 // RR7
```

[C#]

```
// ■Nmc_OutPort/Nmc_InPort
// When the board has one IC, use WR0_A ~| WR7_A/RR0_A ~ RR7_A
// When the board has 2 ICs, use WR0_A ~ WR7_A/RR0_A ~ RR7_A for IC_A, WR0_B ~ WR7_B/RR0_B ~ RR7_B for IC_B.
// ■Nmc_WriteReg/Nmc_ReadReg
// Use WR0 ~ WR7/RR0 ~ RR7
```

```
public enum REG_MCX : int
```

```
{
    //■Nmc_OutPort
    // Write register address
    // WR0~WR7 for IC-A
    WR0_A  =0x0000,
    WR1_A  =0x0001,
    WR2_A  =0x0002,
    WR3_A  =0x0003,
    WR4_A  =0x0004,
    WR5_A  =0x0005,
    WR6_A  =0x0006,
    WR7_A  =0x0007,

    // WR0~WR7 for IC-B
    WR0_B  =0x0008,
    WR1_B  =0x0009,
    WR2_B  =0x000A,
    WR3_B  =0x000B,
    WR4_B  =0x000C,
    WR5_B  =0x000D,
    WR6_B  =0x000E,
    WR7_B  =0x000F,
```



```

//■ Nmc_InPort
// Read register address
// RR0~RR7 for IC-A
RR0_A  =0x0000,
RR1_A  =0x0001,
RR2_A  =0x0002,
RR3_A  =0x0003,
RR4_A  =0x0004,
RR5_A  =0x0005,
RR6_A  =0x0006,
RR7_A  =0x0007,

// RR0~RR7 for IC-B
RR0_B  =0x0008,
RR1_B  =0x0009,
RR2_B  =0x000A,
RR3_B  =0x000B,
RR4_B  =0x000C,
RR5_B  =0x000D,
RR6_B  =0x000E,
RR7_B  =0x000F,

//■ Nmc_WriteReg
// Write register address
WR0    =0x0000,
WR1    =0x0001,
WR2    =0x0002,
WR3    =0x0003,
WR4    =0x0004,
WR5    =0x0005,
WR6    =0x0006,
WR7    =0x0007,

//■ Nmc_ReadReg
// Read register address
RR0    =0x0000,
RR1    =0x0001,
RR2    =0x0002,
RR3    =0x0003,
RR4    =0x0004,
RR5    =0x0005,
RR6    =0x0006,
RR7    =0x0007
}
Example) REG_MCX of WR0      REG_MCX.WR0

```

② Axis assignment

```

[VC]
#define AXIS_ALL      0xF    // All axes
#define AXIS_X       0x1    // X axis
#define AXIS_Y       0x2    // Y axis
#define AXIS_Z       0x4    // Z axis
#define AXIS_U       0x8    // U axis
#define AXIS_NONE    0      // No axis assignment

```

```

[C#]
public enum AXIS : int
{

```

```

// Axis assignment
ALL    =0xF,    // All axes
X      =0x1,    // X axis
Y      =0x2,    // Y axis
Z      =0x4,    // Z axis
U      =0x8,    // U axis
NONE   =0       // No axis assignment
}

```

Example) To assign all axes, **AXIS.ALL**

③ Device ID

[VC]

Device ID is the unique number assigned to the board.
Number of board is as follows.

Board	Device ID
MC8541P / MC8541Pe	0xA808
MC8581P / MC8581Pe	0xA809

[VC]

```

#define ID_MC8541P      0xA808      // MC8541P and MC8541Pe
#define ID_MC8581P      0xA809      // MC8581P and MC8581Pe

```

[C#]

```

public enum Dev_ID : ushort
{
    MC8541P      =0xA808, // MC8541P and MC8541Pe
    MC8581P      =0xA809 // MC8581P and MC8581Pe
}

```

Example) MC8541P is Dev_ID.MC8541P, MC8581P is Dev_ID.MC8581P.

④ Command definition

*Refer to MCX514 User's Manual for available commands.

[VC]

```

// Driving commands
#define MC8500P_CMD_DRVRL      0x0050 // Relative position drive
#define MC8500P_CMD_DRVNR      0x0051 // Counter relative position drive
#define MC8500P_CMD_DRVVP      0x0052 // + direction continuous pulse drive
#define MC8500P_CMD_DRVVM      0x0053 // - direction continuous pulse drive
#define MC8500P_CMD_DRVAB      0x0054 // Absolute position drive
#define MC8500P_CMD_DRVSBRK     0x0056 // Decelerating stop
#define MC8500P_CMD_DRVFBRK     0x0057 // Sudden stop
#define MC8500P_CMD_DIRCP       0x0058 // Direction signal + setting
#define MC8500P_CMD_DIRCM       0x0059 // Direction signal - setting
#define MC8500P_CMD_HMSRC       0x005A // Automatic home search execution

// Interpolation commands
#define MC8500P_CMD_1CIP        0x0060 // 1-axis linear interpolation drive (For multi-chip) *MC8581P only.
#define MC8500P_CMD_2CIP        0x0061 // 2-axis linear interpolation drive
#define MC8500P_CMD_3CIP        0x0062 // 3-axis linear interpolation drive
#define MC8500P_CMD_4CIP        0x0063 // 4-axis linear interpolation drive
#define MC8500P_CMD_CIPCW       0x0064 // CW circular interpolation drive
#define MC8500P_CMD_CIPCCW      0x0065 // CCW circular interpolation drive
#define MC8500P_CMD_BPIP2       0x0066 // 2-axis bit pattern interpolation drive
#define MC8500P_CMD_BPIP3       0x0067 // 3-axis bit pattern interpolation drive
#define MC8500P_CMD_BPIP4       0x0068 // 4-axis bit pattern interpolation drive
#define MC8500P_CMD_HLCW        0x0069 // CW helical interpolation drive
#define MC8500P_CMD_HLCCW       0x006A // CCW helical interpolation drive

```

```

#define MC8500P_CMD_HLPCW      0x006B // CW helical calculation
#define MC8500P_CMD_HLPCCW    0x006C // CCW helical calculation
#define MC8500P_CMD_DECEN     0x006D // Decelerating enabling
#define MC8500P_CMD_DECDIS    0x006E // Decelerating disabling
#define MC8500P_CMD_CLRINTRPT 0x006F // Interpolation interrupt clear
#define MC8500P_CMD_IPSTEP    0x006F // Single step interpolation

// Other commands
#define MC8500P_CMD_VINC      0x0070 // Deceleration increase
#define MC8500P_CMD_VDEC     0x0071 // Deceleration decrease
#define MC8500P_CMD_TMSTA     0x0073 // Timer start
#define MC8500P_CMD_TMSTP    0x0074 // Timer stop
#define MC8500P_CMD_DHOLD     0x0077 // Drive start holding
#define MC8500P_CMD_DFREE     0x0078 // Drive start holding release
#define MC8500P_CMD_R2CLR     0x0079 // Error/finish status clear
#define MC8500P_CMD_RR3P0    0x007A // RR3 page 0 display
#define MC8500P_CMD_RR3P1    0x007B // RR3 page 1 display
#define MC8500P_CMD_TXCLR     0x007C // Finish point maximum value clear
#define MC8500P_CMD_NOP       0x001F // NOP
#define MC8500P_CMD_RST       0x00FF // Command reset

```

[C#]

```
public enum CMD : int
```

```
{
```

```
// Drive commands
```

```

MC8500P_CMD_DRVRL      = 0x0050, // Relative position drive
MC8500P_CMD_DRVNR     = 0x0051, // Counter relative position drive
MC8500P_CMD_DRVVP     = 0x0052, // + direction continuous pulse drive
MC8500P_CMD_DRVVM     = 0x0053, // - direction continuous pulse drive
MC8500P_CMD_DRVAB     = 0x0054, // Absolute position drive
MC8500P_CMD_DRVSBRK   = 0x0056, // Decelerating stop
MC8500P_CMD_DRVFBRK   = 0x0057, // Sudden stop
MC8500P_CMD_DIRCP     = 0x0058, // Direction signal + setting
MC8500P_CMD_DIRCM     = 0x0059, // Direction signal - setting
MC8500P_CMD_HMSRC     = 0x005A, // Automatic home search execution

```

```
// Interpolation commands
```

```

MC8500P_CMD_1CIP      = 0x0060, // 1-axis linear interpolation drive (For multi-chip)*MC8581P only.
MC8500P_CMD_2CIP      = 0x0061, // 2-axis linear interpolation drive
MC8500P_CMD_3CIP      = 0x0062, // 3-axis linear interpolation drive
MC8500P_CMD_4CIP      = 0x0063, // 4-axis linear interpolation drive
MC8500P_CMD_CIPCW     = 0x0064, // CW circular interpolation drive
MC8500P_CMD_CIPCCW    = 0x0065, // CCW circular interpolation drive
MC8500P_CMD_BPIP2     = 0x0066, // 2-axis bit pattern interpolation drive
MC8500P_CMD_BPIP3     = 0x0067, // 3-axis bit pattern interpolation drive
MC8500P_CMD_BPIP4     = 0x0068, // 4-axis bit pattern interpolation drive
MC8500P_CMD_HLCW     = 0x0069, // CW helical interpolation drive
MC8500P_CMD_HLCCW    = 0x006A, // CCW helical interpolation drive
MC8500P_CMD_HLPCW     = 0x006B, // CW helical calculation
MC8500P_CMD_HLPCCW    = 0x006C, // CCW helical calculation
MC8500P_CMD_DECEN     = 0x006D, // Decelerating enabling
MC8500P_CMD_DECDIS    = 0x006E, // Decelerating disabling
MC8500P_CMD_CLRINTRPT = 0x006F, // Interpolation interrupt clear
MC8500P_CMD_IPSTEP    = 0x006F, // Single step interpolation

```

```
// Other commands
```

```

MC8500P_CMD_VINC      = 0x0070, // Deceleration increase
MC8500P_CMD_VDEC     = 0x0071, // Deceleration decrease
MC8500P_CMD_DCC       = 0x0072, // Deviation counter clear output

```

```

MC8500P_CMD_TMSTA      = 0x0073,      // Timer start
MC8500P_CMD_TMSTP      = 0x0074,      // Timer stop
MC8500P_CMD_SPSTA      = 0x0075,      // Split pulse start
MC8500P_CMD_SPSTP      = 0x0076,      // Split pulse stop
MC8500P_CMD_DHOLD      = 0x0077,      // Drive start holding
MC8500P_CMD_DFRET      = 0x0078,      // Drive start holding release
MC8500P_CMD_R2CLR      = 0x0079,      // Error / Finishing status clear
MC8500P_CMD_RR3P0      = 0x007A,      // RR3 Page0 display
MC8500P_CMD_RR3P1      = 0x007B,      // RR3 Page1 display
MC8500P_CMD_TXCLR      = 0x007C,      // Finish point maximum value clear
MC8500P_CMD_NOP        = 0x001F,      // NOP
MC8500P_CMD_RST        = 0x00FF      // Command reset
}

```

Example) To specify 2-axis liner interpolation drive, CMD.MC8500P_CMD_2CIP

⑤ Interpolation finishing message, finishing status

[VC]

// Interpolation finishing message

```

#define WM_BP_END          (WM_USER + 1)    // BP interpolation finishing message
#define WM_CIP_END        (WM_USER + 2)    // Continuous interpolation finishing message

```

//***** BP Interpolation Finishing Status *****

// ■ Normal

```

#define BP_START          0x101    // BP interpolation has started in the background.
#define BP_END            0x102    // BP interpolation has been successfully completed.

```

// ■ Errors before starting the interpolation

```

#define BP_CNT_ERR        0x111    // The number of the specified data is out of range.
#define BP_ALREADY_EXEC   0x112    // BP interpolation or continuous interpolation is already running.
#define BP_THREAD_ERR     0x113    // Thread cannot be started.
#define BP_MALLOC_ERR     0x114    // Memory cannot be allocated.
#define BP_PARAM_ERR      0x116    // The parameter is incorrect.
#define BP_NOT_OPEN_ERR   0x117    // The specified board is not opened.
#define BP_OTHER_ERR      0x118    // Other errors.
#define BP_FUNC_ERR       0x119    // Unusable function is used.

```

// ■ Errors during the interpolation driving

```

#define BP_STOP           0x121    // BP interpolation stopped during driving. (Too fast to stack next data)
#define BP_USER_STOP      0x122    // The user aborted BP interpolation.
#define BP_DRIVE_ERR      0x123    // Error occurred in the board during BP interpolation. (When
                                     the error status was set to RR0.)
#define BP_STOP_CERR      0x124    // Continuous interpolation stops during driving. (Due to RR2 error)
#define BP_GETSC_ERR      0x125    // Stack counter reading error

```

//***** Continuous Interpolation Finishing Status *****

// ■ Normal

```

#define CIP_START         0x201    // Continuous interpolation has started in the background.
#define CIP_END           0x202    // Continuous interpolation has been successfully completed.

```

// ■ Errors before starting the interpolation

```

#define CIP_CNT_ERR       0x211    // The number of the specified data is out of range.
#define CIP_ALREADY_EXEC  0x212    // BP interpolation or continuous interpolation is already running.
#define CIP_THREAD_ERR    0x213    // Thread cannot be started.
#define CIP_MALLOC_ERR    0x214    // Memory cannot be allocated.
#define CIP_CMD_ERR       0x215    // Command error (The wrong command was specified by the user.)
#define CIP_PARAM_ERR     0x216    // The parameter is incorrect.
#define CIP_NOT_OPEN_ERR  0x217    // The specified board is not opened.
#define CIP_OTHER_ERR     0x218    // Other errors.

```

```

#define CIP_FUNC_ERR                0x219    // Unusable function is used.

// ■Errors during the interpolation driving
#define CIP_STOP                    0x221    // Continuous interpolation stopped during driving. (Too fast to set next
data)
#define CIP_USER_STOP              0x222    // The user aborted Continuous interpolation.
#define CIP_DRIVE_ERR              0x223    // Error occurred in the board during Continuous interpolation. (When the
error status was set to RR0.)
#define CIP_STOP_CERR              0x224    // Continuous interpolation stops during driving. (Due to RR2 error)
#define CIP_GETSC_ERR              0x225    // Stack counter reading error

//***** Helical Interpolation   Finishing Status *****
// ■Normal
#define HL_START                    0x301    // Helical interpolation has started.
#define HL_VALUE_END                0x302    // Helical calculation finishes.

// ■Errors before starting helical interpolation
#define HL_CNT_ERR                  0x311    // The number of the specified data is out of range.
#define HL_PARAM_ERR               0x312    // The parameter is incorrect.
#define HL_NOT_OPEN_ERR            0x313    // The specified board is not opened.
#define HL_FUNC_ERR                 0x314    // Unusable function is used.
#define HL_OTHER_ERR               0x315    // Other errors.

[C#]
public enum MSG_ID : int
{
    // Interpolation finishing message
    WM_USER                =0x0400,
    WM_BP_END              =WM_USER+1,    // (WM_USER + 1) BP interpolation finishing message
    WM_CIP_END             =WM_USER+2,    // (WM_USER + 2) Continuous interpolation finishing
message
}
Example) MSG_ID and WM_BP_END    MSG_ID.WM_BP_END

    public enum Nmc_Status : uint
    {

//***** BP Interpolation   Finishing Status *****
// ■Normal
BP_START                    = 0x101,    // BP interpolation has started in the background.
BP_END                      = 0x102,    // BP interpolation has been successfully completed.

// ■Errors before starting the interpolation
BP_CNT_ERR                  = 0x111,    // The number of the specified data is out of range.
BP_ALREADY_EXEC            = 0x112,    // BP interpolation or continuous interpolation is
already running.
BP_THREAD_ERR              = 0x113,    // Thread cannot be started.
BP_MALLOC_ERR              = 0x114,    // Memory cannot be allocated.
BP_PARAM_ERR               = 0x116,    // The parameter is incorrect.
BP_NOT_OPEN_ERR           = 0x117,    // The specified board is not opened.
BP_OTHER_ERR               = 0x118,    // Other errors.
BP_FUNC_ERR                = 0x119,    // Unusable function is used.

// ■Errors during the interpolation driving
BP_STOP                    = 0x121, // BP interpolation stopped during driving. (Too fast to stack next data)
BP_USER_STOP              = 0x122, // The user aborted BP interpolation. The user aborted BP interpolation
BP_DRIVE_ERR              = 0x123, // Error occurred in the board during BP interpolation. (When the error status was set to
RR0.)
BP_STOP_CERR              = 0x124, // Continuous interpolation stops during driving. (Due to RR2 error)
BP_GETSC_ERR              = 0x125, // Stack counter reading error

```

```

//***** Continuous Interpolation   Finishing Status *****

```

```

// ■Normal

```

```

CIP_START          = 0x201, // Continuous interpolation has started in the background.
CIP_END            = 0x202, // Continuous interpolation has been successfully completed.

```

```

// ■Errors before starting the interpolation

```

```

CIP_CNT_ERR        = 0x211,      // The number of the specified data is out of range.
CIP_ALREADY_EXEC   = 0x212,      // BP interpolation or continuous interpolation is already running.
CIP_THREAD_ERR     = 0x213,      // Thread cannot be started.
CIP_MALLOC_ERR     = 0x214,      // Memory cannot be allocated.
CIP_CMD_ERR        = 0x215,      // Command error (The wrong command was specified by the user.)
CIP_PARAM_ERR      = 0x216,      // The parameter is incorrect.
CIP_NOT_OPEN_ERR   = 0x217,      // The specified board is not opened.
CIP_OTHER_ERR      = 0x218,      // Other errors.
CIP_FUNC_ERR       = 0x219,      // Unusable function is used.

```

```

// ■Errors during the interpolation driving

```

```

CIP_STOP           = 0x221, // Continuous interpolation stopped during driving. (Too fast to set next
data)
CIP_USER_STOP      = 0x222, // The user aborted Continuous interpolation.
CIP_DRIVE_ERR      = 0x223, // Error occurred in the board during Continuous interpolation. (When the
error status was set to RR0.)
CIP_STOP_CERR      = 0x224, // Continuous interpolation stops during driving. (Due to RR2 error)
CIP_GETSC_ERR      = 0x225, // Stack counter reading error

```

```

//***** Helical Interpolation   Finishing Status *****

```

```

// ■Normal

```

```

HL_START           = 0x301,      // Helical interpolation has started
HL_VALUE_END       = 0x302,      // Helical calculation finishes.

```

```

// ■Errors before starting helical interpolation

```

```

HL_CNT_ERR         = 0x311,      // The number of the specified data is out of range.
HL_PARAM_ERR       = 0x312,      // The parameter is incorrect.
HL_NOT_OPEN_ERR    = 0x313,      // The specified board is not opened.
HL_FUNC_ERR        = 0x314,      // Unusable function is used. (When using the function for MC8000P to
MC8500P)
HL_OTHER_ERR       = 0x315,      // Other errors.
}

```

⑥ Helical interpolation rotation direction

```

[VC]

```

```

#define HL_DIR_CW      0          // CW helical interpolation
#define HL_DIR_CCW     1          // CCW helical interpolation

```

```

[C#]

```

```

public enum HL_DIR : int
{
    HL_DIR_CW          = 0,          // CW helical interpolation
    HL_DIR_CCW         = 1          // CCW helical interpolation
}

```

(2) The method of axis assignment is as follows:

Axis	VC, VB.NET
X	AXIS_X
Y	AXIS_Y
Z	AXIS_Z
U	AXIS_U
All axes	AXIS_ALL

① To assign 1 axis

Specify one of the following axes: AXIS_X, AXIS_Y, AXIS_Z, and AXIS_U.

Example) Set 1000 to the drive speed of X axis.

```
[VC]      Nmc_Speed(No, IcNo, AXIS_X, 1000);
[VB.NET]  Call Nmc_Speed(No, IcNo, AXIS_X, 1000)
[C#]      MC8000P.Nmc_Speed(No, IcNo, AXIS.X, 1000);
```

② To assign 2 axes

Use Bit OR operator.

For instance, if the user tries to assign X and Y axes simultaneously,

```
[VC] . . . . Specify AXIS_X | AXIS_Y.
[VB.NET] . . . Specify AXIS_X Or AXIS_Y.
[C#] . . . . Specify AXIS.X | AXIS.Y.
```

Example) Set 1000 to the drive speed of X and Y axes.

```
[VC]      Nmc_Speed(No, IcNo, AXIS_X | AXIS_Y, 1000);
[VB.NET]  Call Nmc_Speed(No, IcNo, AXIS_X Or AXIS_Y, 1000)
[C#]      MC8000P.Nmc_Speed(No, IcNo, AXIS.X | AXIS.Y, 1000);
```

③ To assign 3 axes

Use Bit OR operator.

For instance, if the user tries to assign X, Y and Z axes simultaneously,

```
[VC] . . . . Specify AXIS_X | AXIS_Y | AXIS_Z.
[VB.NET] . . . Specify AXIS_X Or AXIS_Y Or AXIS_Z.
[C#] . . . . Specify AXIS.X | AXIS.Y | AXIS.Z.
```

Example) Set 1000 to the drive speed of X, Y and Z axes.

```
[VC]      Nmc_Speed(No, IcNo, AXIS_X | AXIS_Y | AXIS_Z, 1000);
[VB.NET]  Call Nmc_Speed(No, IcNo, AXIS_X Or AXIS_Y Or AXIS_Z, 1000)
[C#]      MC8000P.Nmc_Speed(No, IcNo, AXIS.X | AXIS.Y | AXIS.Z, 1000);
```

④ To assign all axes

Specify AXIS_ALL.

Example) Set 1000 to the drive speed of all axes.

```
[VC]      Nmc_Speed(No, IcNo, AXIS_ALL, 1000);
[VB.NET]  Call Nmc_Speed(No, IcNo, AXIS_ALL, 1000)
```

```
[C#]      MC8000P.Nmc_Speed(No, IcNo, AXIS.ALL, 1000);
```

(3) The structure used in the interpolation function is defined as follows:

① VC

// 2-axis BP interpolation

```
typedef struct _DATA_2BP
{
    USHORT Bp1p;          // BP1P data
    USHORT Bp1m;          // BP1M data
    USHORT Bp2p;          // BP2P data
    USHORT Bp2m;          // BP2M data
} DATA_2BP;
```

// 3-axis BP interpolation

```
typedef struct _DATA_3BP
{
    USHORT Bp1p;          // BP1P data
    USHORT Bp1m;          // BP1M data
    USHORT Bp2p;          // BP2P data
    USHORT Bp2m;          // BP2M data
    USHORT Bp3p;          // BP3P data
    USHORT Bp3m;          // BP3M data
}
```

```

    } DATA_3BP;

// 4-axis BP interpolation
typedef struct _DATA_4BP
{
    USHORT Bp1p;           // BP1P data
    USHORT Bp1m;           // BP1M data
    USHORT Bp2p;           // BP2P data
    USHORT Bp2m;           // BP2M data
    USHORT Bp3p;           // BP3P data
    USHORT Bp3m;           // BP3M data
    USHORT Bp4p;           // BP4P data
    USHORT Bp4m;           // BP4M data
} DATA_4BP;

// 2-axis continuous interpolation
typedef struct _DATA_2CIP  _MC8500P
{
    USHORT Command; // Command number (Set MC8500P_CMD_2CIP, MC8500P_CMD_CIPCW,
MC8500P_CMD_CIPCCW)
    long    Speed;           // Speed (When changing the speed, set 1~4,000,000. When not changing,
set 0.)
    long    EndP1;           // Finishing point (The first axis)
    long    EndP2;           // Finishing point (The second axis)
    long    Center1;         // Circular center point (The first axis)
    long    Center2;         // Circular center point (The second axis)
} DATA_2CIP_MC8500P; // Note: Specify interpolation axis in interpolation mode setting (2A)H.

// 3-axis continuous interpolation
typedef struct _DATA_3CIP  _MC8500P
{
    long    EndP1;           // Finishing point (The first axis)
    long    EndP2;           // Finishing point (The second axis)
    long    EndP3;           // Finishing point (The third axis)
    long    Speed;           // Speed (When changing the speed, set 1~4,000,000. When not changing,
set 0.)
} DATA_3CIP_MC8500P; // Note: Specify interpolation axis in interpolation mode setting (2A)H.

// 4-axis continuous interpolation
typedef struct _DATA_4CIP  _MC8500P
{
    long    EndP1;           // Finishing point (The first axis)
    long    EndP2;           // Finishing point (The second axis)
    long    EndP3;           // Finishing point (The third axis)
    long    EndP4;           // Finishing point (The fourth axis)
    long    Speed;           // Speed (When changing the speed, set 1~4,000,000. When not changing,
set 0.)
} DATA_4CIP_MC8500P; // Note: Specify interpolation axis in interpolation mode setting (2A)H.

// Interpolation mode setting
typedef struct _DATA_IPMODE
{
    BOOL    Cxiv;           // Interpolation axis change in circular interpolation (TURE: Change,
FALSE: Not change)
    BOOL    Lmdf;           // Short axis pulse equalization (TRUE: Enable, FALSE: Disable)
    USHORT Vcnst;           // Constant vector speed (0:None, 1:2-axis simple, 2:3-axis simple,
3:2-axis high accuracy)
}
DATA_IPMODE;

```



```
// Helical interpolation
typedef struct _DATA_HL
{
    USHORT Direction;          // Rotation direction (Set HL_DIR_CW: CW circular interpolation or HL_DIR_CCW:
    // CCW circular interpolation.)
    long Speed;                // Speed (1~2,000,000)
    long CenterX;              // Circular center point (X-axis)
    long CenterY;              // Circular center point (Y-axis)
    long EndPX;                // Finish point (X-axis)
    long EndPY;                // Finish point (Y-axis)
    long MoveZ;                // Moving amount (Z-axis) (0:Z-axis is not used. other than 0: Moving
    // amount of Z-axis)
    long MoveU;                // Moving amount (U-axis) (0:U-axis is not used. other than 0: Moving
    // amount of U-axis)
    USHORT HINum;              // Helical rotation number (0~65,535)
    long HIValue;              // Helical calculation value (0: Find helical calculation value before executing
    // interpolation, 0 or more: Execute interpolation with the calculation value which is
    // set
    DATA_IPMODE IpMode;      // Interpolation mode setting.
}
DATA_HL;
```

②VB.NET

' 2-axis BP interpolation

Structure DATA_2BP

```
Dim Bp1p As Short ' BP1P data
Dim Bp1m As Short ' BP1M data
Dim Bp2p As Short ' BP2P data
Dim Bp2m As Short ' BP2M data
```

End Structure

' 3-axis BP interpolation

Structure DATA_3BP

```
Dim Bp1p As Short ' BP1P data
Dim Bp1m As Short ' BP1M data
Dim Bp2p As Short ' BP2P data
Dim Bp2m As Short ' BP2M data
Dim Bp3p As Short ' BP3P data
Dim Bp3m As Short ' BP3M data
```

End Structure

' 4-axis BP interpolation

Structure DATA_4BP

```
Dim Bp1p As Short ' BP1P data
Dim Bp1m As Short ' BP1M data
Dim Bp2p As Short ' BP2P data
Dim Bp2m As Short ' BP2M data
Dim Bp3p As Short ' BP3P data
Dim Bp3m As Short ' BP3M data
Dim Bp4p As Short ' BP4P data
Dim Bp4m As Short ' BP4M data
```

End Structure

' 2-axis continuous interpolation

Structure DATA_2CIP_MC8500P

```
Dim Cmd As Short ' Command number (Set one of CMD_IP_2ST, CMD_IP_CW, CMD_IP_CCW.)
Dim Speed As Integer ' Speed (When changing the speed, set 1~4,000,000. When not changing, set 0.)
Dim EndP1 As Integer ' Finishing point (The first axis)
```



```

        this.Bp1m = bp1m;
        this.Bp2p = bp2p;
        this.Bp2m = bp2m;
    }
    public  ushort   Bp1p;    // BP1P data
    public  ushort   Bp1m;    // BP1M data
    public  ushort   Bp2p;    // BP2P data
    public  ushort   Bp2m;    // BP2M data
}

// 3-axis BP interpolation
[StructLayout(LayoutKind.Sequential)]
public struct DATA_3BP
{
    public  DATA_3BP(ushort bp1p,ushort bp1m,ushort bp2p,ushort bp2m,ushort bp3p,ushort bp3m)
    {
        this.Bp1p = bp1p;
        this.Bp1m = bp1m;
        this.Bp2p = bp2p;
        this.Bp2m = bp2m;
        this.Bp3p = bp3p;
        this.Bp3m = bp3m;
    }
    public  ushort   Bp1p;    // BP1P data
    public  ushort   Bp1m;    // BP1M data
    public  ushort   Bp2p;    // BP2P data
    public  ushort   Bp2m;    // BP2M data
    public  ushort   Bp3p;    // BP3P data
    public  ushort   Bp3m;    // BP3M data
}

// 4-axis BP interpolation
[StructLayout(LayoutKind.Sequential)]
public struct DATA_4BP
{
    public  DATA_4BP(ushort bp1p,ushort bp1m,ushort bp2p,ushort bp2m,ushort bp3p, ushort
bp4p,ushort bp3m)
    {
        this.Bp1p = bp1p;
        this.Bp1m = bp1m;
        this.Bp2p = bp2p;
        this.Bp2m = bp2m;
        this.Bp3p = bp3p;
        this.Bp3m = bp3m;
        this.Bp4p = bp4p;
        this.Bp4m = bp4m;
    }
    public  ushort   Bp1p;    // BP1P data
    public  ushort   Bp1m;    // BP1M data
    public  ushort   Bp2p;    // BP2P data
    public  ushort   Bp2m;    // BP2M data
    public  ushort   Bp3p;    // BP3P data
    public  ushort   Bp3m;    // BP3M data
    public  ushort   Bp4p;    // BP4P data
    public  ushort   Bp4m;    // BP4M data
}

// 2-axis continuous interpolation
[StructLayout(LayoutKind.Sequential)]

```

```

public struct DATA_2CIP_MC8500P
{
    public    DATA_2CIP_MC8500P(ushort command,ushort speed,int endp1,int endp2,int center1,int
center2)
    {
        this.Command      = command;
        this.Speed = speed;
        this.EndP1= endp1;
        this.EndP2= endp2;
        this.Center1      = center1;
        this.Center2      = center2;
    }
    public    ushort    Command;          // Command number (Set one of CMD_IP_2ST, CMD_IP_CW,
CMD_IP_CCW.)
    public    ushort    Speed;           // Speed (When changing the speed, set 1~4,000,000. When
not changing, set 0.)
    public    int       EndP1;           // Finishing point (The first axis)
    public    int       EndP2;           // Finishing point (The second axis)
    public    int       Center1;        // Circular center point (The first axis)
    public    int       Center2;        // Circular center point (The second axis)
}
// Note: Specify interpolation axis in interpolation mode setting
(2A)H.

```

// 3-axis continuous interpolation

[StructLayout(LayoutKind.Sequential)]

public struct DATA_3CIP_MC8500P

```

{
    public    DATA_3CIP_MC8500P(int endp1,int endp2,int endp3,ushort speed)
    {
        this.EndP1= endp1;
        this.EndP2= endp2;
        this.EndP3= endp3;
        this.Speed = speed;
    }
    public    int       EndP1;          // Finishing point (The first axis)
    public    int       EndP2;          // Finishing point (The second axis)
    public    int       EndP3;          // Finishing point (The third axis)
    public    ushort    Speed;         // Speed (When changing the speed, set 1~4,000,000. When not
changing, set 0.)
}
// Note: Specify interpolation axis in interpolation mode setting
(2A)H.

```

// 4-axis BP interpolation

[StructLayout(LayoutKind.Sequential)]

public struct DATA_4CIP_MC8500P

```

{
    public    DATA_4CIP_MC8500P(int endp1,int endp2,int endp3,int endp4, ushort speed)
    {
        this.EndP1= endp1;
        this.EndP2= endp2;
        this.EndP3= endp3;
        this.EndP4= endp4;
        this.Speed = speed;
    }
    public    int       EndP1;          // Finishing point (The first axis)
    public    int       EndP2;          // Finishing point (The second axis)
    public    int       EndP3;          // Finishing point (The third axis)
    public    int       EndP4;          // Finishing point (The fourth axis)
    public    ushort    Speed;         // Speed (When changing the speed, set 1~4,000,000. When not

```

```

changing, set 0.)    }                                     // Note: Specify interpolation axis in interpolation mode setting
(2A)H.

// Interpolation mode setting
[StructLayout(LayoutKind.Sequential)]
public struct DATA_IPMODE
{
    public DATA_IPMODE(bool cxiv, bool lmdf, ushort vcnst)
    {
        this.Cxiv = cxiv;
        this.Lmdf = lmdf;
        this.Vcnst= vcnst;
    }
    public bool    Cxiv;        // Interpolation axis change in circular interpolation (TURE: Change, FALSE: Not
change)
    public bool    Lmdf        // Short axis pulse equalization (TRUE: Enable, FALSE: Disable)
    public ushort  Vcnst;      // Constant vector speed (0:None, 1:2-axis simple, 2:3-axis simple, 3:2-axis high
accuracy)
}

    // Helical interpolation
[StructLayout(LayoutKind.Sequential)]
public struct DATA_HL
{
    public DATA_HL(ushort direction, int speed, int centerX, int centerY, int endPX, int endPY, int moveZ, int
moveU, ushort hlNum, int hlValue, DATA_IPMODE ipMode)
    {
        this.Direction =    direction;
        this.Speed =        speed;
        this.CenterX =      centerX;
        this.CenterY =      centerY;
        this.EndPX =        endPX;
        this.EndPY =        endPY;
        this.MoveZ =        moveZ;
        this.MoveU =        moveU;
        this.HlNum =        hlNum;
        this.HlValue =      hlValue;
        this.IpMode =       ipMode;
    }
    public ushort  Direction; // Rotation direction Rotation direction (Set HL_DIR_CW: CW circular interpolation or
HL_DIR_CCW: CCW circular interpolation.)
    public int     Speed;     // Speed (1~2,000,000)
    public int     CenterX;   // Circular center point (X-axis)
    public int     CenterY;   // Circular center point (Y-axis)
    public int     EndPX;     // Finish point (X-axis)
    public int     EndPY;     // Finish point (Y-axis)
    public int     MoveZ;     // Moving amount (Z-axis) (0:Z-axis is not used. other than 0: Moving amount of Z-axis)
    public int     MoveU;     // Moving amount (U-axis) (0:U-axis is not used. other than 0: Moving amount of
U-axis)
    public ushort  HlNum;     // Helical rotation number (0~65,535)
    public int     HlValue;   // Helical calculation value
    // (0: Find helical calculation value before executing interpolation. 0 or more: Execute
interpolation with the calculation value which is set.)
    public DATA_IPMODE IpMode; // Interpolation mode setting.
}

```

Examples of structure are as follows:

Example 1) Not define and initialize at the same time

```

DATA_2BP [] Data2Bp = new DATA_2BP[4];          // 2-axis BP interpolation

// Interpolation data setting
Data2Bp[0].Bp1p = 0xFF30;    // 1111 1111 0011 0000  BP1 + direction      10 pulse
Data2Bp[0].Bp1m = 0;        // 0000 0000 0000 0000  BP1 - direction      0 pulse
Data2Bp[0].Bp2p = 0;        // 0000 0000 0000 0000  BP2 + direction      0 pulse
Data2Bp[0].Bp2m = 0x84FF;   // 1000 0100 1111 1111  BP2 - direction      10 pulse

Data2Bp[1].Bp1p = 0xAC35;    // 1010 1100 0011 0101  BP1 + direction      8 pulse
Data2Bp[1].Bp1m = 0;        // 0000 0000 0000 0000  BP1 - direction      0 pulse
Data2Bp[1].Bp2p = 0xC000;    // 1100 0000 0000 0000  BP2 + direction      2 pulse
Data2Bp[1].Bp2m = 0x36E7;   // 0011 0110 1110 0111  BP2 - direction      10 pulse

Data2Bp[2].Bp1p = 0x3F3F;    // 0011 1111 0011 1111  BP1 + direction      12 pulse
Data2Bp[2].Bp1m = 0xC000;    // 1100 0000 0000 0000  BP1 - direction      2 pulse
Data2Bp[2].Bp2p = 0xFBDA;    // 1111 1011 1101 1010  BP2 + direction      12 pulse
Data2Bp[2].Bp2m = 0;        // 0000 0000 0000 0000  BP2 - direction      0 pulse

Data2Bp[3].Bp1p = 0;         // 0000 0000 0000 0000  BP1 + direction      0 pulse
Data2Bp[3].Bp1m = 0x1CF2;    // 0001 1100 1111 0010  BP1 - direction      8 pulse
Data2Bp[3].Bp2p = 0xFFFF;    // 1111 1111 1111 1111  BP2 + direction      16 pulse
Data2Bp[3].Bp2m = 0;        // 0000 0000 0000 0000  BP2 - direction      0 pulse

```

Example 2) Define and initialize at the same time

```

// 2-axis BP interpolation data      BP1P,  BP1M,  BP2P,  BP2M (Data for chapter 3.4.8 in MCX514 Manual)
DATA_2BP[] Data2Bp = new DATA_2BP[]
{
    new DATA_2BP(0xFFE4, 0x0000, 0x0000, 0x03FF),
    new DATA_2BP(0x03FF, 0x4000, 0xFFD0, 0x0000),
    new DATA_2BP(0x0000, 0xFFFF, 0x4AAB, 0x0000),
    new DATA_2BP(0xFE80, 0x000F, 0x1FFF, 0x0000),
    new DATA_2BP(0x97FF, 0x8000, 0x0000, 0x7F20),
};

```

(4) The interpolation axis (IpAxis) specified by the interpolation function is as follows:

Specify interpolation axis from X, Y, Z and U axis.

D15	D14	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
0	0	0	0	0	0	0	0	0	0	0	0	U-EN	Z-EN	Y-EN	X-EN

◆ Description of each bit

D3~0 U-EN~X-EN Specify interpolation axis from the following table.
0 : Not used as interpolation axis, 1 : Used as interpolation axis

Axis	Bit to specify.
X	D0
Y	D1
Z	D2
U	D3

Main axis should be specified in order of X-EN>Y-EN>Z-EN>U-EN. The axis of which bit is set 1 is selected.

(5) About the speed change when continuous interpolation function is executed.

Continuous interpolation function can change the speed during interpolation driving. The user can set the speed to each segment.

To change the speed during interpolation driving, set TRUE (True) to the function parameter SpdChgFlg.

◆ How to change the speed for each segment

Set the speed of each segment to the Speed of DATA_2CIP_MC8500P, the speed of DATA_3CIP_MC8500P, the speed of DATA_4CIP_MC8500P.

- When set the different speed from the previous segment, set 1~4,000,000.
- When set the same speed as the previous segment, set 0.

(6) Address assignment

The address of Nmc_OutPort or Nmc_InPort function should be assigned I/O address described in each board manual. I/O addresses such as Write register or Read register are as follows. See each board manual for more details.

Board	Address of Write register	Address of Read register
MC8541P / MC8541Pe	0~7	0~7
MC8581P / MC8581Pe	0~F	0~F

Note1: The address is given in hexadecimal.

Note2: It is easy to access the write or read register by using not Nmc_OutPort or Nmc_InPort function but the functions for write or read registers.

(7) IC number assignment

- ① When the board has one IC, set 0.
- ② When the board has 2 ICs, set the following value.
 - IC-A: 0
 - IC-B: 1

The number of IC chips and the assignment of IC number for each board are shown in the table below.

Board	Number of IC	IC number
MC8541P / MC8541Pe	1	0
MC8581P / MC8581Pe	2	0,1

Note: IC indicates MCX514.

5.1.4 Usage

■ API Function Declaration

API function declaration is defined in the following files.

VC++	: MC8000P_DLL.h
VB.NET	: MC8000P_DLL.vb
C#	: Refer to User's Manual or IntelliSense.

■ Usage

- (1) Start process . . . Execute Nmc_Open once before using each function.
- (2) End process . . . Execute Nmc_Close or Nmc_CloseAll at the end of program.

■ Board Number

The board number specified from an application should be as follows.

	Rotary switch value of board	Board number should be specified (decimal number)
1	0~9	0~9
2	A~F	10~15

■ Notes for Use of Function

(1) About VC, VB, C# (all languages)

- ① When each function is used before executing Nmc_Open function, operation is not guaranteed.
- ② When the board number, which is not connected, is assigned, the operation of each function is not guaranteed
- ③ Do not access the one board from 2 or more applications at the same time (such as Nmc_Open).
- ④ When other than Nmc_Open function is executed after executing Nmc_Close(Nmc_CloseAll) function. Operation is not guaranteed.

(2) VC, C# only

- ① When using the interrupt handling function, the time from the interrupt generation to user-defined function is not guaranteed by the nature of Windows.
- ② When the user tries to perform the interrupt, do not execute the close handling (Nmc_Close or Nmc_CloseAll) while the interrupt user-defined function (the function designated by Nmc_SetEvent) is running. Before executing the close handling, make sure that the interrupt user-defined function is finished.

■ How to handle an interrupt by VC

① Set the interrupt by using Nmc_Open function.

```
Nmc_Open(No, TRUE); // The second argument. TRUE: interrupt, FALSE: not interrupt
```

② Set the user-defined function handling an interrupt by using Nmc_SetEvent function, and set which interrupt is allowed or not.

```
Nmc_SetEvent(No, MC_EventProc, IpParam); // Set the user function address and argument.
Nmc_WriteReg(No, IcNo, AXIS_ALL, 0x8000); // Interrupt occurs at the stop of the specified IC (All axes).
```

③ If an interrupt occurs, the interrupt user-defined function set by Nmc_SetEvent is called.

The interrupt user-defined function can check the interrupt factor. To read the interrupt factor of RR1, use Nmc_ReadEvent function.

■ The example of the interrupt user-defined function

```
DWORD WINAPI MC_EventProc(LPVOID lpParam)
{
    . . . .
    long RrIrX, RrIrY, RrIrZ, RrIrU;
    Nmc_ReadEvent(No, IcNo, &RrIrX,&RrIrY,&RrIrZ,&RrIrU);
}
```



```

    . . . .
    return 0;
}

```

- ④ Use `Nmc_ResetEvent` to release the interrupt user-defined function. By executing this function, the user-defined function is not called if an interrupt occurs in the board.

```
Nmc_ResetEvent(No);
```

■ How to handle an interrupt by C# (C# only)

- ① Set the method to handle an interrupt by using `MC8000P.Nmc_SetEvent` function. Arguments cannot be specified. When multiple boards are used, example is as follows.

(When the board number is 0)

```

MC8000P.callback[0] = new MC8000P.UserThread(isr);           // isr is the interrupt user-defined function.
bool ret = MC8000P.Nmc_SetEvent(0, MC8000P.callback[0], param); // Board number 0 is specified to the first argument.
                                                    // Set the function address and argument.
MC8000P.Nmc_WriteReg1(0, (int)IC.A, AXIS.ALL, 0x0080);     // Generate an interrupt at the stop (All axes).
    . . .

```

(When the board number is 1)

```

MC8000P.callback[1] = new MC8000P.UserThread(isr2);        // isr is the interrupt user-defined function.
bool ret = MC8000P.Nmc_SetEvent(1, MC8000P.callback[1], param); // Board number 1 is specified to the first argument.
                                                    // Set the function address and argument.
MC8000P.Nmc_WriteReg1(1, (int)IC.A, AXIS.ALL, 0x0080);     // Generate an interrupt at the stop (All axes).
    . . .

```

- ② The interrupt handling function can check the interrupt factor. To read the interrupt factor of RR1, use `MC8000P.Nmc_ReadEvent` function.

(Interrupt user function of the board number 0)

```

static void isr(int param)
{
    int Rr1X, Rr1Y, Rr1Z, Rr1U;
    MC8000P.Nmc_ReadEvent(0, (int)IC.A, out Rr1X, out Rr1Y, out Rr1Z, out Rr1U);
    . . . .
}

```

(Interrupt user function of the board number 0)

```

static void isr2(int param)
{
    int Rr1X, Rr1Y, Rr1Z, Rr1U;
    MC8000P.Nmc_ReadEvent(1, (int)IC.A, out Rr1X, out Rr1Y, out Rr1Z, out Rr1U);
    . . . .
}

```

- ③ Use `MC8000P.Nmc_ResetEvent` method to release the interrupt handling function. By executing this function, the interrupt user-defined function method is not called if an interrupt occurs in the board.

■ Continuous Interpolation

When executing the continuous interpolation, please read the chapter “3.7 Continuous Interpolation” of MCX514 user’s manual carefully and execute the process described in the chapter in the application. Continuous Interpolation Functions *1 execute some of the process by DLL. So they will be used to execute the process of the continuous interpolation. But there are some notes when using Continuous Interpolation Functions. Please note them.

*1 : Nmc_2CIPExecMC8500P, Nmc_3CIPExecMC8500P, Nmc_4CIPExecMC8500P
 Nmc_2CIPExecMC8500P_BG, Nmc_3CIPExecMc8500P_BG, Nmc_4CIPExecMC8500P_BG

Notes for when using Continuous Interpolation Function:

Make sure to disable short axis pulse equalization. If enabled, unexpected operation may occur.

In Continuous interpolation function, continuous interpolation is executed by setting all the data of 1~8 segments to pre-buffer of MCX514 in advance.

Check the error and if the error occurs, function is ended. When the error is not occurred, check continuous interpolation pre-buffer stack counter (SC) of RR0, and write the data and interpolation commands of the next segment if it can be written. At this time, 6 is displayed as the writable stack counter value in this function. (Up to 6 stages of pre-buffer can be used after starting continuous interpolation drive in this function.)

This process is repeated until continuous interpolation finishes in this function. This function is not suitable to use when the user wants to execute the other process during executing this function because loop of error check and check process of writable state of next segment data are constantly performed inside DLL.

In this case, do not use continuous interpolation function but create continuous interpolation process by the application referring to MCX514 user’s manual.

About acceleration/deceleration drive in continuous interpolation, see the chapter “3.8 Acceleration / Deceleration Control in Interpolation” of MCX514 user’s manual. When using continuous interpolation function, the initial speed should be set for 4,000,000. (Don’t change the initial speed during this function is executing.) In this case the fixed speed driving mode is applied in each segment.

■The BP (Bit Pattern) Interpolation

When executing the BP interpolation, please read the chapter “3.4 The Bit Pattern Interpolation” of MCX514 user’s manual carefully and execute the process described in the chapter in the application. The BP interpolation functions *2 execute some of the process by DLL. So they will be used to execute the process of the BP interpolation. But there are some notes when using the BP interpolation functions. Please note them.

*2 : Nmc_2BPExecMC8500P, Nmc_3BPExecMC8500P, Nmc_4BPExecMC8500P
 Nmc_2BPExecMC8500P_BG, Nmc_3BPExecMC8500P_BG, Nmc_4BPExecMC8500P_BG

Notes for when using the BP Interpolation Function

Make sure to disable short axis pulse equalization. If enabled, unexpected operation may occur.

In BP interpolation function, continuous interpolation is executed by setting all the data of 1~8 segments to pre-buffer of MCX514 in advance.

Check the error and if the error occurs, function is ended. When the error is not occurred, check continuous interpolation pre-buffer stack counter (SC) of RR0, and write the data and interpolation commands of the next segment if it can be written. At this time, 6 is displayed as the writable stack counter value in this function. (Up to 6 stages of pre-buffer can be used after starting continuous interpolation drive in this function.)

This process is repeated until continuous interpolation finishes in this function. This function is not suitable to use when the user wants to execute the other process during executing this function because loop of error check and check process of writable state of next segment data are constantly performed inside DLL.

In this case, do not use BP interpolation function but create BP interpolation process by the application referring to MCX514 user’s manual.

About acceleration/deceleration drive in BP interpolation, see the chapter “3.8 Acceleration / Deceleration Control in Interpolation” of MCX514 user’s manual.

■Notes for Use of Interpolation Function

(1) Concerning the following interpolation function, the user can execute only one interpolation function at once.

While executing the interpolation function, the other interpolation function cannot be executed. If executed, an error will return.

Nmc_2BPExecMC8500P Nmc_2BPExecMC8500P_BG Nmc_2CIPExecMC8500P Nmc_2CIPExecMC8500P_BG

Nmc_3BPExecMC8500P	Nmc_3BPExecMC8500P_BG	Nmc_3CIPExecMC8500P	Nmc_3CIPExecMC8500P_BG
Nmc_4BPExecMC8500P	Nmc_4BPExecMC8500P_BG	Nmc_4CIPExecMC8500P	Nmc_4CIPExecMC8500P_BG

(2) While executing the above interpolation function, do not perform the following operation.

- ① Execution of the interpolation command (60h~6Fh)
- ② Change of interpolation mode setting (2Ah)

(3) The following interpolation function is executed in the background, so that the memory for interpolation data is allocated at the start of interpolation function and then the interpolation data specified by the user is copied. Then, when the interpolation process in the background is finished, the memory will be released and the message will be sent to the user window.

Therefore, while executing the following interpolation function in the background, do not exit the application.

Then, while executing the following interpolation function in the background, do not execute the close handling (Nmc_Close or Nmc_CloseAll).

If you want to stop the execution of interpolation function, execute the interpolation stop function (Nmc_IPStop) and make sure to receive the stop message.

Nmc_2BPExecMC8500P_BG	Nmc_3BPExecMC8500P_BG	Nmc_4BPExecMC8500P_BG
Nmc_2CIPExecMC8500P_BG	Nmc_3CIPExecMC8500P_BG	Nmc_4CIPExecMC8500P_BG

■Notes for when using helical interpolation function.

(1) Concerning the following helical interpolation function, the user can execute only one helical interpolation function to one IC at once.

Don't execute helical calculation function (Nmc_HLValueExe) during driving after executing helical interpolation function (Nmc_HLExec).

In this case, execute helical calculation function after checking that helical interpolation driving stops.

Similarly, don't execute helical interpolation function during executing helical calculation function (Nmc_HLValueExe).

Nmc_HLValueExe	Nmc_HLExec
----------------	------------

(2) When executing the function related helical interpolation as above, interpolation mode setting (2A)H is set as the details specified by argument.

(3) Helical interpolation function (Nmc_HLExec) is executed by constant speed drive.

Therefore, when this function is executed, initial speed of X-axis is set by specified drive speed value.

(4) Don't execute the process as follows during executing the function related helical interpolation as above.

- ① Execute interpolation command (60h~6Fh)
- ② Change interpolation mode setting (2Ah)

(5) Don't execute continuous interpolation function as follows during executing the function related helical interpolation as above.

Execute them after checking that helical calculation and helical interpolation drive finish.

Nmc_2BPExecMC8500P	Nmc_2BPExecMC8500P_BG	Nmc_2CIPExecMC8500P	Nmc_2CIPExecMC8500P_BG
Nmc_3BPExecMC8500P	Nmc_3BPExecMC8500P_BG	Nmc_3CIPExecMC8500P	Nmc_3CIPExecMC8500P_BG
Nmc_4BPExecMC8500P	Nmc_4BPExecMC8500P_BG	Nmc_4CIPExecMC8500P	Nmc_4CIPExecMC8500P_BG

■Notes for when developing multithread applications

This chapter describes the notes for developing applications which work in multithread.

In Nmc_xxx function, there are functions executing axis switching, data writing into WR6, WR7 and data reading to RR6, RR7.

Each Nmc_xxx function is as follows:

◆ Functions executing axis switching

Nmc_Reset	Nmc_Command	Nmc_Command_IP		
Nmc_WriteReg0	Nmc_WriteReg1	Nmc_WriteReg2	Nmc_WriteReg3	
Nmc_ReadReg2	Nmc_ReadReg3P	Nmc_ReadReg3		
Nmc_Jerk	Nmc_DJerk	Nmc_Acc	Nmc_Dec	Nmc_StartSpd Nmc_Speed
Nmc_Pulse	Nmc_Pulse__VB	Nmc_DecP	Nmc_DecP__VB	Nmc_Center Nmc_Lp
Nmc_Ep	Nmc_CompP	Nmc_CompM	Nmc_AccOfst	Nmc_HomeSpd Nmc_LpMax
Nmc_RpMax	Nmc_MR0	Nmc_MR1	Nmc_MR2	Nmc_MR
3Nmc_SpeedInc	Nmc_Timer			
Nmc_MRmMode	Nmc_PIO1Mode	Nmc_PIO2Mode	Nmc_HMSrch1Mode	Nmc_HMSrch2Mode
Nmc_FilterMode	Nmc_Sync0Mode	Nmc_Sync1Mode	Nmc_Sync2Mode	Nmc_Sync3Mode
Nmc_ReadLp	Nmc_ReadEp	Nmc_ReadSpeed	Nmc_ReadAccDec	Nmc_ReadMR0
Nmc_ReadMR1	Nmc_ReadMR2	Nmc_ReadMR3	Nmc_ReadCT	Nmc_ReadWR1
Nmc_ReadWR2	Nmc_ReadWR3	Nmc_ReadMRM	Nmc_ReadP1M	Nmc_ReadP2M
Nmc_ReadAc	Nmc_ReadStartSpd	Nmc_ReadSetSpeed	Nmc_ReadPulse	
Nmc_2BPExecMC8500P	Nmc_3BPExecMC8500P	Nmc_4BPExecMC8500P		
Nmc_2BPExecMC8500P_BG	Nmc_3BPExecMC8500P_BG	Nmc_4BPExecMC8500P_BG		
Nmc_2CIPExecMC8500P	Nmc_3CIPExecMC8500P	Nmc_4CIPExecMC8500P		
Nmc_2CIPExecMC8500P_BG	Nmc_3CIPExecMC8500P_BG	Nmc_4CIPExecMC8500P_BG		
Nmc_HLValueExec	Nmc_HLExec			
Nmc_WriteRegSetAxis	Nmc_ReadRegSetAxis	Nmc_WriteData		
Nmc_ReadData				

◆ Functions executing data writing into WR6, WR7

Nmc_Jerk	Nmc_DJerk	Nmc_Acc	Nmc_Dec	Nmc_StartSpd	Nmc_Speed
Nmc_Pulse	Nmc_Pulse__VB	Nmc_DecP	Nmc_DecP__VB	Nmc_Center	Nmc_Lp
Nmc_Ep	Nmc_CompP	Nmc_CompM	Nmc_AccOfst	Nmc_HomeSpd	Nmc_LpMax
Nmc_RpMax	Nmc_MR0	Nmc_MR1	Nmc_MR2	Nmc_MR3	
Nmc_SpeedInc	Nmc_Timer				
Nmc_MRmMode	Nmc_PIO1Mode	Nmc_PIO2Mode	Nmc_HMSrch1Mode	Nmc_HMSrch2Mode	
Nmc_FilterMode	Nmc_Sync0Mode	Nmc_Sync1Mode	Nmc_Sync2Mode	Nmc_Sync3Mode	
Nmc_2BPExecMC8500P		Nmc_3BPExecMC8500P		Nmc_4BPExecMC8500P	
Nmc_2BPExecMC8500P_BG		Nmc_3BPExecMC8500P_BG		Nmc_4BPExecMC8500P_BG	
Nmc_2CIPExecMC8500P		Nmc_3CIPExecMC8500P		Nmc_4CIPExecMC8500P	
Nmc_2CIPExecMC8500P_BG		Nmc_3CIPExecMC8500P_BG		Nmc_4CIPExecMC8500P_BG	
Nmc_HLValueExec		Nmc_HLExec			
Nmc_WriteReg6		Nmc_WriteReg7			
Nmc_WriteRegSetAxis		Nmc_WriteData			

When writing into WR6, WR7 by Nmc_OutPort or Nmc_WriteReg

◆ Functions executing data reading to RR6, RR7

Nmc_ReadLp	Nmc_ReadEp	Nmc_ReadSpeed	Nmc_ReadAccDec	Nmc_ReadMR0	Nmc_ReadMR1
Nmc_ReadMR2	Nmc_ReadMR3	Nmc_ReadCT	Nmc_ReadTX		
Nmc_ReadCHLN	Nmc_ReadHLV	Nmc_ReadWR1	Nmc_ReadWR2	Nmc_ReadWR3	
Nmc_ReadMRM	Nmc_ReadP1M	Nmc_ReadP2M	Nmc_ReadAc	Nmc_ReadStartSpd	
Nmc_ReadSetSpeed	Nmc_ReadPulse				
Nmc_ReadData					

To perform WR1~WR3 writing, RR1~RR2 reading, data writing command and data reading command, basically use the following Nmc_xxx function.

◆ WR1~WR3 writing

Nmc_WriteReg1	Nmc_WriteReg2	Nmc_WriteReg3	Nmc_WriteRegSetAxis
---------------	---------------	---------------	---------------------

◆ RR1~RR2 reading

Nmc_ReadReg2	Nmc_ReadReg3P	Nmc_ReadReg3	Nmc_ReadRegSetAxis
--------------	---------------	--------------	--------------------

◆ Data writing command

Nmc_Jerk	Nmc_DJerk	Nmc_Acc	Nmc_Dec	Nmc_StartSpd
Nmc_Speed	Nmc_Pulse	Nmc_Pulse__VB	Nmc_DecP	Nmc_DecP__VB
Nmc_Center	Nmc_Lp	Nmc_Ep	Nmc_CompP	Nmc_CompM
Nmc_AccOfst	Nmc_HomeSpd	Nmc_LpMax	Nmc_RpMax	Nmc_MR0
Nmc_MR1	Nmc_MR2	Nmc_MR3	Nmc_SpeedInc	Nmc_Timer
Nmc_MRmMode	Nmc_PIO1Mode	Nmc_PIO2Mode	Nmc_HMSrch1Mode	Nmc_HMSrch2Mode
Nmc_FilterMode	Nmc_Sync0Mode	Nmc_Sync1Mode	Nmc_Sync2Mode	Nmc_Sync3Mode
Nmc_WriteData				

◆ Data reading command

Nmc_ReadLp	Nmc_ReadEp	Nmc_ReadSpeed	Nmc_ReadAccDec	Nmc_ReadMR0
Nmc_ReadMR1	Nmc_ReadMR2	Nmc_ReadMR3	Nmc_ReadCT	Nmc_ReadTX
Nmc_ReadCHLN	Nmc_ReadHLV	Nmc_ReadWR1	Nmc_ReadWR2	Nmc_ReadWR3
Nmc_ReadMRM	Nmc_ReadP1M	Nmc_ReadP2M	Nmc_ReadAc	Nmc_ReadStartSpd

Nmc_ReadSetSpeed Nmc_ReadPulse
Nmc_ReadData

When trying to execute the commands such as WR1~WR3 data writing, RR1~RR2 data reading, data writing and reading, the user must take care in multithread environment if the same operations are performed without these functions.

(1) For example, when writing into WR1, Nmc_WriteReg1 is used; however, there is other way as follows:

```
① Nmc_OutPort(No, MCX_WR0, 0x011F);           // Switch to X axis (IC-A).
② Nmc_OutPort(No, MCX_WR1, Data);             // Write to WR1 (IC-A).
```

Also, the following functions can perform the same operation.

```
③ Nmc_WriteReg(No, IcNo, MCX_WR0, 0x011F); // Switch to X axis.
④ Nmc_WriteReg(No, IcNo, MCX_WR1, Data);   // Write to WR1.
```

In this case, if Nmc_xxx function to switch the axis is executed between ① and ② or ③ and ④, the data will be written into the WR1 of a different axis.

(2) For example, when setting the speed, Nmc_Speed is used; however, there is other way as follows:

```
① Nmc_OutPort( No, MCX_WR6, Data );           // Write to WR6 (IC-A).
② Nmc_OutPort( No, MCX_WR0, 0x0105 );         // Set WR6 data to the speed of X axis (IC-A).
```

Also, the following functions can perform the same operation.

```
③ Nmc_WriteReg6(No, IcNo, Data);             // Write to WR6.
④ Nmc_Command(No, IcNo, AXIS_X, 0x05);       // Set WR6 data to the speed of X axis.
```

In this case, if Nmc_xxx function to write data into WR6, WR7 is executed between ① and ② or ③ and ④, the other data will be set to the speed.

(3) For example, when reading logical position counter, Nmc_ReadLp is used; however, there is other way as follows:

```
① Nmc_OutPort( No, MCX_WR0, 0x0130 );         // Read logical position counter of X axis to RR6, RR7 (IC-A)
② d6 = Nmc_InPort( No, MCX_RR6 );             // Read from RR6 (IC-A)
③ d7 = Nmc_InPort( No, MCX_RR7 );             // Read from RR7 (IC-A)
```

In this case, if Nmc_xxx function to read data to RR6, RR7 is executed between ① and ② or ② and ③, the different data will be read.

Thus, in multithread environment, when calling API function more than twice to execute the objective operation, the user needs not to perform such an operation or needs to take exclusive control.

When the operation is finished by calling Nmc_xxx function once, it properly works in multithread environment. Each function of Nmc_xxx takes exclusive control each other.

Also, when the used develop the application which combines multithread and interruption, avoid to generate the interrupt and access to the board at the same time.

5.2 Notes on Programming

(1) Initial setting of input signal filter

Each input signal of the board, for example, a limit signal, uses the built-in integral filter of MCX514. The device driver provided by NOVA electronics sets the filter as shown below for each input signal by writing input signal filter mode (60h) to MCX514 by default when PC is powered on.

Filter delay time: : 512μsec

Each Input Signal Filter Enable/Disable:

Signal	Enable / Disable
EMG	Enable
nLMTP, nLMTM	Enable
nSTOP0, nSTOP1	Enable
nINPOS, nALARM	Enable
nPIO6	Enable
nSTOP2	Enable
nECA, nECB	Disable

To switch Enable/Disable of these input signal filters on the application, see chapter 7.3.6 of MCX514 user's manual. It can be changed by extension mode setting command (25h). The following example shows that all ICs of all axes (X, Y, Z and U axes) of the board number 0 are set to the same setting as the table above. Nmc_ExpMode executes extension mode setting command (25h).

Example 1)

```
Nmc_FilterMode(0, 0, AXIS_ALL, 0xAA7F); // Setting for IC-A
```

Example 2)

```
// Setting for IC-A
Nmc_WriteReg6(0, 0, 0xAA7F);
Nmc_WriteReg0(0, 0, 0x0F25);
```

Note:

①When executing command reset (00FF), the filter of each input signal is set inside the device driver same as the default when PC is powered on.

(2) PC standby mode and hibernation mode

In this device driver, the operation after standby or hibernation mode is not guaranteed.

When the user tries to access the board after standby or hibernation mode, be sure to restart PC before access

(3) Interrupt support

The user can use the interrupt in the application only developed in VC++ and C#.

Supported interrupts are as follows:

- All the interrupt reported by RR1 register.
- The interrupt that occurs when the value of stack counter changes from 8 to 7 and 4 to 3 in continuous interpolation drive bit pattern interpolation.

(4) Interrupt clearing

①The interrupt reported by RR1 register.

The interrupt is cleared after the driver read RR1, just after the interrupt occurs in the board.

Then, user-defined function of the application for interrupt is called. (Only when user-defined function has been set.)

②The interrupt that occurs when the value of stack counter changes from 8 to 7 and 4 to 3 in continuous interpolation drive bit pattern interpolation.

The interrupt is cleared inside driver, just after the interrupt occurs in the board.
Then, user-defined function of the application for interrupt is called. (Only when user-defined function has been set.)

5.3 Evaluation tool for MCX514.

MCX514 evaluation tool is used to evaluate the board equipped with MCX514 (MC8541P/MC8541Pe and MC8581P/MC8581Pe). The user can download on our website (Attached with MC8000P device driver software.). Before executing the evaluation tool, install MC8000P device driver.

Note: This chapter describes the outline of MCX514 evaluation tool. For more details, see ReadMe.txt in Tool\MCX514 Board folder.

5.3.1 Execution Program

Execution program is MCX514.exe.
For 32bitOS is in Tool\MCX514 Board\32 Tool folder, for 64bitOS in Tool\MCX514 Board\64 Tool folder.

■Regarding MCX514.

Each evaluation tool evaluates the MCX304 described below.

●MCX514.exe

- ①MCX514 of the board equipped with only one MCX514 (MC8541P, MC8541Pe).
- ②MCX514 of the board equipped with 2 or more MCX514 (MC8581P, MC8581Pe).

■ Regarding program execution

Multiple MCX514.exe can simultaneously be executed to the multiple board. Specify the different names for these exe file before executing. (Example : MCX514-A.exe, MCX514-B.exe and so on.) Multiple MCX514.exe cannot be executed to the ICs on the same board. 同

■When error occurs when activating.

When error occurs and cannot be executed in activating, process it according to the chapter [3.2.2 When error occurs in executing sample program and evaluation tool].

5.3.2 Function overview

Start the evaluation tool, and the Board Number Select Window appears. The user can select the board number (setting value of rotary switch (0~F) on the board).

And if the Board Name Display button is pressed, the board name will be shown at the side of the board number (only the board using this device driver). After selecting the board number, press OK button, and the Main Window appears.

In the Main Window, the user can perform parameter settings for each axis, drive/other command execution, current position/speed display and interrupt window display. In mode setting window, (write register, synchronous action, automatic home search PIO, multi-purpose register, input signal filter and interpolation mode setting window) and read register window, mode setting and read register checking can be executed.

5.3.3 Main Window

In the main window, the user can do the following operations as shown below.

The screenshot shows a software interface for a CNC controller. It is divided into several functional areas:

- Position Counter setting:** Located on the left, it includes checkboxes for '現在ドライブ速度' (Current Drive Speed), '現在加速度' (Current Acceleration), '現在タイマー値' (Current Timer Value), and 'MR0' through 'MR3'. Below these are fields for '論理位置カウンタ' (Logical Position Counter) and '実位置カウンタ' (Actual Position Counter), each with a 'CL' button.
- Drive command:** A table with columns for X, Y, Z, and U axes. It contains fields for '補間終点最大値' (Interpolation End Point Max Value) and '現在へリカル回転数' (Current Helical Rotation Count).
- Other commands:** A large table for parameter setting and reading for each axis (X, Y, Z, U). It includes parameters like '加速度増加率' (Acceleration Increase Rate), '減速度増加率' (Deceleration Increase Rate), '初速度' (Initial Speed), 'ドライブ速度' (Drive Speed), '移動リルス数/終点' (Move Pulse Count/End Point), 'マニュアル減速点' (Manual Deceleration Point), '円弧・中心' (Arc/Center), 'ソフトリミット' (Soft Limit), '加速PCオフセット' (Acceleration PC Offset), 'LP最大値' (LP Max Value), 'RP最大値' (RP Max Value), 'MR0' through 'MR3', '原点検出速度' (Origin Detection Speed), '速度増減値' (Speed Increase/Decrease Value), 'タイマー値' (Timer Value), '補間・終点最大値' (Interpolation/End Point Max Value), 'へリカル回転数' (Helical Rotation Count), and 'へリカル演算値' (Helical Calculation Value). Each parameter has a dropdown menu and a 'read' button.
- Synchronous action command:** A list of commands numbered 50 to 6F, including '相対位置ドライブ' (Relative Position Drive), '反相対位置ドライブ' (Inverse Relative Position Drive), '+方向連続ドライブ' (+ Direction Continuous Drive), '-方向連続ドライブ' (- Direction Continuous Drive), '絶対位置ドライブ' (Absolute Position Drive), 'ドライブ減速停止' (Drive Deceleration Stop), 'ドライブ即停止' (Drive Immediate Stop), '方向信号+設定' (Direction Signal + Setting), '方向信号-設定' (Direction Signal - Setting), '自動原点出し実行' (Automatic Origin Return Execution), '速度増加' (Speed Increase), '速度減少' (Speed Decrease), 'タイマー起動' (Timer Start), 'タイマー停止' (Timer Stop), 'ドライブ開始ホールド' (Drive Start Hold), 'ドライブ開始フリー' (Drive Start Free), and 'エラー終了ステータスクリア' (Error End Status Clear).
- Interpolation command:** A list of commands numbered 60 to 6F, including '1軸直線(マルチチップ)' (1-axis Linear (Multi-chip)), '2軸直線補間' (2-axis Linear Interpolation), '3軸直線補間' (3-axis Linear Interpolation), '4軸直線補間' (4-axis Linear Interpolation), 'CW円弧補間' (CW Arc Interpolation), 'CCW円弧補間' (CCW Arc Interpolation), '2軸BP補間' (2-axis BP Interpolation), '3軸BP補間' (3-axis BP Interpolation), '4軸BP補間' (4-axis BP Interpolation), 'CWへリカル補間' (CW Helical Interpolation), 'CCWへリカル補間' (CCW Helical Interpolation), 'CWへリカル演算' (CW Helical Calculation), 'CCWへリカル演算' (CCW Helical Calculation), '減速有効' (Deceleration Effective), '減速無効' (Deceleration Ineffective), and '補間ステップ補間刻み込みクリア' (Interpolation Step Interpolation Pitch Clear).
- Setting window (6 windows):** A bottom section containing buttons for 'リードレジスタ表示' (Read Register Display), 'ライトレジスタ設定' (Write Register Setting), '同期動作設定' (Synchronous Action Setting), '自動原点出し設定' (Automatic Origin Return Setting), 'PIO信号設定' (PIO Signal Setting), '多目的レジスタ入力信号フィルタ設定' (Multi-purpose Register Input Signal Filter Setting), '補間モード設定' (Interpolation Mode Setting), and 'プロット表示' (Plot Display).


Current position and drive speed are read out and displayed at intervals by checking left side of each item. Current drive speed of interpolation drive is displayed by reading the calculated pulse speed of the main axis.

Interrupt [IC number : 0]

The '割り込み' (Interrupt) window shows the status of various interrupt bits. The title bar indicates '[IC番号 : 0]'. The main area contains a table with columns for bits D15 through D0 and rows for axes X, Y, Z, and U. A legend at the top right states: 'このRR1は、Nmc_ReadEvent関数で読み出しています。注意:補間割り込みは表示されません' (This RR1 is read out by the Nmc_ReadEvent function. Note: Interpolation interrupt is not displayed). In the table, the bit D7 for axis X is marked with a solid black circle, indicating that an interrupt has occurred for that specific bit.

5.3.4 Write register setting window

Set WR1~WR5 (Mode register and output register) and read WR1~WR3 (Mode register) in write register setting window.




All the buttons of WR4 and WR5 can be checked. However, PIO signals of MC8541P/MC8541Pe and MC8581P/MC8581Pe which can be used are limited. Please refer to hardware user's manual to set them correctly.

5.3.5 Synchronous action setting window

Set synchronous action register (SYNC0~SYNC3) in synchronous action setting window.

Synchronous action setting window




Kinds of synchronous action of MC8541P/MC8541Pe and MC8581P/MC8581Pe which can be used are limited. Please refer to hardware user's manual to set them correctly.

5.3.6 Automatic home search setting window

Set automatic home search register (H1M and H2M) in automatic home search setting window.


Automatic home search setting window



5.3.7 PIO signal setting window

Set and read PIO (PIO1 and PIO2) in PIO signal setting window.


PIO signal setting window [※nPIO0~nPIO3signal (D0,1~6,7 bit) are output only. Don't set general input (○○).]



5.3.8 Multi-purpose register / input signal filter setting window

Set and read Multi-purpose register (MRM) and set input signal filter setting (FLM) in multi-purpose register / input signal filter setting window.


Multi-purpose register / input signal filter setting window



5.3.9 Interpolation mode setting window

Set interpolation mode (IPM) in interpolation mode setting window.

Interpolation mode setting



Please make sure to clear all the setting buttons when the evaluation of interpolation drive and then, evaluate any other function.

5.3.10 Read register window

Read and display the current value of RR0, RR2, RR3, RR4 and RR5 (Status register and PIO read register) in read register window. Reading interval is 50mSEC. About RR1, display it in interrupt window when interrupt occurs.

Read register [※RR1 is displayed in interrupt window when interrupt occurs.]

